Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103
<u>District I</u> – (575) 393-6161	Energy, Minerals and Natural R	esources WELL API NO.	Revised August 1, 2011
1625 N French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283	RECEIVED DIV	USION 30-025	5-12512
811 S First St , Artesia, NM 88210 <u>District III</u> – (505) 334-6178	FEB 27 2012 South St. Francis I		
1000 Rio Biazos Rd , Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe, NM 8/303	6. State Oil & G	as Lease No.
1220 S. St. Francis Di, Santa Fe, NM 87505	HORRSOCD	B-3290	
SUNDRY NO	TICES AND REPORTS ON WELLS		or Unit Agreement Name
DIFFERENT RESERVOIR USE "APP	POSALS TO DRILL OR TO DEEPEN OR PLUG BA LICATION FOR PERMIT" (FORM C-101) FOR SUG		'U'
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well Other	8. Well Number	
2 Name of Operator	<u> </u>	9. OGRID Num	ber
3. Address of Operator	xico-formerly XERIC Oil f	10. Pool name o	r Wıldcat
1625 N. French]	Drive Hobbs, NM 882		-ayburg San Andres
4. Well Location			· ront
Unit Letter <u>B</u> Section 8	: 330 feet from the North Township 195 Range	line and 1650 feet from NMPM	om the <u>East</u> line County LEA
Section 0	11. Elevation (Show whether DR, RKB		County LIFA
		, , , , , , , , , , , , , , , , , , ,	
12 Chack	Appropriate Box to Indicate Nature	of Natice Penart or Other	· Data
		•	
NOTICE OF I PERFORM REMEDIAL WORK [NTENTION TO: PLUG AND ABANDON REF	SUBSEQUENT RE	PORT OF: ALTERING CASING □
TEMPORARILY ABANDON [MMENCE DRILLING OPNS.	P AND A
PULL OR ALTER CASING [SING/CEMENT JOB	
DOWNHOLE COMMINGLE	J		
OTHER:		HER:	
	npleted operations. (Clearly state all pertin work). SEE RULE 19.15.7 14 NMAC. Fo		
proposed completion or r		1	S
•	SEE ATTACHED.		
ī			
Spud Date:	Rig Release Date:		
<u> </u>			
I hereby certify that the information	on above is true and complete to the best of	my knowledge and belief.	
\sim M \sim 0.8	P		1 1
SIGNATURE ALLE	TITLE COMP	liance Office, D	ATE 2/27/2012
Towns on maint areas		(b)	/ /
Type or print name For State Use Only	E-mail address:	Pi	HONE:
		anno-	7 77 7-1-
APPROVED BY:	TITLE JAS	T IVE D	ATE <u>Z-Z7-20/Z</u>

February 27, 2012

State of NM formerly Xeric Oil & Gas

Mexico 'U' #1

30-025-12512

UL-B Sec8-T19S-R38E

- 1. MIRU Plugging Rig.
- 2. Confirm top of fish @ 1900' or casing part @ 1800'.
- 3. RIH w/ packer to 1600', est. rate.
- 4. Sqz. w/100 sxs cmt. WOC and tag. TOC should be @ 1700'.
- 5. Circ w/ MLF.
- 6. Spot 50 sxs cmt 1700'-1200'. WOC and tag.
- 7. Spot 50 sxs cmt 500' to surface.
- 8. RDMO plugging rig.
- 9. Install P/A marker.

Office District I	o Appropriate District	State of Ne	w Mexico	Form C-103
		Energy, Minerals and	l Natural Resources	May 27, 2004
	., Hobbs, NM 88240			WELL API NO.
District II	re Artecia NIM 99210	OIL CONSERVA	TION DIVISION	30-025-12512
District III	,		5. Indicate Type of Lease	
	1000 Rio Brazos Rd., Aztec, NM 87410		STATE X FEE	
District IV	Dr., Santa Fe, NM	Santa Fe, F	1101 9 1 2 0 2	6. State Oil & Gas Lease No.
87505	Di., Santa Pe, Nivi	, ,	V	B-3290
	SUNDRY NOTIO	CES AND REPORTS ON W	/ELLS	7. Lease Name or Unit Agreement Name
		ALS TO DRILL OR TO DEEPEN		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			MEXICO "U"	
1. Type of Well: Oil Well Gas Well Other			8. Well Number 1	
2. Name of Or		<u> </u>		9. OGRID Number
		GAS CORPORATION		025482
3. Address of Operator			10. Pool name or Wildcat	
	•	MIDLAND, TX 79702		Hobbs Grayburg San Andres
4. Well Locati				nobbs Glayburg San Andres
Unit I		330 feet from the	Namet Samuel	1650 Seat Security R
			North line and	
Section	n 8	Township 19S		NMPM County Lea
		11. Elevation (Show wheth	ier DR, RKB, RT, GR, ei	c.)
Pit or Below-grade	Tank Application or	Closura		
1 .				
Pit type	1	terDistance from nearest	t fresh water wellI	Pistance from nearest surface water
Pit Liner Thicknes	is: mil	Below-Grade Tank: Volum	e bbls;	Construction Material
	12. Check A	ppropriate Box to India	cate Nature of Notice	e, Report or Other Data
		PPP		o, respect of Outer Burn
	NOTICE OF IN	TENTION TO:	SU	BSEQUENT REPORT OF:
PERFORM RE	MEDIAL WORK 🔲	PLUG AND ABANDON		
TEMPORARIL	Y ABANDON 🔲	CHANGE PLANS		RILLING OPNS. P AND A
PULL OR ALTI	ER CASING	MULTIPLE COMPL [CASING/CEME	INT JOB 🔲 💍 🔆
				1 30° C
OTHER:		Γ		mpt SWD Conversion 🛛 📉
	· · · · · · · · · · · · · · · · · · ·			
13. Descrit	pe proposed or compl	eted operations. (Clearly sta	ate all pertinent details,	and give pertinent dates, including estimated date
13. Describ of start	ing any proposed wo	eted operations. (Clearly stark). SEE RULE 1103. For	ate all pertinent details, Multiple Completions:	
13. Describ of start	be proposed or compling any proposed wormpletion.	eted operations. (Clearly stark). SEE RULE 1103. For	ate all pertinent details, Multiple Completions:	and give pertinent dates, including estimated date
13. Describ of start or reco	ing any proposed wo mpletion.	rk). SEE RULE 1103. For	Multiple Completions:	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
13. Describ of start	ing any proposed wo mpletion. MIRU REECC	rk). SEE RULE 1103. For i	Multiple Completions:	and give pertinent dates, including estimated date
13. Describ of start or reco	ing any proposed wo mpletion. MIRU REECC TIGHT SPOT	rk). SEE RULE 1103. For the second of the service. ND @ 1800'.	Multiple Completions: WELLHEAD & AT	Attach wellbore diagram of proposed completion TEMPT TO POOH W/2 3/8" TBG. HIT
13. Describ of start or reco	ing any proposed wo mpletion. MIRU REECC TIGHT SPOT TBG WON'T I	rk). SEE RULE 1103. For the second of the service. ND @ 1800'. MOVE. SHOOT OFF T	Multiple Completions: WELLHEAD & AT BG ABOVE CHEC	And give pertinent dates, including estimated date Attach wellbore diagram of proposed completion TEMPT TO POOH W/2 3/8" TBG. HIT K VALVE ON SUB PUMP. PULL
13. Describ of start or reco 9/18/00 9/19/00	ing any proposed wo mpletion. MIRU REECC TIGHT SPOT TBG WON'T I ENOUGH WE	rk). SEE RULE 1103. For the second of the service. ND @ 1800'. MOVE. SHOOT OFF TEIGHT TO PART THE F	Multiple Completions: WELLHEAD & AT BG ABOVE CHEC REMAINING CABLE	And give pertinent dates, including estimated date Attach wellbore diagram of proposed completion TEMPT TO POOH W/2 3/8" TBG. HIT K VALVE ON SUB PUMP. PULL EIN HOLE.
13. Described of start of recomplete of 9/18/00 9/19/00 9/20/00	ing any proposed wo mpletion. MIRU REECO TIGHT SPOT TBG WON'T I ENOUGH WE RIH W/SPEAI	rk). SEE RULE 1103. For the second of the service. ND @ 1800'. MOVE. SHOOT OFF TEIGHT TO PART THE FR TO CATCH POWER	Multiple Completions: WELLHEAD & AT BG ABOVE CHEC REMAINING CABLE CABLE. GET ALL	And give pertinent dates, including estimated date Attach wellbore diagram of proposed completion TEMPT TO POOH W/2 3/8" TBG. HIT K VALVE ON SUB PUMP. PULL E IN HOLE. OF CABLE.
13. Describ of start or reco 9/18/00 9/19/00	ing any proposed wo mpletion. MIRU REECO TIGHT SPOT TBG WON'T I ENOUGH WE RIH W/SPEAI RIH W/OVER	RK). SEE RULE 1103. For S WELL SERVICE. ND @ 1800'. MOVE. SHOOT OFF T EIGHT TO PART THE F R TO CATCH POWER SHOT & CATCH FISH.	Multiple Completions: WELLHEAD & AT BG ABOVE CHEC REMAINING CABLE CABLE. GET ALL CANNOT MOVE	And give pertinent dates, including estimated date Attach wellbore diagram of proposed completion TEMPT TO POOH W/2 3/8" TBG. HIT K VALVE ON SUB PUMP. PULL IN HOLE. OF CABLE. ABOVE 1800'. RELEASE FISH &
13. Described of start of recomplete of start or recomplete of the start of recomplete of the start of the st	ing any proposed wo mpletion. MIRU REECO TIGHT SPOT TBG WON'T I ENOUGH WE RIH W/SPEAI RIH W/OVER POOH W/OVI	CK). SEE RULE 1103. For SOMELL SERVICE. ND @ 1800'. MOVE. SHOOT OFF TEIGHT TO PART THE FOR TO CATCH POWER SHOT & CATCH FISH.	Multiple Completions: WELLHEAD & AT BG ABOVE CHECK REMAINING CABLE CABLE. GET ALL CANNOT MOVE A IPER SUB & 6 DC's	And give pertinent dates, including estimated date Attach wellbore diagram of proposed completion TEMPT TO POOH W/2 3/8" TBG. HIT K VALVE ON SUB PUMP. PULL IN HOLE. OF CABLE. ABOVE 1800'. RELEASE FISH & START PUSHING FISH TO BTM.
13. Described of start of start or reconstruction 9/18/00 9/19/00 9/21/00 9/22/00	ing any proposed won mpletion. MIRU REECO TIGHT SPOT TBG WON'T I ENOUGH WE RIH W/SPEAI RIH W/OVER POOH W/OVI PARTED TBO	CK). SEE RULE 1103. For SOMELL SERVICE. ND @ 1800'. MOVE. SHOOT OFF TEIGHT TO PART THE FOR TO CATCH POWER SHOT & CATCH FISH. SOME SHOT. RIH W/BUM SOME PUSHING TO BTM.	Multiple Completions: WELLHEAD & AT BG ABOVE CHECK REMAINING CABLE CABLE. GET ALL CANNOT MOVE A IPER SUB & 6 DC'S WAITING ON RIG F	And give pertinent dates, including estimated date Attach wellbore diagram of proposed completion TEMPT TO POOH W/2 3/8" TBG. HIT K VALVE ON SUB PUMP. PULL E IN HOLE. OF CABLE. ABOVE 1800'. RELEASE FISH & S. START PUSHING FISH TO BTM. REPAIRS.
13. Described of start of recomplete of start or recomplete of the start of recomplete of the start of the st	ing any proposed won mpletion. MIRU REECO TIGHT SPOT TBG WON'T I ENOUGH WE RIH W/SPEAI RIH W/OVER POOH W/OVI PARTED TBO ATTEMPT TO	CK). SEE RULE 1103. For the control of the control	Multiple Completions: WELLHEAD & AT BG ABOVE CHECK REMAINING CABLE CABLE. GET ALL CANNOT MOVE A IPER SUB & 6 DC'S WAITING ON RIG F WASHOVER PIPE	And give pertinent dates, including estimated date Attach wellbore diagram of proposed completion TEMPT TO POOH W/2 3/8" TBG. HIT K VALVE ON SUB PUMP. PULL E IN HOLE. OF CABLE. ABOVE 1800'. RELEASE FISH & S. START PUSHING FISH TO BTM. REPAIRS. & TAGGED FILL 100' ABOVE TOP OF
13. Described of start of start or reconstruction 9/18/00 9/19/00 9/21/00 9/22/00	ing any proposed wormpletion. MIRU REECO TIGHT SPOT TBG WON'T I ENOUGH WE RIH W/SPEAI RIH W/OVER POOH W/OVI PARTED TBO ATTEMPT TO	CK). SEE RULE 1103. For the control of the control	Multiple Completions: WELLHEAD & AT BG ABOVE CHECK REMAINING CABLE CABLE. GET ALL CANNOT MOVE A IPER SUB & 6 DC's WAITING ON RIG F WASHOVER PIPE A + MILL. RIH W/ DC	And give pertinent dates, including estimated date Attach wellbore diagram of proposed completion TEMPT TO POOH W/2 3/8" TBG. HIT K VALVE ON SUB PUMP. PULL E IN HOLE. OF CABLE. ABOVE 1800'. RELEASE FISH & S. START PUSHING FISH TO BTM. REPAIRS. & TAGGED FILL 100' ABOVE TOP OF C's + BIT. CIRCULATED FILL OUT TO
13. Described of start of start or recomplete o	ing any proposed wormpletion. MIRU REECO TIGHT SPOT TBG WON'T I ENOUGH WE RIH W/SPEAI RIH W/OVER POOH W/OVI PARTED TBO ATTEMPT TO FISH. POOH	CK). SEE RULE 1103. For the control of the control	Multiple Completions: WELLHEAD & AT BG ABOVE CHECK REMAINING CABLE CABLE. GET ALL CANNOT MOVE A IPER SUB & 6 DC'S WAITING ON RIG F WASHOVER PIPE A + MILL. RIH W/ DC BLOCK & WAIT ON	And give pertinent dates, including estimated date Attach wellbore diagram of proposed completion TEMPT TO POOH W/2 3/8" TBG. HIT K VALVE ON SUB PUMP. PULL IN HOLE. OF CABLE. ABOVE 1800'. RELEASE FISH & START PUSHING FISH TO BTM. REPAIRS. & TAGGED FILL 100' ABOVE TOP OF C's + BIT. CIRCULATED FILL OUT TO I RESULTS.
13. Described of start of start or reconstruction 9/18/00 9/19/00 9/21/00 9/22/00	ing any proposed wormpletion. MIRU REECO TIGHT SPOT TBG WON'T I ENOUGH WE RIH W/SPEAI RIH W/OVER POOH W/OVI PARTED TBO ATTEMPT TO FISH. POOH	CK). SEE RULE 1103. For the control of the control	Multiple Completions: WELLHEAD & AT BG ABOVE CHECK REMAINING CABLE CABLE. GET ALL CANNOT MOVE A IPER SUB & 6 DC'S WAITING ON RIG F WASHOVER PIPE A + MILL. RIH W/ DC BLOCK & WAIT ON	And give pertinent dates, including estimated date Attach wellbore diagram of proposed completion TEMPT TO POOH W/2 3/8" TBG. HIT K VALVE ON SUB PUMP. PULL IN HOLE. OF CABLE. ABOVE 1800'. RELEASE FISH & START PUSHING FISH TO BTM. REPAIRS. & TAGGED FILL 100' ABOVE TOP OF C's + BIT. CIRCULATED FILL OUT TO I RESULTS.
13. Described of start of start or recomplete o	ing any proposed wormpletion. MIRU REECO TIGHT SPOT TBG WON'T I ENOUGH WE RIH W/SPEAI RIH W/OVER POOH W/OVI PARTED TBO ATTEMPT TO FISH. POOH	CK). SEE RULE 1103. For the control of the control	Multiple Completions: WELLHEAD & AT BG ABOVE CHECK REMAINING CABLE CABLE. GET ALL CANNOT MOVE A IPER SUB & 6 DC'S WAITING ON RIG F WASHOVER PIPE A + MILL. RIH W/ DC BLOCK & WAIT ON	And give pertinent dates, including estimated date Attach wellbore diagram of proposed completion TEMPT TO POOH W/2 3/8" TBG. HIT K VALVE ON SUB PUMP. PULL IN HOLE. OF CABLE. ABOVE 1800'. RELEASE FISH & START PUSHING FISH TO BTM. REPAIRS. & TAGGED FILL 100' ABOVE TOP OF C's + BIT. CIRCULATED FILL OUT TO I RESULTS.
13. Described of start of start or recomplete o	ing any proposed wormpletion. MIRU REECO TIGHT SPOT TBG WON'T I ENOUGH WE RIH W/SPEAI RIH W/OVER POOH W/OVI PARTED TBO ATTEMPT TO FISH. POOH	CK). SEE RULE 1103. For the control of the control	Multiple Completions: WELLHEAD & AT BG ABOVE CHECK REMAINING CABLE CABLE. GET ALL CANNOT MOVE A IPER SUB & 6 DC'S WAITING ON RIG F WASHOVER PIPE A + MILL. RIH W/ DC BLOCK & WAIT ON	And give pertinent dates, including estimated date Attach wellbore diagram of proposed completion TEMPT TO POOH W/2 3/8" TBG. HIT K VALVE ON SUB PUMP. PULL IN HOLE. OF CABLE. ABOVE 1800'. RELEASE FISH & START PUSHING FISH TO BTM. REPAIRS. & TAGGED FILL 100' ABOVE TOP OF C's + BIT. CIRCULATED FILL OUT TO I RESULTS.
13. Described of start of start or reco. 9/18/00 9/19/00 9/20/00 9/21/00 9/22/00 9/27/00 9/28/00	ing any proposed wormpletion. MIRU REECO TIGHT SPOT TBG WON'T I ENOUGH WE RIH W/SPEAI RIH W/OVER POOH W/OVI PARTED TBO ATTEMPT TO FISH. POOH TOP OF FISH CSG PARTED	CK). SEE RULE 1103. For all WELL SERVICE. ND @ 1800'. MOVE. SHOOT OFF THE FOR TO CATCH POWER SHOT & CATCH FISH. SHOT & CATCH &	Multiple Completions: WELLHEAD & AT BG ABOVE CHECK REMAINING CABLE CABLE CABLE CANNOT MOVE IPER SUB & 6 DC'S WAITING ON RIG F WASHOVER PIPE + MILL RIH W/ DC BLOCK & WAIT ON DO'. SI FOR EVALL	And give pertinent dates, including estimated date Attach wellbore diagram of proposed completion TEMPT TO POOH W/2 3/8" TBG. HIT K VALVE ON SUB PUMP. PULL EIN HOLE. OF CABLE. ABOVE 1800'. RELEASE FISH & START PUSHING FISH TO BTM. REPAIRS. & TAGGED FILL 100' ABOVE TOP OF C'S + BIT. CIRCULATED FILL OUT TO I RESULTS. JATION.
13. Described of start of start of start or reco. 9/18/00 9/19/00 9/20/00 9/21/00 9/22/00 9/27/00 I hereby certify to	ing any proposed wormpletion. MIRU REECO TIGHT SPOT TBG WON'T I ENOUGH WE RIH W/SPEAI RIH W/OVER POOH W/OVI PARTED TBO ATTEMPT TO FISH. POOH TOP OF FISH CSG PARTED	O WELL SERVICE. ND @ 1800'. MOVE. SHOOT OFF TEIGHT TO PART THE FER TO CATCH POWER SHOT & CATCH FISH. ERSHOT. RIH W/BUM ERSHOT. RIH W/BUM O MILL OVER FISH W/ W/WASHOVER PIPE I. RUN IMPRESSION D. FISH STUCK @ 190	Multiple Completions: WELLHEAD & AT BG ABOVE CHECK REMAINING CABLE CABLE. GET ALL CANNOT MOVE IPER SUB & 6 DC'S WAITING ON RIG F WASHOVER PIPE + MILL. RIH W/ DC BLOCK & WAIT ON DO'. SI FOR EVALL of the best of my knowle	And give pertinent dates, including estimated date Attach wellbore diagram of proposed completion TEMPT TO POOH W/2 3/8" TBG. HIT K VALVE ON SUB PUMP. PULL EIN HOLE. OF CABLE. ABOVE 1800'. RELEASE FISH & S. START PUSHING FISH TO BTM. REPAIRS. & TAGGED FILL 100' ABOVE TOP OF C'S + BIT. CIRCULATED FILL OUT TO I RESULTS. JATION.
13. Described of start of start of start or reco. 9/18/00 9/19/00 9/20/00 9/21/00 9/22/00 9/27/00 I hereby certify to	ing any proposed wormpletion. MIRU REECO TIGHT SPOT TBG WON'T I ENOUGH WE RIH W/SPEAI RIH W/OVER POOH W/OVI PARTED TBO ATTEMPT TO FISH. POOH TOP OF FISH CSG PARTED	O WELL SERVICE. ND @ 1800'. MOVE. SHOOT OFF TEIGHT TO PART THE FER TO CATCH POWER SHOT & CATCH FISH. ERSHOT. RIH W/BUM ERSHOT. RIH W/BUM O MILL OVER FISH W/ W/WASHOVER PIPE I. RUN IMPRESSION D. FISH STUCK @ 190	Multiple Completions: WELLHEAD & AT BG ABOVE CHECK REMAINING CABLE CABLE. GET ALL CANNOT MOVE IPER SUB & 6 DC'S WAITING ON RIG F WASHOVER PIPE + MILL. RIH W/ DC BLOCK & WAIT ON DO'. SI FOR EVALL of the best of my knowle	And give pertinent dates, including estimated date Attach wellbore diagram of proposed completion TEMPT TO POOH W/2 3/8" TBG. HIT K VALVE ON SUB PUMP. PULL EIN HOLE. OF CABLE. ABOVE 1800'. RELEASE FISH & START PUSHING FISH TO BTM. REPAIRS. & TAGGED FILL 100' ABOVE TOP OF C'S + BIT. CIRCULATED FILL OUT TO I RESULTS. JATION.
13. Described of start of start of start of start of reco. 9/18/00 9/19/00 9/20/00 9/21/00 9/22/00 9/27/00 I hereby certify to grade tank has been	ing any proposed wormpletion. MIRU REECO TIGHT SPOT TBG WON'T I ENOUGH WE RIH W/SPEAI RIH W/OVER POOH W/OVI PARTED TBO ATTEMPT TO FISH. POOH TOP OF FISH CSG PARTED	WELL SERVICE. ND @ 1800'. MOVE. SHOOT OFF TEIGHT TO PART THE FOR TO CATCH POWER SHOT & CATCH FISH. ERSHOT. RIH W/BUM ERSHOT. RIH W/BUM ENDING TO BTM. 'O MILL OVER FISH W/W W/WASHOVER PIPE I. RUN IMPRESSION D. FISH STUCK @ 190 Above is true and complete to closed according to NMOCD guide	Multiple Completions: WELLHEAD & AT BG ABOVE CHECK REMAINING CABLE CABLE. GET ALL CANNOT MOVE IPER SUB & 6 DC'S WAITING ON RIG F WASHOVER PIPE + MILL. RIH W/ DC BLOCK & WAIT ON DO'. SI FOR EVALL of the best of my knowled delines \(\Brightarrow\), a general permit	And give pertinent dates, including estimated date Attach wellbore diagram of proposed completion TEMPT TO POOH W/2 3/8" TBG. HIT K VALVE ON SUB PUMP. PULL EIN HOLE. OF CABLE. ABOVE 1800'. RELEASE FISH & E. START PUSHING FISH TO BTM. REPAIRS. & TAGGED FILL 100' ABOVE TOP OF C's + BIT. CIRCULATED FILL OUT TO I RESULTS. JATION. dge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan
13. Described of start of start of start or reco. 9/18/00 9/19/00 9/20/00 9/21/00 9/22/00 9/27/00 I hereby certify to	ing any proposed wormpletion. MIRU REECO TIGHT SPOT TBG WON'T I ENOUGH WE RIH W/SPEAI RIH W/OVER POOH W/OVI PARTED TBO ATTEMPT TO FISH. POOH TOP OF FISH CSG PARTED	WELL SERVICE. ND @ 1800'. MOVE. SHOOT OFF TEIGHT TO PART THE FOR TO CATCH POWER SHOT & CATCH FISH. ERSHOT. RIH W/BUM ERSHOT. RIH W/BUM ENDING TO BTM. 'O MILL OVER FISH W/W W/WASHOVER PIPE I. RUN IMPRESSION D. FISH STUCK @ 190 Above is true and complete to closed according to NMOCD guide	Multiple Completions: WELLHEAD & AT BG ABOVE CHECK REMAINING CABLE CABLE. GET ALL CANNOT MOVE IPER SUB & 6 DC'S WAITING ON RIG F WASHOVER PIPE + MILL. RIH W/ DC BLOCK & WAIT ON DO'. SI FOR EVALL of the best of my knowle	And give pertinent dates, including estimated date Attach wellbore diagram of proposed completion TEMPT TO POOH W/2 3/8" TBG. HIT K VALVE ON SUB PUMP. PULL EIN HOLE. OF CABLE. ABOVE 1800'. RELEASE FISH & S. START PUSHING FISH TO BTM. REPAIRS. TAGGED FILL 100' ABOVE TOP OF C'S + BIT. CIRCULATED FILL OUT TO RESULTS. JATION. dge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan
13. Described of start of start of start of start of reco. 9/18/00 9/19/00 9/20/00 9/21/00 9/22/00 9/27/00 I hereby certify to grade tank has been signature.	ing any proposed wompletion. MIRU REECO TIGHT SPOT TBG WON'T I ENOUGH WE RIH W/SPEAI RIH W/OVER POOH W/OVI PARTED TBO ATTEMPT TO FISH. POOH TOP OF FISH CSG PARTEI	WELL SERVICE. ND (2) 1800'. MOVE. SHOOT OFF TEIGHT TO PART THE FER TO CATCH POWER SHOOT & CATCH FISH. ERSHOT. RIH W/BUM BE PUSHING TO BTM. O MILL OVER FISH W/W W/WASHOVER PIPE I. RUN IMPRESSION D. FISH STUCK (2) 190 Above is true and complete to closed according to NMOCD guid	Multiple Completions: WELLHEAD & AT BG ABOVE CHECK REMAINING CABLE CABLE. GET ALL CANNOT MOVE A IPER SUB & 6 DC'S WAITING ON RIG F WASHOVER PIPE + MILL. RIH W/ DC BLOCK & WAIT ON DO'. SI FOR EVALU of the best of my knowle delines , a general permit	And give pertinent dates, including estimated date Attach wellbore diagram of proposed completion TEMPT TO POOH W/2 3/8" TBG. HIT K VALVE ON SUB PUMP. PULL EIN HOLE. OF CABLE. ABOVE 1800'. RELEASE FISH & E. START PUSHING FISH TO BTM. REPAIRS. A TAGGED FILL 100' ABOVE TOP OF C's + BIT. CIRCULATED FILL OUT TO I RESULTS. JATION. Adde and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan Lalyst DATE 3/15/05
13. Described of start of start of start of start of reco. 9/18/00 9/19/00 9/20/00 9/21/00 9/22/00 9/27/00 I hereby certify to grade tank has been	ing any proposed wompletion. MIRU REECO TIGHT SPOT TBG WON'T I ENOUGH WE RIH W/SPEAI RIH W/OVER POOH W/OVI PARTED TBO ATTEMPT TO FISH. POOH TOP OF FISH CSG PARTEI	O WELL SERVICE. ND (a) 1800'. MOVE. SHOOT OFF TEIGHT TO PART THE FER TO CATCH POWER SHOT & CATCH FISH. ERSHOT. RIH W/BUM OF PUSHING TO BTM. O MILL OVER FISH W/W W/WASHOVER PIPE I. RUN IMPRESSION D. FISH STUCK (a) 190 Above is true and complete to blosed according to NMOCD guidence. TITE ford E-mail address TITE Ford E-mail address O WELL SERVICE. ND (a) 1800'. TITE TO CATCH TO THE	Multiple Completions: WELLHEAD & AT BG ABOVE CHECK REMAINING CABLE CABLE. GET ALL CANNOT MOVE PER SUB & 6 DC'S WAITING ON RIGHT WASHOVER PIPE + MILL. RIH W/ DC BLOCK & WAIT ON DO'. SI FOR EVALL of the best of my knowled delines , a general permit CLE Production Ar ess: Acrawford@xericoi	And give pertinent dates, including estimated date Attach wellbore diagram of proposed completion TEMPT TO POOH W/2 3/8" TBG. HIT K VALVE ON SUB PUMP. PULL EIN HOLE. OF CABLE. ABOVE 1800'. RELEASE FISH & S. START PUSHING FISH TO BTM. REPAIRS. & TAGGED FILL 100' ABOVE TOP OF C's + BIT. CIRCULATED FILL OUT TO I RESULTS. IATION. dge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1
13. Described of start of start or recomplished o	ing any proposed wompletion. MIRU REECO TIGHT SPOT TBG WON'T I ENOUGH WE RIH W/SPEAI RIH W/OVER POOH W/OVI PARTED TBO ATTEMPT TO FISH. POOH TOP OF FISH CSG PARTEI	O WELL SERVICE. ND (a) 1800'. MOVE. SHOOT OFF TEIGHT TO PART THE FER TO CATCH POWER SHOT & CATCH FISH. ERSHOT. RIH W/BUM OF PUSHING TO BTM. O MILL OVER FISH W/W W/WASHOVER PIPE I. RUN IMPRESSION D. FISH STUCK (a) 190 Above is true and complete to blosed according to NMOCD guidence. TITE ford E-mail address TITE Ford E-mail address O WELL SERVICE. ND (a) 1800'. TITE TO CATCH TO THE	Multiple Completions: WELLHEAD & AT BG ABOVE CHECK REMAINING CABLE CABLE. GET ALL CANNOT MOVE PER SUB & 6 DC'S WAITING ON RIGHT WASHOVER PIPE + MILL. RIH W/ DC BLOCK & WAIT ON DO'. SI FOR EVALL of the best of my knowled delines , a general permit CLE Production Ar ess: Acrawford@xericoi	And give pertinent dates, including estimated date Attach wellbore diagram of proposed completion TEMPT TO POOH W/2 3/8" TBG. HIT K VALVE ON SUB PUMP. PULL EIN HOLE. OF CABLE. ABOVE 1800'. RELEASE FISH & START PUSHING FISH TO BTM. REPAIRS. A TAGGED FILL 100' ABOVE TOP OF C'S + BIT. CIRCULATED FILL OUT TO I RESULTS. JATION. Age and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan . Lalyst DATE 3/15/05 Com Telephone No. 432-683-3171
13. Described of start of recompliance of start	MIRU REECO TIGHT SPOT TBG WON'T I ENOUGH WE RIH W/SPEAI RIH W/OVER POOH W/OVI PARTED TBO ATTEMPT TO FISH. POOH TOP OF FISH CSG PARTED That the information a movement of the constructed or or or only The constructed or	O WELL SERVICE. ND (a) 1800'. MOVE. SHOOT OFF TEIGHT TO PART THE FER TO CATCH POWER SHOT & CATCH FISH. ERSHOT. RIH W/BUM OF PUSHING TO BTM. O MILL OVER FISH W/W W/WASHOVER PIPE I. RUN IMPRESSION D. FISH STUCK (a) 190 Above is true and complete to blosed according to NMOCD guidence. TITE ford E-mail address TITE Ford E-mail address O WELL SERVICE. ND (a) 1800'. TITE TO CATCH TO THE	Multiple Completions: WELLHEAD & AT BG ABOVE CHECK REMAINING CABLE CABLE. GET ALL CANNOT MOVE PER SUB & 6 DC'S WAITING ON RIGHT WASHOVER PIPE + MILL. RIH W/ DC BLOCK & WAIT ON DO'. SI FOR EVALL of the best of my knowled delines , a general permit CLE Production Ar ess: Acrawford@xericoi	And give pertinent dates, including estimated date Attach wellbore diagram of proposed completion TEMPT TO POOH W/2 3/8" TBG. HIT K VALVE ON SUB PUMP. PULL EIN HOLE. OF CABLE. ABOVE 1800'. RELEASE FISH & START PUSHING FISH TO BTM. REPAIRS. A TAGGED FILL 100' ABOVE TOP OF C'S + BIT. CIRCULATED FILL OUT TO I RESULTS. JATION. Age and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan . Lalyst DATE 3/15/05 Com Telephone No. 432-683-3171
13. Described of start of recompliance of start or recompliance or recompliance of start of start or recompliance	MIRU REECO TIGHT SPOT TBG WON'T I ENOUGH WE RIH W/SPEAI RIH W/OVER POOH W/OVI PARTED TBO ATTEMPT TO FISH. POOH TOP OF FISH CSG PARTED That the information a movement of the constructed or or or only The constructed or	O WELL SERVICE. ND (a) 1800'. MOVE. SHOOT OFF TEIGHT TO PART THE FER TO CATCH POWER SHOT & CATCH FISH. ERSHOT. RIH W/BUM OF PUSHING TO BTM. O MILL OVER FISH W/W W/WASHOVER PIPE I. RUN IMPRESSION D. FISH STUCK (a) 190 Above is true and complete to blosed according to NMOCD guidence. TITE ford E-mail address TITE Ford E-mail address O WELL SERVICE. ND (a) 1800'. TITE TO CATCH TO THE	Multiple Completions: WELLHEAD & AT BG ABOVE CHECK REMAINING CABLE CABLE. GET ALL CANNOT MOVE A IPER SUB & 6 DC'S WAITING ON RIG F WASHOVER PIPE + MILL. RIH W/ DC BLOCK & WAIT ON DO'. SI FOR EVALU of the best of my knowle delines , a general permit	And give pertinent dates, including estimated date Attach wellbore diagram of proposed completion TEMPT TO POOH W/2 3/8" TBG. HIT K VALVE ON SUB PUMP. PULL EIN HOLE. OF CABLE. ABOVE 1800'. RELEASE FISH & S. START PUSHING FISH TO BTM. REPAIRS. & TAGGED FILL 100' ABOVE TOP OF C's + BIT. CIRCULATED FILL OUT TO I RESULTS. IATION. dge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1

Office	Tew Mexico Form C-103			
<u>District I</u> Energy, Minerals a 1625 N. French Dr., Hobbs, NM 88240	nd Natural Resources May 27, 2004 WELL API NO.			
District II OIL CONCEDV	ATION DIVISION 30-025-12512			
1301 W. Grand Ave, Artesia, NW 66210	St. Francis Dr. 5. Indicate Type of Lease STATE X FEE			
1000 Pro Deepes Pd. Agtes NM 97410	NM 87505 6. State Oil & Gas Lease No.			
1220 S. St. Francis Dr., Santa Fe, NM	B-3290			
SUNDRY NOTICES AND REPORTS ON (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEP	EN OR PLUG BACK TO A			
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM PROPOSALS.)	C-101) FOR SUCH MEXICO "U" 8. Well Number 1			
1. Type of Well: Oil Well X Gas Well Other				
2. Name of Operator XERIC OIL & GAS CORPORATION	9. OGRID Number 025482			
3. Address of Operator	10. Pool name or Wildcat			
P. O. BOX 352, MIDLAND, TX 79702	Hobbs Grayburg San Andres			
4. Well Location	N 11 1 1650 6 16 1 7 1 17			
Unit Letter B : 330 feet from the Section 8 Township 19				
* ***	ether DR, RKB, RT, GR, etc.)			
Pit or Below-grade Tank Application or Closure				
	est fresh water well Distance from nearest surface water time bbls; Construction Material			
Pit Liner Thickness: mil Below-Grade Tank: Volu				
12. Check Appropriate Box to Inc	licate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON TEMPORARILY ABANDON ☐ CHANGE PLANS	REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. P AND A			
TEMPORARILY ABANDON	CASING/CEMENT JOB			
OTHER:	State all pertinent details, and give pertinent dates, including estimated date			
	or Multiple Completions: Attach wellbore diagram of proposed completion			
or recompletion.	THE OF CONCERNATION DIVICION BALLOT			
	THE OIL CONSERVATION DIVISION MUST			
	BE NOTIFIED 24 HOURS PRIOR TO THE			
1. MIRU Pulling Unit	BEGINNING OF PLUGGING OPERATIONS.			
2. Tag top of fish $@ \pm 1900$ '.				
3. Circulate hole w/9.65# fresh water				
4. Set cement retainer @ \pm 1700' and	=			
5. Spot 50 sx cmt @ top of retainer a				
6. Spot 50 sx cmt 500' & circulate to7. RD Pulling Unit, install dry hole n	, _ , _ , _ , _ , _ , _ , _ , _ , _ , _			
Wellbore Diagram Attached	panier & cream location.			
Wonder Blagram / Mached	TE LANGE			
I hereby certify that the information above is true and complet	e to the best of my knowledge and belief. I further certify that any pit or below-			
grade tank has been/yith be constructed or closed according to NMOCD	guidelines , a general permit or an (attached) alternative OCD-approved plan.			
SIGNATURE Charle Agusta.	TITLE Production Analyst DATE 11/10/05			
	dress: Acrawford@xogoperating.com Telephone No. 432-683-3171			
For State Use Only				
APPROVED BY: Jam Www.	CHELD REPRESENTATIVE II/STAFF MANAGE			
Conditions of Approval (if ary):	NOV 2 2 2005			
v	•			

XERIC OIL & GAS CORP. WELLBORE DIAGRAM

WELL: Mexico V#1

COUNTY: Lea

STATE: NM

