Submit 1 Copy To Appropriate District	State of New Me	exico	Form C-103				
Office <u>District 1</u> – (575) 393-6161	Energy, Minerals and Natu	ural Resources	Revised August 1, 2011				
1625 N French Dr Hobbs NM 88240	WELL API NO.						
<u>District II</u> – (575) 748-1283	30-025-23868						
	811 S First St., Artesia, NM 88210 OIL CONSERVATION DIVISION						
District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	STATE 🔲 FEE 🛛 🗸						
<u>District IV</u> – (505) 476-3460	6. State Oil & Gas Lease No.						
1220 S St. Francis Dr , Santa Fe, NM	309574						
87505 SUNDRY NOT	7. Lease Name or Unit Agreement Name						
(DO NOT USE THIS FORM FOR PROPOS	Langlie Jal Unit						
DIFFERENT RESERVOIR USE "APPLIC							
PROPOSALS.)	8. Well Number 49₩-						
1. Type of Well: Oil Well							
2. Name of Operator	9. OGRID Number						
Resaca	263848						
3. Address of Operator	10. Pool name or Wildcat						
1331 Lamar Street, Suite 1450	Langlie Mattix: 7Rivers-Queen-Grayburg						
4. Well Location			· · · · · · · · · · · · · · · · · · ·				
Unit Letter <u>H</u> :	0feet from the <u>East</u> line						
Section 6	Township 25S	Range 37E	NMPM Lea County				
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3229' GR							
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data							
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:							
PERFORM REMEDIAL WORK 🗌	PLUG AND ABANDON	-DEMEDIAL WOR					
TEMPORARILY ABANDON	CHANGE PLANS						
PULL OR ALTER CASING	MULTIPLE COMPL	Per Underground	d Injection Control Program Manual				
			hall be set within or less than 100				
		feet of the upper	most injection perfs or open hole.				
OTHER: Locate casing leak & cement squeeze if necessary,							

OTHER: Locate casing leak & cement squeeze if necessary, Run MIT

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

 \boxtimes

Objective: Locate casing leak & repair with cement squeeze if necessary. Run Mechanical Integrity Test.

- 1.) MIRU Pulling Unit & Above Ground Steel Pit
- 2.) Pressure Test casing to locate leak.
- 3.) Once leak is located, cement squeeze if necessary, w/ appropriate sacks of cement.
- 4.) Drill out cement & circulate well clean.
- 5.) Pressure Test casing to make sure casing repair was successful.
- 6.) Run Mechanical Integrity Test (Notify NMOCD- Hobbs 24 hrs. prior to test); Pull chart for NMOCD.
- 7.) RDMO Pulling Unit, clean location, clean & dispose of pit fluids. Place well on injection.

Conserv MUST BE NOTIN Spud Date: Spud Date:		Rig Releas	se Date:		of Approval: 1 i bs office 24 h ing MIT Test	Durs
I hereby certify that the informat	ion above is true and	d complete to the	he best of my	v knowledge and b	elief.	
SIGNATURE	H.	TITLE	Engineer	Assistant	DATE	2/27/2012
Type or print name Mela	<u>nie Reyes</u> E-1	mail address: <u>n</u>	nelanie.reyes	@resacaexploitati	on.com PHONE:	<u>(432) 580-8500</u>
For State Use Only APPROVED BY Conditions of Approval (if any):	Pingel		STAFF	ME	DATE MAR	<u>3-1-2012</u> 01 2012



2/28/2012

LANGLIE JAL UNIT # 49 WELL HISTORY

RUPU Unfience well off, Work on PKR, Trs to Rel, Rel PKR POH 97 its 2 3/8 tbg, 4 1/2 adj pkr close well 8/30/2004 8/30/2004 RU lobo, tbg testers, hook up providence kill truck, pumping 30 bbls pkr fluid down on ass fluid started cornering out of ground POH LD 97 jts 4 1/2 PKR Fienge well with 1 -JT Dorve to location, rigged up wireline open well, laid down ??? And 2 3/8 tbg set cast iron plug at 3396 with 20 foot cement on top, 7/22/2005 tallied tbg to 2630' came out with 100 its in derrick shut down to let cement set flagged well with 25? Shut in well, 7/12/2005 Ran CIBP in 4 1/2 casting set at 3096 Ran 3" dump bailor in 4 1/2 casting dumped 20' cement Cost 4 1/2 cast iron bridge plug Rental #20 setting tool Cost 2 sks cement 7/13/2005 unflanged well, no PSI, pulled 2 jt 2 3/8 packer in hole 46 or 96? Jts pressured up to test plug, and packer came out in sets of 5 stanb or 76 jts in derrrick testing through tubing wing for casing leak, started laying down tubing, tester, laid down rest of tubing 26 its found leak at close to surface, flanged well with 1 it 2 3/8 shut well in 7/14/2005 unflaged well, ran 79 its 2 3/8 from derrick in hole, laid down 77 its on racks, dug around well to get to casing took Bradenhead off unflanged casing 4 1/2" rigged up wireline to free casing its 2 attempts did not unscrew of right points laid down lit of 4 1/2 casing with 6' casing sub shut in well 7/15/2005 picked up oversto for 4 1/2" casing, with charge over 2 7/8 tbg sand ? 4' sub 2 7/8' 1-2 sub 2 7/8 on top wireline ???/// 2 jts 4 1/2" casing laid through casing laid 3 its down closed well in shut down 7/18/2005 picked up 1 - 4 1/2 " drill collar with shoe and fishing tool changed over on bottom 7/19/2005 no psi 4? Drill collar and cross over sub and 7 1/2 shoe ??? Tools pick up 7 1/2 shoe and 4 1/2 crossover sub 2 jts of 2 7/8 tbg and power swivel wash over 1 feeot shoe, did not went down, poh 40 swivel and 2 its of 2 7/8 and tools go back in w 4 1/2 drill bit and 1 its of drill collar 4 1/2 2 its of 2 7/8 tbg brake drill bit, pick up another 7 1/2 drill bit crossover sub 1 x 4 1/2 drill collar 2 jts of 2 7/8 washover from surface to 73 feet I/d swivel 2.7 jts d collar The above all occurred between 7/14/2005 - 7/20/2005 open well, ran in hole w 7" drill bit 1 x 4 1/2 drill collar 2 jts of 2 7/8 tbg pick up power swivel tag top of fish L/D swivel, POH, with 2 jts 2 7/8 drill 7/20/2005 drill collar cross over sub and drill bit go back in with 7' feet wash pip shoe crossover sob drill collar 1 it of 2 7/8 tbg power swivel wash over 20 feet from top of fish down 40 swivel, POH everything, go back in with LOG cutters 2.3 x 1/2 and NC Pull L/D the 3 its go back with spear tool drill collar ???? 2 7/8 fish piece of csg POH with all tools and piece of csg go back in with 7 in mill shoe drill collar 2its 2 7/8 mull 1" in POH go back with lead over shot 3 its csg fewer, shut down 7/21/2005 R/U kill truck to test csg pressure op not held pressure RDMO 2/8/2007 Rig up unit for 2 3/8 tubing- ran 3 its of 2 3/8 tubing displace fuid in hole spot ploymer on bottom, pressure up 600# lbs Polymer held blend off pressure come out of hole with tubing spot 4 ft sub with collar on bottom, packer well off repressed well head 300# rig down 2/7/2008 Spot right, tighten well head, wait on backhoe to fill in hole around well head, got hold filled in tubing for well got dropped off, rigged up