Form 3160-5 April 2004)	UNITED STATES DEPARTMENT OF THE I BUREAU OF LAND MANA	OCD-HOBB	2 7 2012	FORM APPROVED OM B No 1004-0137 Expires March 31, 2007 5 Lease Senal No	
SUNI	DRY NOTICES AND REP(ORTS ON WELLS		NMLC034117B	
abandone	se this form for proposals to ed well. Use Form 3160-3 (AP	D) for such proposals	CEIVED	6 If Indian, Allottee or Tribe Name	
	ITRIPLICATE- Other instru	ctions on reverse sid	le.	7 If Unit or CA/Agreement, Name and/or No	
1 Type of Well □ □ Gas Well □ □ Other				8 Well Name and No.	
2. Name of Operator DC Energy LLC				Crosby Deep#1 9 API Well No	
		b Phone No (include area cod 770-757-3715	le)	30-025-23891	
	, Sec, T., R., M., or Survey Despription)			10 Field and Pool, or Exploratory Area Crosby FUSSelman	
Sec 28 T25S R37E 330FSL 1980 FWL				11 County or Parish, State	
12 (1)	K APPROPRIATE DOVIES TO D	INCATE NATINE OF		Lea County	
TYPE OF SUBMISSION	12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA SUBMISSION TYPE OF ACTION				
	Acidize Deepen Production (Start/Resume) Water Shut-Off				
Notice of Intent	Alter Casing	1 [′]	clamation	Well Integrity	
Subsequent Report	Casing Repair New Construction Recomplete			Other	
Final Abandonment Noti	ice Convert to Injection	,			
MIRU Circulate Hole w/9#m SET 50 SACKS CEM CUT 5 1/2" CASING SET STUB PLUG 50' SET 50 SACKS CEM SET 50 SACKS CEM SET 10 SACKS SURI INSTALC DRY HOL	IENT AT 7430' & TAG 1 @ +/- 4000 'IN AND OUTOR'S 1/2" STUB AND END PLUS @ 3810' ENT PLUG @ 1500' FACE PLUG @ 30' E DIARKER		FIONS (ED FOR OF APPROVAL rior to work being started.	
4 Thereby certify that the	foregoing is true and correct				
ССЕЛО ОСД НОВ	foregoing is true and correct	Title MANAGIN	IG MEMBER		
4 Thereby certify that the Name (Printed/Typed)	foregoing is true and correct	Title MANAGIN Date			
 4 Thereby certify that the Printed/Typed, DAN JOHNS 	foregoing is true and correct	Date	03/01	^{/201} APPROVED	
 4 Thereby certify that the Printed/Typed, DAN JOHNS 	foregoing is true and correct SON. M. Jahnson .	Date	03/01	E	
4 I hereby certify that the Name (Printed/Typed, DAN JOHNS Signature pproved by onditions of approval, if any, i rufy that the applicant holds hich would entitle the applicant	foregoing is true and correct SON M Jakana THIS SPACE FOR FEI are attached Approval of this notice does legal or equitable utile to those rights in the integrations increase of Jakana and	Date DERAL OR STATE C Trile Tot warrant or subject lease Office	03/01 DFFICE US	E	

:

.

.

•

•

L MAR 2 9 2012

•

946'al 172 Sx Comand 75 082 809 6 0026 0 998 9 6 6 Dornent co/s.v/oot 0588 Ti pour Band E 80 9 557822180 IMD, SE 00 8 R, 8878 Jait TO PHO MIS AICSTEEOS STOODE And a DHL Frad S octil Defrad S octil Defrad S #LI 60 8 575 05 Ø 000h /` 0 \$ 0 60 0 0 VUIJ DOL \$59,74,5 60 ଡ୍ଡ -BS0 8/5 B 3797 ,4E8 000 ©® • ۰Ó 0000 - fun #005/3 @ -100/ 5×505 7054 08 10 **6** 6 00 996 966 966 20 90 **N** 000 000 0 ® al 575 000 80 <u>a</u> ® ® ' 0 8 0000 100 9 000 69 0 0.08 00 791012 הרחלפותה -התקצא רדה HFTRA DC 330, EZT : 1086 EMT 16887 - 37-08: Idu 368'SSE'82-N XISTA 1# food K850XD Wolldore Schematic of

Crosby Deep 1 30-025-23891 DC Energy LLC March 21, 2012 Conditions of Approval

See attached standard Conditions of Approval for plug and abandonment.

In reviewing the well bore, it was determined that a plug was not set across the DV tool at 9200'. Second, the initial perforations from 8810'-8834', 8863'-8880' and 8939'-8943' were squeezed by setting a CICR at 8850'. There is no approval in the well record for this operation. Third, in October 1978, additional perforations from 8734'-8788' were added to the Fusselman and a CICR set at 8760'. Fourth, in December 1992, perforations were added from 8662'-8708'. Operator at that time set a CIBP at 8688', which is in the middle of the perforations and added 35' of cement. Even if this cement actually built to 35' on the CIBP, the cement top is only 9' above the perforations. Previous operator reported perforations from 7146'-7211. Therefore, since this is the final abandonment for this well, the well bore shall be cleaned out to TD.

- 1. Operator to clean out hole with a bit and scraper to ~9400'. Operator shall run a gauge ring to 8800' to verify that CIBPs can be set.
- 2. Operator to set a plug across the DV tool at 9200'. Plug shall be Class H, minimum of 25 sacks, 190 feet in length and set from 9290' to 9100'. WOC and tag at 9100' or shallower.
- 3. For the Fusselman perforations, operator shall set a Class H cement plug from 9000'-8575'. This will cover the Fusselman perforations and Fusselman top. WOC and tag at 8575' or shallower. Operator has the option of setting a CIBP at 8720' and placing a 190' Class H plug on top of the CIBP, minimum of 25 sacks. WOC and tag at 8575' or shallower. This plug will separate the Fusselman perforations and top from the Devonian. Formations plugs are required to be set across the top of the formation.
- 4. Devonian perforations from 8032'-8218'. Operator shall set a Class H cement plug from 8270'-7960'. WOC and tag at 7960' or shallower. Operator has the option of setting a CIBP at 8020', tag CIBP and pump a 25 sack Class H plug on CIBP. This will provide a plug for the Devonian perforations and the Devonian top.
- 5. Previous operator submitted well bore schematic with perforations from 7146'-7211'. This was requested on an NOI, but operator did not submit a Subsequent Report detailing this work. Operator shall move the proposed cement plug for 7120' to 7275'. Plug shall be Class C, a minimum of 25 sacks and placed from 7275'-7000'. WOC and tag at 7000' or shallower.

- 6. Casing leak that was squeezed from 5043'-5707' shall have a plug across the casing leak. Plug shall be set from 5707'-5150'. At 5130', casing shall be perforated for the Glorietta plug (top is 5073'). Attempt to establish circulation, if circulation is established, pump a minimum of 25 sacks of Class C cement. Tag plug at 4980' or shallower. If circulation cannot be established, set plug from 5150'-4980' and tag at 4980' or shallower.
- BLM inspector to be on location when operator performs free point on the 5-1/2" casing. If free point is above 3900' (near intermediate shoe), BLM inspector will confer with BLM engineer prior to cutting casing.
 - a. If the free point is above 3900', the intermediate shoe plug will require modification. Contact BLM engineer for review.
- 8. Proposed stub plug shall be set a minimum of 50' inside the stub. Class C cement plug of a minimum of 25 sacks to be 140' in length. WOC and tag a minimum of 50' above the cut unless 7.a changes this condition.
- 9. Intermediate shoe plug per original plan, if not already set, shall be set from 3860'- 3730'. Plug to be a minimum of 25 sacks of Class C and tagged at 3730' or shallower.
- 10. Top of Yates/Base of Salt plug required. Operator to set a minimum 25 sack Class C plug from 2490'-2370'. Plug to be tagged at 2370' or shallower.
- 11. Plug at 1500' to be replaced by Top of Salt plug. Plug to be a minimum of 25 sacks Class C and set from 1410' to 1300'. Plug to be tagged at 1300' or shallower.
- 12. Surface shoe plug shall be set from 560' to surface. Operator shall place sufficient Class C cement at 560' to bring cement to surface. This will provide additional protection for the surface water.
- 13. Operator will check all annuli when well head is cut off to verify cement to surface in all annuli.
- 14. Ground level marker required see attached COA.
- 15. Clean location.

WWI 032112

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

2. <u>Notification</u>: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. **Before pumping cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.**

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged</u>.

8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation procedure.

Requirements for ground level dry hole markers <u>Well Identification Markers</u> Conditions of Approval (COA)

The BLM Carlsbad Field Office (CFO) Conditions of Approval (COA) Requires that ground level dry hole markers be placed on well within the Lesser Prairie Chicken habitat area. The dry hole markers will be to the following specifications. The operator will construct the markers as follows:

- 1. An 8 inch X 8 inch steel plate 1/8 to 3/16 of an inch thick is to be placed on the old dry hole marker stand pipe 2 inches from ground level, in the Lesser Prairie Chicken habitat area.
- 2. Steel plate may be welded or bolted approximately 2 inches from ground level on the stand pipes. If plates are bolted to the stand pipe, the person installing the plate will be required to weld a pipe collar on the plate and place a minimum of two set screws/bolt on each collar. Aluminum data plates may be bolted with minimum ¼ inch bolt and locking nuts or self tapping fine threaded screws. A minimum of one in each corner is to be installed on each plate.
- 3. An 8 inch x 8 inch aluminum plate, which is 12 gauge or .080 sign material (1/8 inch aluminum plate may be used in place of the .080 plate) with the required information for that well stamped or engraved in a minimum 3/8 inch tall letter or number.
- 4. The following information will be stamped or engraved on the 8 inch X 8 inch aluminum plate in the following order.
 - a. First row: Operators name
 - b. Second row: Well name and number
 - c. Third row: Legal location to include ¹/₄ ¹/₄, Section, Township, and range. If the legal location cannot be placed on one row it can be split into two rows with the ¹/₄ ¹/₄ (example: 1980 FNL 1980 FWL) being on the top row.
 - d. Fourth row: Lease Number and API number.
 - i. Example marker plate: (attached)

NMOCD Order No. R-12965 also required the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a ground level dry hole marker was installed as required in the COA's from the BLM.