Submit 1 Copy To Appropriate District Office	State of New Mexic			orm C-103
District 1 – (575) 393-6161	Energy, Minerals and Natural	Resources	Revised A ELL API NO.	ugust 1, 2011
1625 N. French Dr., Hobbs, NM 88240 District II - (575) 748-1283		30-	041-00244	
01L CONSERVATION DIVISION District III - (505) 334-6178 06 2012 1220 South St. Francis Dr.		IVISION 5.	Indicate Type of Lease	
1000 Rio Brazzos Rd., Aztec, NM 87410 Santa Fe, NM 87505		- ⊢	STATE FEE	
District IV - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM RE(87505	CEIVED	5 6.	State Oil & Gas Lease No.	·
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			Lease Name or Unit Agreem	ent Name
	SALS TO DRILL OR TO DEEPEN OR PLUG I CATION FOR PERMIT" (FORM C-101) FOR S	UCH Mili	nesand Unit	
1. Type of Well: Oil Well	Gas Well Other		Well Number 163	/
Name of Operator Apache Corporation			OGRID Number 2420	
3. Address of Operator		1	. Pool name or Wildcat	,
303 Veterans Airpark Lane, Ste 300	0, Midland TX 79705	Mili	nesand, San Andres	
4. Well Location Unit Letter:	1980 feet from the South	line and	feet from the	line
Section 12	Township 08S Range		MPM Roosevelt County	
	11. Elevation (Show whether DR, RF	(B, RT, GR, etc.)		
12. Check A	Appropriate Box to Indicate Natu	re of Notice, Rep	ort or Other Data	•
NOTICE OF IN	ITENTION TO:	SUBSE	QUENT REPORT OF:	
PERFORM REMEDIAL WORK		EMEDIAL WORK	□ ALTERING C	
TEMPORARILY ABANDON	i	OMMENCE DRILLIN		x
PULL OR ALTER CASING	MULTIPLE COMPL C	ASING/CEMENT JO	В	
DOWNHOLE COMMINGLE		•		
	ļ			
OTHER:		THER:		
13. Describe proposed or comp	leted operations. (Clearly state all pert	nent details, and giv		
13. Describe proposed or comp of starting any proposed wo	leted operations. (Clearly state all pertork). SEE RULE 19.15.7.14 NMAC. F	nent details, and giv		
13. Describe proposed or comp	leted operations. (Clearly state all pertork). SEE RULE 19.15.7.14 NMAC. F	nent details, and giv		
13. Describe proposed or comp of starting any proposed wo	leted operations. (Clearly state all pertork). SEE RULE 19.15.7.14 NMAC. F	nent details, and giv		
Describe proposed or comp of starting any proposed wo proposed completion or reco	leted operations. (Clearly state all pert ork). SEE RULE 19.15.7.14 NMAC. F ompletion.	nent details, and giv or Multiple Comple	tions: Attach wellbore diagra	ım of
13. Describe proposed or comp of starting any proposed wo proposed completion or rece 1. Notified Maxey Brown w/C 1240 3/29/12. 3. Tag Toc @	leted operations. (Clearly state all pertork). SEE RULE 19.15.7.14 NMAC. Fompletion. OCD on MIRU & P/A intent 3/28/12 1200 3/29/12. 4. Mix /circ 17	nent details, and giv or Multiple Comple 2. Sqz 50sx clas bbls MLF from 120	tions: Attach wellbore diagra s c cmt from 1340 (top of 0-surf 3/29/12. 5. Perf	m of
13. Describe proposed or comp of starting any proposed wo proposed completion or rece 1. Notified Maxey Brown w/C 1240 3/29/12. 3. Tag Toc @ mix/circ 100 sx class c cmt	leted operations. (Clearly state all pert ork). SEE RULE 19.15.7.14 NMAC. Fompletion. OCD on MIRU & P/A intent 3/28/12 1200 3/29/12. 4. Mix /circ 17 down 4 1/2 csg out @ perf & up 4	nent details, and give or Multiple Completed 2. Sqz 50sx classed 1/2 X 8 5/8 annu	s c cmt from 1340 (top of 0-surf 3/29/12. 5. Perf	m of
13. Describe proposed or comp of starting any proposed wo proposed completion or rece 1. Notified Maxey Brown w/C 1240 3/29/12. 3. Tag Toc @ mix/circ 100 sx class c cmt	leted operations. (Clearly state all pertork). SEE RULE 19.15.7.14 NMAC. Fompletion. OCD on MIRU & P/A intent 3/28/12 1200 3/29/12. 4. Mix /circ 17	nent details, and give or Multiple Completed 2. Sqz 50sx classed 1/2 X 8 5/8 annu	tions: Attach wellbore diagra s c cmt from 1340 (top of 0-surf 3/29/12. 5. Perf	m of
13. Describe proposed or comp of starting any proposed wo proposed completion or rece 1. Notified Maxey Brown w/C 1240 3/29/12. 3. Tag Toc @ mix/circ 100 sx class c cmt	leted operations. (Clearly state all pert ork). SEE RULE 19.15.7.14 NMAC. Fompletion. OCD on MIRU & P/A intent 3/28/12 1200 3/29/12. 4. Mix /circ 17 down 4 1/2 csg out @ perf & up 4	nent details, and give or Multiple Completed 2. Sqz 50sx classed 1/2 X 8 5/8 annu	s c cmt from 1340 (top of 0-surf 3/29/12. 5. Perf	m of
13. Describe proposed or comp of starting any proposed wo proposed completion or rece 1. Notified Maxey Brown w/C 1240 3/29/12. 3. Tag Toc @ mix/circ 100 sx class c cmt	leted operations. (Clearly state all pert ork). SEE RULE 19.15.7.14 NMAC. Fompletion. OCD on MIRU & P/A intent 3/28/12 1200 3/29/12. 4. Mix /circ 17 down 4 1/2 csg out @ perf & up 4.1 head, install dry hole plate,	nent details, and give or Multiple Completed 2. Sqz 50sx classed 1/2 X 8 5/8 annu	s c cmt from 1340 (top of 0-surf 3/29/12. 3/29/12	m of
13. Describe proposed or comp of starting any proposed wo proposed completion or rece 1. Notified Maxey Brown w/C 1240 3/29/12. 3. Tag Toc @ mix/circ 100 sx class c cmt	leted operations. (Clearly state all pert ork). SEE RULE 19.15.7.14 NMAC. Fompletion. OCD on MIRU & P/A intent 3/28/12 1200 3/29/12. 4. Mix /circ 17 down 4 1/2 csg out @ perf & up 4.1 head, install dry hole plate,	nent details, and given or Multiple Completed 2. Sqz 50sx clased by the square of the	s c cmt from 1340 (top of 0-surf 3/29/12. 5. Perflus to surf 3/29/12. 3/29/12	m of
13. Describe proposed or comp of starting any proposed wo proposed completion or rece 1. Notified Maxey Brown w/C 1240 3/29/12. 3. Tag Toc @ mix/circ 100 sx class c cmt	leted operations. (Clearly state all pert ork). SEE RULE 19.15.7.14 NMAC. Fompletion. OCD on MIRU & P/A intent 3/28/12 1200 3/29/12. 4. Mix /circ 17 down 4 1/2 csg out @ perf & up 4.1 head, install dry hole plate,	nent details, and given or Multiple Completed 2. Sqz 50sx clased by the square of the	s c cmt from 1340 (top of 0-surf 3/29/12. 5. Perflus to surf 3/29/12. 3/29/12 f well bore only. etained pending receipt eport of Well Plugging)	m of
13. Describe proposed or comp of starting any proposed wo proposed completion or rece 1. Notified Maxey Brown w/C 1240 3/29/12. 3. Tag Toc @ mix/circ 100 sx class c cmt	leted operations. (Clearly state all pertork). SEE RULE 19.15.7.14 NMAC. Fompletion. OCD on MIRU & P/A intent 3/28/12 1200 3/29/12. 4. Mix /circ 17 down 4 1/2 csg out @ perf & up 4.1 head, install dry hole plate,	nent details, and give or Multiple Completed on Multiple Completed 2. Sqz 50sx classobls MLF from 120 1/2 X 8 5/8 annuback fill cellar opproved for plugging of ability under bond is received (Subsequent Received Subsequent	s c cmt from 1340 (top of 0-surf 3/29/12. 5. Perflus to surf 3/29/12. 3/29/12 f well bore only, etained pending receipt cport of Well Plugging) DCD Web Page under	m of
13. Describe proposed or comp of starting any proposed wo proposed completion or rece 1. Notified Maxey Brown w/C 1240 3/29/12. 3. Tag Toc @ mix/circ 100 sx class c cmt	leted operations. (Clearly state all pertork). SEE RULE 19.15.7.14 NMAC. Fompletion. OCD on MIRU & P/A intent 3/28/12 1200 3/29/12. 4. Mix /circ 17 down 4 1/2 csg out @ perf & up 4.1 head, install dry hole plate,	nent details, and give or Multiple Completed. 2. Sqz 50sx classed. 2. Sqz 50sx classed	s c cmt from 1340 (top of 0-surf 3/29/12. 5. Perflus to surf 3/29/12. 3/29/12 f well bore only, etained pending receipt cport of Well Plugging) DCD Web Page under	m of
13. Describe proposed or comp of starting any proposed wo proposed completion or rec 1. Notified Maxey Brown w/C 1240 3/29/12. 3. Tag Toc @ mix/circ 100 sx class c cmt 6. Cut/Remove anchors & wel	leted operations. (Clearly state all pert ork). SEE RULE 19.15.7.14 NMAC. Fompletion. OCD on MIRU & P/A intent 3/28/12 1200 3/29/12. 4. Mix /circ 17 down 4 1/2 csg out @ perf & up 4.1 head, install dry hole plate,	nent details, and give or Multiple Completed. 2. Sqz 50sx classed. 2. Sqz 50sx classed	s c cmt from 1340 (top of 0-surf 3/29/12. 5. Perflus to surf 3/29/12. 3/29/12 f well bore only, etained pending receipt cport of Well Plugging) DCD Web Page under	m of
13. Describe proposed or comp of starting any proposed wo proposed completion or rec 1. Notified Maxey Brown w/C 1240 3/29/12. 3. Tag Toc @ mix/circ 100 sx class c cmt 6. Cut/Remove anchors & wel	leted operations. (Clearly state all pertork). SEE RULE 19.15.7.14 NMAC. Fompletion. OCD on MIRU & P/A intent 3/28/12 1200 3/29/12. 4. Mix /circ 17 down 4 1/2 csg out @ perf & up 4.1 head, install dry hole plate, Rig Release Date:	nent details, and give or Multiple Completed of Multiple Color of Color (Subsequent Research of Multiple Color of Color of Multiple Color of Color of Multiple Color of	s c cmt from 1340 (top of 0-surf 3/29/12. 5. Perflus to surf 3/29/12. 3/29/12 f well bore only, etained pending receipt cport of Well Plugging) OCD Web Page under .nm.us/ocd.	m of
13. Describe proposed or comp of starting any proposed wo proposed completion or rec 1. Notified Maxey Brown w/C 1240 3/29/12. 3. Tag Toc @ mix/circ 100 sx class c cmt 6. Cut/Remove anchors & wel	leted operations. (Clearly state all pert ork). SEE RULE 19.15.7.14 NMAC. Fompletion. OCD on MIRU & P/A intent 3/28/12 1200 3/29/12. 4. Mix /circ 17 down 4 1/2 csg out @ perf & up 4.1 head, install dry hole plate,	nent details, and give or Multiple Completed of Multiple Color of Color (Subsequent Research of Multiple Color of Color of Multiple Color of Color of Multiple Color of	s c cmt from 1340 (top of 0-surf 3/29/12. 5. Perflus to surf 3/29/12. 3/29/12 f well bore only, etained pending receipt cport of Well Plugging) OCD Web Page under .nm.us/ocd.	m of
13. Describe proposed or comp of starting any proposed wo proposed completion or rec. 1. Notified Maxey Brown w/C 1240 3/29/12. 3. Tag Toc @ mix/circ 100 sx class c cmt 6. Cut/Remove anchors & wel Spud Date:	leted operations. (Clearly state all pertork). SEE RULE 19.15.7.14 NMAC. Fompletion. OCD on MIRU & P/A intent 3/28/12 1200 3/29/12. 4. Mix /circ 17 down 4 1/2 csg out @ perf & up 4.1 head, install dry hole plate, Rig Release Date:	nent details, and give or Multiple Completed on Multiple Completed of Multiple Completed on Multiple Completed	s c cmt from 1340 (top of 0-surf 3/29/12. 5. Perflus to surf 3/29/12. 3/29/12 f well bore only. etained pending receipt cport of Well Plugging) DCD Web Page under .nm.us/ocd.	m of
13. Describe proposed or comp of starting any proposed wo proposed completion or rec 1. Notified Maxey Brown w/C 1240 3/29/12. 3. Tag Toc @ mix/circ 100 sx class c cmt 6. Cut/Remove anchors & wel	leted operations. (Clearly state all pertork). SEE RULE 19.15.7.14 NMAC. Fompletion. OCD on MIRU & P/A intent 3/28/12 1200 3/29/12. 4. Mix /circ 17 down 4 1/2 csg out @ perf & up 4.1 head, install dry hole plate, Rig Release Date:	nent details, and give or Multiple Completed of Multiple Color of Color (Subsequent Research of Multiple Color of Color of Multiple Color of Color of Multiple Color of	s c cmt from 1340 (top of 0-surf 3/29/12. 5. Perflus to surf 3/29/12. 3/29/12 f well bore only, etained pending receipt cport of Well Plugging) OCD Web Page under .nm.us/ocd.	m of
13. Describe proposed or comp of starting any proposed wo proposed completion or rec. 1. Notified Maxey Brown w/C 1240 3/29/12. 3. Tag Toc 6 mix/circ 100 sx class c cmt 6. Cut/Remove anchors & wel Spud Date: I hereby certify that the information a	leted operations. (Clearly state all pertork). SEE RULE 19.15.7.14 NMAC. Fompletion. OCD on MIRU & P/A intent 3/28/12 1200 3/29/12. 4. Mix /circ 17 down 4 1/2 csg out @ perf & up 4.1 head, install dry hole plate, Rig Release Date:	nent details, and give or Multiple Completed on Multiple Completed of Multiple Completed on Multiple Completed	s c cmt from 1340 (top of 0-surf 3/29/12. 5. Perflus to surf 3/29/12. 3/29/12 f well bore only. etained pending receipt cort of Well Plugging) DCD Web Page undermus/ocd. DATE 4/2/12	em of E bad csg) E @ 400,
13. Describe proposed or comp of starting any proposed we proposed completion or rece 1. Notified Maxey Brown w/C 1240 3/29/12. 3. Tag Toc @ mix/circ 100 sx class c cmt 6. Cut/Remove anchors & wel Spud Date:	leted operations. (Clearly state all pertork). SEE RULE 19.15.7.14 NMAC. Fompletion. OCD on MIRU & P/A intent 3/28/12 1200 3/29/12. 4. Mix /circ 17 down 4 1/2 csg out @ perf & up 4.1 head, install dry hole plate, Rig Release Date:	nent details, and give or Multiple Completed on Multiple Completed of Multiple Completed on Multiple Completed	s c cmt from 1340 (top of 0-surf 3/29/12. 5. Perflus to surf 3/29/12. f well bore only. etained pending receipt sport of Well Plugging) OCD Web Page under .nm.us/ocd. belief. DATE 4/2/12	em of E bad csg) E @ 400,
13. Describe proposed or comp of starting any proposed we proposed completion or rec. 1. Notified Maxey Brown w/C 1240 3/29/12. 3. Tag Toc @ mix/circ 100 sx class c cmt 6. Cut/Remove anchors & wel Spud Date: I hereby certify that the information a SIGNATURE Type or print name For State Use Only	leted operations. (Clearly state all pertork). SEE RULE 19.15.7.14 NMAC. Fompletion. OCD on MIRU & P/A intent 3/28/12 1200 3/29/12. 4. Mix /circ 17 down 4 1/2 csg out @ perf & up 4.1 head, install dry hole plate, Rig Release Date:	nent details, and give or Multiple Completed on Multiple Completed of Multiple Completed on Multiple Completed	s c cmt from 1340 (top of 0-surf 3/29/12. 5. Perflus to surf 3/29/12. 3/29/12 f well bore only. etained pending receipt cort of Well Plugging) DCD Web Page undermus/ocd. DATE 4/2/12	em of E bad csg) E @ 400,
13. Describe proposed or comp of starting any proposed wo proposed completion or rec. 1. Notified Maxey Brown w/C 1240 3/29/12. 3. Tag Toc @ mix/circ 100 sx class c cmt 6. Cut/Remove anchors & wel Spud Date: I hereby certify that the information a	leted operations. (Clearly state all pertork). SEE RULE 19.15.7.14 NMAC. Fompletion. OCD on MIRU & P/A intent 3/28/12 1200 3/29/12. 4. Mix /circ 17 down 4 1/2 csg out @ perf & up 4.1 head, install dry hole plate, Rig Release Date:	nent details, and give or Multiple Completed on Multiple Completed of Multiple Completed on Multiple Completed	s c cmt from 1340 (top of 0-surf 3/29/12. 5. Perflus to surf 3/29/12. 3/29/12 f well bore only. etained pending receipt cort of Well Plugging) DCD Web Page undermus/ocd. DATE 4/2/12	em of E bad csg) E @ 400,