Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
District I = (575) 393-6161	Energy, Minerals and Natural Resources	Revised August 1, 2011
1625 N French Dr., Hobbs, NM 88240BBS O <u>District II</u> – (575) 748-1283	JB	WELL API NO. 30-025-07491
811 S. First St. Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III - (505) 334-6178 1000 Rio Brazos Rd , Aztec, NM 80449 16	2012 1220 South St. Francis Dr.	STATE FEE
$\frac{D1SU1CU1V}{} = (303)476-3460$	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S St Francis Dr , Santa Fe, NM 87505	ÆĎ	
	S AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	S TO DRILL OR TO DEEPEN OR PLUG BACK TO A	North Hobbs (G/SA) Unit /
DIFFERENT RESERVOIR USE "APPLICATI PROPOSALS) /	ON FOR PERMIT" (FORM C-101) FOR SUCH	Section 31
	Well Other	8. Well Number 311
2. Name of Operator /		9. OGRID Number: 157984
Occidental Permian Ltd.		10. Pool name on Wildoot Hobbs (C/SA)
3. Address of Operator HCR 1 Box 90 Denver City, TX 79323	•	10. Pool name or Wildcat Hobbs (G/SA)
4. Well Location		
	feet from the North line and 2310	feet from the East line
		<u>-</u> - /
Section 31	Township 18S Range 38 . Elevation (Show whether DR, RKB, RT, GR, etc.)	
	649' GR	
12. Check App	ropriate Box to Indicate Nature of Notice,	Report or Other Data
• •	•	•
NOTICE OF INTE	_	SEQUENT REPORT OF:
	LUG AND ABANDON REMEDIAL WOF	
	HANGE PLANS COMMENCE DR	
	ULTIPLE COMPL CASING/CEMEN	II JOB
DOWNHOLE COMMINGLE		
OTUED.	□ OTHER:	
OTHER:	U JOHNER.	
13. Describe proposed or completed	d operations. (Clearly state all pertinent details, ar	
 Describe proposed or completed of starting any proposed work). 	d operations. (Clearly state all pertinent details, ar SEE RULE 19.15.7.14 NMAC. For Multiple Co	
13. Describe proposed or completed	d operations. (Clearly state all pertinent details, ar SEE RULE 19.15.7.14 NMAC. For Multiple Co	
 Describe proposed or completed of starting any proposed work). 	d operations. (Clearly state all pertinent details, ar SEE RULE 19.15.7.14 NMAC. For Multiple Co	
 Describe proposed or completed of starting any proposed work). proposed completion or recomp 	d operations. (Clearly state all pertinent details, ar SEE RULE 19.15.7.14 NMAC. For Multiple Co	
 Describe proposed or completed of starting any proposed work). 	d operations. (Clearly state all pertinent details, ar SEE RULE 19.15.7.14 NMAC. For Multiple Co	
 Describe proposed or completed of starting any proposed work). proposed completion or recomp POOH with prod equip. Clean out to 4270 Acid treat with 1500 gal of 15% 	d operations. (Clearly state all pertinent details, ar SEE RULE 19.15.7.14 NMAC. For Multiple Colletion.	
 Describe proposed or completed of starting any proposed work). proposed completion or recomp POOH with prod equip. Clean out to 4270 Acid treat with 1500 gal of 15% RIH with prod equipment. 	d operations. (Clearly state all pertinent details, ar SEE RULE 19.15.7.14 NMAC. For Multiple Colletion.	
 Describe proposed or completed of starting any proposed work). proposed completion or recomp POOH with prod equip. Clean out to 4270 Acid treat with 1500 gal of 15% 	d operations. (Clearly state all pertinent details, ar SEE RULE 19.15.7.14 NMAC. For Multiple Colletion.	
 Describe proposed or completed of starting any proposed work). proposed completion or recomp POOH with prod equip. Clean out to 4270 Acid treat with 1500 gal of 15% RIH with prod equipment. 	d operations. (Clearly state all pertinent details, ar SEE RULE 19.15.7.14 NMAC. For Multiple Colletion.	
 Describe proposed or completed of starting any proposed work). proposed completion or recomp POOH with prod equip. Clean out to 4270 Acid treat with 1500 gal of 15% RIH with prod equipment. 	d operations. (Clearly state all pertinent details, ar SEE RULE 19.15.7.14 NMAC. For Multiple Colletion.	
 Describe proposed or completed of starting any proposed work). proposed completion or recomp POOH with prod equip. Clean out to 4270 Acid treat with 1500 gal of 15% RIH with prod equipment. 	d operations. (Clearly state all pertinent details, ar SEE RULE 19.15.7.14 NMAC. For Multiple Colletion.	
 Describe proposed or completed of starting any proposed work). proposed completion or recomp POOH with prod equip. Clean out to 4270 Acid treat with 1500 gal of 15% RIH with prod equipment. 	d operations. (Clearly state all pertinent details, ar SEE RULE 19.15.7.14 NMAC. For Multiple Colletion.	
 Describe proposed or completed of starting any proposed work). proposed completion or recomp POOH with prod equip. Clean out to 4270 Acid treat with 1500 gal of 15% RIH with prod equipment. Return well to production 	d operations. (Clearly state all pertinent details, ar SEE RULE 19.15.7.14 NMAC. For Multiple Colletion.	
 Describe proposed or completed of starting any proposed work). proposed completion or recomp POOH with prod equip. Clean out to 4270 Acid treat with 1500 gal of 15% RIH with prod equipment. 	d operations. (Clearly state all pertinent details, ar SEE RULE 19.15.7.14 NMAC. For Multiple Colletion.	
 Describe proposed or completed of starting any proposed work). proposed completion or recomp POOH with prod equip. Clean out to 4270 Acid treat with 1500 gal of 15% RIH with prod equipment. Return well to production 	d operations. (Clearly state all pertinent details, ar SEE RULE 19.15.7.14 NMAC. For Multiple Colletion.	
13. Describe proposed or completed of starting any proposed work), proposed completion or recomp 1) POOH with prod equip. 2) Clean out to 4270 3) Acid treat with 1500 gal of 15% 4) RIH with prod equipment. 5) Return well to production Spud Date:	d operations. (Clearly state all pertinent details, ar SEE RULE 19.15.7.14 NMAC. For Multiple Colletion. PAD acid Rig Release Date:	empletions: Attach wellbore diagram of
13. Describe proposed or completed of starting any proposed work), proposed completion or recomp 1) POOH with prod equip. 2) Clean out to 4270 3) Acid treat with 1500 gal of 15% 4) RIH with prod equipment. 5) Return well to production Spud Date:	d operations. (Clearly state all pertinent details, ar SEE RULE 19.15.7.14 NMAC. For Multiple Colletion.	empletions: Attach wellbore diagram of
13. Describe proposed or completed of starting any proposed work), proposed completion or recomp 1) POOH with prod equip. 2) Clean out to 4270 3) Acid treat with 1500 gal of 15% 4) RIH with prod equipment. 5) Return well to production Spud Date:	Rig Release Date: Rig Release Date:	ge and belief.
13. Describe proposed or completed of starting any proposed work), proposed completion or recomp 1) POOH with prod equip. 2) Clean out to 4270 3) Acid treat with 1500 gal of 15% 4) RIH with prod equipment. 5) Return well to production Spud Date:	Rig Release Date: Rig Release Date:	ge and belief.
13. Describe proposed or completed of starting any proposed work), proposed completion or recomp 1) POOH with prod equip. 2) Clean out to 4270 3) Acid treat with 1500 gal of 15% 4) RIH with prod equipment. 5) Return well to production Spud Date:	d operations. (Clearly state all pertinent details, ar SEE RULE 19.15.7.14 NMAC. For Multiple Colletion. PAD acid Rig Release Date:	ge and belief.
13. Describe proposed or completed of starting any proposed work). proposed completion or recomp 1) POOH with prod equip. 2) Clean out to 4270 3) Acid treat with 1500 gal of 15% 4) RIH with prod equipment. 5) Return well to production Spud Date: I hereby certify that the information above SIGNATURE Type or print name _ Steve Snead	Rig Release Date: Rig Release Date:	ge and belief. DATE 5/14/12
13. Describe proposed or completed of starting any proposed work). proposed completion or recomp 1) POOH with prod equip. 2) Clean out to 4270 3) Acid treat with 1500 gal of 15% 4) RIH with prod equipment. 5) Return well to production Spud Date: Signature Type or print name _ Steve Snead	Rig Release Date: TITLE _Lift Specialist E-mail address:stevesnead@oxy.co.	ge and belief. DATE 5/14/12 OM PHONE: _806-592-6312
13. Describe proposed or completed of starting any proposed work). proposed completion or recomp 1) POOH with prod equip. 2) Clean out to 4270 3) Acid treat with 1500 gal of 15% 4) RIH with prod equipment. 5) Return well to production Spud Date: Signature Type or print name _ Steve Snead	Rig Release Date: TITLE _Lift Specialist E-mail address:stevesnead@oxy.co.	ge and belief. DATE 5/14/12 OM PHONE: _806-592-6312
13. Describe proposed or completed of starting any proposed work). proposed completion or recomp 1) POOH with prod equip. 2) Clean out to 4270 3) Acid treat with 1500 gal of 15% 4) RIH with prod equipment. 5) Return well to production Spud Date: Signature Type or print name _ Steve Snead	Rig Release Date: TITLE _Lift Specialist	ge and belief. DATE 5/14/12 OM PHONE: _806-592-6312