
Submit 1 Copy To Appropriate District State of New Mexico	Form C-103
Office Finergy Minerals and Natural Resources	Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240 HOBBS OCD	WELL API NO.
811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION	30-025 - 05858 5. Indicate Type of Lease
District III - (505) 334-6178 JUL 0 5 2012 220 South St. Francis Dr. 1000 Rio Biazos Rd., Aztec, NM 87410	STATE STEE
<u>District IV</u> – (505) 476-3460 Santa Fe, NW 8/505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	કાપછ(
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	East Eumont Unit /
PROPOSALS)	
1. Type of Well: Oil Well Gas Well Other Injection 2. Name of Operator	8. Well Number 9. 9. OGRID Number 192463
OXY USA WTP Limited Partnership	9. OGKID Number 192403
3. Address of Operator	10. Pool name or Wildcat
P.O. Box 50250 Midland, TX 79710	Eumont Tates TRan
4. Well Location Unit Letter K: 1980 feet from the South line and 1980 feet from the West line	
Section 2 Township 205 Range 37E 11. Elevation (Show whether DR, RKB, RT, GR, etc.	
3613'	,
	••
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data
NOTICE OF INTENTION TO:	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	K ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR	· —
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN DOWNHOLE COMMINGLE	I JOB
L	
	- MIT-TA Status R
13. Describe proposed or completed operations. (Clearly state all pertinent details, an	d give pertinent dates, including estimated date
	d give pertinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co.	d give pertinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.	d give pertinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of .
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 6/28/12 NDWH, NU BOP & test. Rel pkr & POOH w/ pkr & tbg. RIH w/ 3-3/4" bit	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of & 4-1/2" scrapper to 3710'
 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 6/28/12 NDWH, NU BOP & test. Rel pkr & POOH w/ pkr & tbg. RIH w/ 3-3/4" bit 6/29/12 POOH w/ bit & scrapper, RIH & set CIBP @ 3696', test CIBP held OK. No 	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of . . & 4-1/2" scrapper to 3710' of tify NMOCD of test.
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 6/28/12 NDWH, NU BOP & test. Rel pkr & POOH w/ pkr & tbg. RIH w/ 3-3/4" bit	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of . . & 4-1/2" scrapper to 3710' of tify NMOCD of test.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 6/28/12 NDWH, NU BOP & test. Rel pkr & POOH w/ pkr & tbg. RIH w/ 3-3/4" bit 6/29/12 POOH w/ bit & scrapper, RIH & set CIBP @ 3696', test CIBP held OK. No 7/2/12 POOH, LD tbg, RD BOP, NUWH, RIH w. 10jts tbg, circ hole w/ pkr fluid. 	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of . . & 4-1/2" scrapper to 3710' of tify NMOCD of test.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 6/28/12 NDWH, NU BOP & test. Rel pkr & POOH w/ pkr & tbg. RIH w/ 3-3/4" bit 6/29/12 POOH w/ bit & scrapper, RIH & set CIBP @ 3696', test CIBP held OK. No 7/2/12 POOH, LD tbg, RD BOP, NUWH, RIH w. 10jts tbg, circ hole w/ pkr fluid. 	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of . . & 4-1/2" scrapper to 3710' of tify NMOCD of test.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 6/28/12 NDWH, NU BOP & test. Rel pkr & POOH w/ pkr & tbg. RIH w/ 3-3/4" bit 6/29/12 POOH w/ bit & scrapper, RIH & set CIBP @ 3696', test CIBP held OK. No 	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of . . & 4-1/2" scrapper to 3710' of tify NMOCD of test.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 6/28/12 NDWH, NU BOP & test. Rel pkr & POOH w/ pkr & tbg. RIH w/ 3-3/4" bit 6/29/12 POOH w/ bit & scrapper, RIH & set CIBP @ 3696', test CIBP held OK. No 7/2/12 POOH, LD tbg, RD BOP, NUWH, RIH w. 10jts tbg, circ hole w/ pkr fluid. 	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of . . & 4-1/2" scrapper to 3710' of tify NMOCD of test.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 6/28/12 NDWH, NU BOP & test. Rel pkr & POOH w/ pkr & tbg. RIH w/ 3-3/4" bit 6/29/12 POOH w/ bit & scrapper, RIH & set CIBP @ 3696', test CIBP held OK. No 7/2/12 POOH, LD tbg, RD BOP, NUWH, RIH w. 10jts tbg, circ hole w/ pkr fluid. 	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of . . & 4-1/2" scrapper to 3710' of tify NMOCD of test.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 6/28/12 NDWH, NU BOP & test. Rel pkr & POOH w/ pkr & tbg. RIH w/ 3-3/4" bit 6/29/12 POOH w/ bit & scrapper, RIH & set CIBP @ 3696', test CIBP held OK. No 7/2/12 POOH, LD tbg, RD BOP, NUWH, RIH w. 10jts tbg, circ hole w/ pkr fluid. This Approval of Temporary 2 - 70/3 Abandonment Expires 	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of . . & 4-1/2" scrapper to 3710' of tify NMOCD of test.
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 6/28/12 NDWH, NU BOP & test. Rel pkr & POOH w/ pkr & tbg. RiH w/ 3-3/4".bit 6/29/12 POOH w/ bit & scrapper, RIH & set CIBP @ 3696', test CIBP held OK. No 7/2/12 POOH, LD tbg, RD BOP, NUWH, RIH w. 10jts tbg, circ hole w/ pkr fluid. If This Approval of Temporary 2 – 20/3 Abandonment Expires Rig Release Date:	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of . & 4-1/2" scrapper to 3710' otify NMOCD of test. Run MIT test to 540#, no loss. RDPU.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 6/28/12 NDWH, NU BOP & test. Rel pkr & POOH w/ pkr & tbg. RIH w/ 3-3/4" bit 6/29/12 POOH w/ bit & scrapper, RIH & set CIBP @ 3696', test CIBP held OK. No 7/2/12 POOH, LD tbg, RD BOP, NUWH, RIH w. 10jts tbg, circ hole w/ pkr fluid. This Approval of Temporary 2 - 70/3 Abandonment Expires 	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of . & 4-1/2" scrapper to 3710' otify NMOCD of test. Run MIT test to 540#, no loss. RDPU.
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 6/28/12 NDWH, NU BOP & test. Rel pkr & POOH w/ pkr & tbg. RiH w/ 3-3/4".bit 6/29/12 POOH w/ bit & scrapper, RIH & set CIBP @ 3696', test CIBP held OK. No 7/2/12 POOH, LD tbg, RD BOP, NUWH, RIH w. 10jts tbg, circ hole w/ pkr fluid. If This Approval of Temporary 2 – 20/3 Abandonment Expires Rig Release Date:	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of & 4-1/2" scrapper to 3710' otify NMOCD of test. Run MIT test to 540#, no loss. RDPU.
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 6/28/12 NDWH, NU BOP & test. Rel pkr & POOH w/ pkr & tbg. RiH w/ 3-3/4".bit 6/29/12 POOH w/ bit & scrapper, RIH & set CIBP @ 3696', test CIBP held OK. No 7/2/12 POOH, LD tbg, RD BOP, NUWH, RIH w. 10jts tbg, circ hole w/ pkr fluid. If This Approval of Temporary 2 – 20/3 Abandonment Expires Rig Release Date:	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of . & 4-1/2" scrapper to 3710' otify NMOCD of test. Run MIT test to 540#, no loss. RDPU.
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 6/28/12 NDWH, NU BOP & test. Rel pkr & POOH w/ pkr & tbg. RIH w/ 3-3/4" bit 6/29/12 POOH w/ bit & scrapper, RIH & set CIBP @ 3696', test CIBP held OK. No 7/2/12 POOH, LD tbg, RD BOP, NUWH, RIH w. 10jts tbg, circ hole w/ pkr fluid. If This Approval of Temporary 2 - 20/3 Abandonment Expires Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledged SIGNATURE TITLE Regulatory Advisor	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of & 4-1/2" scrapper to 3710' otify NMOCD of test. Run MIT test to 540#, no loss. RDPU.
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 6/28/12 NDWH, NU BOP & test. Rel pkr & POOH w/ pkr & tbg. RIH w/ 3-3/4" bit 6/29/12 POOH w/ bit & scrapper, RIH & set CIBP @ 3696', test CIBP held OK. No 7/2/12 POOH, LD tbg, RD BOP, NUWH, RIH w. 10jts tbg, circ hole w/ pkr fluid. It is Approval of Temporary 2 - 70/3 Abandonment Expires Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge.	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of & 4-1/2" scrapper to 3710' otify NMOCD of test. Run MIT test to 540#, no loss. RDPU.
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 6/28/12 NDWH, NU BOP & test. Rel pkr & POOH w/ pkr & tbg. RiH w/ 3-3/4".bit 6/29/12 POOH w/ bit & scrapper, RIH & set CIBP @ 3696', test CIBP held OK. Not 7/2/12 POOH, LD tbg, RD BOP, NUWH, RIH w. 10jts tbg, circ hole w/ pkr fluid. If This Approval of Temporary 2 - 20/3 Abandonment Expires Spud Date: Rig Release Date: Thereby certify that the information above is true and complete to the best of my knowledged SIGNATURE TITLE Regulatory Advisor E-mail address: david stewart@c	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of & 4-1/2" scrapper to 3710' otify NMOCD of test. Run MIT test to 540#, no loss. RDPU. e and belief. DATE 7(3(12) DAYLON PHONE: 432-685-5717
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 6/28/12 NDWH, NU BOP & test. Rel pkr & POOH w/ pkr & tbg. RIH w/ 3-3/4" bit 6/29/12 POOH w/ bit & scrapper, RIH & set CIBP @ 3696', test CIBP held OK. No 7/2/12 POOH, LD tbg, RD BOP, NUWH, RIH w. 10jts tbg, circ hole w/ pkr fluid. If the scrapper of Temporary 2 - 20/3 Abandonment Expires Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledged SIGNATURE TITLE Regulatory Advisor Type or print name E-mail address: david stewart@c	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of & 4-1/2" scrapper to 3710' otify NMOCD of test. Run MIT test to 540#, no loss. RDPU.

JUL 1:0 2012

OXY USA WTP LP East Eumont Unit #915 API No. 30-025-05858



12-1/4" hole @ 1430' 8-5/8" csg @ 1430' w/ 730sx-TOC-Surf-Circ

7-7/8" hole @ 3820 5-1/2" csg @ 3522' w/ 400sx-TOC-1212'-Calc

4-1/2" liner @ 3494-3820' w/ 100sx-TOC-3494'-Circ

Perfs @ 3746-3812'

CIBP @ 3696'

PB-3819'