Submit 3 Copies To Appropriate District Office	State 0.	f New Me	exico			Form C	-103
District I	Energy, Mineral	s and Natu	ıral Resources			March 4	, 2004
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.				
District II	OIL CONSER	VATION	DIVISION	30-025-34528			
1301 W. Grand Ave., Artesia, NM 88210 District III	District III 1220 South St. Francis Dr.			5. Indicate Type of Lease			
1000 Rio Brazos Rd., Aztec, NM 87410			STA		FEE 🔲		
District IV	Santa i	re, inivi o	7303	6. State Oil	& Gas Lea	ise No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505							
	ICES AND REPORTS (ON WELLS	3	7. Lease Na	ıme or Uni	t Agreement Na	ame /
(DO NOT USE THIS FORM FOR PROPO	SALS TO DRILL OR TO DE	EPEN OR PL	UG BACK TO A			_	
DIFFERENT RESERVOIR. USE "APPLI	CATION FOR PERMIT" (FO	RM C-101) F	OR SUCH	L\	an Etten	G .	
PROPOSALS.)				8. Well Nu	mber		
1. Type of Well: Oil Well Gas Well Other			19				
2. Name of Operator				9. OGRID Number			
Chevron U	SA Inc						
3. Address of Operator				10. Pool name or Wildcat			
15 Smith Rd, Midland, TX 79705				PAD, BLINEBRY, TUBB, DRNK, ABO			
4. Well Location							~
	407	Court	41	1650		Foot	
Unit Letter O :	467 feet from the	e Sout	tn line and	1650 _ _{f∈}	et from the	East	_line
Section 9	Township		ange 37-E	7 12122 212	∟ea Co	unty	
	11. Elevation (Show)	whether DR	, RKB, RT, GR, etc.,)			
Pit or Below-grade Tank Application (Fo						,	0 4000
Pit Location: UL O Sect 9 Twp	20S Rng 37E Pit type	Steel D	epth to Groundwater_	30 Distance 1	rom nearest	fresh water well_	Over 1000
Distance from nearest surface water	Below-grade Tank L	ocation UL_	SectTwr	Rng	;		
467 feet from the South line and	1650 feet from the East	line (S	Steel Tank)				
	in .		,				
NOTICE OF IN	Appropriate Box to I ITENTION TO: PLUG AND ABANDO		SUB	SEQUENT	REPO	RT OF:	G □
	ITÊNTION TO:			SEQUENT	REPO		G □
NOTICE OF IN	ITÊNTION TO:		SUB	SEQUENT K	REPOI	RT OF: ERING CASIN IG AND	G □ Ø
NOTICE OF IN PERFORM REMEDIAL WORK	ITÊNTION TO: PLUG AND ABANDO CHANGE PLANS	п и	SUB REMEDIAL WOR COMMENCE DR	SEQUENT K ILLING OPNS	REPOI	RT OF: ERING CASIN	
NOTICE OF IN	ITÊNTION TO: PLUG AND ABANDO CHANGE PLANS MULTIPLE	DN 🗆	SUB REMEDIAL WOR COMMENCE DR	SEQUENT K ILLING OPNS	REPOI	RT OF: ERING CASIN IG AND	
NOTICE OF IN PERFORM REMEDIAL WORK	ITÊNTION TO: PLUG AND ABANDO CHANGE PLANS	п и	SUB REMEDIAL WOR COMMENCE DR	SEQUENT K ILLING OPNS	REPOI	RT OF: ERING CASIN IG AND INDONMENT	Ø
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	ITÊNTION TO: PLUG AND ABANDO CHANGE PLANS MULTIPLE	п и	SUB REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB	SEQUENT K ILLING OPNS	REPOI	RT OF: ERING CASIN IG AND INDONMENT	Ø
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:	ITÊNTION TO: PLUG AND ABANDO CHANGE PLANS MULTIPLE COMPLETION	П и	SUB REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER:	SEQUENT K ILLING OPNS ND	REPOI	RT OF: ERING CASIN IG AND INDONMENT	
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp	PLUG AND ABANDO CHANGE PLANS MULTIPLE COMPLETION Dieted operations. (Clean	ON	SUB REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER: pertinent details, an	SEQUENT K ILLING OPNS ND	REPOI	RT OF: ERING CASIN IG AND INDONMENT Cluding estimate	☑ ded date
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or compof starting any proposed w	PLUG AND ABANDO CHANGE PLANS MULTIPLE COMPLETION Dieted operations. (Clean	ON	SUB REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER: pertinent details, an	SEQUENT K ILLING OPNS ND	REPOI	RT OF: ERING CASIN IG AND INDONMENT Cluding estimate	☑ ded date
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON TEMPORARILY	PLUG AND ABANDO CHANGE PLANS MULTIPLE COMPLETION Dieted operations. (Clean	ON	SUB REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER: pertinent details, an	SEQUENT K ILLING OPNS ND	REPOI	RT OF: ERING CASIN IG AND INDONMENT Cluding estimate	☑ ded date
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or component of starting any proposed wor recompletion. 1. Notify OCD 24 hours Prior to MI & RU. 2. Set 5 1/2 CIBP @ 6700' Spot 50sx plug 6700	PLUG AND ABANDO CHANGE PLANS MULTIPLE COMPLETION Deleted operations. (Clean ork). SEE RULE 1103.	ON Compared to the compared	SUB REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER: pertinent details, an	SEQUENT K ILLING OPNS ND d give pertine ttach wellbore	REPOI ALT PLU ABA Int dates, in diagram o	RT OF: ERING CASIN IG AND INDONMENT Cluding estimate	☑ ded date
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or compostarting any proposed wor recompletion. 1. Notify OCD 24 hours Prior to MI & RU. 2. Set 5 1/2 CIBP @ 6700' Spot 50sx plug 6700. 3. Spot 60sx plug 5750-5100 (Weir Blinebry-Mo	PLUG AND ABANDO CHANGE PLANS MULTIPLE COMPLETION Detected operations. (Clear ork). SEE RULE 1103.	ON Compared to the compared	SUB REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER: pertinent details, an	SEQUENT K SILLING OPNS ND d give pertine stach wellbore 9. Perf @ 300	REPOI ALT PLU ABA Int dates, in diagram o	RT OF: ERING CASIN IG AND ANDONMENT Cluding estimat f proposed com urf inside & Out	☑ ded date
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or component of starting any proposed wor recompletion. 1. Notify OCD 24 hours Prior to MI & RU. 2. Set 5 1/2 CIBP @ 6700' Spot 50sx plug 6700 3. Spot 60sx plug 5750-5100 (Weir Blinebry-Mod. Displace hole w/MLF, 9.5# Brine w/12.5# gel 5. Spot 40sx plug 4000-3800 (S. Andres) WOC	PEROCO (Lateral, ABO Monument Tumument Paddock) WOC Tag 5085.	ON Compared to the compared	SUB REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER: pertinent details, an	SEQUENT K ILLING OPNS ND d give pertine ttach wellbore 9. Pert @ 300 5 1/2 CSG	REPOI ALT PLL ABA Int dates, in diagram o	RT OF: ERING CASING IG AND ANDONMENT cluding estimate f proposed community unit inside & Out	☑ ded date
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or compost starting any proposed wor recompletion. 1. Notify OCD 24 hours Prior to MI & RU. 2. Set 5 1/2 CIBP @ 6700' Spot 50ax plug 6700. 3. Spot 60ex plug 5750-5100 (Weir Blinebry-Mod. Displace hole w/MLF, 9.5# Brine w/12.5# gel	PLUG AND ABANDO CHANGE PLANS MULTIPLE COMPLETION Detected operations. (Clear ork). SEE RULE 1103. 100 100 100 100 100 100 100 100 100 1	ON Compared to the compared	SUB REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER: pertinent details, an	SEQUENT K ILLING OPNS ND d give pertine ttach wellbore 9. Pert @ 300 5 1/2 CSG	REPOI ALT PLU ABA Int dates, in diagram of Circ CMT to S WOC Tag @ su	RT OF: ERING CASING IG AND ANDONMENT cluding estimate f proposed community unit inside & Out	☑ ded date
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or compostarting any proposed wor recompletion. 1. Notify OCD 24 hours Prior to MI & RU. 2. Set 5 1/2 CIBP @ 6700' Spot 50sx plug 6700' 3. Spot 60sx plug 5750-5100 (Weir Blinebry-Mo 4. Displace hole w/MLF, 9.5# Brine w/12.5# gel 5. Spot 40sx plug 4000-3800 (S. Andres) WOC 6. Spot 25sx plug 2600-2400 (Yates).	PLUG AND ABANDO CHANGE PLANS MULTIPLE COMPLETION Detect operations. (Clear ork). SEE RULE 1103. P6200 (Lateral, ABO Monument Tunument Paddock) WOC Tag 5085. Tag @ 3767. It) WOC Tag 1015.	ON Compared to the compared	SUB REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER: pertinent details, an	SEQUENT K ILLING OPNS ND d give pertine ttach wellbore 9. Pert @ 300 5 1/2 CSG	REPOI ALT PLU ABA Int dates, in diagram of Circ CMT to S WOC Tag @ su	RT OF: ERING CASING IG AND ANDONMENT cluding estimate f proposed community unit inside & Out	☑ ded date
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or composed or composition. 1. Notify OCD 24 hours Prior to MI & RU. 2. Set 5 1/2 CIBP @ 6700' Spot 50sx plug 6700 3. Spot 60sx plug 5750-5100 (Weir Blinebry-Mod. Displace hole w/MLF, 9.5# Brine w/12.5# gets 5. Spot 40sx plug 4000-3800 (S. Andres) WOC 6. Spot 25sx plug 2600-2400 (Yates). 7. Spot 25sx plug 1200-1006 (8 5/8 Shoe, T-Sa 8. Perf @ 1015' sqz 50sx CMT WOC Tag @ 91	PLUG AND ABANDO CHANGE PLANS MULTIPLE COMPLETION Detected operations. (Clean ork). SEE RULE 1103. C6200 (Lateral, ABO Monument Tunument Paddock) WOC Tag 5085. P/BBL. Tag @ 3767. It woc Tag 1015' 3'.	PN	SUB REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER: pertinent details, an ole Completions: An	SEQUENT K SILLING OPNS ND d give pertine stach wellbore 9. Perf @ 300 5 1/2 CSG 10. Install Dry	REPOI ALT BLU ABA Int dates, in diagram of Circ CMT to S WOC Tag @ su Hole Marker 4-2	RT OF: ERING CASIN IG AND ANDONMENT cluding estimat f proposed com urf inside & Out rt. 18-05.	ted date apletion
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or composed was correcompletion. 1. Notify OCD 24 hours Prior to MI & RU. 2. Set 5 1/2 CIBP @ 6700' Spot 50sx plug 6700 3. Spot 60sx plug 5750-5100 (Weir Blinebry-Mod. 4. Displace hole w/MLF, 9.5# Brine w/12.5# gel 5. Spot 40sx plug 4000-3800 (S. Andres) WOC 6. Spot 25sx plug 2800-2400 (Yates). 7. Spot 25sx plug 1200-1006 (8 5/8 Shoe, T-Sa 8. Perf @ 1015' sqz 50sx CMT WOC Tag @ 91 I hereby certify that the information	PLUG AND ABANDO CHANGE PLANS MULTIPLE COMPLETION Dieted operations. (Clear ork). SEE RULE 1103. 16200 (Lateral, ABO Monument Tunument Paddock) WOC Tag 5085'. Tag @ 3767'. Tag woc Tag 1015' 3'. Labove is true and comp	rly state all For Multipubb, Weir Drinker	SUB REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER: pertinent details, an ole Completions: An one	SEQUENT K ILLING OPNS ND d give pertine ttach wellbore 9. Perf @ 300 5 1/2 CSG 10. Install Dry	REPOI ALT PLU ABA Int dates, in diagram o CITC CMT to S WOC Tag @ su Hole Marker 4-2	RT OF: ERING CASIN IG AND ANDONMENT cluding estimat f proposed com urf inside & Out rf. 18-05.	ted date apletion
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or composed or composition. 1. Notify OCD 24 hours Prior to MI & RU. 2. Set 5 1/2 CIBP @ 6700' Spot 50sx plug 6700 3. Spot 60sx plug 5750-5100 (Weir Blinebry-Mod. Displace hole w/MLF, 9.5# Brine w/12.5# gets 5. Spot 40sx plug 4000-3800 (S. Andres) WOC 6. Spot 25sx plug 2600-2400 (Yates). 7. Spot 25sx plug 1200-1006 (8 5/8 Shoe, T-Sa 8. Perf @ 1015' sqz 50sx CMT WOC Tag @ 91	PLUG AND ABANDO CHANGE PLANS MULTIPLE COMPLETION Dieted operations. (Clear ork). SEE RULE 1103. 16200 (Lateral, ABO Monument Tunument Paddock) WOC Tag 5085'. Tag @ 3767'. Tag woc Tag 1015' 3'. Labove is true and comp	rly state all For Multipubb, Weir Drinker	SUB REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER: pertinent details, an ole Completions: An one	SEQUENT K ILLING OPNS ND d give pertine ttach wellbore 9. Perf @ 300 5 1/2 CSG 10. Install Dry	REPOI ALT PLU ABA Int dates, in diagram o CITC CMT to S WOC Tag @ su Hole Marker 4-2	RT OF: ERING CASIN IG AND ANDONMENT cluding estimat f proposed com urf inside & Out rf. 18-05.	ted date apletion
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or composed of starting any proposed wor recompletion. 1. Notify OCD 24 hours Prior to MI & RU. 2. Set 5 1/2 CIBP @ 6700' Spot 50sx plug 6700 3. Spot 60sx plug 5750-5100 (Weir Blinebry-Mod. Displace hole w/MLF, 9.5# Brine w/12.5# gel. 5. Spot 40sx plug 4000-3800 (S. Andres) WOC. 6. Spot 25sx plug 1200-1006 (8 5/8 Shoe, T-Sa. 8. Perf @ 1015' sqz 50sx CMT WOC Tag @ 91 I hereby certify that the information grade tank has been/will be constructed of	PLUG AND ABANDO CHANGE PLANS MULTIPLE COMPLETION Dieted operations. (Clear ork). SEE RULE 1103. 16200 (Lateral, ABO Monument Tunument Paddock) WOC Tag 5085'. Tag @ 3767'. Tag woc Tag 1015' 3'. Labove is true and comp	on in the state all for Multipubb, Weir Drinkar	SUB REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER: pertinent details, an ole Completions: An one	SEQUENT K ILLING OPNS ND d give pertine ttach wellbore 9. Perf @ 300 5 1/2 CSG 10. Install Dry te and belief. or an (attached)	REPOI ALT PLU ABA Int dates, in diagram o Clic CMT to S WOC Tag @ su Hole Marker 4-2	RT OF: ERING CASIN IG AND ANDONMENT cluding estimat f proposed com urf inside & Out rf. 18-05. Lify that any pit of OCD-approved pl	ted date apletion
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or compost of starting any proposed wor recompletion. 1. Notify 0CD 24 hours Prior to MI & RU. 2. Set 5 1/2 CIBP @ 6700' Spot 50sx plug 6700' 3. Spot 60sx plug 5750-5100 (Weir Blinebry-Mod. 4. Displace hole w/MLF, 9.5# Brine w/12.5# gel 5. Spot 40sx plug 4000-3800 (S. Andres) WOC. 6. Spot 25sx plug 2800-2400 (Yates). 7. Spot 25sx plug 1200-1006 (8 5/8 Shoe, T-Sa. 8. Perf @ 1015' sqz 50sx CMT WOC Tag @ 91 I hereby certify that the information grade tank has been/will be constructed of	PLUG AND ABANDO CHANGE PLANS MULTIPLE COMPLETION Dieted operations. (Clear ork). SEE RULE 1103. 16200 (Lateral, ABO Monument Tunument Paddock) WOC Tag 5085: P/BBL. Tag @ 3767. 11) WOC Tag 1015' 3'. 1 above is true and comply related according to NMOC	rly state all For Multipubb, Weir Drinker	SUB REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER: pertinent details, an ole Completions: Ar ord) WOC Tag 6194'.	SEQUENT K ILLING OPNS ND d give pertine ttach wellbore 9. Perf @ 300 5 1/2 CSG 10. Install Dry te and belief. or an (attached)	REPOI ALT PLU ABA Int dates, in diagram o Clic CMT to S WOC Tag @ su Hole Marker 4-2	RT OF: ERING CASIN IG AND ANDONMENT cluding estimat f proposed com urf inside & Out rf. 18-05.	ted date apletion
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or composed of starting any proposed wor recompletion. 1. Notify OCD 24 hours Prior to MI & RU. 2. Set 5 1/2 CIBP @ 6700' Spot 50sx plug 6700 3. Spot 60sx plug 5750-5100 (Weir Blinebry-Mod. Displace hole w/MLF, 9.5# Brine w/12.5# gel. 5. Spot 40sx plug 4000-3800 (S. Andres) WOC. 6. Spot 25sx plug 1200-1006 (8 5/8 Shoe, T-Sa. 8. Perf @ 1015' sqz 50sx CMT WOC Tag @ 91 I hereby certify that the information grade tank has been/will be constructed of	PLUG AND ABANDO CHANGE PLANS MULTIPLE COMPLETION Dieted operations. (Clear ork). SEE RULE 1103. 16200 (Lateral, ABO Monument Tunument Paddock) WOC Tag 5085: P/BBL. Tag @ 3767. 11) WOC Tag 1015' 3'. 1 above is true and comply related according to NMOC	on in the state all for Multipubb, Weir Drinkar	SUB REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER: pertinent details, an ole Completions: An only woc Tag 6194'.	SEQUENT K ILLING OPNS ND d give pertine ttach wellbore 9. Perf @ 300 5 1/2 CSG 10. Install Dry te and belief. or an (attached)	REPOI ALT BLU ABA Int dates, in diagram of Clic CMT to S WOC Tag @ su Hole Marker 4-2 I further cert alternative	RT OF: ERING CASING AND ANDONMENT Cluding estimate for proposed compart inside & Out ort. 18-05. Tify that any pit of OCD-approved plants.	ted date apletion
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or compost starting any proposed wor recompletion. 1. Notify OCD 24 hours Prior to MI & RU. 2. Set 5 1/2 CIBP @ 6700' Spot 50sx plug 6700 3. Spot 60sx plug 5750-5100 (Weir Blinebry-Mo 4. Displace hole w/MLF, 9.5# Brine w/12.5# get 5. Spot 40sx plug 4000-3800 (S. Andres) WOC 6. Spot 25sx plug 4000-3800 (S. Andres) WOC 6. Spot 25sx plug 2600-2400 (Yates). 7. Spot 25sx plug 1200-1006 (8 5/8 Shoe, T-Sa 8. Perf @ 1015' sqz 50sx CMT WOC Tag @ 91 I hereby certify that the information grade tank has been/will be constructed of	PLUG AND ABANDO CHANGE PLANS MULTIPLE COMPLETION Dieted operations. (Clear ork). SEE RULE 1103. 16200 (Lateral, ABO Monument Tunument Paddock) WOC Tag 5085: P/BBL. Tag @ 3767. 11) WOC Tag 1015' 3'. 1 above is true and comply related according to NMOC	on in the state all for Multipulate, Weir Drinkar letter to the bounded by the state all for multipulate and the state all for multipulate a	SUB REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER: pertinent details, an ole Completions: An only woc Tag 6194'.	SEQUENT K ILLING OPNS ND d give pertine ttach wellbore 9. Perf @ 300 5 1/2 CSG 10. Install Dry te and belief. or an (attached)	REPOI ALT BLU ABA Int dates, in diagram of Clic CMT to S WOC Tag @ su Hole Marker 4-2 I further cert alternative	RT OF: ERING CASIN IG AND ANDONMENT cluding estimat f proposed com urf inside & Out rf. 18-05. Lify that any pit of OCD-approved pl	ted date apletion
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or compost starting any proposed wor recompletion. 1. Notify OCD 24 hours Prior to MI & RU. 2. Set 5 1/2 CIBP @ 6700' Spot 50ax plug 6700' 3. Spot 60ax plug 5750-5100 (Weir Blinebry-Mod. 4. Displace hole w/MLF. 9, 548 Brine w/12.5# gel 5. Spot 40ax plug 4000-3800 (S. Andres) WOC 6. Spot 25ax plug 2600-2400 (Yates). 7. Spot 25ax plug 1200-1006 (8 5/8 Shoe, T-Sa 8. Perf @ 1015' sqz 50ax CMT WOC Tag @ 91 I hereby certify that the information grade tank has been/will be censtructed of SIGNATURE Type or print name	PLUG AND ABANDO CHANGE PLANS MULTIPLE COMPLETION Dieted operations. (Clear ork). SEE RULE 1103. 16200 (Lateral, ABO Monument Tunument Paddock) WOC Tag 5085: P/BBL. Tag @ 3767. 11) WOC Tag 1015' 3'. 1 above is true and comply related according to NMOC	on in the state all for Multipubly, Weir Drinkar lete to the bord guidelines in the state all for t	SUB REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER: pertinent details, an ole Completions: An only woc Tag 6194'.	SEQUENT K ILLING OPNS ND d give pertine ttach wellbore 9. Perf @ 300 5 1/2 CSG 10. Install Dry te and belief. or an (attached)	REPOI ALT BLU ABA Int dates, in diagram of Clic CMT to S WOC Tag @ su Hole Marker 4-2 I further cert alternative	RT OF: ERING CASING AND ANDONMENT Cluding estimate for proposed compart inside & Out ort. 18-05. Tify that any pit of OCD-approved plants.	ted date apletion
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or compost starting any proposed wor recompletion. 1. Notify OCD 24 hours Prior to MI & RU. 2. Set 5 1/2 CIBP @ 6700' Spot 50sx plug 6700 3. Spot 60sx plug 5750-5100 (Weir Blinebry-Mo 4. Displace hole w/MLF, 9.5# Brine w/12.5# get 5. Spot 40sx plug 4000-3800 (S. Andres) WOC 6. Spot 25sx plug 4000-3800 (S. Andres) WOC 6. Spot 25sx plug 2600-2400 (Yates). 7. Spot 25sx plug 1200-1006 (8 5/8 Shoe, T-Sa 8. Perf @ 1015' sqz 50sx CMT WOC Tag @ 91 I hereby certify that the information grade tank has been/will be constructed of	PLUG AND ABANDO CHANGE PLANS MULTIPLE COMPLETION Dieted operations. (Clear ork). SEE RULE 1103. 16200 (Lateral, ABO Monument Tunument Paddock) WOC Tag 5085: P/BBL. Tag @ 3767. 11) WOC Tag 1015' 3'. 1 above is true and comply related according to NMOC	on in the state all for Multipubb, Weir Drinkan lette to the bin	SUB REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER: pertinent details, an ole Completions: An one	SEQUENT K JULING OPNS ND d give pertine ttach wellbore 9. Perf @ 300 5 1/2 CSG 10. Install Dry ge and belief. or an (attached) nt	REPOI ALT BLU ABA Int dates, in diagram of Clic CMT to S WOC Tag @ su Hole Marker 4-2 I further cert alternative	RT OF: ERING CASING AND ANDONMENT Cluding estimate for proposed compart inside & Out ort. 18-05. Tify that any pit of OCD-approved plants.	ted date apletion
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or composition of starting any proposed wor recompletion. 1. Notify OCD 24 hours Prior to MI & RU. 2. Set 5 1/2 CIBP @ 6700' Spot 50sx plug 6700 3. Spot 60sx plug 5750-5100 (Weir Blinebry-Mod. Displace hole w/MLF, 9.5# Brine w/12.5# gel 5. Spot 40sx plug 4000-3800 (S. Andres) WOC. 6. Spot 25sx plug 2600-2400 (Yates). 7. Spot 25sx plug 1200-1006 (8 5/8 Shoe, T-Sa. 8. Perf @ 1015' sqz 50sx CMT WOC Tag @ 91 I hereby certify that the information grade tank has been/will be constructed of SIGNATURE Type or print name (This space for State use)	PLUG AND ABANDO CHANGE PLANS MULTIPLE COMPLETION Dieted operations. (Clear ork). SEE RULE 1103. 16200 (Lateral, ABO Monument Tunument Paddock) WOC Tag 5085: P/BBL. Tag @ 3767. 11) WOC Tag 1015' 3'. 1 above is true and comply related according to NMOC	on in the state all for Multipubb, Weir Drinkan lete to the boundedines in the state all and the state all and the state all for Multipubb, Weir Drinkan in	SUB REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER: pertinent details, an ole Completions: An only woc Tag 6194'.	SEQUENT K JULING OPNS ND d give pertine ttach wellbore 9. Perf @ 300 5 1/2 CSG 10. Install Dry ge and belief. or an (attached) nt	REPOI ALT BLU ABA Int dates, in diagram of Clic CMT to S WOC Tag @ su Hole Marker 4-2 I further cert alternative	RT OF: ERING CASING AND ANDONMENT Cluding estimate for proposed compart inside & Out ort. 18-05. Tify that any pit of OCD-approved plants.	ted date apletion
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or compost starting any proposed wor recompletion. 1. Notify OCD 24 hours Prior to MI & RU. 2. Set 5 1/2 CIBP @ 6700' Spot 50ax plug 6700' 3. Spot 60ax plug 5750-5100 (Weir Blinebry-Mod. 4. Displace hole w/MLF. 9, 548 Brine w/12.5# gel 5. Spot 40ax plug 4000-3800 (S. Andres) WOC 6. Spot 25ax plug 2600-2400 (Yates). 7. Spot 25ax plug 1200-1006 (8 5/8 Shoe, T-Sa 8. Perf @ 1015' sqz 50ax CMT WOC Tag @ 91 I hereby certify that the information grade tank has been/will be censtructed of SIGNATURE Type or print name	PLUG AND ABANDO CHANGE PLANS MULTIPLE COMPLETION Dieted operations. (Clear ork). SEE RULE 1103. 16200 (Lateral, ABO Monument Tunument Paddock) WOC Tag 5085: P/BBL. Tag @ 3767. 11) WOC Tag 1015' 3'. 1 above is true and comply related according to NMOC	on in the state all for Multipubb, Weir Drinkan lette to the bin	SUB REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER: pertinent details, an ole Completions: An one	SEQUENT K JULING OPNS ND d give pertine ttach wellbore 9. Perf @ 300 5 1/2 CSG 10. Install Dry ge and belief. or an (attached) nt	REPOI ALT BLU ABA Int dates, in diagram of Clic CMT to S WOC Tag @ su Hole Marker 4-2 I further cert alternative	RT OF: ERING CASING AND ANDONMENT Cluding estimate for proposed compart inside & Out ort. 18-05. Tify that any pit of OCD-approved plants.	ted date apletion

1 # 1