

Office

Energy, Minerals and Natural Resources

October 13, 2009

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

WELL API NO.

30-025-24584

5. Indicate Type of Lease

STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

MARK

8. Well Number 9

9. OGRID Number 4323

10. Pool name or Wildcat

PENROSE SKELLY GRAYBURG

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

CHEVRON U.S.A. INC.

3. Address of Operator

15 SMITH ROAD, MIDLAND, TEXAS 79705

4. Well Location

Unit Letter G: 2172 feet from the NORTH line and 1972 feet from the EAST line

Section 3 Township 22S Range 37E NMPM County LEA

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐TEMPORARILY ABANDON ☐ CHANGE PLANS ☐PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐COMMENCE DRILLING OPNS. ☐ P AND A ☐CASING/CEMENT JOB ☐

OTHER: INTENT TO SONIC HAMMER, ACIDIZE, SC SQZ

OTHER:

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

CHEVRON INTENDS TO SONIC HAMMER, ACIDIZE & SCALE SQUEEZE THE SUBJECT WELL.

PLEASE FIND ATTACHED, THE INTENDED PROCEDURE, WELLBORE DIAGRAM, & C-144 INFORMATION.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE

REGULATORY SPECIALIST

DATE 07-30-2012

Type or print name DENISE PINKERTON

E-mail address: leakejd@chevron.com

PHONE: 432-687-7375

For State Use Only

APPROVED BY

TITLE

DATE

8-1-2012

Conditions of Approval (if any):

AUG 01 2012

Mark #9 – [30-025-24584]

Penrose Skelly field

T22S, R37E, Section 3

N 32° 25' 20.0274", W -103° 8' 54.4194" (NAD27)

Job: Sonic Hammer, Acidize & Scale Squeeze

This procedure is meant to be followed. It is up to the WSM, Remedial Engineer and Production Engineer to make the decisions necessary to do SAFELY what is best for the well. In the extent that this procedure does not reflect actual operations, please contact RE, PE and Superintendent for possible MOC.

Procedure:

1. MI & RU Workover unit.
2. Verify that well does not have pressure/flow. If well has pressure, record tubing and casing pressures on WellView report. Bleed down well; if necessary, kill with cut brine fluid (8.6 ppg).
- **Caliper elevators and tubular EACH DAY prior to handling tubing/rods/tools. Note in JSA & WellView when and what items are callipered within the task step that includes that work.**
3. Unseat pump. POOH with rods & pump. Examine rod string for paraffin/corrosion. Do not hot water, unless significant paraffin is seen. ND wellhead, unset TAC, NU BOP.
4. POOH & LD 1 joint, PU 5-1/2" packer and set @ ~ 25'. Close and test BOP pipe rams to 250psi (low)/ 500psi (high). Record testing pressures on WellView report. Release and LD packer.
5. PU tubing and run back in hole to tag for fill.
Depths: (TAC 3,574', Bottom Perfs 3,846', EOT 3,898', PBTD 3,915')
6. RU Scanners and POOH while scanning all 2-7/8" 6.5# J-55 production tubing. LD all non-yellow band joints. If fill is tagged:
 - a. Above 3,900' proceed to step #7.
 - b. Below 3,900' skip to step #9.

Strap pipe out of the hole to verify depths. Send scan report to lqbi@chevron.com.

- **Caliper elevators and tubular EACH DAY prior to handling tubing/rods/tools. Note in JSA & WellView when and what items are callipered within the task step that includes that work.**

7. PU and RIH with 4-3/4" Milled Tooth (MT) Bit, 4 (3-1/2') drill collars on 2-7/8" 6.5# L-80 Workstring. RU power swivel and C/O to 3,915'. POOH with 2-7/8" WS and bit. LD bit and BHA.

Note: If circulation is not expected/achieved, notify Remedial Engineer to discuss C/O with bailer (proceed to step #8) or utilize foam/air unit (continue to supplemental procedure at end).

8. PU and RIH with 4-3/4" MT and Bulldog bailer on 2-7/8" 6.5# L-80 WS. Clean out to 3,915'. POOH with 2-7/8" WS and bit. LD bit and BHA.

- **Expect trapped pressure inside tubing while breaking connections during bailing operations, discuss on JSA and mitigate hazard. Use mudbucket (remove bottom seals if applicable) while breaking connections.**
- 9. Contact sonic tool representative to be on-site during job. PU and RIH with Sonic Hammer tool and 2-7/8" Workstring to 3,850' or enough depth to cover the bottom perforations (@ 3,846') with a whole stand. Hydrotest tubing to 6,000 psi. Stand back tubing to top perforations (@ 3,650'). Install stripper head and stand pipe with sufficient treating line to move tools vertically ~ 60'. RU pressure gauges to allow monitoring of tubing and casing pressures during job.
- 10. MI and RU Petroplex equipment. Titrate acids and verify concentration (HCl \pm 1.5%). Treat all intervals from 3,645' to 3,850' with 20 bbls of 8.6 ppg cut brine water per interval (**see Table 1**). Pump down Sonic Hammer tool at 5 BPM while reciprocating tool across intervals. Do not exceed 5,000 psi tubing pressure. Leave annulus open in circulation mode while treating intervals with brine water.

Perf Intervals for Acid			
Interval (#)	Depth	Net Feet (ft)	Acid Volume (gal)
1	3,645' - 3,705'	60	1,500
2	3,710' - 3,755'	45	1,000
3	3,760' - 3,795'	35	1,000
4	3,800' - 3,850'	50	1,250
Total		190	4,750

Table 1

- 11. Follow the brine water wash with 4,750 gals 15% NEFE HCl of total acid for all intervals. Spot 3 bbls of acid outside tubing, shut in casing, pump 1,500 gals of acid @ 5 BPM over first treating interval from 3,645' – 3,705', monitor casing pressure not exceeding 500 psi on backside. Flush tubing with brine water after every acidizing interval, make a connection and continue with remaining interval. **Refer to Table 1.**
- 12. Shut in well for 1 hr to allow time for acid to spend. Monitor and bleed off excess pressure at surface if necessary to keep casing pressure below 500 psi.
- 13. Scale squeeze well with a total of 150 bbls 8.6 ppg brine water mixed with 3 drums (165 gallons) Baker SCW-358 Scale Inhibitor Chemical. Pump down Sonic Hammer tool at a max rate of 5 BPM. Start from lowest interval of 3,850' – 3,800' and continue moving uphole per pump schedule (**see Table 2**). Ensure top of tubing is flushed with brine water before making a connection.

Scale Squeeze Pump Schedule						
Step		Interval (ft)	Max Rate (BPM)	Volume Brine (bbl)	Volume Scale Chem. (gal)	Cum Volume (bbl)
1	Pump Chemical/brine while moving from	3850' - 3800'	5	11	45	12
2	Pump Brine while moving from	3850' - 3800'	5	19		31
3	Move pipe to next interval of	3795' - 3760'				31
4	Pump Brine while moving from	3795' - 3760'	5	5		36
5	Pump Chemical/brine while moving from	3795' - 3760'	5	8	35	45
6	Pump Brine while moving from	3795' - 3760'	5	12		57
7	Move pipe to next interval of	3755' - 3710'				57
8	Pump Brine while moving from	3755' - 3710'	5	5		62
9	Pump Chemical/brine while moving from	3755' - 3710'	5	7	30	70
10	Pump Brine while moving from	3755' - 3710'	5	13		83
11	Move pipe to next interval of	3705' - 3645'				83
12	Pump Brine while moving from	3705' - 3645'	5	8		91
13	Pump Chemical/brine while moving from	3705' - 3645'	5	13	55	105
14	Pump Brine while moving from	3705' - 3645'	5	49		154

Table 2

14. PU workstring to higher than top perforations. Displace tubing volume with 8.6 ppg cut brine water. Do not exceed 500 psi casing pressure or 5 BPM while pumping scale squeeze or casing flush. Release Petroplex.
15. TOH and LD 2-7/8" WS and Sonic Hammer tool.
16. RIH with 2-7/8" production tubing and hydrotest to 6,000 psi. **Pump 8.6 ppg cut brine water containing soap and biocide per ALCR.**
17. ND BOP, set TAC, NU WH. RIH with rods and pump per ALCR's recommendation/Rodstar design. Hang well on.
18. RD and release Workover unit. Turn well over to production.

FOAM / AIR CLEANOUT PROCEDURE

- This procedure is an addition to the original procedure.
 1. Install flowback manifold with two chokes. All components on flowback manifold must be rated to at least 5,000 psi. If possible, flowback manifold components should be hydrotested before delivery. Hardline pipes from 2" casing valve to manifold to half pit with gas buster.
 2. Install flowback tank downwind from rig.
 3. Position Air unit upwind from Rig next to water tanks. Have vacuum truck on standby to empty halfpit. (if needed)
 4. RIH with 4-3/4" MT bit, 4 (3-1/2") drill collars on 2-7/8" 6.5# L-80 WS.
 5. NU stripper head with **NO Outlets** (Check stripper cap for thread type - course threads preferred). **Stripper head to be stump tested to 1,000 psi before being delivered to rig.** Check chart or test at rig.
 6. RU foam air unit. Make quality foam on surface before going down hole with foam/air. Install flapper float at surface before beginning to pump. Break circulation with foam/air. Evacuate fluid from well.

Pump high quality foam at all times. Do not pump dry air at any time. Fluid injection rates will generally be above 12 gallons per minute.

Whenever there is pressure on the stripper head, have a dedicated person continuously monitor pressure at choke manifold and have a dedicated person at accumulator ready to close annular BOP in case stripper leaks. Do not allow pressure on stripper head to exceed 500 psi. If pressure cannot be controlled below 500 psi, stop pumping, close BOP and bleed off pressure.

7. Clean out fill to 3,915' with low RPM's rotation and circulation, always keep pipe moving. Short trips can be beneficial to hole cleaning. Circulate well clean for at least 1 hour at the end of the day and pull up above the perforations before shut down for night. If the foam/air unit goes down, pull above the perforations.
8. When tripping out of hole, have special float bleed off tool available to relieve trapped pressure below float.

Ensure that high quality, stiff foam is pumped while circulating the fill. Stiff foam is required to prevent segregation while circulating. Monitor flow and pressures carefully when cleaning out.

Before rigging up power swivel to rotate, carefully inspect Kelly hose to ensure that it is in good condition. Ensure that swivel packing is in good condition.

Continue on with original procedure for completion.


Figure 1 is a vertical bar chart illustrating the distribution of 1000 random numbers across four stages. The y-axis represents the number of occurrences, ranging from 3,600 to 3,900. The x-axis represents the stages. The legend indicates: Perfs (thin line), Stage 1 (thick line), Stage 2 (dotted line), Stage 3 (thick line), and Stage 4 (thick line). The chart shows four distinct stages of distribution, each with a range of values and a central peak.

Stage	Min Value	Max Value	Central Peak
Stage 1	3,645	3,705	3,675
Stage 2	3,710	3,755	3,732
Stage 3	3,760	3,795	3,777
Stage 4	3,850	3,900	3,875

196


Chevron U.S.A. Inc. Wellbore Diagram : MARK 09

Lease: OEU EUNICE		Well No.: MARK 9	Field: FLD-PENROSE SKELLY	
Location: 2172FNL1972FEL		Sec.: N/A	Blk:	Survey: N/A
County: Lea	St.: New Mexico	Refno: EN7263	API: 3002524584	Cost Center: UCU490200
Section: 3		Township: 022 S		Range: 037 E
Current Status: ACTIVE			Dead Man Anchors Test Date: NONE	
Directions:				




Ground Elevation (MSL):: 3393.00	Spud Date: 12/08/1973	Compl. Date: 12/29/1973
Well Depth Datum:: CS1000N	Elevation (MSL):: 0.00	Correction Factor: 9.00
Last Updated by: bujq	Date: 07/13/2012	

H&P 227 BOP Stack



H&P #227 CHOKE MANIFOLD



Valves 6,8,12 - master valves, closest to pressure
 All other valves are working valves
 4", 10K Valves - 5, 6, 8, 9, 12, 13
 4", 5K Valves - 11, 14, 15, 16, 17
 10 - Manual Choke
 Valve 7 - goes up to sensors/gauges

N/C = NORMALLY CLOSED
N/O = NORMALLY OPEN