

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised August 1, 2011

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-31583
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Bison State
8. Well Number 1
9. OGRID Number 004378
10. Pool name or Wildcat Buffalo Queen

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator CHI Operating, Inc.	
3. Address of Operator P.O. Box 1799 Midland, TX 79702	
4. Well Location Unit Letter L : 2310 feet from the South line and 990 feet from the West line Section 32 Township 18S Range 33E NMPM County Eddy Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Current Perfs: Delaware 4456-4480'
POOH with production string
Set CIBP @ 4430' to abandon Delaware perfs
Dump 35' cmt on top of CIBP
Set CIBP @ 380' with 35' on top
Pump 10 sx surface plug
Intall dry hole marker
Wellbore Diagram attached with procedure

A. CIBP WELL/MLF
B. Spot 25 sx cmt @ 2650'
C. Spot 25 sx cmt @ 1400'
D. Spot 50 sx from 425' to SURFACE

The Oil Conservation Division Must be notified
24 hours prior to the beginning of plugging operations.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Pam Corbett TITLE Regulatory Clerk DATE 7/25/12


Type or print name PAM CORBETT E-mail address: pamc@chienergyinc.com PHONE: 432-685-5001

For State Use Only

APPROVED BY [Signature] TITLE Dist. Mgr. DATE 8-16-2012
Conditions of Approval (if any):

AUG 16 2012

Bison State No. 1
2310 FSL & 990 FWL
Section 32, T18S, R32E
Lea County, New Mexico
API 30-025-31583



8-5/8" 24# J55 @ 375'
cmt at surface

TS 1400'
BS 2650'

Delaware Perfs: 4,456-4,480'

5-1/2" 15 5# J55 @ 4,560'
Cmt @ surface

Plug and Abandon Procedure

Current Perfs: Delaware 4456-4480'

POOH W/ production string

Set CIBP @ 4430' to abandon Delaware Perfs

Dump 35' cmt on top of CIBP

Set CIBP @ 380' w 35' on top

~~Pump 10 sx surface plug~~

Install dry hole marker

- A. Circ Well w/MLF
B. Spot 25 sx cmt @ 2650'
C. Spot 25 sx cmt @ 1400'
D. Spot 50 sx cmt from
425' to Surface