Submit I Copy To Appropriate District State of New Mexico				Form C-103
District 1 – (575) 393-6161 Energy, Minerals and Natural Resources		WELL API NO.	Revised August 1, 2011	
District II – (575) 748-1283 811 S. First St., Artesia, NM 882100BBS OCD OIL CONSERVATION DIVISION District III – (505) 334-6178 1220 South St. Francis Dr.				0-025-32365
		5. Indicate Type o STATE		
1000 Rio Brazos Rd., Aztec, NM 87410 District IV - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, SEP 87505 Santa Fe, NM 87505		6. State Oil & Gas Lease No.		
87505			B-1399-10	
SUNDRY NOTICE OND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROSSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Vacuum Glorieta E. Tract 5	Unit Agreement Name ast Unit
PROPOSALS.) Image: Control of C			8. Well Number	06
2. Name of Operator ConocoPhillips Company			9. OGRID Number 217817	
3. Address of Operator p. O. Box 51810			10. Pool name or Wildcat	
Midland, TX 79710			Vacuum; Glorieta	
4. Well Location Unit Letter P : 1085 feet from the South line and 1210 feet from the East line				
		inte und <u>1210</u> ge 35E	NMPM	County LEA
	on (Show whether DR, R.	KB, RT, GR, etc.)		
3959' <u>GR</u>				
12. Check Appropriate	Box to Indicate Nati	ure of Notice, F	Report or Other I	Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK				
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI				PANDA
PULL OR ALTER CASING MULTIPLE DOWNHOLE COMMINGLE		CASING/CEMENT	JOB 🗌	
OTHER: Change out pump type		DTHER: tinent details and	give pertipent dates	including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
PROCEDURE				
 MI & RU WSU. Rod string is suspected to be parted at shear coupling at 6129'. COOH w/ rods. Fish remainder of rods and pump. Send rods in for 				
inspection. Send pump in to Don-Nan for				
inspection. 3. RIH w/ swab cup and tag for fluid level. Report results to engine				
4. NDWH. NUBOP. COOH w/ tbg. Scan tbg while COOH.				
5. PU bit and scraper and RIH on production tbg. Cleanout to PBTD @ 6221'. Pressure test tbg to 5000 psi while RIH. COOH w/ tbg and lay down bit and scraper.				
6. RU spoolers and RIH w/ ESP and production tbg as specified in Wellview. Set pump intake at 6050'. Ensure that pump is operating				
correctly. 7. NDBOP, NUWH. RD WSU & MO. Contact Production Specialist when well is ready to be put on production.				
Spud Date:	Rig Release Date:	:		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
I nereby certify that the information above is true	and complete to the best	or my knowledge	and belief.	
SIGNATURE Mon	TITLE Staff Reg	ulatory Techniciar	<u>n'</u> DAT	ГЕ <u>08/29/2012</u>
Type or print name <u>Rhonda Rogers</u> E-mail address: <u>rogerrs@conocophillips.com</u> PHONE: <u>(432)688-9174</u>				
Stall Dillion				
APPROVED BY. Conditions of Approval (if any):	TITLE	ST. MA	DAT	Е – -
			-	EP 0 5 2012
			.8	Er ya

.