

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N French Dr, Hobbs, NM 88240
District II - (575) 748-1283
811 S First St, Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd, Aztec, NM 87410
District IV - (505) 476-3460
1220 S St Francis Dr., Santa Fe, NM 87505

State of New Mexico

Oil, Gas, Minerals and Natural Resources

Form C-103

Revised August 1, 2011

HOBBS OFFICE
OCT 09 2012
RECEIVED

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-05509
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name North Hobbs (G/SA) Unit Section 26
8. Well Number 411
9. OGRID Number: 157984
10. Pool name or Wildcat Hobbs (G/SA)
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3660.8 GL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other TA Injector ☐

2. Name of Operator
Occidental Permian Ltd.

3. Address of Operator
HCR 1 Box 90 Denver City, TX 79323

4. Well Location

Unit Letter A : 330' feet from the North line and 330 feet from the East line
Section 26 Township 18S Range 37E NMPM Lea County

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. TIH and tag CIBP at 4045'. Cap with 35' of cmt. (25sx cmt if thru tubing)
2. Circulate 10# MLF.
3. Spot 25 sx of cmt from 2803'-2903'. WOC. Tag.
4. Perf and sqz 50 sx of cmt at 1765'. WOC. Tag.
5. Perforate at 400'. Sqz well and circulate to surface. Top well-off as necessary.
6. Cut off wellhead and install dry hole marker with labeling.
7. Clean up location, remove anchors.

Oil Conservation Division - Hobbs office **Must be Notified**
24 hours prior to the beginning of Plugging Operations begin.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Mendy Johnson

TITLE

ADMIN ASSOCIATE

DATE

10/5/2012

Type or print name

Mendy Johnson

E-mail address

Mendy-Johnson@ocd.nm.gov

PHONE:

806-592-6280

For State Use Only

APPROVED BY:

Mah White

TITLE

Compliance Officer

DATE

10-18-2012

Conditions of Approval (if any):

OCT 18 2012

Occidental Permian Ltd.

NHSAU #411

30-025-05509

Lea Co., NM

