District I	State of New Mexico			Form C-103			
1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources			March 4, 2004 WELL API NO.			
District II OH CONCEDVATION DIVISION				30-025-02186			
1301 W. Grand Ave., Artesia, NM 88210 District III	01 W. Grand 1100., 1100sia, 1111 00210			5. Indicate Type of Lease			
1000 Rio Brazos Rd., Aztec, NM 87410						FEE No.	
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505				6. State Oil & Gas Lease No. B-1576			
SUNDRY NOTICES AND REPORTS ON WELLS					7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				West Vacuum Unit			
PROPOSALS.) 1. Type of Well:					8. Well Number		
Oil Well Gas Well Other				17			
2. Name of Operator					9. OGRID Number		
Chevron USA Inc							
3. Address of Operator 15 Smith Rd, Midland, TX 79705				10. Pool name or Wildcat Vacuum Grayburg San Andres			
4. Well Location				<u> </u>			
Unit Letter H :	1980 feet from the	e Norti	h line and	660	feet from	m theEas	t line
Section 33	Township	17-S Da	ange 34-E	NMPM	Lea	County	
Section	11. Elevation (Show)				200	County	
	·						
Pit or Below-grade Tank Application (For Pit Location: UL H Sect 33 Twp 1						annat frank mater	Over 1000'
Distance from nearest surface water_						arest iresu water	wen
1980 feet from the North line and 6		-	Steel Tank)	,Kng	···································		
			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				
12 Check A	appropriate Box to I	Indicate N	lature of Notice	Report of	· Other	Data	
NOTICE OF IN		maicate 14				PORT OF:	
PERFORM REMEDIAL WORK		AL CT					
	FEOG AND ADAMDO	NA EST	REMEDIAL WOR	lK .		ALTERING C	ASING 🗌
TEMPORARILY ABANDON	CHANGE PLANS		REMEDIAL WOR		_		ASING □
	CHANGE PLANS		COMMENCE DR	ILLING OPI		ALTERING C	
TEMPORARILY ABANDON PULL OR ALTER CASING				ILLING OPI	_	ALTERING C. PLUG AND	
	CHANGE PLANS		COMMENCE DR	ILLING OPI		ALTERING C. PLUG AND	
PULL OR ALTER CASING	CHANGE PLANS MULTIPLE COMPLETION		COMMENCE DR CASING TEST A CEMENT JOB OTHER:	ILLING OPI ND	NS.	ALTERING C. PLUG AND ABANDONME	ENT
OTHER: 13. Describe proposed or complete of starting any proposed wo	CHANGE PLANS MULTIPLE COMPLETION leted operations. (Clean	□ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □	COMMENCE DR CASING TEST A CEMENT JOB OTHER: pertinent details, an	ILLING OPI ND	NS.	ALTERING C. PLUG AND ABANDONM!	ENT
OTHER: 13. Describe proposed or complete of starting any proposed we or recompletion. 1. Notify OCD 24 hours prior too Miles.	CHANGE PLANS MULTIPLE COMPLETION letted operations. (Clear rk). SEE RULE 1103. & RU.	☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐	COMMENCE DR CASING TEST A CEMENT JOB OTHER: pertinent details, an	ILLING OPI ND	NS.	ALTERING C. PLUG AND ABANDONM!	ENT
OTHER: 13. Describe proposed or complete of starting any proposed we or recompletion. 1. Notify OCD 24 hours prior too MI 2. RIH Tag CIBP at 4025, spot 25so	CHANGE PLANS MULTIPLE COMPLETION letted operations. (Clear rk). SEE RULE 1103. & RU. c, plug from 4025-3800 (S.	☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐	COMMENCE DR CASING TEST A CEMENT JOB OTHER: pertinent details, an	ILLING OPI ND	NS.	ALTERING C. PLUG AND ABANDONM!	ENT
PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed we or recompletion. 1. Notify OCD 24 hours prior too MI 2. RIH Tag CIBP at 4025, spot 25ss 3. Displace hole w/MLF, 9.5# Brine 4. Spot 25sx, plug from 2700-2500	CHANGE PLANS MULTIPLE COMPLETION letted operations. (Clear rk). SEE RULE 1103. & RU. c, plug from 4025-3800 (S. w/12.5# gel P/BBL. (Yates, B-Salt).	☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐	COMMENCE DR CASING TEST A CEMENT JOB OTHER: pertinent details, an	ILLING OPI ND	NS.	PLUG AND ABANDONME	ENT
PULL OR ALTER CASING OTHER: 13. Describe proposed or completion. 1. Notify OCD 24 hours prior too MI 2. RIH Tag CIBP at 4025, spot 25ss 3. Displace hole w/MLF, 9.5# Brine 4. Spot 25sx, plug from 2700-2500 5. Spot 25sx plug 1550-1300 (9 5/8	CHANGE PLANS MULTIPLE COMPLETION letted operations. (Clear rk). SEE RULE 1103. & RU. c, plug from 4025-3800 (S. w/12.5# gel P/BBL. (Yates, B-Salt). Shoe, T-Salt) WOC Tag.	☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐	COMMENCE DR CASING TEST A CEMENT JOB OTHER: pertinent details, an	ILLING OPI ND	NS.	PLUG AND ABANDONME	ENT
PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed we or recompletion. 1. Notify OCD 24 hours prior too MI 2. RIH Tag CIBP at 4025, spot 25ss 3. Displace hole w/MLF, 9.5# Brine 4. Spot 25sx, plug from 2700-2500	CHANGE PLANS MULTIPLE COMPLETION letted operations. (Clear rk). SEE RULE 1103. & RU. c, plug from 4025-3800 (S. w/12.5# gel P/BBL. (Yates, B-Salt). Shoe, T-Salt) WOC Tag.	☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐	COMMENCE DR CASING TEST A CEMENT JOB OTHER: pertinent details, an	ILLING OPI ND	NS.	PLUG AND ABANDONME	ENT
PULL OR ALTER CASING OTHER: 13. Describe proposed or comploof starting any proposed wo or recompletion. 1. Notify OCD 24 hours prior too MI 2. RIH Tag CIBP at 4025, spot 25ss 3. Displace hole w/MLF, 9.5# Brine 4. Spot 25sx, plug from 2700-2500 5. Spot 25sx plug 1550-1300 (9 5/8 6. Spot 30sx plug 300-Surf (Surf) W 7. Install dry hole marker. I hereby certify that the information a	CHANGE PLANS MULTIPLE COMPLETION letted operations. (Clear rk). SEE RULE 1103. & RU. c, plug from 4025-3800 (S. w/12.5# gel P/BBL. (Yates, B-Salt). Shoe, T-Salt) WOC Tag. /OC Tag. above is true and complete.	rly state all p For Multip Andres) WO	COMMENCE DR CASING TEST A CEMENT JOB OTHER: pertinent details, and le Completions: A C Tag.	ILLING OPI ND ad give perti ttach wellbo	nent date ore diagr	PLUG AND ABANDONME es, including es am of proposed	stimated date
PULL OR ALTER CASING OTHER: 13. Describe proposed or completion. 1. Notify OCD 24 hours prior too MI 2. RIH Tag CIBP at 4025, spot 25ss 3. Displace hole w/MLF, 9.5# Brine 4. Spot 25sx, plug from 2700-2500 5. Spot 25sx plug 1550-1300 (9 5/8 6. Spot 30sx plug 300-Surf (Surf) W 7. Install dry hole marker. I hereby certify that the information grade tank has been/will be constructed or	CHANGE PLANS MULTIPLE COMPLETION letted operations. (Clear rk). SEE RULE 1103. & RU. c, plug from 4025-3800 (S. w/12.5# gel P/BBL. (Yates, B-Salt). Shoe, T-Salt) WOC Tag. /OC Tag. above is true and complete.	rly state all p For Multip Andres) WO	COMMENCE DR CASING TEST A CEMENT JOB OTHER: pertinent details, an ile Completions: A C Tag.	ILLING OPI ND ad give perti ttach wellbo	nent date ore diagr	PLUG AND ABANDONME es, including es am of proposed er certify that any ative OCD appro	stimated date
OTHER: 13. Describe proposed or complete of starting any proposed wo or recompletion. 1. Notify OCD 24 hours prior too Mile 2. RIH Tag CIBP at 4025, spot 25ss 3. Displace hole w/MLF, 9.5# Brine 4. Spot 25sx, plug from 2700-2500 5. Spot 25sx plug 1550-1300 (9 5/8 6. Spot 30sx plug 300-Surf (Surf) W. 7. Install dry hole marker. I hereby certify that the information a grade tank has been/will be constructed or SIGNATURE	CHANGE PLANS MULTIPLE COMPLETION leted operations. (Clear rk). SEE RULE 1103. & RU. «, plug from 4025-3800 (S. w/12.5# gel P/BBL. (Yates, B-Salt). Shoe, T-Salt) WOC Tag. /OC Tag. above is true and completosed according to NMOC.	rly state all p For Multip Andres) WO	COMMENCE DR CASING TEST A CEMENT JOB OTHER: pertinent details, and le Completions: A C Tag. C Tag. est of my knowledg , a general permit Consulta	ILLING OPI ND ad give perti ttach wellbo	nent date	PLUG AND ABANDONME es, including es am of proposes er certify that any ative OCD appro	stimated date a completion pit or below-wed plan .
PULL OR ALTER CASING OTHER: 13. Describe proposed or completion. 1. Notify OCD 24 hours prior too MI 2. RIH Tag CIBP at 4025, spot 25ss 3. Displace hole w/MLF, 9.5# Brine 4. Spot 25sx, plug from 2700-2500 5. Spot 25sx plug 1550-1300 (9 5/8 6. Spot 30sx plug 300-Surf (Surf) W 7. Install dry hole marker. I hereby certify that the information grade tank has been/will be constructed or	CHANGE PLANS MULTIPLE COMPLETION leted operations. (Clear rk). SEE RULE 1103. & RU. «, plug from 4025-3800 (S. w/12.5# gel P/BBL. (Yates, B-Salt). Shoe, T-Salt) WOC Tag. /OC Tag. above is true and completosed according to NMOC.	rly state all p For Multip Andres) WO	COMMENCE DR CASING TEST A CEMENT JOB OTHER: pertinent details, and le Completions: A C Tag. C Tag. est of my knowledg , a general permit Consulta	ILLING OPI ND ad give perti ttach wellbo	nent date	PLUG AND ABANDONME es, including es am of proposed er certify that any ative OCD appro	stimated date a completion pit or below-wed plan .
OTHER: 13. Describe proposed or complous of starting any proposed wo or recompletion. 1. Notify OCD 24 hours prior too MI 2. RIH Tag CIBP at 4025, spot 25ss 3. Displace hole w/MLF, 9.5# Brine 4. Spot 25sx, plug from 2700-2500 5. Spot 25sx plug 1550-1300 (9 5/8 6. Spot 30sx plug 300-Surf (Surf) W 7. Install dry hole marker. I hereby certify that the information agrade tank has been/will be constructed or	CHANGE PLANS MULTIPLE COMPLETION leted operations. (Clear rk). SEE RULE 1103. & RU. «, plug from 4025-3800 (S. w/12.5# gel P/BBL. (Yates, B-Salt). Shoe, T-Salt) WOC Tag. /OC Tag. above is true and completosed according to NMOC.	rly state all p For Multip Andres) WO	COMMENCE DR CASING TEST A CEMENT JOB OTHER: pertinent details, and le Completions: A C Tag. C Tag. est of my knowledg , a general permit Consultated	ILLING OPI ND ad give perti ttach wellbo	nent date ore diagr	PLUG AND ABANDONME es, including es am of proposed er certify that any ative OCD appro	stimated date a completion pit or below-wed plan .
OTHER: 13. Describe proposed or complosed starting any proposed wo or recompletion. 1. Notify OCD 24 hours prior too MI 2. RIH Tag CIBP at 4025, spot 25ss 3. Displace hole w/MLF, 9.5# Brine 4. Spot 25sx, plug from 2700-2500 5. Spot 25sx plug 1550-1300 (9 5/8 6. Spot 30sx plug 300-Surf (Surf) W 7. Install dry hole marker. I hereby certify that the information grade tank has been/will be constructed or SIGNATURE Type or print name Immy Bag Type or print name Immy Bag	CHANGE PLANS MULTIPLE COMPLETION leted operations. (Clear rk). SEE RULE 1103. & RU. «, plug from 4025-3800 (S. w/12.5# gel P/BBL. (Yates, B-Salt). Shoe, T-Salt) WOC Tag. /OC Tag. above is true and completosed according to NMOC.	rly state all p For Multip Andres) WO	COMMENCE DR CASING TEST A CEMENT JOB OTHER: pertinent details, and le Completions: A C Tag. C Tag. est of my knowledg , a general permit Consultated	ILLING OPI ND ad give perti ttach wellbo	nent date ore diagr	PLUG AND ABANDONME es, including es am of proposes er certify that any ative OCD appro DATE 5	pit or below-wed plan [].
OTHER: 13. Describe proposed or complor of starting any proposed wo or recompletion. 1. Notify OCD 24 hours prior too MI 2. RIH Tag CIBP at 4025, spot 25ss 3. Displace hole w/MLF, 9.5# Brine 4. Spot 25sx, plug from 2700-2500 5. Spot 25sx plug 1550-1300 (9 5/8 6. Spot 30sx plug 300-Surf (Surf) W 7. Install dry hole marker. I hereby certify that the information agrade tank has been/will be constructed or SIGNATURE Type or print name	CHANGE PLANS MULTIPLE COMPLETION leted operations. (Clear rk). SEE RULE 1103. & RU. «, plug from 4025-3800 (S. w/12.5# gel P/BBL. (Yates, B-Salt). Shoe, T-Salt) WOC Tag. /OC Tag. above is true and completosed according to NMOC.	rly state all p For Multip Andres) WO	COMMENCE DR CASING TEST A CEMENT JOB OTHER: pertinent details, and le Completions: A C Tag. C Tag. est of my knowledg , a general permit Consulta	ILLING OPI ND ad give perti ttach wellbo	nent date ore diagr	PLUG AND ABANDONME es, including es am of proposes er certify that any ative OCD appro DATE 5	stimated date a completion pit or below-wed plan .

THE OIL CONSERVATION DIVISION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS.

PLUGGING & ABANDONMENT WORKSHEET (2 STRING CSNG) USA IVC. OPERATOR CHEURON LEASENAME WEST VACUUM UNIT WELL 17-5 RNG 34-E 33 TWN **SECT** (do (EWL 1980 NS L FROM FORMATION OF TO S. ANDRES TD: 4110 FORMATION @ PBTD PBTD: MLF SET @ TOC TOC DETERMENED BY SIZE 95/8 1480 SURE Ciec SURFACE INTMED 1 INTMED 2 512 4110 1800 CALC PERF CIEGO PROD TOC DETERMINED BY CIEC 530 SX SIZE TOP BOT MLF 542 × 95/8 LINER 1 2/81 LINER 2 CUT & PULL 62 TOP - BOTTOM - 4685 4110 INTMED 1 MLF INTMED 2 orzatiót.z NOW WELL PROD REQUIRED PLUGS DISTRICT ! PLUG TYPE BACKS NUTLER WOODS CANT PLUG YATE **EMPLE** CUEEN OH 35 SK2 TAND SE DEUTYAND SHOE 50 SIG PLUD#3 AN ANDRES CIRP/35' TLUO () 25 575 ruo m CAPITAL REST 50 SXS STUB PLUD#4 200 SXS RETNR SCI STAF 10 EXE S. AMDOS 25 KUDSI CHEERLY CARRON YATES 15 MATERIA CUMACA 95/85 15 BONG SPEDIO SULF CLORETA NUMBER OF STREET 14047 120011 **ADITAL** -

MEANN

CORPOR

TD 4110

DEPTH

6400

5350-5450

4800

4800

3600'-3700'

0-10

4025

2700

1550

<u> 300</u>

PLUO # 10

PLUG #