## State of New Mexico Energy, Minerals and Natural Resources Department

white-autor

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE OIL CONSERVATION D	IVISION
DISTRICT I 1220 South St. Francis D 1625 N. French Dr., Hobbs, NM 88240 Santa Fe, NM 87505	WELL API NO. 30-025-07528
DISTRICT II	5. Indicate Type of Lease
1301 W. Grand Ave, Artesia, NM 88210	STATE X FEE
DISTRICT III	6. State Oil & Gas Lease No.
1000 Rio Brazos Rd, Aztec, NM 87410	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BAC	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such pro	
1. Type of Well: Oil Well X Gas Well Other	8. Well No. 111
Name of Operator     Occidental Permian Ltd.	9. OGRID No. 157984
3. Address of Operator	10. Pool name or Wildcat HOBBS (G/SA)
1017 W. Stanolind Rd., HOBBS, NM 88240 505/397-8200	
4. Well Location	
<u> </u>	Feet From The WEST Line
11. Elevation (Show whether DF, RKB, RT GR, etc.)	ange 38-E NMPM LEA County
3646' GR	
Pit or Below-grade Tank Application or Closure	Division 6
Pit Type Depth of Ground Water Distance from nearest fresh was Pit Liner Thickness mil Below-Grade Tank: Volume bbls; O	
12. Check Appropriate Box to Indicate Nature of Notic NOTICE OF INTENTION TO:	e, Report, or Other Data SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL V	WORK X ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE	E DRILLING OPNS. PLUG & ABANDONMENT
	E DRILLING OPNS. PLUG & ABANDONMENT
PULL OR ALTER CASING Multiple Completion CASING TEST OTHER: OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give	E DRILLING OPNS. PLUG & ABANDONMENT  ST AND CEMENT JOB  e pertinent dates, including estimated date of starting any
PULL OR ALTER CASING Multiple Completion CASING TEST OTHER: OTHER:	E DRILLING OPNS. PLUG & ABANDONMENT  ST AND CEMENT JOB  e pertinent dates, including estimated date of starting any
PULL OR ALTER CASING Multiple Completion CASING TEST OTHER: OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagrant.  1. RUPU. Pull production equipment.	E DRILLING OPNS. PLUG & ABANDONMENT  ST AND CEMENT JOB  e pertinent dates, including estimated date of starting any m of proposed completion or recompletion.
PULL OR ALTER CASING Multiple Completion CASING TEST OTHER: OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagra  1. RUPU. Pull production equipment. 2. Perforate the following intervals; 4096-4100, 4103-06, 4134-40, 4156-62, 4169-7	E DRILLING OPNS. PLUG & ABANDONMENT  ST AND CEMENT JOB  e pertinent dates, including estimated date of starting any m of proposed completion or recompletion.
PULL OR ALTER CASING Multiple Completion CASING TEST OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagra  1. RUPU. Pull production equipment. 2. Perforate the following intervals; 4096-4100, 4103-06, 4134-40, 4156-62, 4169-73. Stimule perfs 4096-4232 w/2100 g 15% NEFE HCL acid.	E DRILLING OPNS. PLUG & ABANDONMENT  ST AND CEMENT JOB  e pertinent dates, including estimated date of starting any m of proposed completion or recompletion.
PULL OR ALTER CASING Multiple Completion CASING TEST OTHER: OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagra  1. RUPU. Pull production equipment. 2. Perforate the following intervals; 4096-4100, 4103-06, 4134-40, 4156-62, 4169-7	E DRILLING OPNS. PLUG & ABANDONMENT  ST AND CEMENT JOB  e pertinent dates, including estimated date of starting any m of proposed completion or recompletion.
PULL OR ALTER CASING Multiple Completion CASING TEST OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagra  1. RUPU. Pull production equipment. 2. Perforate the following intervals; 4096-4100, 4103-06, 4134-40, 4156-62, 4169-73. Stimule perfs 4096-4232 w/2100 g 15% NEFE HCL acid.  4. Run Reda ESP equipment, 129 jts 2-3/8" tbg w/drain valve. Intake set @4068'.	E DRILLING OPNS. PLUG & ABANDONMENT  ST AND CEMENT JOB  e pertinent dates, including estimated date of starting any m of proposed completion or recompletion.
PULL OR ALTER CASING Multiple Completion CASING TEST OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagra  1. RUPU. Pull production equipment. 2. Perforate the following intervals; 4096-4100, 4103-06, 4134-40, 4156-62, 4169-73. Stimule perfs 4096-4232 w/2100 g 15% NEFE HCL acid. 4. Run Reda ESP equipment, 129 jts 2-3/8" tbg w/drain valve. Intake set @4068'. 5. Install QCI wellhead connection. 6. RDPU. Clean Location.	E DRILLING OPNS. PLUG & ABANDONMENT  ST AND CEMENT JOB  e pertinent dates, including estimated date of starting any m of proposed completion or recompletion.
PULL OR ALTER CASING Multiple Completion CASING TEST OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagra  1. RUPU. Pull production equipment. 2. Perforate the following intervals; 4096-4100, 4103-06, 4134-40, 4156-62, 4169-73. Stimule perfs 4096-4232 w/2100 g 15% NEFE HCL acid. 4. Run Reda ESP equipment, 129 jts 2-3/8" tbg w/drain valve. Intake set @4068'. 5. Install QCI wellhead connection. 6. RDPU. Clean Location.  Rig Up Date: 05/04/2005	E DRILLING OPNS. PLUG & ABANDONMENT  ST AND CEMENT JOB  e pertinent dates, including estimated date of starting any m of proposed completion or recompletion.
PULL OR ALTER CASING Multiple Completion CASING TEST OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagra  1. RUPU. Pull production equipment. 2. Perforate the following intervals; 4096-4100, 4103-06, 4134-40, 4156-62, 4169-73. Stimule perfs 4096-4232 w/2100 g 15% NEFE HCL acid. 4. Run Reda ESP equipment, 129 jts 2-3/8" tbg w/drain valve. Intake set @4068'. 5. Install QCI wellhead connection. 6. RDPU. Clean Location.	E DRILLING OPNS. PLUG & ABANDONMENT  ST AND CEMENT JOB  e pertinent dates, including estimated date of starting any m of proposed completion or recompletion.
PULL OR ALTER CASING Multiple Completion CASING TEST OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagra  1. RUPU. Pull production equipment. 2. Perforate the following intervals; 4096-4100, 4103-06, 4134-40, 4156-62, 4169-73. Stimule perfs 4096-4232 w/2100 g 15% NEFE HCL acid. 4. Run Reda ESP equipment, 129 jts 2-3/8" tbg w/drain valve. Intake set @4068'. 5. Install QCI wellhead connection. 6. RDPU. Clean Location.  Rig Up Date: 05/04/2005	E DRILLING OPNS. PLUG & ABANDONMENT  ST AND CEMENT JOB  e pertinent dates, including estimated date of starting any m of proposed completion or recompletion.
PULL OR ALTER CASING Multiple Completion CASING TESTOTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagra  1. RUPU. Pull production equipment. 2. Perforate the following intervals; 4096-4100, 4103-06, 4134-40, 4156-62, 4169-73. Stimule perfs 4096-4232 w/2100 g 15% NEFE HCL acid. 4. Run Reda ESP equipment, 129 jts 2-3/8" tbg w/drain valve. Intake set @4068'. 5. Install QCI wellhead connection. 6. RDPU. Clean Location.  Rig Up Date: 05/04/2005 Rig Down Date: 05/06/2005	E DRILLING OPNS.  ST AND CEMENT JOB  PLUG & ABANDONMENT  Proposed completion or recompletion.  Plug & ABANDONMENT  Plug & ABAN
PULL OR ALTER CASING	E DRILLING OPNS.  PLUG & ABANDONMENT  Proposed completion or recompletion.  PROPOSED TO STAND CEMENT JOB  PLUG & ABANDONMENT
PULL OR ALTER CASING  Multiple Completion  CASING TEST OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagra  1. RUPU. Pull production equipment. 2. Perforate the following intervals; 4096-4100, 4103-06, 4134-40, 4156-62, 4169-73. Stimule perfs 4096-4232 w/2100 g 15% NEFE HCL acid. 4. Run Reda ESP equipment, 129 jts 2-3/8" tbg w/drain valve. Intake set @4068'. 5. Install QCI wellhead connection. 6. RDPU. Clean Location.  Rig Up Date: 05/04/2005 Rig Down Date: 05/06/2005  I hereby certify that the information above is true and complete to the best of my knowledge and belief constructed or closed according to NMOCD guidelines , a general permit or an (attacplan)	E DRILLING OPNS.  ST AND CEMENT JOB  Department dates, including estimated date of starting any m of proposed completion or recompletion.  Page 120 deg ph. (84 holes).
PULL OR ALTER CASING	E DRILLING OPNS. PLUG & ABANDONMENT  Expertinent dates, including estimated date of starting any mof proposed completion or recompletion.  73, 4179-82, and 4223-32, using 2 spf, 120 deg ph. (84 holes).  74
PULL OR ALTER CASING	E DRILLING OPNS.  PLUG & ABANDONMENT  Prince pertinent dates, including estimated date of starting any most proposed completion or recompletion.  Page 12 2 2 3 2 4 2 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5
PULL OR ALTER CASING	E DRILLING OPNS. PLUG & ABANDONMENT  Expertinent dates, including estimated date of starting any mof proposed completion or recompletion.  73, 4179-82, and 4223-32, using 2 spf, 120 deg ph. (84 holes).  74