Subtitit 3 Copies To Appropriate District	State of New Mexico		Form C-103	
Office District I	Energy, Minerals and Natural Reson	irces	May 27, 2004	
1625 N. French Dr., Hobbs, NM 88240	•	WELL API NO. 30-025-01416		
<u>District 11</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISI	ON 5. Indicate Type of	of Longo	
District III	1220 South St. Francis Dr.		FEE	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505	6. State Oil & Ga		
1220 S. St. Francis Dr., Santa Fe, NM	,		2 20000 1.101	
87505		K-385-5		
	ICES AND REPORTS ON WELLS SALS TO DRILL OR TO DEEPEN OR PLUG BACK 1		Unit Agreement Name	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		State 35	ľ	
PROPOSALS.)	Car Wall D Other	8. Well Number	2	
1. Type of Well: Oil Well Gas Well Other  2. Name of Operator			9. OGRID Number	
Mack Energy Corporation		9. OGRID Nullio	013837	
3. Address of Operator		I 0. Pool name or	I 0. Pool name or Wildcat	
P. O. Box 960 Artesia, NM 88211-0960		Corbin;Abo		
4. Well Location				
Unit Letter N	330 feet from the South lin	e and 1650 feet fro	m the West line	
Section35	Township 17S Range	33E NMPM	County Lea, NM	
	I 1. Elevation (Show whether DR, RKB, RT			
	4118' GR	,		
Pit or Below-grade Tank Application		0001	1500	
_	ater $\frac{150'}{}$ Distance from nearest fresh water well $\frac{2}{}$	Distance from nearest surf	face water 1500	
Pit Liner Thickness: 12 mil	Below-Grade Tank: Volume	bbls; Construction Material		
12. Check A	Appropriate Box to Indicate Nature of	Notice, Report or Other	Data	
		•		
	ITENTION TO:	SUBSEQUENT RE	_	
PERFORM REMEDIAL WORK	<b>. </b>	DIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON		ENCE DRILLING OPNS.	P AND A	
	·	ENCE DRILLING OPNS	P AND A	
TEMPORARILY ABANDON D	MULTIPLE COMPL CASIN	G/CEMENT JOB		
TEMPORARILY ABANDON DEPUBLIES CASING DEP	·	G/CEMENT JOB		
TEMPORARILY ABANDON DEPUBLICATION DEPUBLICATION DEPUBLICATION DE LA COMPUNITATION DEL COMPUNITATION DE LA COMPUNITATION DEL COMPUNITATION DE LA COMPUNITATION DEL COMPUNITATION DE LA COMPUNITATION DEL COMPUNITATION DE LA COMPUN	MULTIPLE COMPL CASING	G/CEMENT JOB  ::  details, and give pertinent date	es, including estimated date	
TEMPORARILY ABANDON DEPUBLICATION DEPUBLICATION DEPUBLICATION DE LA COMPUNITATION DEL COMPUNITATION DE LA COMPUNITATION DEL COMPUNITATION DE LA COMPUNITATION DEL COMPUNITATION DE LA COMPUNITATION DEL COMPUNITATION DE LA COMPUN	MULTIPLE COMPL CASING OTHER  oleted operations. (Clearly state all pertinent of	G/CEMENT JOB  ::  details, and give pertinent date	es, including estimated date	
TEMPORARILY ABANDON DEPUBLICATION DEPUBLICATION DEPUBLICATION DESCRIBED PROPOSED OF STATEMENT OF STATEMENT DESCRIBED PROPOSED OF STATEMENT DESCRIBED PROPOSED OF STATEMENT DESCRIPTION DESCRIPTION DESCRIPTION DESCRIPTION DE	MULTIPLE COMPL CASING OTHER pleted operations. (Clearly state all pertinent of cork). SEE RULE 1103. For Multiple Completions.	G/CEMENT JOB  ::  details, and give pertinent date	es, including estimated date	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:  13. Describe proposed or composed was or recompletion.  1. Notify OCD 24 hours prior to 2. Set CIBP @ 3882' w/ 35' cemes	MULTIPLE COMPL CASING OTHER OTHER OF THE PROPERTY OF THE PROPE	details, and give pertinent date etions: Attach wellbore diagraphith mud.	es, including estimated date	
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or composed was or recompletion.  1. Notify OCD 24 hours prior to 2. Set CIBP @ 3882' w/ 35' cemes 3. Set 35 sx cement plug 50' above	MULTIPLE COMPL  OTHER  Other  Ork). SEE RULE 1103. For Multiple Comples  Starting plugging operations.  In cap above perfs at 3982" and circ hole we and below 8 5/8" csg from 3159-3059'. We are the starting plugging operations.	details, and give pertinent date etions: Attach wellbore diagraphith mud.	es, including estimated date	
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or composition of starting any proposed was or recompletion.  1. Notify OCD 24 hours prior to 2. Set CIBP @ 3882' w/ 35' cemes 3. Set 35 sx cement plug 50' about 4. Set 35 sx plug @ 1675' 50' about 4.	MULTIPLE COMPL  OTHER	details, and give pertinent date etions: Attach wellbore diagraphith mud.	es, including estimated date	
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or composite of starting any proposed was or recompletion.  1. Notify OCD 24 hours prior to 2. Set CIBP @ 3882' w/ 35' cemes 3. Set 35 sx cement plug 50' above 4. Set 35 sx plug @ 1675' 50' above 5. Perf @ 401' squeeze 50' above	MULTIPLE COMPL  OTHER  Other  Ork). SEE RULE 1103. For Multiple Comples  Starting plugging operations.  In cap above perfs at 3982" and circ hole we and below 8 5/8" csg from 3159-3059'. We are the starting plugging operations.	details, and give pertinent date etions: Attach wellbore diagraphith mud.	es, including estimated date	
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or composite of starting any proposed was or recompletion.  1. Notify OCD 24 hours prior to 2. Set CIBP @ 3882' w/ 35' cemes 3. Set 35 sx cement plug 50' above 4. Set 35 sx plug @ 1675' 50' above 5. Perf @ 401' squeeze 50' above 6. Set 10 sx surface plug.	MULTIPLE COMPL  OTHER	details, and give pertinent date etions: Attach wellbore diagraphith mud.	es, including estimated date	
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or composite of starting any proposed was or recompletion.  1. Notify OCD 24 hours prior to 2. Set CIBP @ 3882' w/ 35' cemes 3. Set 35 sx cement plug 50' above 4. Set 35 sx plug @ 1675' 50' above 5. Perf @ 401' squeeze 50' above	MULTIPLE COMPL  OTHER	details, and give pertinent date etions: Attach wellbore diagraphith mud.	es, including estimated date	
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or composite of starting any proposed was or recompletion.  1. Notify OCD 24 hours prior to 2. Set CIBP @ 3882' w/ 35' cemes 3. Set 35 sx cement plug 50' above 4. Set 35 sx plug @ 1675' 50' above 5. Perf @ 401' squeeze 50' above 6. Set 10 sx surface plug.	MULTIPLE COMPL  OTHER	details, and give pertinent date etions: Attach wellbore diagraphith mud.	es, including estimated date	
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or composite of starting any proposed was or recompletion.  1. Notify OCD 24 hours prior to 2. Set CIBP @ 3882' w/ 35' cemes 3. Set 35 sx cement plug 50' above 4. Set 35 sx plug @ 1675' 50' above 5. Perf @ 401' squeeze 50' above 6. Set 10 sx surface plug.	MULTIPLE COMPL  OTHER	details, and give pertinent date etions: Attach wellbore diagraphith mud.	es, including estimated date	
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or composite of starting any proposed was or recompletion.  1. Notify OCD 24 hours prior to 2. Set CIBP @ 3882' w/ 35' cemes 3. Set 35 sx cement plug 50' above 4. Set 35 sx plug @ 1675' 50' above 5. Perf @ 401' squeeze 50' above 6. Set 10 sx surface plug.	OTHER OBJECT OF THE POPULATION	details, and give pertinent date etions: Attach wellbore diagraphith mud.	es, including estimated date am of proposed completion	
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or composite of starting any proposed was or recompletion.  1. Notify OCD 24 hours prior to 2. Set CIBP @ 3882' w/ 35' cemes 3. Set 35 sx cement plug 50' above 4. Set 35 sx plug @ 1675' 50' above 5. Perf @ 401' squeeze 50' above 6. Set 10 sx surface plug.	OTHER OLL (Clearly state all pertinent of cork). SEE RULE 1103. For Multiple Complestarting plugging operations.  In cap above perfs at 3982" and circ hole we and below 8 5/8" csg from 3159-3059'. We top of salt.  In and below 11 3/4" shoe. WOC and tag.	details, and give pertinent date etions: Attach wellbore diagraphic with mud.	es, including estimated date am of proposed completion	
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or composite of starting any proposed was or recompletion.  1. Notify OCD 24 hours prior to 2. Set CIBP @ 3882' w/ 35' cemes 3. Set 35 sx cement plug 50' above 4. Set 35 sx plug @ 1675' 50' above 5. Perf @ 401' squeeze 50' above 6. Set 10 sx surface plug.	OTHER OTHER COMPL  Starting plugging operations. It cap above perfs at 3982" and circ hole we and below 8 5/8" csg from 3159-3059'. We top of salt.  and below 11 3/4" shoe. WOC and tag.  THE OIL ( BE NOTI	details, and give pertinent date etions: Attach wellbore diagraphic with mud.  WOC and tag.  CONSERVATION DIVIDIS PR	es, including estimated date am of proposed completion  VISION MUST  IOR TO THE	
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or composite of starting any proposed was or recompletion.  1. Notify OCD 24 hours prior to 2. Set CIBP @ 3882' w/ 35' cemes 3. Set 35 sx cement plug 50' above 4. Set 35 sx plug @ 1675' 50' above 5. Perf @ 401' squeeze 50' above 6. Set 10 sx surface plug.	OTHER OTHER COMPL  Starting plugging operations. It cap above perfs at 3982" and circ hole we and below 8 5/8" csg from 3159-3059'. We top of salt.  and below 11 3/4" shoe. WOC and tag.  THE OIL ( BE NOTI	details, and give pertinent date etions: Attach wellbore diagraphic with mud.  WOC and tag.  CONSERVATION DIVIDIS PR	es, including estimated date am of proposed completion  VISION MUST  IOR TO THE	
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or composite of starting any proposed was or recompletion.  1. Notify OCD 24 hours prior to 2. Set CIBP @ 3882' w/ 35' cemes 3. Set 35 sx cement plug 50' above 4. Set 35 sx plug @ 1675' 50' above 5. Perf @ 401' squeeze 50' above 6. Set 10 sx surface plug.	OTHER OTHER COMPL  Starting plugging operations. It cap above perfs at 3982" and circ hole we and below 8 5/8" csg from 3159-3059'. We top of salt.  and below 11 3/4" shoe. WOC and tag.  THE OIL ( BE NOTI	details, and give pertinent date etions: Attach wellbore diagraphic with mud.	es, including estimated date am of proposed completion  VISION MUST  IOR TO THE	
TEMPORARILY ABANDON DULL OR ALTER CASING COTHER:  13. Describe proposed or compost of starting any proposed wor recompletion.  1. Notify OCD 24 hours prior to 2. Set CIBP @ 3882' w/ 35' cemes 3. Set 35 sx cement plug 50' above 4. Set 35 sx plug @ 1675' 50' above 5. Perf @ 401' squeeze 50' above 6. Set 10 sx surface plug.  7. Install dry hole marker.	OTHER OPEN CASING OTHER OPEN CORN. SEE RULE 1103. For Multiple Complestarting plugging operations. Int cap above perfs at 3982" and circ hole we and below 8 5/8" csg from 3159-3059'. We top of salt. In and below 11 3/4" shoe. WOC and tag.  THE OIL OBE NOTIBEGINNIN	CONSERVATION DIVISION DIVISIONI DIVISIO	es, including estimated date am of proposed completion  VISION MUST IOR TO THE PERATIONS.	
TEMPORARILY ABANDON DULL OR ALTER CASING COTHER:  13. Describe proposed or compost of starting any proposed wor recompletion.  1. Notify OCD 24 hours prior to 2. Set CIBP @ 3882' w/ 35' cemes 3. Set 35 sx cement plug 50' above 4. Set 35 sx plug @ 1675' 50' above 5. Perf @ 401' squeeze 50' above 6. Set 10 sx surface plug.  7. Install dry hole marker.	OTHER  OTHER  In other conditions (Clearly state all pertinent of the conditions). SEE RULE 1103. For Multiple Comples of the conditions o	CONSERVATION DIVISION DIVISION OF PLUGGING O	es, including estimated date am of proposed completion  VISION MUST IOR TO THE PERATIONS.	
TEMPORARILY ABANDON DULL OR ALTER CASING COTHER:  13. Describe proposed or compost of starting any proposed wor recompletion.  1. Notify OCD 24 hours prior to 2. Set CIBP @ 3882' w/ 35' cemes 3. Set 35 sx cement plug 50' above 4. Set 35 sx plug @ 1675' 50' above 5. Perf @ 401' squeeze 50' above 6. Set 10 sx surface plug.  7. Install dry hole marker.	MULTIPLE COMPL  OTHER  Other  John See Rule 1103. For Multiple Completed operations.  Other  John See Rule 1103. For Multiple Completed operations.  Other  John See Rule 1103. For Multiple Completed operations.  Other and circ hole was and circ hole was and below 8 5/8" csg from 3159-3059'. We top of salt.  In the other seeds of the seed of the seeds of	details, and give pertinent date etions: Attach wellbore diagraphic with mud.  WOC and tag.  CONSERVATION DIVIDITIES OF PLUGGING OF PLUGGI	es, including estimated date am of proposed completion  VISION MUST IOR TO THE PERATIONS.  certify that any pit or belownative OCD-approved plan	
TEMPORARILY ABANDON DULL OR ALTER CASING COTHER:  13. Describe proposed or compost of starting any proposed wor recompletion.  1. Notify OCD 24 hours prior to 2. Set CIBP @ 3882' w/ 35' cemes 3. Set 35 sx cement plug 50' above 4. Set 35 sx plug @ 1675' 50' above 5. Perf @ 401' squeeze 50' above 6. Set 10 sx surface plug.  7. Install dry hole marker.	OTHER  OTHER  In other conditions (Clearly state all pertinent of the conditions). SEE RULE 1103. For Multiple Comples of the conditions o	details, and give pertinent date etions: Attach wellbore diagraphic with mud.  WOC and tag.  CONSERVATION DIVIDITIES OF PLUGGING OF PLUGGI	es, including estimated date am of proposed completion  VISION MUST IOR TO THE PERATIONS.	
TEMPORARILY ABANDON DULL OR ALTER CASING DULL OR AL	MULTIPLE COMPL  OTHER  Other  John See Rule 1103. For Multiple Completed operations. (Clearly state all pertinent of the cork). SEE Rule 1103. For Multiple Completed operations.  Int cap above perfs at 3982" and circ hole were and below 8 5/8" csg from 3159-3059'. We top of salt.  In the color of the complete operation of the color of the co	CONSERVATION DIVIDITIES OF PLUGGING OF PLUGGING OF PLUGGING OF PLUGGING OF The permit of an (attached) alternal permit of a permit o	es, including estimated date am of proposed completion  VISION MUST IOR TO THE PERATIONS.  certify that any pit or belownative OCD-approved plan   DATE 5/25/2005	
TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER:  13. Describe proposed or composition of starting any proposed wor recompletion.  1. Notify OCD 24 hours prior to 2. Set CIBP @ 3882' w/ 35' cemes 3. Set 35 sx cement plug 50' above 4. Set 35 sx plug @ 1675' 50' above 6. Set 10 sx surface plug.  7. Install dry hole marker.  I hereby certify that the information grade tank has been/will be constructed of SIGNATURE  Type or print name Jerry W. Sherr	MULTIPLE COMPL  OTHER  Other  Joleted operations. (Clearly state all pertinent of the cork). SEE RULE 1103. For Multiple Comples  Starting plugging operations.  In cap above perfs at 3982" and circ hole we and below 8 5/8" csg from 3159-3059". We top of salt.  and below 11 3/4" shoe. WOC and tag.  THE OIL (  BE NOTE  BEGINNIN  Above is true and complete to the best of my key and complete to the bes	CONSERVATION DIVIDITIES OF PLUGGING OF PLUGGING OF PLUGGING OF PLUGGING OF THE PROPERTY OF THE	es, including estimated date am of proposed completion  VISION MUST IOR TO THE PERATIONS.  certify that any pit or belownative OCD-approved plan   DATE 5/25/2005  Celephone No. (505)748-1288	
TEMPORARILY ABANDON DULL OR ALTER CASING DULL OR ALTER CASING DOTHER:  13. Describe proposed or composition of starting any proposed wor recompletion.  1. Notify OCD 24 hours prior to 2. Set CIBP @ 3882' w/ 35' cemes 3. Set 35 sx cement plug 50' above 4. Set 35 sx plug @ 1675' 50' above 5. Perf @ 401' squeeze 50' above 6. Set 10 sx surface plug.  7. Install dry hole marker.	MULTIPLE COMPL  OTHER  Other  Joleted operations. (Clearly state all pertinent of the cork). SEE RULE 1103. For Multiple Comples  Starting plugging operations.  In cap above perfs at 3982" and circ hole we and below 8 5/8" csg from 3159-3059". We top of salt.  and below 11 3/4" shoe. WOC and tag.  THE OIL (  BE NOTE  BEGINNIN  Above is true and complete to the best of my key and complete to the bes	CONSERVATION DIVIDITIES OF PLUGGING OF PLUGGING OF PLUGGING OF PLUGGING OF THE PROPERTY OF THE	es, including estimated date am of proposed completion  VISION MUST IOR TO THE PERATIONS.  certify that any pit or belownative OCD-approved plan   DATE 5/25/2005  Celephone No. (505)748-1288	
TEMPORARILY ABANDON DULL OR ALTER CASING DULL OR ALTER CASING DOTHER:  13. Describe proposed or composition of starting any proposed wor recompletion.  1. Notify OCD 24 hours prior to 2. Set CIBP @ 3882' w/ 35' cemes 3. Set 35 sx cement plug 50' above 4. Set 35 sx plug @ 1675' 50' above 6. Set 10 sx surface plug.  7. Install dry hole marker.  I hereby certify that the information grade tank has been/will be constructed of SIGNATURE Derry W. Sherr For State Use Only  APPROVED BY: James Derry W. Sherr For State Use Only	MULTIPLE COMPL  OTHER  Other  Joleted operations. (Clearly state all pertinent of the cork). SEE RULE 1103. For Multiple Comples  Starting plugging operations.  In cap above perfs at 3982" and circ hole we and below 8 5/8" csg from 3159-3059". We top of salt.  and below 11 3/4" shoe. WOC and tag.  THE OIL (  BE NOTE  BEGINNIN  Above is true and complete to the best of my key and complete to the bes	CONSERVATION DIVIDITIES OF PLUGGING OF PLUGGING OF PLUGGING OF PLUGGING OF THE PROPERTY OF THE	es, including estimated date am of proposed completion  VISION MUST IOR TO THE PERATIONS.  certify that any pit or belownative OCD-approved plan   DATE 5/25/2005  Celephone No. (505)748-1288	
TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER:  13. Describe proposed or composition of starting any proposed wor recompletion.  1. Notify OCD 24 hours prior to 2. Set CIBP @ 3882' w/ 35' cemes 3. Set 35 sx cement plug 50' above 4. Set 35 sx plug @ 1675' 50' above 5. Perf @ 401' squeeze 50' above 6. Set 10 sx surface plug.  7. Install dry hole marker.  I hereby certify that the information grade tank has been/will be constructed of SIGNATURE  Type or print name Jerry W. Sherr For State Use Only	MULTIPLE COMPL  OTHER  Other  Joleted operations. (Clearly state all pertinent of the cork). SEE RULE 1103. For Multiple Comples  Starting plugging operations.  In cap above perfs at 3982" and circ hole we and below 8 5/8" csg from 3159-3059". We top of salt.  and below 11 3/4" shoe. WOC and tag.  THE OIL (  BE NOTE  BEGINNIN  Above is true and complete to the best of my key and complete to the bes	CONSERVATION DIVIDITIES OF PLUGGING OF PLUGGING OF PLUGGING OF PLUGGING OF The permit of an (attached) alternal permit of a permit o	es, including estimated date am of proposed completion  VISION MUST IOR TO THE PERATIONS.  certify that any pit or belownative OCD-approved plan   DATE 5/25/2005  Celephone No. (505)748-1288	

## MACK ENERGY CORPORATION STATE 35 #2 Sec 35 T17S R33E 330FSL 165FWL

