Submit 3 Copies To Appropriate District State of New Mexico	Form C-103		
Office Energy, Minerals and Natural Resources	May 27, 2004		
District I Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240	WELL API NO.		
District II	30-025-20845		
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	5. Indicate Type of Lease		
District III 1000 Rio Brazos Rd., Aztec, NM 87410 1220 South St. Francis Dr.	STATE X FEE		
District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM	B-1576-3		
87505			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH DEPODSALS)	7. Lease Name or Unit Agreement Name Vacuum Glorieta East Unit Tract 19		
PROPOSALS.) 1. Type of Well: Oil Well X Gas Well Other	8. Well Number 2		
2. Name of Operator	9. OGRID Number		
ConocoPhillips Company	217817		
	10. Pool name or Wildcat		
3. Address of Operator 4001 Penbrook St. Odessa, TX 79762			
	Vacuum; Glorieta		
4. Well Location	-		
Unit Letter K : 2310 feet from the South line and 23	10feet from theline		
Section 32 Township 17S Range 35E	NMPM CountyLea		
11. Elevation (Show whether DR, RKB, RT, GR, etc., 3964' GL			
Pit or Below-grade Tank Application 🗌 or Closure 🗌			
	ance from nearest surface water		
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Co	nstruction Material		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK D PLUG AND ABANDON REMEDIAL WOR			
TEMPORARILY ABANDON 🛛 CHANGE PLANS 🗌 COMMENCE DRI			
PULL OR ALTER CASING			
OTHER: OTHER:			
13. Describe proposed or completed operations. (Clearly state all pertinent details, and	d give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion.			
1.Test anchors as required.			
2.Hold safety meeting & MIRU Well Service Unit.			
3.POOH with rods and insert pump as required.			
4.RU pump truck and kill well. Ensure well is dead. ND wellhead. NU BOPE.			
5.POOH with production tubing. Visually inspect tubing while COOH. If condition is go	od use tubing as workstring If-not-lay		
down production tubing and PU 2-3/8" tubing workstring.	00, use tubing as workstring. It not have		
5.POOH with production tubing. Visually inspect tubing while COOH. If condition is good, use tubing as workstring. If not lay down production tubing and PU 2-3/8" tubing workstring. 6.TIH with bit and casing scraper to top perf at 5992'. POOH with bit & casing scraper. 7 PU and GIH with 4-1/2" CIBP on workstring. Set CIPP within 100' of top performing at 5002'			
7.PU and GIH with 4-1/2" CIBP on workstring. Set CIBP within 100' of top perforation at 5992'.			
8. Test casing and CIBP to 500 psig for 30 minutes per NMOCD requirements	tor.		
9.RU pump truck and circulate well with inhibited packer fluid containing corrosion inhibitor.			
10.POOH and lay down workstring.			
11.ND BOPE and NU wellhead.			
12.RDMO well service unit.			
	Net Lev		
	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~		
	2621282		
I hereby certify that the information above is true and complete to the best of my knowledg	e and belief. I further certify that any nit or below-		

grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan .

SIGNATURE Ulla Manco	TITLE Regulatory Specialist	DATE 05/31/2005

Type or print name Alva Franco For State Use Only

APPROVED BY: _____ Conditions of Approval (if any):

ORIGINAL SIGNER DE CONSTRUCTION DE CONSTRUCTURA DE CONSTRUCTUR		offelephone No	0. (432)368-1665
	ware and a provide the second	DATE	
permeasure and the contract of the second			