

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 5-27-2004

FILE IN TRIPLICATE

OIL CONSERVATION DIVISION

DISTRICT I

1625 N. French Dr., Hobbs, NM 88240

DISTRICT II

1301 W. Grand Ave., Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd, Aztec, NM 87410

1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.
30-025-37102

5. Indicate Type of Lease

STATE ☒ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)

7. Lease Name or Unit Agreement Name

NORTH HOBBS (G/SA) UNIT
Section 30

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other ☐

8. Well No. 617

2. Name of Operator

Occidental Permian Ltd.

9. OGRID No. 157984

3. Address of Operator

1017 W. Stanolind Rd., HOBBS, NM 88240 505/397-8200

10. Pool name or Wildcat HOBBS (G/SA)

4. Well Location

Unit Letter D : 900 Feet From The NORTH 863 Feet From The WEST Line
Section 30 Township 18-S Range 38-E NMPM LEA County

11. Elevation (Show whether DF, RKB, RT GR, etc.)

3658' GR

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit Type _____ Depth of Ground Water _____ Distance from nearest fresh water well _____ Distance from nearest surface water

Pit Liner Thickness _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ Multiple Completion ☐

OTHER: _____ ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG & ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: New Well Completion ☒

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. RUPU. Drill out DV tool @3521'. Tag PBTD @4367'.
2. Perforate the following interval; 4159-60 using 1 spf. (2 holes).
3. Perforate the following intervals; 4165-72, 4197-4202, 4211-28, 4232-35, 4241-46, 4251-54, 4258-63, 4267-70, 4273-86 and 4290-4301 using 2 spf, 120 deg ph. (134 holes).
4. Stimulate perms 4159 to 4301 w/3610 g 15% NEFE HCL acid in 43 settings.
5. RIH Reda ESP equipment on 125 jts 2-7/8" tbg w/drain valve. Intake set @4112'.
6. Install QCI wellhead connection. RDPU. Clean Location.

Rig Up Date: 06/08/2005

Rig Down Date: 06/10/2005

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐ , a general permit ☐ or an (attached) alternative OCD-approved plan ☐

SIGNATURE

Robert Gilbert

TITLE Workover Completion Specialist

DATE 06/15/2005

TYPE OR PRINT NAME Robert Gilbert

E-mail address: robert_gilbert@oxy.com

TELEPHONE NO. 505/397-8206

For State Use Only

APPROVED BY

[Signature]

TITLE

PETROLEUM ENGINEER

DATE

CONDITIONS OF APPROVAL IF ANY:

JUN 16 2005