Office	State of New M		Form C-103	
District I	Energy, Minerals and Nat	ural Resources	WELL API NO.	7
1625 N. French Dr., Hobbs, NM 882 District II	OIL CONTENTAL TYON		30-025-27489	
1301 W. Grand Ave., Artesia, NM 8 District III			5. Indicate Type of Lease	1
1000 Rio Brazos Rd., Aztec, NM 87	1220 South St. Fra		STATE 🗌 FEE 🔀	
District IV 1220 S. St. Francis Dr., Santa Fe, NA	Santa Fe, NM 8	37505 (5)	6. State Oil & Gas Lease No.	
87505 St. Francis Dr., Santa Fe, Nr	MI Programme Control of the Control	78		
	NOTICES AND REPORTS ON WELL	S S	7. Lease Name or Unit Agreement Name	1
DIFFERENT RESERVOIR. USE ".	PROPOSALS TO DRILL OR TO DEEPEN OR P APPLICATION FOR PERMIT" (FORM C-101)	LUG BACK TOTA/ FOR SUCH	Fowler-Hair	
PROPOSALS.)	7	GLDIEL C.	8. Well Number 2	-
 Type of Well: Oil Well Name of Operator 	Gas Well Other	GLAIG		4
Imperia	of Operating Go.		9. OGRID Number 217168	
3. Address of Operator			10. Pool name or Wildcat,	1
414 W Texas	Ave, Ste 308 Midlan	1 TX79701	Langlie-Mattix	1 .
4. Well Location	,			┦
Unit LetterC	: 660 feet from the Nov	th line and 19	180 feet from the West line	
Section 11	Township 245		NMPM Lea County N.M.	
	11. Elevation (Show whether D			
Pit or Below-grade Tank Application				1
Pit type <u>Stee</u> Depth to Gr	oundwaterDstance from nearest fresh	water well Dist	tance from nearest surface water	1
Pit Liner Thickness:	mil Below-Grade Tank: Volume	bbls; Co	nstruction Material	_
12. Ch	eck Appropriate Box to Indicate	Nature of Notice,	Report or Other Data	
		•		
NOTICE C PERFORM REMEDIAL WOR	OF INTENTION TO:		SEQUENT REPORT OF:	
TEMPORARILY ABANDON		REMEDIAL WOR	<u>=</u>	
PULL OR ALTER CASING		COMMENCE DRI		
TOLE ON ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	I JOB 📋	
OTHER:	□	OTHER:	The second secon	
13. Describe proposed or of starting any proposed	completed operations. (Clearly state al sed work). SEE RULE 1103. For Mult	OTHER: I pertinent details, and iple Completions: At	d give pertinent dates, including estimated datach wellbore diagram of proposed completio	te n
13. Describe proposed or of starting any propose or recompletion.	sed work). SEE RULE 1103. For Mult	l pertinent details, an iple Completions: At	d give pertinent dates, including estimated datatach wellbore diagram of proposed completio	te n
13. Describe proposed or of starting any propose or recompletion.	sed work). SEE RULE 1103. For Mult MIRU Workover	l pertinent details, and iple Completions: At	tach wellbore diagram of proposed completio	te n
13. Describe proposed or of starting any propose or recompletion.	sed work). SEE RULE 1103. For Mult MIRU Workover	l pertinent details, and iple Completions: At	tach wellbore diagram of proposed completio	te n
13. Describe proposed or of starting any propose or recompletion.	sed work). SEE RULE 1103. For Mult MIRU Workover Ran gamma vay -	I pertinent details, and iple Completions: At Righton Bond log	tach wellbore diagram of proposed completion W Collay locator	n
13. Describe proposed or of starting any propose or recompletion.	sed work). SEE RULE 1103. For Mult MIRU Workover Ran gamma vay - Get CIBP a 3500.	I pertinent details, and iple Completions: At Ria bond log Dumped	w collar locator 30' cement w bailer	n •
13. Describe proposed or of starting any propose or recompletion.	MIRU Workover Ran gamma ray - Get CIBP = 3500. Perforated 5½"	I pertinent details, and iple Completions: At Ria bond log Dumped Casing W	w collar locator 30' cement w bailer 14 shots @ 3396, 91,	r 69,
13. Describe proposed or of starting any propose or recompletion.	SEE RULE 1103. For Mult MIRU Workover Ran gamma ray - Get CIBP a 3500. Perforated 5½" 3329, 3274, 43, 6	I pertinent details, and iple Completions: At bond log bond log bumped casing ways 2960	w collar locator 30' cement w bailer 14 shots @ 3396, 91, 18, 2876,54 & 2734	r 69,
13. Describe proposed or of starting any propose or recompletion.	MIRU Workover Ran gamma ray - Get CIBP = 3500. Perforated 5½"	I pertinent details, and iple Completions: At bond log bond log bumped casing ways 2960	w collar locator 30' cement w bailer 14 shots @ 3396, 91, 18, 2876,54 & 2734	r 69,
13. Describe proposed or of starting any propose or recompletion.	SEE RULE 1103. For Mult MIRU Workover Ran gamma ray - Get CIBP a 3500. Perforated 5½" 3329, 3274, 43, 6	I pertinent details, and iple Completions: At bond log bond log bumped casing ways 2960	w collar locator 30' cement w bailer 14 shots @ 3396, 91, 18, 2876,54 & 2734	r 69,
13. Describe proposed or of starting any propose or recompletion.	SEE RULE 1103. For Mult MIRU Workover Ran gamma ray - Get CIBP a 3500. Perforated 5½" 3329, 3274, 43, 6	I pertinent details, and iple Completions: At hond log bond log bumped casing way, 2960 to rigged	w collar locator 30' cement w bailer 14 shots @ 3396, 91, 18, 2876,54 & 2734	r 69,
13. Describe proposed or of starting any proposed or recompletion. 05-13-2003	MIRU Workover Ran gamma ray = Get CIBP = 3500. Perforated 52" 3329, 3274, 43, 6 Cleaned location	I pertinent details, and iple Completions: At Big bond log bumped casing ways a rigged Per JG	w collar locator 30' cement w bailer 14 shots @ 3396, 91, 18, 2876,54 & 2734 down unit	r 69,
13. Describe proposed or of starting any proposed or recompletion. 05-13-2003	MIRU Workover Ran gamma ray = Get CIBP = 3500. Perforated 52" 3329, 3274, 43, 6 Cleaned location SI 15/13 nation above is true and complete to the	I pertinent details, and iple Completions: At Big bond log bumped Casing was 7, 2960 to rigged best of my knowledge	tach wellbore diagram of proposed completion w collar locator 30' cement w bailer 14 shots @ 3396, 91, 18, 2876,54 & 2734 down unit	r 69,
13. Describe proposed or of starting any propose or recompletion. 05-13-2003 Thereby certify that the information of the construction of the con	MIRU Workover Ran gamma ray - Set CIBP a 3500. Perforated 5½" 3329, 3274, 43, 6 Cleaned location SI 15/03 nation above is true and complete to the according to NMOCD guideline	I pertinent details, and iple Completions: At hond log bond log bumped casing ways and the rigged best of my knowledges a general permit a consult	tach wellbore diagram of proposed completion w collar locator 30' cement w bailer 14 shots @ 3396, 91, 18, 2876,54 & 2734 down unit te and belief. I further certify that any pit or below or an (attached) alternative OCD-approved plan	r 69,
13. Describe proposed or of starting any propose or recompletion. 05-13-2003 Thereby certify that the information of the starting any proposed or recompletion.	MIRU Workover Ran gamma ray - Get CIBP a 3500. Perforated 5½" 3329, 3274, 43, 6 Cleaned location SI 15/13 nation above is true and complete to the letted or closed according to NMOCD guideline STOWN TITLE	I pertinent details, and iple Completions: At hond log bond log bumped casing ways and the rigged best of my knowledges a general permit a consult	tach wellbore diagram of proposed completion w collar locator 30' cement w bailer 14 shots @ 3396, 91, 18, 2876,54 & 2734 down unit te and belief. I further certify that any pit or below or an (attached) alternative OCD-approved plan	n 69,
13. Describe proposed or of starting any proposed or recompletion. 05-13-2003 Thereby certify that the information of the starting any proposed or recompletion.	MIRU Workover Ran gamma ray - Get CIBP = 3500. Perforated 5½" 3329, 3274, 43, 6 Cleaned location SI 15/13 nation above is true and complete to the locat or closed according to NMOCD guideline SOUTH TITLE	I pertinent details, and iple Completions: At hond log bond log bumped casing ways and the rigged best of my knowledges a general permit a consult	tach wellbore diagram of proposed completion w collar locator 30' cement w bailer 14 shots @ 3396, 91, 18, 2876,54 & 2734 down unit te and belief. I further certify that any pit or below or an (attached) alternative OCD-approved plan	n 69,
13. Describe proposed or of starting any propose or recompletion. 05-13-2003 Thereby certify that the information of the starting any proposed or recompletion.	MIRU Workover Ran gamma ray - Get CIBP = 3500. Perforated 5½" 3329, 3274, 43, 6 Cleaned location SI 15/13 nation above is true and complete to the locat or closed according to NMOCD guideline SOUTH TITLE	I pertinent details, and iple Completions: At hond log bond log bumped casing ways and the rigged best of my knowledges a general permit a consult	tach wellbore diagram of proposed completion w collar locator 30' cement w bailer 14 shots @ 3396, 91, 18, 2876,54 & 2734 down unit te and belief. I further certify that any pit or below or an (attached) alternative OCD-approved plan	n 69,
13. Describe proposed or of starting any proposed or recompletion. 05-13-2003 Thereby certify that the information of the start in	MIRU Workover Ran gamma ray - Get CIBP = 3500. Perforated 5½" 3329, 3274, 43, 6 Cleaned location SI 15/13 nation above is true and complete to the need or closed according to NMOCD guideline. SOURCE E-mail	I pertinent details, and iple Completions: At Prigonal log Dumped Casing War, 2960 to rigged best of my knowledges a general permit a consult	tach wellbore diagram of proposed completion w collar locator 30' cement w bailer 14 shots @ 3396, 91, 18, 2876,54 & 2734 down unit te and belief. I further certify that any pit or below or an (attached) alternative OCD-approved plan DATE June 23, ENGINEER Telephone No. 432-68 JUL 0 2005	n 69,
13. Describe proposed or of starting any proposed or recompletion. 05-13-2003 Thereby certify that the information of the starting any proposed or recompletion.	MIRU Workover Ran gamma ray - Get CIBP = 3500. Perforated 52" 3329, 3274, 43, 6 Cleaned location SI 15/13 nation above is true and complete to the locat or closed according to NMOCD guideline. Sould Jr E-mail	I pertinent details, and iple Completions: At hond log bond log bumped casing ways and the rigged best of my knowledges a general permit a consult	tach wellbore diagram of proposed completion w collar locator 30' cement w bailer 14 shots @ 3396, 91, 18, 2876,54 & 2734 down unit te and belief. I further certify that any pit or below or an (attached) alternative OCD-approved plan	n 69,