Submit 3 Copies To Appropriate District Office	State of New Mexico	Form C-103 May 27, 2004
District I 1625 N. French Dr., Hobbs, NM 88240 District II	Energy, Minerals and Natural Resources	WELL API NO. 30-025-03422
1301 W. Grand Ave., Artesia, NM 88210 <u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505	5. Indicate Type of Lease STATE X FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa PC, ININ 87505	6. State Oil & Gas Lease No. B-1399
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		7. Lease Name or Unit Agreement Name Shell State
	Gas Well Dother	8. Well Number 4
2. Name of Operator Hal J. Rasmussen Operating		9. OGRID Number 667939
3. Address of Operator 550 W. Texas, Ste 500 Midland, 2X 79702		10. Pool name or Wildcat
4. Well Location	J Midland, 1X /9/02	Wilson Yates 7 Rivers Assoc
	660 feet from the South line and	
Section 7	Township 21S Range 35E	NMPM Lea County
	11. Elevation (Show whether DR, RKB, RT, GR, et 3685 GL	(C.)
Pit or Below-grade Tank Application o	<u>r Closure []</u> ater 40 Distance from nearest fresh water well E	Nistance from nearest surface water
Pit type STELL Depth to Groundw Pit Liner Thickness: mil		Construction Material
	Appropriate Box to Indicate Nature of Notice	
		BSEQUENT REPORT OF:
	PLUG AND ABANDON REMEDIAL WO	
	CHANGE PLANS COMMENCE D	RILLING OPNS. P AND A
PULL OR ALTER CASING	MULTIPLE COMPL CASING/CEME	NT JOB
OTHER: 13. Describe proposed or comp of starting any proposed we	OTHER: OTHER: Other operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions:	and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. 6/13 1. Notify OCD B TOC @ 3400'. 3. Circ Tag TOC @ 1680'. 6. 6/20/05. 6/20 7. Sqz surface. 10. RDMO. C	OTHER: leted operations. (Clearly state all pertinent details,	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion . 2/ 2% CaCl 3570', WOC & tag 0 sx. cmt. @ 1855'. 6/18/05 5. ' thru perfs @ 170', no tag on 47'. 9. Spot 15 sx. cmt. 47' to 1 dry hole marker, and clean
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. 6/13 1. Notify OCD B TOC @ 3400'. 3. Circ Tag TOC @ 1680'. 6. 6/20/05. 6/20 7. Sqz	Deted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: uddy Hill 6/17 2. Spot 30 sx. cmt ulate hole w/ 9.5# MLF. 4. Spot 3 Sqz. 175 sx. cmt. under pkr. @ 30 . 175 sx. cmt. 6/21 8. Tag TOC @	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion . 2/ 2% CaCl 3570', WOC & tag 0 sx. cmt. @ 1855'. 6/18/05 5. I' thru perfs @ 170', no tag on 47'. 9. Spot 15 sx. cmt. 47' to
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. 6/13 1. Notify OCD B TOC @ 3400'. 3. Circ Tag TOC @ 1680'. 6. 6/20/05. 6/20 7. Sqz surface. 10. RDMO. C	Deted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: uddy Hill 6/17 2. Spot 30 sx. cmt ulate hole w/ 9.5# MLF. 4. Spot 3 Sqz. 175 sx. cmt. under pkr. @ 30 . 175 sx. cmt. 6/21 8. Tag TOC @	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion . 2/ 2% CaCl 3570', WOC & tag 0 sx. cmt. @ 1855'. 6/18/05 5. ' thru perfs @ 170', no tag on 47'. 9. Spot 15 sx. cmt. 47' to 1 dry hole marker, and clean
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. 6/13 1. Notify OCD B TOC @ 3400'. 3. Circ Tag TOC @ 1680'. 6. 6/20/05. 6/20 7. Sqz surface. 10. RDMO. C location. Approved as to plugging Liability under bond is	Deted operations. (Clearly state all pertinent details, jork). SEE RULE 1103. For Multiple Completions: uddy Hill 6/17 2. Spot 30 sx. cmt ulate hole w/ 9.5# MLF. 4. Spot 3 Sqz. 175 sx. cmt. under pkr. @ 30 . 175 sx. cmt. 6/21 8. Tag TOC @ ut off wellhead & anchors, instal	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion . 2/ 2% CaCl 3570', WOC & tag 0 sx. cmt. @ 1855'. 6/18/05 5. ' thru perfs @ 170', no tag on 47'. 9. Spot 15 sx. cmt. 47' to 1 dry hole marker, and clean
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. 6/13 1. Notify OCD B TOC @ 3400'. 3. Circ Tag TOC @ 1680'. 6. 6/20/05. 6/20 7. Sqz surface. 10. RDMO. C location.	Deted operations. (Clearly state all pertinent details, jork). SEE RULE 1103. For Multiple Completions: uddy Hill 6/17 2. Spot 30 sx. cmt ulate hole w/ 9.5# MLF. 4. Spot 3 Sqz. 175 sx. cmt. under pkr. @ 30 . 175 sx. cmt. 6/21 8. Tag TOC @ ut off wellhead & anchors, instal	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion . 2/ 2% CaCl 3570', WOC & tag 0 sx. cmt. @ 1855'. 6/18/05 5. ' thru perfs @ 170', no tag on 47'. 9. Spot 15 sx. cmt. 47' to 1 dry hole marker, and clean
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. 6/13 1. Notify OCD B TOC @ 3400'. 3. Circ Tag TOC @ 1680'. 6. 6/20/05. 6/20 7. Sqz surface. 10. RDMO. C location. Approved as to plugging Liability under bond is surface restoration is co I hereby certify that the information	DOTHER: Deted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: uddy Hill 6/17 2. Spot 30 sx. cmt ulate hole w/ 9.5# MLF. 4. Spot 3 Sqz. 175 sx. cmt. under pkr. @ 30 . 175 sx. cmt. 6/21 8. Tag TOC @ ut off wellhead & anchors, instal g of the Well Bore. retained until ompleted.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion . 2/ 2% CaCl 3570', WOC & tag 0 sx. cmt. @ 1855'. 6/18/05 5. ' thru perfs @ 170', no tag on 47'. 9. Spot 15 sx. cmt. 47' to 1 dry hole marker, and clean 134475
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. 6/13 1. Notify OCD B TOC @ 3400'. 3. Circ Tag TOC @ 1680'. 6. 6/20/05. 6/20 7. Sqz surface. 10. RDMO. C location. Approved as to plugging Liability under bond is surface restoration is co	Deted operations. (Clearly state all pertinent details, jork). SEE RULE 1103. For Multiple Completions: uddy Hill 6/17 2. Spot 30 sx. cmt ulate hole w/ 9.5# MLF. 4. Spot 3 Sqz. 175 sx. cmt. under pkr. @ 30 . 175 sx. cmt. 6/21 8. Tag TOC @ ut off wellhead & anchors, instal	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion . 2/ 2% CaCl 3570', WOC & tag 0 sx. cmt. @ 1855'. 6/18/05 5. ' thru perfs @ 170', no tag on 47'. 9. Spot 15 sx. cmt. 47' to 1 dry hole marker, and clean 1344 1575
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. 6/13 1. Notify OCD B TOC @ 3400'. 3. Circ Tag TOC @ 1680'. 6. 6/20/05. 6/20 7. Sqz surface. 10. RDMO. C location. Approved as to plugging Liability under bond is surface restoration is co I hereby certify that the information	Detect operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: uddy Hill 6/17 2. Spot 30 sx. cmt ulate hole w/ 9.5# MLF. 4. Spot 3 Sqz. 175 sx. cmt. under pkr. @ 30 . 175 sx. cmt. 6/21 8. Tag TOC @ ut off wellhead & anchors, instal g of the Well Bore. retained until ompleted.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion . 2/ 2% CaCl 3570', WOC & tag 0 sx. cmt. @ 1855'. 6/18/05 5. ' thru perfs @ 170', no tag on 47'. 9. Spot 15 sx. cmt. 47' to 1 dry hole marker, and clean 134475
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. 6/13 1. Notify OCD B TOC @ 3400'. 3. Circ Tag TOC @ 1680'. 6. 6/20/05. 6/20 7. Sqz surface. 10. RDMO. C location. Approved as to plugging Liability under bond is surface restoration is co I hereby certify that the information grade tank has been/will be constructed on	Deted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: uddy Hill 6/17 2. Spot 30 sx. cmt ulate hole w/ 9.5# MLF. 4. Spot 3 Sqz. 175 sx. cmt. under pkr. @ 30 . 175 sx. cmt. 6/21 8. Tag TOC @ ut off wellhead & anchors, instal g of the Well Bore. retained until ompleted.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion . 2/ 2% CaCl 3570', WOC & tag 0 sx. cmt. @ 1855'. 6/18/05 5. ' thru perfs @ 170', no tag on 47'. 9. Spot 15 sx. cmt. 47' to 1 dry hole marker, and clean
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. 6/13 1. Notify OCD B TOC @ 3400'. 3. Circ Tag TOC @ 1680'. 6. 6/20/05. 6/20 7. Sqz surface. 10. RDMO. C location. Approved as to plugging Liability under bond is surface restoration is co I hereby certify that the information grade tank has been/will be constructed on SIGNATURE Type or print name Roger Mas	Image: construction of the state and complete to the best of my knowled to the best of my knowled to the best of my knowled to the state and complete to the best of my knowled to the state and th	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion . 2/ 2% CaCl 3570', WOC & tag 0 sx. cmt. @ 1855'. 6/18/05 5. ' thru perfs @ 170', no tag on 47'. 9. Spot 15 sx. cmt. 47' to 1 dry hole marker, and clean

~