17 · •		o Oli Conservat 1625 N. Fren	ch Drivo					
	UNITED STAT PARTMENT OF THE UREAU OF LAND MAN	FORM APPROVED OMB No. 1004-0135 Expires November 30, 2000						
	5. Lease Serial No. LC- 0634580							
SUNDRY Do not use this abandoned well	6. If Indian, Allottee or Tribe Name							
SUBMIT IN TRIP	7. If Unit or CA/Agreement, Name and/or No.							
1. Type of Well Oil Well Gas Well X	8. Well Name and No. Warren Unit Blinebry Tubb WF #75							
2. Name of Operator ConocoPhillips Company	9. API Well No.							
3a. Address 4001 Penbrook Street Odess	co TV 70762	3b. Phone No. (in (505)391-3128		30-025-26312				
4. Location of Well (Footage, Sec., 7			•	10. Field and Pool, or Exploratory Area Warren Unit Blinebry Tubb				
1980' FSL 1980' FWL Sec. 34 - T20S - R38E - UL '				11. County or Parish, State Lea NM				
12. CHECK APPI	ROPRIATE BOX(ES)	TO INDICATE NA	TURE OF NOTICE	, REPORT, OR OTHER DATA				
TYPE OF SUBMISSION	SION TYPE OF ACTION							
Notice of Intent	Acidize	Deepen	Production (St	art/Resume) 🗌 Water Shut-Off				
-	Alter Casing	Fracture Treat	Reclamation	Well Integrity				
X Subsequent Report	Casing Repair Change Plans	New Construction	•	Mandon Leak				
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposa					
If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final At	nally or recomplete horizontall ork will be performed or provided of operations. If the operation re bandonment Notices shall be fit	y, give subsurface location de the Bond No. on file w esults in a multiple compl	ns measured and true vert ith BLM/BIA. Required s etion or recompletion in a	proposed work and approximate duration thereof. ical depths of all pertinent markers and zones. ubsequent reports shall be filed within 30 days new interval, a Form 3160-4 shall be filed once on, have been completed, and the operator has				
If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final At determined that the site is ready for f The above referenced well fi was replaced (see attached	nally or recomplete horizontally ork will be performed or provided doperations. If the operation re bandonment Notices shall be fif final inspection.) failed annual Bradenh repair summary). A N	y, give subsurface location de the Bond No. on file w esults in a multiple compli- iled only after all requiren nead test and was AIT was conducted	ns measured and true vert th BLM/BIA. Required s etion or recompletion in a ments, including reclamation found to have a pr	ical depths of all pertinent markers and zones. ubsequent reports shall be filed within 30 days new interval, a Form 3160-4 shall be filed once				
If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final At determined that the site is ready for the The above referenced well for	nally or recomplete horizontally ork will be performed or provided doperations. If the operation re bandonment Notices shall be fif final inspection.) failed annual Bradenh repair summary). A N	y, give subsurface location de the Bond No. on file w esults in a multiple compli- iled only after all requiren nead test and was AIT was conducted	ns measured and true vert th BLM/BIA. Required s etion or recompletion in a ments, including reclamation found to have a pr	ical depths of all pertinent markers and zones. ubsequent reports shall be filed within 30 days new interval, a Form 3160-4 shall be filed once on, have been completed, and the operator has oblem with the packer. The packer				
If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final At determined that the site is ready for f The above referenced well f was replaced (see attached attached chart) and was with	nally or recomplete horizontally ork will be performed or provided doperations. If the operation re bandonment Notices shall be fif final inspection.) failed annual Bradenh repair summary). A N	y, give subsurface location de the Bond No. on file w esults in a multiple compli- iled only after all requiren nead test and was AIT was conducted	ns measured and true vert th BLM/BIA. Required s etion or recompletion in a ments, including reclamation found to have a pr	ical depths of all pertinent markers and zones. ubsequent reports shall be filed within 30 days new interval, a Form 3160-4 shall be filed once on, have been completed, and the operator has oblem with the packer. The packer				
If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final At determined that the site is ready for f The above referenced well f was replaced (see attached attached chart) and was with	nally or recomplete horizontally ork will be performed or provided operations. If the operation r bandonment Notices shall be fi final inspection.) failed annual Bradenh repair summary). A N nessed by Buddy Hill	y, give subsurface location de the Bond No. on file w esults in a multiple compli- iled only after all requiren nead test and was AIT was conducted with the NMOCD.	ns measured and true vert th BLM/BIA. Required s etion or recompletion in a ments, including reclamation found to have a pr	ical depths of all pertinent markers and zones. ubsequent reports shall be filed within 30 days new interval, a Form 3160-4 shall be filed once on, have been completed, and the operator has oblem with the packer. The packer				
If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final At determined that the site is ready for f The above referenced well f was replaced (see attached attached chart) and was with Packer set at 5314' 4. I hereby certify that the foregoing is Name (<i>Printed/Typed</i>)	nally or recomplete horizontally ork will be performed or provided operations. If the operation r bandonment Notices shall be fi final inspection.) failed annual Bradenh repair summary). A N nessed by Buddy Hill	y, give subsurface location de the Bond No. on file w esults in a multiple compli- iled only after all requiren nead test and was AIT was conducted with the NMOCD. With the NMOCD.	ns measured and true vert th BLM/BIA. Required s etion or recompletion in a nents, including reclamatic found to have a pr t on 7-14-05 casin an 7-14-05 casin an 7-14-05 casin	ical depths of all pertinent markers and zones. ubsequent reports shall be filed within 30 days new interval, a Form 3160-4 shall be filed once on, have been completed, and the operator has oblem with the packer. The packer				
If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involver testing has been completed. Final At determined that the site is ready for f The above referenced well f was replaced (see attached attached chart) and was with Packer set at 5314' 4. I hereby certify that the foregoing is Name (<i>Printed/Typed</i>) John Abney	nally or recomplete horizontalit ork will be performed or provide d operations. If the operation r bandonment Notices shall be fit final inspection.) failed annual Bradenth repair summary). A N nessed by Buddy Hill true and correct	y, give subsurface location de the Bond No. on file w esults in a multiple compli- iled only after all requiren nead test and was AIT was conducted with the NMOCD. Title SHE Date 07/2	ns measured and true vert th BLM/BIA. Required s etion or recompletion in a nents, including reclamatic found to have a pr d on 7-14-05 casin an 7-14-05 casin an 7-14-05 casin b on 7-14-05 casin d on 7-14-05 casin	ical depths of all pertinent markers and zones. absequent reports shall be filed within 30 days new interval, a Form 3160-4 shall be filed once on, have been completed, and the operator has roblern with the packer. The packer g was tested at 500# for 30 min. (see				
If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final At determined that the site is ready for f The above referenced well f was replaced (see attached attached chart) and was with Packer set at 5314' 4. I hereby certify that the foregoing is Name (Printed/Typed) John Abney Signature ACCEPTEDFOF	nally or recomplete horizontall ork will be performed or provided operations. If the operation r bandonment Notices shall be fi final inspection.) failed annual Bradenh repair summary). A N nessed by Buddy Hill true and correct	y, give subsurface location de the Bond No. on file w esults in a multiple compli- iled only after all requiren nead test and was AIT was conducted with the NMOCD. Title SHE Date 07/2	ns measured and true vert th BLM/BIA. Required s etion or recompletion in a nents, including reclamatic found to have a pr t on 7-14-05 casin an 7-14-05 casin an 7-14-05 casin	ical depths of all pertinent markers and zones. absequent reports shall be filed within 30 days new interval, a Form 3160-4 shall be filed once on, have been completed, and the operator has roblern with the packer. The packer g was tested at 500# for 30 min. (see				
If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involver testing has been completed. Final At determined that the site is ready for f The above referenced well f was replaced (see attached attached chart) and was with Packer set at 5314' 4. I hereby certify that the foregoing is Name (<i>Printed/Typed</i>) John Abney	nally or recomplete horizontality or recomplete horizontality or recomplete horizontality of operations. If the operation rebandonment Notices shall be final inspection.) failed annual Bradenth repair summary). A Nonessed by Buddy Hill the seed by Budd	y, give subsurface location de the Bond No. on file w esults in a multiple compli- iled only after all requiren nead test and was AIT was conducted with the NMOCD. Title SHE Date 07/2 FOR FEDERAL OR	ns measured and true vert th BLM/BIA. Required s etion or recompletion in a nents, including reclamatic found to have a pr a on 7-14-05 casin a on 7-14-05 casin a casin b casin a casin b casin casin b casin b casin	ical depths of all pertinent markers and zones. absequent reports shall be filed within 30 days new interval, a Form 3160-4 shall be filed once on, have been completed, and the operator has roblern with the packer. The packer g was tested at 500# for 30 min. (see				

ConocoPhillips

Daily summary

WARREN UNIT 075

Job Type: REPAIR DOWNHOLE FAILURE

API/Bottom Hole UW 300252631200	1	Field Name WARREN	Area HOBBS	County LEA	State/Provinc		perato r		License No.	
Original KB Elevation	n (ft) Grou	nd Elevation (ft)	KB-CF (ft)	KB-TH (ft)		d Date	CONOCOPHILLIPS COMPANY BVILLE ACC			
· · · · · · · · · · · · · · · · · · ·	PL		J				•····•			
Start Date		<u></u>	La	ast 24hr Sum	i in the second			Day Total	Cum Cost	
7/5/2005 00:00	MIRU, H DID NO	leld Pre-Job Safet T have packer. Ta	y Meeting, Rig up k llied and PU works	ill truck, Install BOP, tring, RIH w/26 jts of v	POOH W/ 179 jts vorkstring and over	of tubing, ershot. Sl		4,434.87	4,434.8	
7/6/2005 00:00	Held Pre-Job Safety meeting, open well, PU RIH W/92 Jts of workstring and retrieving head to 2940', latch onto packer, POOH w/packer. PU Bit and Scraper, RIH to 5510', tagged scale, worked packer to 5520', POOH w/scraper, PU RIH with 5.5" Packer and RBP and 20 stands of pipe. SION						>	3,109.60	7,544.4	
7/7/2005 00:00	Held Pre-job safety meeting, bled off well, ran tubing, packer and plug, set plug at 5500', set packer at 5487', could not get test, leaked 100# in 10 minutes at several different settings up hole. Came out of hole with tubing, packer and plug. Ran different packer w/ seating nipple and plug, set at plug at 5500' and packer at 5487'. WOULD NOT TEST, leaked 100# in 10 minutes. Dropped standing valve in SN, tested tubing, Would Not Hold, leaked 160# in 10 minutes. SION						s.	4,341.06	11,885.5	
7/8/2005 07:00	Held Pre-Job safety meeting, Bled off well, 25#, installed enviro-vat. Pulled 12 stands out at a time pressure testing them, looking for hole. DID NOT FIND HOLE, Found trash in standing valve. RIH w/ pker. set at 2940', test to 550#, Leaked, ran pker down to 5487' (Plug @ 5500') Tested plug, Leaked. SION							3,909.76	15,795.2	
7/11/2005 00:00	Held Pre-Job safety meeting. Moved packer and plug up hole. Set plug at 5412' and set packer at 5372', Test backside, gained 15# in 5 min., Tested tubing and RBP, lost 60# in 15 min., Released pker and RBP, Set RBP @ 5507', set pker @ 5500', Tested backside, gained 65# in 20 min., tested tubing, lost 60 # in 20 min., released pressure. SION							4,020.14	19,815.43	
7/12/2005 00:00	Held Pre-Job Safety meeting, Tubing had 160#, casing had 120#. Bled well down, load casing w/7 bbls, pressured tested casing to 555#, load tubing pressure tested tubing to 530#. tested for 20 mins., casing held pressure of 555#, tubing bled off to 500#. Released pker and plug, POOH w/ pker and plug laying down 2 3/8" workstring., RIH w/ AD1 tension packer, 2 3/8" IPC Seating Nipple and 179 its of 2 3/8" IPC J-55 tubing, set pker @ 5514' load csg. w/ 60 bbls of water, test backside to 520# for 20 mins., csg held. bled of pressure. SION						for H	6,017.48	25,832.91	
7/13/2005 00:00	LEAK. re	elease pker ND BC	OP, NU Well head,	10 bbls of wtr. test cs Pumped 50 bbls of pa 0# for 30 min. RDMO	acker fluid. ND we	nin. DID N II head se	IOT et	5,676.82	31,509.73	

