	State of New Mexico	Form C-103
Office District I	Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION	30-025-26142
District III	1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	STATE FEE S
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Salita Fe, INIVI 67303	6. State Oil & Gas Lease No.
87505		
	CES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
PROPOSALS.)	CATION FOR PERMIT" (FORM C-101) FOR SUCH	Joy 17
· · · · · · · · · · · · · · · · · · ·	Gas Well Other	8. Well Number 1
2. Name of Operator	Gus Weit Guici	9. OGRID Number
•	roleum, Inc.	24173
3. Address of Operator		10. Pool name or Wildcat
-	1 Luling, TX 78648	Wildcat Wolfcamp
4. Well Location	<i>J</i> ,	
	1000 for the North Control of	CCO COLL Free Har
	1980feet from theNorth line and	
Section 17	Township 14S Range 36E	NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
Pit or Below-grade Tank Application o	3954' GR	
Pit typesteelDepth to Groundwat	erDistance from nearest fresh water wellD	stance from nearest surface water
Pit Liner Thickness: mil	Below-Grade Tank: Volume bbls;	Construction Material
12. Check A	appropriate Box to Indicate Nature of Notic	e. Report or Other Data
		o, respect of a mar z mm
NOTICE OF IN	TENTION TO: SU	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WO	ORK ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS COMMENCE D	PRILLING OPNS. P AND A
PULL OR ALTER CASING	MULTIPLE COMPL CASING/CEME	ENT JOB
	_	
OTHER:	OTHER:	
12 D 1		
	eted operations. (Clearly state all pertinent details,	
of starting any proposed wo	leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions:	
of starting any proposed we or recompletion.		
of starting any proposed we or recompletion. 7/07/05 1. Notified NMOCD.	rk). SEE RULE 1103. For Multiple Completions:	
of starting any proposed we or recompletion. 7/07/05 1. Notified NMOCD. 7/11/05 2. Set CIbP @ 9984' as per 1	rk). SEE RULE 1103. For Multiple Completions: NMOCD Billy P.	Attach wellbore diagram of proposed completion
of starting any proposed we or recompletion. 7/07/05 1. Notified NMOCD. 7/11/05 2. Set CIbP @ 9984' as per 17/12/05 3. Circulate hole w/ 9.5 MLI	rk). SEE RULE 1103. For Multiple Completions: NMOCD Billy P. F. 4. Spot 30 sx. cmt. 9984' – 9681'. 5. Spot 25 sx. c	Attach wellbore diagram of proposed completion
of starting any proposed we or recompletion. 7/07/05 1. Notified NMOCD. 7/11/05 2. Set CIbP @ 9984' as per 17/12/05 3. Circulate hole w/ 9.5 MLI 7283'. 7. Spot 85 sx. cmt	rk). SEE RULE 1103. For Multiple Completions: NMOCD Billy P. F. 4. Spot 30 sx. cmt. 9984' – 9681'. 5. Spot 25 sx. c @ 4690'.	Attach wellbore diagram of proposed completion mt. 8620' – 8368' 6 Spot 25 sx. cmt. 7535' -
of starting any proposed we or recompletion. 7/07/05 1. Notified NMOCD. 7/11/05 2. Set CIbP @ 9984' as per 17/12/05 3. Circulate hole w/ 9.5 MLI 7283'. 7. Spot 85 sx. cmt 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'.	rk). SEE RULE 1103. For Multiple Completions: NMOCD Billy P. F. 4. Spot 30 sx. cmt. 9984' – 9681'. 5. Spot 25 sx. c @ 4690'. ot 40 sx. cmt. @ 2154' – 2007'. 10. Spot 40 sx. cmt.	mt. 8620' – 8368' 6. Spot 25 sx. cmt. 7535' - 2/2% CaCl @ 421', WQC & tag FQC @
of starting any proposed we or recompletion. 7/07/05 1. Notified NMOCD. 7/11/05 2. Set CIbP @ 9984' as per 17/12/05 3. Circulate hole w/ 9.5 MLI 7283'. 7. Spot 85 sx. cmt 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. Complete the second starting of the second starting star	rk). SEE RULE 1103. For Multiple Completions: NMOCD Billy P. F. 4. Spot 30 sx. cmt. 9984' – 9681'. 5. Spot 25 sx. c @ 4690'.	mt. 8620' – 8368' 6. Spot 25-sx. cmt. 7535' - 2/2% CaCl @ 421', WQC & tag TQC @
of starting any proposed we or recompletion. 7/07/05 1. Notified NMOCD. 7/11/05 2. Set CIbP @ 9984' as per 17/12/05 3. Circulate hole w/ 9.5 MLI 7283'. 7. Spot 85 sx. cmt 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'.	rk). SEE RULE 1103. For Multiple Completions: NMOCD Billy P. F. 4. Spot 30 sx. cmt. 9984' – 9681'. 5. Spot 25 sx. c @ 4690'. ot 40 sx. cmt. @ 2154' – 2007'. 10. Spot 40 sx. cmt.	mt. 8620' – 8368' 6. Spot 25 sx. cmt. 7535' - 2/2% CaCl @ 421', WQC & tag FQC @
of starting any proposed we or recompletion. 7/07/05 1. Notified NMOCD. 7/11/05 2. Set CIbP @ 9984' as per 17/12/05 3. Circulate hole w/ 9.5 MLI 7283'. 7. Spot 85 sx. cmt 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'.	rk). SEE RULE 1103. For Multiple Completions: NMOCD Billy P. F. 4. Spot 30 sx. cmt. 9984' – 9681'. 5. Spot 25 sx. c @ 4690'. ot 40 sx. cmt. @ 2154' – 2007'. 10. Spot 40 sx. cmt.	Attach wellbore diagram of proposed completion mt. 8620' – 8368' 6 Spot 25 sx. cmt. 7535' - 2/ 2% CaCl @ 421', WQC & tag TQC @
of starting any proposed we or recompletion. 7/07/05 1. Notified NMOCD. 7/11/05 2. Set CIbP @ 9984' as per 17/12/05 3. Circulate hole w/ 9.5 MLI 7283'. 7. Spot 85 sx. cmt 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. Complete the second starting of the second starting star	NMOCD Billy P. 7. 4. Spot 30 sx. cmt. 9984' – 9681'. 5. Spot 25 sx. c @ 4690'. 10t 40 sx. cmt. @ 2154' – 2007'. 10. Spot 40 sx. cmt. 30' – surface. 15. RDMO. Cut off wellhead & anch	mt. 8620' – 8368' 6. Spot 25-sx. cmt. 7535' - 2/2% CaCl @ 421', WQC & tag TQC @
of starting any proposed we or recompletion. 7/07/05 1. Notified NMOCD. 7/11/05 2. Set CIbP @ 9984' as per 17/12/05 3. Circulate hole w/ 9.5 MLI 7283'. 7. Spot 85 sx. cmt 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'.	NMOCD Billy P. F. 4. Spot 30 sx. cmt. 9984' – 9681'. 5. Spot 25 sx. c @ 4690'. ot 40 sx. cmt. @ 2154' – 2007'. 10. Spot 40 sx. cmt. 30' – surface. 15. RDMO. Cut off wellhead & anch	Attach wellbore diagram of proposed completion mt. 8620' – 8368' 6 Spot 25 sx. cmt. 7535' - 2/ 2% CaCl @ 421', WQC & tag TQC @
of starting any proposed we or recompletion. 7/07/05 1. Notified NMOCD. 7/11/05 2. Set CIbP @ 9984' as per 17/12/05 3. Circulate hole w/ 9.5 MLI 7283'. 7. Spot 85 sx. cmt 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. CMLI 7/13/05 8. Tag TOC @ 3948'.	NMOCD Billy P. F. 4. Spot 30 sx. cmt. 9984' – 9681'. 5. Spot 25 sx. c @ 4690'. ot 40 sx. cmt. @ 2154' – 2007'. 10. Spot 40 sx. cmt. 30' – surface. 15. RDMO. Cut off wellhead & anch Approved as to plugging of the Well Bore. Liability under bond is retained until	mt. 8620' – 8368' 6. Spot 25 sx. cmt. 7535' - 2/2% CaCl @ 421', WQC & tag FQC @
of starting any proposed we or recompletion. 7/07/05 1. Notified NMOCD. 7/11/05 2. Set CIbP @ 9984' as per 17/12/05 3. Circulate hole w/ 9.5 MLI 7283'. 7. Spot 85 sx. cmt 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. Complete the second starting of the second starting star	NMOCD Billy P. F. 4. Spot 30 sx. cmt. 9984' – 9681'. 5. Spot 25 sx. c @ 4690'. ot 40 sx. cmt. @ 2154' – 2007'. 10. Spot 40 sx. cmt. 30' – surface. 15. RDMO. Cut off wellhead & anch	mt. 8620' – 8368' 6. Spot 25-sx. cmt. 7535' - 2/2% CaCl @ 421', WQC & tag TQC @
of starting any proposed we or recompletion. 7/07/05 1. Notified NMOCD. 7/11/05 2. Set CIbP @ 9984' as per 17/12/05 3. Circulate hole w/ 9.5 MLI 7283'. 7. Spot 85 sx. cmt 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. Complete the second starting of the second starting star	NMOCD Billy P. F. 4. Spot 30 sx. cmt. 9984' – 9681'. 5. Spot 25 sx. c @ 4690'. ot 40 sx. cmt. @ 2154' – 2007'. 10. Spot 40 sx. cmt. 30' – surface. 15. RDMO. Cut off wellhead & anch Approved as to plugging of the Well Bore. Liability under bond is retained until	mt. 8620' – 8368' 6. Spot 25-sx. cmt. 7535' - 2/2% CaCl @ 421', WQC & tag TQC @
of starting any proposed we or recompletion. 7/07/05 1. Notified NMOCD. 7/11/05 2. Set CIbP @ 9984' as per 17/12/05 3. Circulate hole w/ 9.5 MLI 7283'. 7. Spot 85 sx. cmt 7/13/05 8. Tag TOC @ 3948'. 9. Spot 85 sx. Complete the second starting of the second starting star	NMOCD Billy P. F. 4. Spot 30 sx. cmt. 9984' – 9681'. 5. Spot 25 sx. c @ 4690'. ot 40 sx. cmt. @ 2154' – 2007'. 10. Spot 40 sx. cmt. 30' – surface. 15. RDMO. Cut off wellhead & anch Approved as to plugging of the Well Bore. Liability under bond is retained until	mt. 8620' – 8368' 6. Spot 25-sx. cmt. 7535' - 2/2% CaCl @ 421', WQC & tag TQC @
of starting any proposed we or recompletion. 7/07/05 1. Notified NMOCD. 7/11/05 2. Set CIbP @ 9984' as per 7/12/05 3. Circulate hole w/ 9.5 MLI 7283'. 7. Spot 85 sx. cmt 7/13/05 8. Tag TOC @ 3948'. 9. Spot 275'. 11. Circ. 10 sx. cmt.	NMOCD Billy P. F. 4. Spot 30 sx. cmt. 9984' – 9681'. 5. Spot 25 sx. c. (2) 4690'. Ot 40 sx. cmt. (2) 2154' – 2007'. 10. Spot 40 sx. cmt. 30' – surface. 15. RDMO. Cut off wellhead & anch. Approved as to plugging of the Well Bore. Liability under bond is retained until surface restoration is completed.	mt. 8620' – 8368' 6. Spot 25-sx. cmt. 7535' - 2/ 2% CaCl @ 421', WOC & tag FQC @ ors, install dry hole marker, and clean location.
of starting any proposed we or recompletion. 7/07/05 1. Notified NMOCD. 7/11/05 2. Set CIbP @ 9984' as per 7/12/05 3. Circulate hole w/ 9.5 MLI 7283'. 7. Spot 85 sx. cmt 7/13/05 8. Tag TOC @ 3948'. 9. Spot 275'. 11. Circ. 10 sx. cmt.	NMOCD Billy P. F. 4. Spot 30 sx. cmt. 9984' – 9681'. 5. Spot 25 sx. c. (2) 4690'. Ot 40 sx. cmt. (2) 2154' – 2007'. 10. Spot 40 sx. cmt. 30' – surface. 15. RDMO. Cut off wellhead & anch. Approved as to plugging of the Well Bore. Liability under bond is retained until surface restoration is completed.	Attach wellbore diagram of proposed completion mt. 8620' – 8368' 6 Spot 25-sx. cmt. 7535' - 2/ 2% CaCl @ 421', WOC & tag TOC @ ors, install dry hole marker, and clean location.
of starting any proposed we or recompletion. 7/07/05 1. Notified NMOCD. 7/11/05 2. Set CIbP @ 9984' as per 7/12/05 3. Circulate hole w/ 9.5 MLI 7283'. 7. Spot 85 sx. cmt 7/13/05 8. Tag TOC @ 3948'. 9. Spot 275'. 11. Circ. 10 sx. cmt.	NMOCD Billy P. F. 4. Spot 30 sx. cmt. 9984' – 9681'. 5. Spot 25 sx. c. (2) 4690'. Ot 40 sx. cmt. (2) 2154' – 2007'. 10. Spot 40 sx. cmt. 30' – surface. 15. RDMO. Cut off wellhead & anch. Approved as to plugging of the Well Bore. Liability under bond is retained until surface restoration is completed.	Attach wellbore diagram of proposed completion mt. 8620' – 8368' 6. Spot 25-sx. cmt. 7535' - 2/ 2% CaCl @ 421', WOC & tag FQC @ ors, install dry hole marker, and clean location.
of starting any proposed we or recompletion. 7/07/05 1. Notified NMOCD. 7/11/05 2. Set CIbP @ 9984' as per 7/12/05 3. Circulate hole w/ 9.5 MLI 7283'. 7. Spot 85 sx. cmt 7/13/05 8. Tag TOC @ 3948'. 9. Spot 275'. 11. Circ. 10 sx. cmt.	NMOCD Billy P. 7. 4. Spot 30 sx. cmt. 9984' – 9681'. 5. Spot 25 sx. c @ 4690'. 10t 40 sx. cmt. @ 2154' – 2007'. 10. Spot 40 sx. cmt. 30' – surface. 15. RDMO. Cut off wellhead & anch Approved as to plugging of the Well Bore. Liability under bond is retained until surface restoration is completed.	Attach wellbore diagram of proposed completion mt. 8620' - 8368' 6 Spot 25 sx. cmt. 7535' - 2/ 2% CaCl @ 421', WOC & tag TOC @ ors, install dry hole marker, and clean location.
of starting any proposed we or recompletion. 7/07/05 1. Notified NMOCD. 7/11/05 2. Set CIbP @ 9984' as per 7/12/05 3. Circulate hole w/ 9.5 MLI 7283'. 7. Spot 85 sx. cmt 7/13/05 8. Tag TOC @ 3948'. 9. Spot 275'. 11. Circ. 10 sx. cmt.	NMOCD Billy P. F. 4. Spot 30 sx. cmt. 9984' – 9681'. 5. Spot 25 sx. c. (2) 4690'. Ot 40 sx. cmt. (2) 2154' – 2007'. 10. Spot 40 sx. cmt. 30' – surface. 15. RDMO. Cut off wellhead & anch. Approved as to plugging of the Well Bore. Liability under bond is retained until surface restoration is completed.	Attach wellbore diagram of proposed completion mt. 8620' – 8368' 6. Spot 25-sx. cmt. 7535' - 2/ 2% CaCl @ 421', WOC & tag FQC @ ors, install dry hole marker, and clean location.
of starting any proposed we or recompletion. 7/07/05 1. Notified NMOCD. 7/11/05 2. Set CIbP @ 9984' as per 17/12/05 3. Circulate hole w/ 9.5 MLI 7283'. 7. Spot 85 sx. cmt 7/13/05 8. Tag TOC @ 3948'. 9. Spot 275'. 11. Circ. 10 sx. cmt. I hereby certify that the information grade tank has been/will be constructed or SIGNATURE	NMOCD Billy P. 7. 4. Spot 30 sx. cmt. 9984' – 9681'. 5. Spot 25 sx. c @ 4690'. 10t 40 sx. cmt. @ 2154' – 2007'. 10. Spot 40 sx. cmt. 30' – surface. 15. RDMO. Cut off wellhead & anch Approved as to plugging of the Well Bore. Liability under bond is retained until surface restoration is completed. above is true and complete to the best of my knowled closed according to NMOCD guidelines , a general permit	Attach wellbore diagram of proposed completion mt. 8620' - 8368' 6 Spot 25 sx. cmt. 7535' - 2/ 2% CaCl @ 421', WOC & tag TOC @ ors, install dry hole marker, and clean location. dge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan . DATE
of starting any proposed we or recompletion. 7/07/05 1. Notified NMOCD. 7/11/05 2. Set CIbP @ 9984' as per 17/12/05 3. Circulate hole w/ 9.5 MLI 7283'. 7. Spot 85 sx. cmt 7/13/05 8. Tag TOC @ 3948'. 9. Spot 275'. 11. Circ. 10 sx. cmt. I hereby certify that the information grade tank has been/will be constructed or SIGNATURE	NMOCD Billy P. 7. 4. Spot 30 sx. cmt. 9984' – 9681'. 5. Spot 25 sx. c @ 4690'. 10t 40 sx. cmt. @ 2154' – 2007'. 10. Spot 40 sx. cmt. 30' – surface. 15. RDMO. Cut off wellhead & anch Approved as to plugging of the Well Bore. Liability under bond is retained until surface restoration is completed. Above is true and complete to the best of my knowled closed according to NMOCD guidelines , a general permit TITLE Agent E-mail address:	Attach wellbore diagram of proposed completion mt. 8620' - 8368' 6. Spot 25 sx. cmt. 7535' - 2/ 2% CaCl @ 421', WOC & tag TOC @ ors, install dry hole marker, and clean location. dge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan . DATE 7/19/05 Telephone No. 432-530-0907
of starting any proposed we or recompletion. 7/07/05 1. Notified NMOCD. 7/11/05 2. Set CIbP @ 9984' as per 17/12/05 3. Circulate hole w/ 9.5 MLI 7283'. 7. Spot 85 sx. cmt 7/13/05 8. Tag TOC @ 3948'. 9. Spot 275'. 11. Circ. 10 sx. cmt. I hereby certify that the information grade tank has been/will be constructed or SIGNATURE	NMOCD Billy P. 3. 4. Spot 30 sx. cmt. 9984' – 9681'. 5. Spot 25 sx. c. (2) 4690'. 30' – surface. 15. RDMO. Cut off wellhead & anch Approved as to plugging of the Well Bore. Liability under bond is retained until surface restoration is completed. Above is true and complete to the best of my knowled according to NMOCD guidelines , a general permit TITLE Agent E-mail address: E-mail address:	Attach wellbore diagram of proposed completion mt. 8620' – 8368' 6 Spot 25 sx. cmt. 7535' - 2/ 2% CaCl @ 421', WOC & tag TOC @ ors, install dry hole marker, and clean location. dge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan . DATE
of starting any proposed we or recompletion. 7/07/05 1. Notified NMOCD. 7/11/05 2. Set CIbP @ 9984' as per 17/12/05 3. Circulate hole w/ 9.5 MLI 7283'. 7. Spot 85 sx. cmt 7/13/05 8. Tag TOC @ 3948'. 9. Spot 275'. 11. Circ. 10 sx. cmt. I hereby certify that the information grade tank has been/will be constructed or SIGNATURE	NMOCD Billy P. 3. 4. Spot 30 sx. cmt. 9984' – 9681'. 5. Spot 25 sx. c. (2) 4690'. 30' – surface. 15. RDMO. Cut off wellhead & anch Approved as to plugging of the Well Bore. Liability under bond is retained until surface restoration is completed. Above is true and complete to the best of my knowled according to NMOCD guidelines , a general permit TITLE Agent E-mail address: E-mail address:	Attach wellbore diagram of proposed completion mt. 8620' – 8368' 6 Spot 25 sx. cmt. 7535' - 2/ 2% CaCl @ 421', WOC & tag TOC @ ors, install dry hole marker, and clean location. dge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan . DATE
of starting any proposed we or recompletion. 7/07/05 1. Notified NMOCD. 7/11/05 2. Set CIbP @ 9984' as per 7/12/05 3. Circulate hole w/ 9.5 MLI 7283'. 7. Spot 85 sx. cmt 7/13/05 8. Tag TOC @ 3948'. 9. Spot 275'. 11. Circ. 10 sx. cmt. I hereby certify that the information grade tank has been/will be constructed or SIGNATURE Type or print name Roger Massey For State Use Only	NMOCD Billy P. 3. 4. Spot 30 sx. cmt. 9984' – 9681'. 5. Spot 25 sx. c. (2) 4690'. 30' – surface. 15. RDMO. Cut off wellhead & anch Approved as to plugging of the Well Bore. Liability under bond is retained until surface restoration is completed. Above is true and complete to the best of my knowled according to NMOCD guidelines , a general permit TITLE Agent E-mail address: E-mail address:	Attach wellbore diagram of proposed completion mt. 8620' - 8368' 6. Spot 25 sx. cmt. 7535' - 2/ 2% CaCl @ 421', WOC & tag TOC @ ors, install dry hole marker, and clean location. dge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan . DATE 7/19/05 Telephone No. 432-530-0907