

New Mexico Oil Conservation Division, District I

1625 N. French Drive

Albuquerque, NM 87133

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 2160-2 (APN) for such proposals.

FORM APPROVED
OILD No. 1001-0135
Expires November 30, 2000

5. Lease Serial No.

NMMN 01917

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

Gulf Homan Fed #1

9. API Well No.

3002508144

10. Field and Pool or Exploratory Area

DOUBLE X Delaware

11. County or Parish, State

Lea, NM

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

MARKS and GARNER

3. Address

P.O. Box 1089 Hobbs NM 565-393-9358

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

660FSL 8 660 FEL

SCSE 18-248-32E

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Abandon

☐ Alter Casing

☐ Casing Repair

☐ Change Frame

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ Plug Completion

☒ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recombine

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☐ Other

13. To be completed by the owner of the well. State all pertinent details, including estimated starting date of any proposed work and approximate amount thereof. If the work is to be done by a contractor, include name of contractor, address, and telephone number. Attach the report under which the work will be performed, if applicable. If the work is to be done by the owner, attach the report under which the work will be performed, if applicable. If the work is to be done by a contractor, attach the report under which the work will be performed, if applicable. If the work is to be done by the owner, attach the report under which the work will be performed, if applicable.

Set CIBP @ 4950 with 25' cement on top of Plug

Set 100' cement @ 2400'

Set 50' Plug @ Surface

Cut & Pull 4 1/2 casing @ 2000'

Install Dry hole marker, clean location.

Set 50' in & out of 4 1/2 casing stub

Set 100' @ Base of Salt

Set 50' in & out of 8 7/8 shoe @ 323'

CRUINION WELBOAR APPROVED CONTROLLER

7-28-05

AUG 1 2005

**GARY GOURLEY
PETROLEUM ENGINEER**

APPROVED FOR 3 MONTH PERIOD

ENDING 11-1-05

GWW