State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION 310 Old Santa Fe Trail, Room 206

WELL API NO. 30-025-24714-00-00

5.	Indicate Type of Lease STATE X	FEE
6.	State Oil & Gas Lease No.	

DISTRICT II	Conta Es Nous M	Santa Fe New Marion 97503			
P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico 87503		5. Indicate Type of Lease STATE X FEE		
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410			6 8 0		res
TOO RIG BIRDS RE, AMEL 1919 87410	6. State Oil & Gas Lease No. B-1167				
SUNDRY NOTICE	7. Lease Name or Utut Agreement Name State JJ				
(DO NOT USE THIS FORM FOR PROPOS DIFFERENT RESERVOI					
(FORM C-101)					
1. Type of Well:			 •		
OI. X WELL	OTHER				
Name of Operator John H. Hendrix Corporation			8. Well No.	4	
3. Address of Operator	2702 2040		: 9. Pool nam		
PO Box 3040; Midland, Texas 79	3/02-3040		Langlie	Mattix	
4. Well Location Unit Letter P 330	Courth	000		 .	
Unit Letter : 330	Feet From The South	Line and 860	Fee:	From The East	Lin
Section 13	Township 23S	Range 36E	NMPM	Lea	5
	TOWERD	ether DF, RKB, RT, GR, etc.)	NMPM	7////////	County
	/// <u>}</u>				
11. Check App	ropriate Box to Indica	te Nature of Notice. I	Report, or C	ther Data	
NOTICE OF INTEN				T REPORT OF	
	· _	=		—.	
PERFORM REMEDIAL WORK	PLUG AND ABANDON X	REMEDIAL WORK	,	ALTERING CAS	ING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLIN	G OPNS.	PLUG AND ABA	NDONMENT
PULL OR ALTER CASING		CASING TEST AND C	BOLTNAMA		
OTHER:		OTHER:			
12. Describe Proposed or Completed Operations	(Clearly state all pertinent deta	ills, and give pertinent dates, in	cluding estimated	date of starting any pro	posed
work) SEE RULE 1103.			/	6678910777	
 Rig up P&A equipment. Set CIBP at 3400^t. 	Dig and line work pit.	NU BOP.	\(\sigma_{\gamma_{0}}^{\gamma_{0}}\)	6 1 8 9 10 17 7 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	`. }
3. Circulate hole w/ 9.5# m	and .				
			\ _	APR 2003	
4. Cap CIBP w/ 20 sx. cem			3031	RLOLIVED	
5. Spot 20 sx cement from		5 5	/ ଲ	Hobbs ·	
6. Perforate at 2600'. Sque			, , , , , , ,	•	
7. Perforate at 1300'. Squ				t). Tag	
8. Perforate at 408'. Sque	eze w/ 100 sx. cement.	Displace TOC to 308	'. Tag	- 10 NOVA	
9. Cut off wellhead. Spot 1	0 sx. surface plug.	THECOMM	CCIONITALICA	DE MOTIEIER 24	
10. Install P&A marker	-			BE NOTIFIED 24 BEGINNING OF	
		PLUCCING		DECHINATING OF	

PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.							
SIGNATURE MOC	1/2	TITLE Agent	DATE 04/08/03				
TYPE OR PRINT NAME H. Boatright			IONE NO.				
**************************************			***				

OC FIELD REPRESENTATIVE II/STAFF MANAGER

APR 1 0 2003


DATE -

WELL NAME AND NUMBER

State JJ #4

John J Hendrix Corporation Lea County, New Mexico

State Lease # B-1167
WELLBORE CONFIGURATION



WELL NAME AND NUMBER

State JJ #4

John J Hendrix Corporation Lea County, New Mexico

AFTER PLUGGING

State Lease # B-1167

WELLBORE CONFIGURATION

