

Submit 3 Copies To Appropriate District
Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

March 4, 2004

WELL API NO.

30-025-30163

5. Indicate Type of Lease

STATE ☒ FEE ☒

6. State Oil & Gas Lease No.

LH 1840

7. Lease Name or Unit Agreement Name

Corbin State

8. Well Number

1

9. OGRID Number

10. Pool name or Wildcat

West Corbin (Delaware)

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

EOG Resources, Inc

3. Address of Operator

P.O. Box 2267, Midland, TX, 79702

4. Well Location

Unit Letter F : 1980 feet from the North line and 1980 feet from the West line

Section 16 Township 18-S Range 33-E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3887 GL

Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)

Pit Location: UL F Sect 16 Twp 18S Rng 35E Pit type Steel Depth to Groundwater 100 Distance from nearest fresh water well Over 1000

Distance from nearest surface water 1980 feet from the North line and 1980 feet from the West line (Steel Tank)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Set 5 1/2 CIBP @ 6510', cap W/25sx Class C CMT WOC Tag @ 6277.
2. Pick up tubing to +/- 4260 Spot 30sx cmt plug.
3. Pick up tubing to +/- 3050 Spot 30sx cmt plug. Tag @ 2792 CSG Shoe @ 3000.
4. Pick up tubing to +/- 1690 Spot 25sx cmt plug.
5. Pick up tubing to +/- 405 Spot 40sx cmt plug to surface.
6. Cut casing 3' below surface, weld plate and abandonment marker to casing. Clean location and restore location. P&A Complete 8-24-05

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE

TITLE

Consultant

DATE 8-24-05

Type or print name

Jimmy Bagley

E-mail address:

Telephone No. 432-561-8600

(This space for State use)

APPROVED BY

TITLE

DATE

Conditions of approval, if any

SEP 07 2005
OC FIELD REPRESENTATIVE II/STAFF MANAGER