

• Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised May 08, 2003

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-10366
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-934
7. Lease Name or Unit Agreement Name New Mexico M State
8. Well Number 32
9. OGRID Number
10. Pool name or Wildcat Lang-Mat 7R, Qn, Gr

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☒ Other

2. Name of Operator
GP II Energy Inc

3. Address of Operator
P.O. Box 50682, Midland TX 79710

4. Well Location
Unit Letter M : 660 feet from the south line and 660 feet from the west line
Section 19 Township 22S Range 37E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
GL 3424


12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
MULTIPLE COMPLETION <input type="checkbox"/>	OTHER: <input type="checkbox"/>
OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

See enclosed proposed procedure and well bore diagram

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Joe L. Compton TITLE Agent DATE 5-23-03


Type or print name Joe L. Compton Telephone No. 432-684-4748
(This space for State use)

APPROVED BY Larry W. Wink TITLE OC FIELD REPRESENTATIVE II / STAFF MANAGER DATE MAY 28 2003
Conditions of approval, if any:


GP II ENERGY, INC.
 NEW MEXICO "M" STATE #32
 660' FWL & 660' FSL
 SEC 19, T22S, R37E
 LEA COUNTY, NEW MEXICO
 T.D. 3863'

STATE LEASE #: B-934
 WELL TYPE: WIW
 SPUD DATE: FEB. 17, 1961
 COMP. DATE: FEB 27, 1961
 GL ELEVATION: 3424'
 DF ELEVATION: 3432'

CURRENT
 ELEVATION 3424'



PROPOSED
 ELEVATION 3424'



Squeeze and Plugging Procedures for the New Mexico "M" State #32

1. RUPU.
2. Install and test BOP.
3. Load hole. Pressure up backside to 500# for 15' to check tubing - casing integrity. TOH with Packer and inspect.
4. GIH with tbg and packer to establish where the casing leak(s) is(are) located. Casing leaks are common in this area from 300' to 700'. Determine where leaks are located.
5. If there are no casing leaks circulate hole with inhibited packer fluid. POH with tubing and packer for TA. GIH with wireline set CIBP within 50' of top perforations ~3700'. GIH with bailer and dump 35' cement on CIBP and fill hole with inhibited KCl water. Set a tubing sub with a valve and bull plug at the surface.
6. If leaks are found, determine location of leaks and POH with tubing and packer.
7. GIH with wire line CIBP and set at approximately 3700'. GIH with bailer and dump 35' cement on CIBP.
8. GIH with perforating gun and perforate casing at base of salt section (2670'). GIH with tubing and pump 50' in and 50' out. WOC and tag plug. Perforate and pump plug at casing leaks. If holes are near the base or top of the salt, pump enough cement to cover both with one plug. Perforate casing at 1260' and pump 50' in 50' out. WOC and tag plug.
9. PU and pump 100'+ cement plug across 7" shoe, sufficient to bring plug 50'+ above top of shoe and 50'+ below 7" casing shoe. PU and WOC.
10. Tag plug set across 7" shoe. PU and set surface plug.
11. Cut off casing and set dry hole marker.
12. Clean and remeditate location.

Note: The NMOCD will be notified at least 24 hours before starting work on well.