Office	s To Appropriate District	State	of New Me	exico		Form C-1	
District I	D- 17-11- >D ( 070.40	Energy, Miner	als and Nati	ural Resources	Г <del>иш </del>	Revised March 25, 1	
District II	Dr., Hobbs, NM 87240			· 	WELL API NO.		
	811 South First, Artesia, NM 87210 OIL CONSERVATION DIVISION District III 2040 South Poshoop					30-025-20123 5. Indicate Type of Lease	
1000 Rio Brazo	1000 Rio Brazos Rd., Aztec, NM 87410					STATE X FEE	
District IV 2040 South Page	checo, Santa Fe, NM 87505	Santa	re, NM 8	/505	6. State Oil & (		
		ICES AND REPORTS	ONINE			5014	
(DO NOT USE DIFFERENT R PROPOSALS.) 1. Type of '	THIS FORM FOR PROPO ESERVOIR. USE "APPLI 	OSALS TO DRILL OR TO E ICATION FOR PERMIT* (F	DEEPEN OR PL	UG BACK TO A	7. Lease Name o	r Unit Agreement Nam	
Oil Well		Other Wate	er Inject	ion	Mes	a Queen	
2. Name o	f Operator Xer	ic Oil & Gas Co	orporatio	on	8. Well No.		
3. Address		O. Box 352			9. Pool name or	14 Wildcat	
4 377 11 7	Mid	lland, TX 7970				en Associated	
4. Well Lo	cation	•					
Uni	t Letter L :	2310 feet from t	he South	line and	feet fro	m the West li	
Can	tion 16		166 5				
Sec	HOIL TO	10. Elevation (Sho	16S Ra		NMPM Lea	County	
			4259	) DF			
	11. Check A	Appropriate Box to	Indicate N				
PERFORM F	NOTICE OF IN	NIENTION TO: ] PLUG AND ABAND	ON [V]	SUE REMEDIAL WOR	SEQUENT RE		
					<u> </u>	ALTERING CASING	
TEMPORAR	ILY ABANDON	CHANGE PLANS	. 🗀	COMMENCE DR	ILLING OPNS.	PLUG AND ABANDONMENT	
PULL OR AL	TER CASING	MULTIPLE COMPLETION		CASING TEST A CEMENT JOB	ND	ADAMOUNICH	
OTHER:	•			OTHER:			
of starti	e proposed or completing any proposed work in proposed or complete in proposed work in prop	ted operations. (Clearly). SEE RULE 1103. F	y state all per or Multiple C	tinent details, and Completions: Attac	give pertinent dates, ch wellbore diagram	including estimated da of proposed completio	
		I init					
1)	MIRU Pulling	Om.		•			
1) 2)		g @ 3300' & tag.		•	٠.,	202122232420	
•	Spot 25 sx plug Spot 25 sx plug	g @ 3300' & tag. g @ 1300' & tag.			/	302021222324252	
2) 3) 4)	Spot 25 sx plug Spot 25 sx plug Cut casing @ 6	g @ 3300' & tag. g @ 1300' & tag. 600' & lay down.				192021222324253	
2) 3) 4) 5)	Spot 25 sx plug Spot 25 sx plug Cut casing @ 6 Spot 25 sx, 50'	g @ 3300' & tag. g @ 1300' & tag. 600' & lay down. ' in and out of stub			31617 July 19	\$20212223242526 BELL THE	
2) 3) 4) 5) 6)	Spot 25 sx plug Spot 25 sx plug Cut casing @ 6 Spot 25 sx, 50° Spot 25 sx @ 5	g @ 3300' & tag. g @ 1300' & tag. 600' & lay down. ' in and out of stub 0' & bring to surfa			4151677	1920212223242526 HLUL WILLIAM OCD STATE OCD ST	
2) 3) 4) 5)	Spot 25 sx plug Spot 25 sx plug Cut casing @ 6 Spot 25 sx, 50'	g @ 3300' & tag. g @ 1300' & tag. 600' & lay down. ' in and out of stude 0' & bring to surfact y hole marker.	ace.		1314151677 <sub>20</sub>	1020212223242526 Hobbs OCD Hobbs	
2) 3) 4) 5) 6)	Spot 25 sx plug Spot 25 sx plug Cut casing @ 6 Spot 25 sx, 50° Spot 25 sx @ 5	g @ 3300' & tag. g @ 1300' & tag. 600' & lay down. ' in and out of stud 0' & bring to surfary hole marker.		SSION MUST BE OR TO THE BEC	NOTIFIED 24 GINNING OF	1020212223242532 1020212223242532 1020212223242532 1020212223242532	
2) 3) 4) 5) 6)	Spot 25 sx plug Spot 25 sx plug Cut casing @ 6 Spot 25 sx, 50° Spot 25 sx @ 5	g @ 3300' & tag. g @ 1300' & tag. 600' & lay down. ' in and out of stub 0' & bring to surfacy hole marker.  The Hole	ACE.  HE COMMIS OURS PRIC	or to the bec Operations fo	NOTIFIED 24 GINNING OF OR THE C-103	1020212223242526 Hobbs ED 102021223242526 Hobbs ED 102021223242526	
2) 3) 4) 5) 6)	Spot 25 sx plug Spot 25 sx plug Cut casing @ 6 Spot 25 sx, 50° Spot 25 sx @ 5	g @ 3300' & tag. g @ 1300' & tag. 600' & lay down. ' in and out of stub 0' & bring to surfacy hole marker.  The Hole	ace. HE COMMIS	or to the bec Operations fo	NOTIFIED 24 GINNING OF OR THE C-103	82021222324262 HOBBS ED WED WED WED WED WED WED WED WED WED	
2) 3) 4) 5) 6) 7)	Spot 25 sx plug Spot 25 sx plug Cut casing @ 6 Spot 25 sx, 50' Spot 25 sx @ 5 RD & install dr	g @ 3300' & tag. g @ 1300' & tag. 600' & lay down. ' in and out of stub 0' & bring to surfacy hole marker.  The PL TO	ace.  HE COMMIS OURS PRIC LUGGING ( O BE APPRO	or to the bec Operations fo Oved.		00212223242526 Hobbs FLUC VED 000	
2) 3) 4) 5) 6) 7)	Spot 25 sx plug Spot 25 sx plug Cut casing @ 6 Spot 25 sx, 50' Spot 25 sx @ 5 RD & install dr	g @ 3300' & tag. g @ 1300' & tag. 600' & lay down. ' in and out of stub 0' & bring to surfacy hole marker.  The Hole	HE COMMIS OURS PRIC LUGGING ( O BE APPRO	OR TO THE BEC OPERATIONS FO OVED.	lge and belief.		
2) 3) 4) 5) 6) 7)	Spot 25 sx plug Spot 25 sx plug Cut casing @ 6 Spot 25 sx, 50° Spot 25 sx @ 5 RD & install dr	g @ 3300' & tag. g @ 1300' & tag. g @ 13	HE COMMIS OURS PRIC LUGGING ( O BE APPRO	or to the bec Operations fo Oved.	lge and belief.	DATE 5/27/03	
2) 3) 4) 5) 6) 7)  I hereby cert	Spot 25 sx plug Spot 25 sx plug Cut casing @ 6 Spot 25 sx, 50° Spot 25 sx @ 5 RD & install dr  ify that the information  Angle Crawfor	g @ 3300' & tag. g @ 1300' & tag. g @ 13	HE COMMIS OURS PRIC LUGGING ( O BE APPRO	OR TO THE BEC OPERATIONS FO OVED.	ge and belief.	DATE_ 5/27/03 915-683-3171	
2) 3) 4) 5) 6) 7)  I hereby cert SIGNATUR Type or print	Spot 25 sx plug Spot 25 sx plug Cut casing @ 6 Spot 25 sx, 50° Spot 25 sx @ 5 RD & install dr  ify that the information  Angle Crawfor	g @ 3300' & tag. g @ 1300' & tag. g @ 13	HE COMMIS OURS PRIC LUGGING ( O BE APPRO	OR TO THE BEC OPERATIONS FO OVED.	ge and belief.	DATE 5/27/03	
2) 3) 4) 5) 6) 7)  I hereby cert SIGNATUR Type or print (This space i	Spot 25 sx plug Spot 25 sx plug Cut casing @ 6 Spot 25 sx, 50° Spot 25 sx @ 5 RD & install dr  ify that the information  Angle Crawfort t name for State use)	g @ 3300' & tag. g @ 1300' & tag. g @ 13	HE COMMIS OURS PRIC LUGGING ( O BE APPRO	OR TO THE BEC OPERATIONS FO OVED.	lge and belief. Analyst Telep	DATE	
2) 3) 4) 5) 6) 7) I hereby cert SIGNATUR Type or print (This space i	Spot 25 sx plug Spot 25 sx plug Cut casing @ 6 Spot 25 sx, 50° Spot 25 sx @ 5 RD & install dr  ify that the information  Angle Crawfort name for State use)  D BY	g @ 3300' & tag. g @ 1300' & tag. g @ 13	HE COMMIS OURS PRIC LUGGING ( O BE APPRO	OR TO THE BEC OPERATIONS FO OVED.	ge and belief.	DATE	
2) 3) 4) 5) 6) 7)  I hereby cert SIGNATUR Type or print (This space i	Spot 25 sx plug Spot 25 sx plug Cut casing @ 6 Spot 25 sx, 50° Spot 25 sx @ 5 RD & install dr  ify that the information  Angle Crawfort t name for State use)	g @ 3300' & tag. g @ 1300' & tag. g @ 13	HE COMMIS OURS PRIC LUGGING ( O BE APPRO	OR TO THE BEC OPERATIONS FO OVED.	lge and belief. Analyst Telep	DATE	

## XERIC OIL & GAS CORP. WELLBORE DIAGRAM

WELL: Mesa Queen Unit #14
COUNTY: Lea
STATE: NM

HOLE SIZE: 11"

CASING: 7" @373'

CEMENTED WITH: 2105X

CEMENT TOP: Suff.

TUBING: \_\_\_\_

PUMP : \_\_\_\_

PACKER:

HOLE SIZE: 6 1/8"

CASING: 41/2" @ 3490"

CEMENTED WITH: 1505X CEMENT TOP: 3071 PERFS:

3400 - 50

PBTD: 3457

TD: 3490