Submit 3 Copies To Appropriate District State of New Mexico Office	Form C-103
District I Energy, Minerals and Natural Resources	Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 87240 District II	WELL API NO.
811 South First, Artesia, NM 87210 OIL CONSERVATION DIVISION	30-025-20255
District III 2040 South Pacheco 1000 Rio Brazos Rd., Aztec, NM 87410	5. Indicate Type of Lease
District IV Santa Fe, NM 87505	STATE X FEE
2040 South Pacheco, Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	E-8160
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name:
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	4
1. Type of Well:	
Oil Well 🖾 Gas Well 🗌 Other	Mesa Queen
2. Name of Operator	8. Well No.
Xeric Oil & Gas Corporation	21
3. Address of Operator P. O. Box 352	9. Pool name or Wildcat
4. Well Location Midland, TX 79702	Mesa Queen Associated
1. Well Education	
Unit Letter M: 990 feet from the South line and 330 feet from the West line	
Section 16 Township 16S Range 32E	NMPM Lea County
10. Elevation (Show whether DR, RKB, RT, GR, e	(c.)
4359 GR	
11. Check Appropriate Box to Indicate Nature of Notice	
	SSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WO	RK ALTERING CASING
TEMPORARILY ABANDON	RILLING OPNS. PLUG AND
PULL OR ALTER CASING MULTIPLE CASING TEST A	ABANDONMENT L
COMPLETION CEMENT JOB	MAD []
OTHER.	
OTHER:	<u></u>
	give pertinent dates including estimated date
12. Describe proposed or completed operations. (Clearly state all pertinent details, and	give pertinent dates, including estimated date
	give pertinent dates, including estimated date ch wellbore diagram of proposed completion
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta	give pertinent dates, including estimated date ch wellbore diagram of proposed completion
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation.	give pertinent dates, including estimated date ch wellbore diagram of proposed completion
Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation. MIRU Pulling Unit.	give pertinent dates, including estimated date ch wellbore diagram of proposed completion
 Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation. MIRU Pulling Unit. Spot 25 sx plug @ 3300' & tag. 	give pertinent dates, including estimated date ch wellbore diagram of proposed completion
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation. 1) MIRU Pulling Unit. 2) Spot 25 sx plug @ 3300' & tag. 3) Spot 25 sx plug @ 1300' & tag.	give pertinent dates, including estimated date ch wellbore diagram of proposed completion
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation. 1) MIRU Pulling Unit. 2) Spot 25 sx plug @ 3300' & tag. 3) Spot 25 sx plug @ 1300' & tag. 4) Cut casing @ 600' & lay down.	give pertinent dates, including estimated date ch wellbore diagram of proposed completion
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation. 1) MIRU Pulling Unit. 2) Spot 25 sx plug @ 3300' & tag. 3) Spot 25 sx plug @ 1300' & tag. 4) Cut casing @ 600' & lay down. 5) Spot 25 sx, 50' in and out of stub & tag.	give pertinent dates, including estimated date ch wellbore diagram of proposed completion
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation. 1) MIRU Pulling Unit. 2) Spot 25 sx plug @ 3300' & tag. 3) Spot 25 sx plug @ 1300' & tag. 4) Cut casing @ 600' & lay down. 5) Spot 25 sx, 50' in and out of stub & tag. 6) Spot 25 sx @ 50' & bring to surface.	give pertinent dates, including estimated date ch wellbore diagram of proposed completion
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation. 1) MIRU Pulling Unit. 2) Spot 25 sx plug @ 3300' & tag. 3) Spot 25 sx plug @ 1300' & tag. 4) Cut casing @ 600' & lay down. 5) Spot 25 sx, 50' in and out of stub & tag. 6) Spot 25 sx @ 50' & bring to surface. 7) RD & install dry hole marker.	ch wellbore diagram of proposed completion
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation. 1) MIRU Pulling Unit. 2) Spot 25 sx plug @ 3300' & tag. 3) Spot 25 sx plug @ 1300' & tag. 4) Cut casing @ 600' & lay down. 5) Spot 25 sx, 50' in and out of stub & tag. 6) Spot 25 sx @ 50' & bring to surface. 7) RD & install dry hole marker. THE COMMISSION MUST BE N	ch wellbore diagram of proposed completion
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation. 1) MIRU Pulling Unit. 2) Spot 25 sx plug @ 3300' & tag. 3) Spot 25 sx plug @ 1300' & tag. 4) Cut casing @ 600' & lay down. 5) Spot 25 sx, 50' in and out of stub & tag. 6) Spot 25 sx @ 50' & bring to surface. 7) RD & install dry hole marker. THE COMMISSION MUST BE N HOURS PRIOR TO THE BEGIL	ch wellbore diagram of proposed completion
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation. 1) MIRU Pulling Unit. 2) Spot 25 sx plug @ 3300' & tag. 3) Spot 25 sx plug @ 1300' & tag. 4) Cut casing @ 600' & lay down. 5) Spot 25 sx, 50' in and out of stub & tag. 6) Spot 25 sx @ 50' & bring to surface. 7) RD & install dry hole marker. THE COMMISSION MUST BE N HOURS PRIOR TO THE BEGING PLUGGING OPERATIONS FOR	ch wellbore diagram of proposed completion
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation. 1) MIRU Pulling Unit. 2) Spot 25 sx plug @ 3300' & tag. 3) Spot 25 sx plug @ 1300' & tag. 4) Cut casing @ 600' & lay down. 5) Spot 25 sx, 50' in and out of stub & tag. 6) Spot 25 sx @ 50' & bring to surface. 7) RD & install dry hole marker. THE COMMISSION MUST BE N HOURS PRIOR TO THE BEGIL	OTIFIED 24
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation. 1) MIRU Pulling Unit. 2) Spot 25 sx plug @ 3300' & tag. 3) Spot 25 sx plug @ 1300' & tag. 4) Cut casing @ 600' & lay down. 5) Spot 25 sx, 50' in and out of stub & tag. 6) Spot 25 sx @ 50' & bring to surface. 7) RD & install dry hole marker. THE COMMISSION MUST BE N HOURS PRIOR TO THE BEGII PLUGGING OPERATIONS FOR TO BE APPROVED.	OTIFIED 24 NING OF THE C-103
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation. 1) MIRU Pulling Unit. 2) Spot 25 sx plug @ 3300' & tag. 3) Spot 25 sx plug @ 1300' & tag. 4) Cut casing @ 600' & lay down. 5) Spot 25 sx, 50' in and out of stub & tag. 6) Spot 25 sx @ 50' & bring to surface. 7) RD & install dry hole marker. THE COMMISSION MUST BE N HOURS PRIOR TO THE BEGING PLUGGING OPERATIONS FOR	OTIFIED 24 NING OF THE C-103
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation. 1) MIRU Pulling Unit. 2) Spot 25 sx plug @ 3300' & tag. 3) Spot 25 sx plug @ 1300' & tag. 4) Cut casing @ 600' & lay down. 5) Spot 25 sx, 50' in and out of stub & tag. 6) Spot 25 sx @ 50' & bring to surface. 7) RD & install dry hole marker. THE COMMISSION MUST BE NHOURS PRIOR TO THE BEGING PLUGGING OPERATIONS FOR TO BE APPROVED. I hereby certify that the information above is true and complete to the best of my knowledge SIGNATURE.	OTIFIED 24 NNING OF THE C-103 CORESTANDED.
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation. 1) MIRU Pulling Unit. 2) Spot 25 sx plug @ 3300' & tag. 3) Spot 25 sx plug @ 1300' & tag. 4) Cut casing @ 600' & lay down. 5) Spot 25 sx, 50' in and out of stub & tag. 6) Spot 25 sx @ 50' & bring to surface. 7) RD & install dry hole marker. THE COMMISSION MUST BE N HOURS PRIOR TO THE BEGIN PLUGGING OPERATIONS FOR TO BE APPROVED. I hereby certify that the information above is true and complete to the best of my knowledged and the complete complete to the best of my knowledged Crawford. TITLE Production	OTIFIED 24 NNING OF THE C-103 COSESTATION dge and belief. Analyst DATE 5/27/03
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation. 1) MIRU Pulling Unit. 2) Spot 25 sx plug @ 3300' & tag. 3) Spot 25 sx plug @ 1300' & tag. 4) Cut casing @ 600' & lay down. 5) Spot 25 sx, 50' in and out of stub & tag. 6) Spot 25 sx @ 50' & bring to surface. 7) RD & install dry hole marker. THE COMMISSION MUST BE N HOURS PRIOR TO THE BEGIN PLUGGING OPERATIONS FOR TO BE APPROVED. I hereby certify that the information above is true and complete to the best of my knowledge of the production of the production angle Creawford. Type or print name	OTIFIED 24 NNING OF THE C-103 CORESTANDED.
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation. 1) MIRU Pulling Unit. 2) Spot 25 sx plug @ 3300' & tag. 3) Spot 25 sx plug @ 1300' & tag. 4) Cut casing @ 600' & lay down. 5) Spot 25 sx, 50' in and out of stub & tag. 6) Spot 25 sx @ 50' & bring to surface. 7) RD & install dry hole marker. THE COMMISSION MUST BE N HOURS PRIOR TO THE BEGIN PLUGGING OPERATIONS FOR TO BE APPROVED. I hereby certify that the information above is true and complete to the best of my knowled surface. TITLE Production Type or print name (This space for State use)	OTIFIED 24 NNING OF THE C-103 Analyst DATE 5/27/03 915-683-3171 Telephone No.
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation. 1) MIRU Pulling Unit. 2) Spot 25 sx plug @ 3300' & tag. 3) Spot 25 sx plug @ 1300' & tag. 4) Cut casing @ 600' & lay down. 5) Spot 25 sx, 50' in and out of stub & tag. 6) Spot 25 sx @ 50' & bring to surface. 7) RD & install dry hole marker. THE COMMISSION MUST BE N HOURS PRIOR TO THE BEGING OPERATIONS FOR TO BE APPROVED. I hereby certify that the information above is true and complete to the best of my knowled SIGNATURE Angle Crawford Type or print name (This space for State use)	OTIFIED 24 NING OF THE C-103 Analyst DATE 5/27/03 915-683-3171 Telephone No.
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation. 1) MIRU Pulling Unit. 2) Spot 25 sx plug @ 3300' & tag. 3) Spot 25 sx plug @ 1300' & tag. 4) Cut casing @ 600' & lay down. 5) Spot 25 sx, 50' in and out of stub & tag. 6) Spot 25 sx @ 50' & bring to surface. 7) RD & install dry hole marker. THE COMMISSION MUST BE N HOURS PRIOR TO THE BEGIN PLUGGING OPERATIONS FOR TO BE APPROVED. I hereby certify that the information above is true and complete to the best of my knowled SIGNATURE Crawford Type or print name (This space for State use) OC FIELD REPRESENTAL TITLE	OTIFIED 24 NNING OF THE C-103 Analyst DATE 5/27/03 915-683-3171 Telephone No.
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation. 1) MIRU Pulling Unit. 2) Spot 25 sx plug @ 3300' & tag. 3) Spot 25 sx plug @ 1300' & tag. 4) Cut casing @ 600' & lay down. 5) Spot 25 sx, 50' in and out of stub & tag. 6) Spot 25 sx @ 50' & bring to surface. 7) RD & install dry hole marker. THE COMMISSION MUST BE N HOURS PRIOR TO THE BEGING OPERATIONS FOR TO BE APPROVED. I hereby certify that the information above is true and complete to the best of my knowled SIGNATURE Angle Crawford Type or print name (This space for State use)	OTIFIED 24 NING OF THE C-103 Analyst DATE 5/27/03 915-683-3171 Telephone No.

XERIC OIL & GAS CORP. WELLBORE DIAGRAM

WELL: Mesa Queen Unit#21
COUNTY: Lea
STATE: NM

HOLE SIZE: 11"

CASING: \$5k"@385"

CEMENTED WITH: 3955X

CEMENT TOP: 5wf.

TUBING: ____

PUMP : ____

PACKER:

HOLE SIZE: 77/8"

CASING: 5/2"@3500"

CEMENTED WITH: 125 SX CEMENT TOP: 2057 PERFS:

3A03'-22'

PBTD: 3477

TD: 3500'