

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103

Revised March 25, 1999

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO. 30-025-20321
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. K-959
7. Lease Name or Unit Agreement Name: Mesa Queen
8. Well No. 9
9. Pool name or Wildcat Mesa Queen Associated

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)


1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other Water Injection
2. Name of Operator Xeric Oil & Gas Corporation
3. Address of Operator P. O. Box 352 Midland, TX 79702
4. Well Location Unit Letter H : 1880 feet from the North line and 990 feet from the East line Section 16 Township 16S Range 32E NMPM Lea County
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 4341 DF

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input checked="" type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

- 1) MIRU Pulling Unit.
- 2) Spot 25 sx plug @ 3300' & tag.
- 3) Spot 25 sx plug @ 1300' & tag.
- 4) Cut casing @ 600' & lay down.
- 5) Spot 25 sx, 50' in and out of stub & tag.
- 6) Spot 25 sx @ 50' & bring to surface.
- 7) RD & install dry hole marker.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Angie Crawford TITLE Production Analyst DATE 5/27/03
Type or print name Angie Crawford Telephone No. 915-683-3171

(This space for State use)

APPROVED BY Larry W. Wink TITLE FIELD REPRESENTATIVE II/STAFF MANAGER DATE MAY 30 2003
Conditions of approval, if any:

XERIC OIL & GAS CORP.
WELLBORE DIAGRAM

WELL: Mesa Queen Unit #9

COUNTY: Lea

STATE: NM

HOLE SIZE: 11"
CASING: 7 5/8" @ 373'
CEMENTED WITH: 250 SX
CEMENT TOP: Surf.

TUBING: _____
RODS: _____
PUMP: _____
PACKER: _____

HOLE SIZE: 6 3/4"
CASING: 4 1/2" @ 3460'
CEMENTED WITH: 200 SX
CEMENT TOP: 568'



PERFS:

3408' - 28'

PBTD: 3470'

TD: 3481'