

Submit 3 Copies To Appropriate District Office

District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO. 30-025-20585
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. E-8310
7. Lease Name or Unit Agreement Name: Mesa Queen
8. Well No. 16
9. Pool name or Wildcat Mesa Queen Associated


SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well ☐ Gas Well ☐ Other Water Injection	
2. Name of Operator Xeric Oil & Gas Corporation	8. Well No. 16
3. Address of Operator P. O. Box 352 Midland, TX 79702	9. Pool name or Wildcat Mesa Queen Associated
4. Well Location Unit Letter <u>J</u> : <u>2310</u> feet from the <u>South</u> line and <u>2310</u> feet from the <u>East</u> line Section <u>16</u> Township <u>16S</u> Range <u>32E</u> NMPM Lea County	
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 4030 GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐ OTHER: ☐	SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ ALTERING CASING ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐ CASING TEST AND CEMENT JOB ☐ OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 1) MIRU Pulling Unit.
- 2) Spot 25 sx plug @ 3300' & tag.
- 3) Spot 25 sx plug @ 1300' & tag.
- 4) Cut casing @ 600' & lay down.
- 5) Spot 25 sx, 50' in and out of stub & tag.
- 6) Spot 25 sx @ 50' & bring to surface.
- 7) RD & install dry hole marker.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Angie Crawford TITLE Production Analyst DATE 5/27/03
Type or print name Angie Crawford Telephone No. 915-683-3171

APPROVED BY Ray W. Wink TITLE FIELD REPRESENTATIVE II / STAFF MANAGER DATE MAY 30 2003
Conditions of approval, if any:

**XERIC OIL & GAS CORP.
WELLBORE DIAGRAM**

WELL: Mesa Queen #16


COUNTY: Lea

STATE: NM

HOLE SIZE: 11"
CASING: 8 5/8" @ 378'
CEMENTED WITH: 200SX
CEMENT TOP: Surf.

TUBING: _____
RODS: _____
PUMP: _____
PACKER: _____

HOLE SIZE: 7 7/8"
CASING: 5 1/2" @ 3503'
CEMENTED WITH: 150SX
CEMENT TOP: 1771'



PERFS:

3412'-3416'

PBTD: 3486'

TD: 3503'