Submit 3 Copies To Appropriate District	State of New Mexico	Form C-103
Office District I	Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
District II	OIL CONSERVATION DIVISION	30-041-20183
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410		STATE FEE
District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM		
87505 SUNDRY NOT	ICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Bease value of other grounds
	CATION FOR PERMIT" (FORM C-101) FOR SUCH	Todd Lower San Andres Unit
PROPOSALS.)	🗆	8. Well Number 322
1. Type of Well: Oil Well	Gas Well Uther	
2. Name of Operator		9. OGRID Number
	etroleum, Inc.	227001 10. Pool name or Wildcat
3. Address of Operator 550 W. Texas, Suite 700 Midland, TX 79701		Todd;Lower San Andres (Assoc)
	1, 1 X /9/01	Todd, Lower San Andres (Assoc)
4. Well Location		
Unit LetterB:	660feet from theNorth line and _	1980feet from theEastline
Section 32	Township 7S Range 36E	NMPM County Roosevelt
	11. Elevation (Show whether DR, RKB, RT, GR, e	
A THE RESIDENCE OF THE SECOND	4128' GR	
Pit or Below-grade Tank Application 🔲 o	or Closure	
Pit type Steel Depth to Groundwa	terDistance from nearest fresh water wellD	istance from nearest surface water
Pit Liner Thickness: mil		Construction Material
12. Check A	Appropriate Box to Indicate Nature of Notic	e, Report or Other Data
NOTICE OF IN	ITENTION TO	IDOCOLICAT DEDOCT OF
		BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WO	
TEMPORARILY ABANDON 📗	CHANGE PLANS	RILLING OPNS. P AND A
PULL OR ALTER CASING	MULTIPLE COMPL CASING/CEME	NT JOB
FULL ON ALTER CASING		
	_	
OTHER:	OTHER:	
OTHER: 13. Describe proposed or comp	OTHER:	and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or composed of starting any proposed we	OTHER:	and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or comp	OTHER:	and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or composed of starting any proposed we	OTHER:	and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion.	OTHER: oleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions:	and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or compof starting any proposed we or recompletion. 8/17/05 Spot 25 sx. cmt. @ 2575', c	OTHER: oleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: displace to 2197', WOC & tag @ 2166'.	and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or compof starting any proposed we or recompletion. 8/17/05 Spot 25 sx. cmt. @ 2575', 68/18/05 Spot 25 sx. cmt. @ 2166', 6	OTHER: oleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: lisplace to 2197', WOC & tag @ 2166'. lisplace to 1788'.	and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or compof starting any proposed we or recompletion. 8/17/05 Spot 25 sx. cmt. @ 2575', c 8/18/05 Spot 25 sx. cmt. @ 2166', c 8/18/05 Cut 4-1/2" csg. @ 360', pul	OTHER: oleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: lisplace to 2197', WOC & tag @ 2166'. lisplace to 1788'. l, spot 50 sx. cmt. @ 410', WOC & tag @ 247'.	and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or composed was or recompletion. 8/17/05 Spot 25 sx. cmt. @ 2575', 68/18/05 Spot 25 sx. cmt. @ 2166', 68/18/05 Cut 4-1/2" csg. @ 360', pul 8/19/05 Spot 10 sx. cmt., surface place.	OTHER: oleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: lisplace to 2197', WOC & tag @ 2166'. lisplace to 1788'. l, spot 50 sx. cmt. @ 410', WOC & tag @ 247'.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or composed was or recompletion. 8/17/05 Spot 25 sx. cmt. @ 2575', 68/18/05 Spot 25 sx. cmt. @ 2166', 68/18/05 Cut 4-1/2" csg. @ 360', pul 8/19/05 Spot 10 sx. cmt., surface place.	OTHER: oleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: lisplace to 2197', WOC & tag @ 2166'. lisplace to 1788'. l, spot 50 sx. cmt. @ 410', WOC & tag @ 247'.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or composed was or recompletion. 8/17/05 Spot 25 sx. cmt. @ 2575', 68/18/05 Spot 25 sx. cmt. @ 2166', 68/18/05 Cut 4-1/2" csg. @ 360', pul 8/19/05 Spot 10 sx. cmt., surface place.	OTHER: oleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: lisplace to 2197', WOC & tag @ 2166'. lisplace to 1788'. l, spot 50 sx. cmt. @ 410', WOC & tag @ 247'.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or compof starting any proposed we or recompletion. 8/17/05 Spot 25 sx. cmt. @ 2575', 68/18/05 Spot 25 sx. cmt. @ 2166', 68/18/05 Cut 4-1/2" csg. @ 360', pul 8/19/05 Spot 10 sx. cmt., surface ple 8/16/05 RDMO. Cut off wellhead &	OTHER: oleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: displace to 2197', WOC & tag @ 2166'. lisplace to 1788'. ll, spot 50 sx. cmt. @ 410', WOC & tag @ 247'. ug. anchors, install dry hole marker, and clean location.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or compof starting any proposed we or recompletion. 8/17/05 Spot 25 sx. cmt. @ 2575', 68/18/05 Spot 25 sx. cmt. @ 2166', 68/18/05 Cut 4-1/2" csg. @ 360', pul 8/19/05 Spot 10 sx. cmt., surface ple 8/16/05 RDMO. Cut off wellhead &	OTHER: oleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: displace to 2197', WOC & tag @ 2166'. lisplace to 1788'. ll, spot 50 sx. cmt. @ 410', WOC & tag @ 247'. ug. anchors, install dry hole marker, and clean location.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or compof starting any proposed we or recompletion. 8/17/05 Spot 25 sx. cmt. @ 2575', 68/18/05 Spot 25 sx. cmt. @ 2166', 68/18/05 Cut 4-1/2" csg. @ 360', pul 8/19/05 Spot 10 sx. cmt., surface ple 8/16/05 RDMO. Cut off wellhead & Approved a	OTHER: oleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: lisplace to 2197', WOC & tag @ 2166'. lisplace to 1788'. l, spot 50 sx. cmt. @ 410', WOC & tag @ 247'. ag. anchors, install dry hole marker, and clean location.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or compof starting any proposed we or recompletion. 8/17/05 Spot 25 sx. cmt. @ 2575', 68/18/05 Spot 25 sx. cmt. @ 2166', 68/18/05 Cut 4-1/2" csg. @ 360', pul 8/19/05 Spot 10 sx. cmt., surface ple 8/16/05 RDMO. Cut off wellhead & Liability upon	OTHER: bleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: lisplace to 2197', WOC & tag @ 2166'. lisplace to 1788'. l, spot 50 sx. cmt. @ 410', WOC & tag @ 247'. lig. c anchors, install dry hole marker, and clean location. s to plugging of the Well Bore.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or compof starting any proposed we or recompletion. 8/17/05 Spot 25 sx. cmt. @ 2575', 68/18/05 Spot 25 sx. cmt. @ 2166', 68/18/05 Cut 4-1/2" csg. @ 360', pul 8/19/05 Spot 10 sx. cmt., surface ple 8/16/05 RDMO. Cut off wellhead & Liability upon	OTHER: bleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: lisplace to 2197', WOC & tag @ 2166'. lisplace to 1788'. l, spot 50 sx. cmt. @ 410', WOC & tag @ 247'. lig. c anchors, install dry hole marker, and clean location. s to plugging of the Well Bore.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or compof starting any proposed we or recompletion. 8/17/05 Spot 25 sx. cmt. @ 2575', 68/18/05 Spot 25 sx. cmt. @ 2166', 68/18/05 Cut 4-1/2" csg. @ 360', pul 8/19/05 Spot 10 sx. cmt., surface ple 8/16/05 RDMO. Cut off wellhead & Liability upon	OTHER: oleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: lisplace to 2197', WOC & tag @ 2166'. lisplace to 1788'. l, spot 50 sx. cmt. @ 410', WOC & tag @ 247'. ag. anchors, install dry hole marker, and clean location.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or compof starting any proposed we or recompletion. 8/17/05 Spot 25 sx. cmt. @ 2575', 68/18/05 Spot 25 sx. cmt. @ 2166', 68/18/05 Cut 4-1/2" csg. @ 360', pul 8/19/05 Spot 10 sx. cmt., surface ple 8/16/05 RDMO. Cut off wellhead & Liability upon	OTHER: bleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: lisplace to 2197', WOC & tag @ 2166'. lisplace to 1788'. l, spot 50 sx. cmt. @ 410', WOC & tag @ 247'. lig. c anchors, install dry hole marker, and clean location. s to plugging of the Well Bore.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or compof starting any proposed we or recompletion. 8/17/05 Spot 25 sx. cmt. @ 2575', 68/18/05 Spot 25 sx. cmt. @ 2166', 68/18/05 Cut 4-1/2" csg. @ 360', pul 8/19/05 Spot 10 sx. cmt., surface ple 8/16/05 RDMO. Cut off wellhead & Liability upon	OTHER: bleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: lisplace to 2197', WOC & tag @ 2166'. lisplace to 1788'. l, spot 50 sx. cmt. @ 410', WOC & tag @ 247'. lig. c anchors, install dry hole marker, and clean location. s to plugging of the Well Bore.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or compof starting any proposed we or recompletion. 8/17/05 Spot 25 sx. cmt. @ 2575', 68/18/05 Spot 25 sx. cmt. @ 2166', 68/18/05 Cut 4-1/2" csg. @ 360', pul 8/19/05 Spot 10 sx. cmt., surface ple 8/16/05 RDMO. Cut off wellhead & Approved a Liability und surface resto	ork). SEE RULE 1103. For Multiple Completions: displace to 2197', WOC & tag @ 2166'. displace to 1788'. displace to 50 sx. cmt. @ 410', WOC & tag @ 247'. displace to sx. cmt. @ 410', woc & tag @ 247'. displace to 1788'. de anchors, install dry hole marker, and clean location. sto plugging of the Well Bore. dier bond is retained until oration is completed.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or compof starting any proposed we or recompletion. 8/17/05 Spot 25 sx. cmt. @ 2575', 68/18/05 Spot 25 sx. cmt. @ 2166', 68/18/05 Cut 4-1/2" csg. @ 360', pul 8/19/05 Spot 10 sx. cmt., surface ple 8/16/05 RDMO. Cut off wellhead & Liability und surface resto	ork). SEE RULE 1103. For Multiple Completions: displace to 2197', WOC & tag @ 2166'. displace to 1788'. displace to 50 sx. cmt. @ 410', WOC & tag @ 247'. displace to install dry hole marker, and clean location. sto plugging of the Well Bore. der bond is retained until oration is completed.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or compof starting any proposed we or recompletion. 8/17/05 Spot 25 sx. cmt. @ 2575', 68/18/05 Spot 25 sx. cmt. @ 2166', 68/18/05 Cut 4-1/2" csg. @ 360', pul 8/19/05 Spot 10 sx. cmt., surface ple 8/16/05 RDMO. Cut off wellhead & Liability und surface resto	OTHER: oleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: lisplace to 2197', WOC & tag @ 2166'. lisplace to 1788'. l, spot 50 sx. cmt. @ 410', WOC & tag @ 247'. ag. anchors, install dry hole marker, and clean location sto plugging of the Well Bore. ler bond is retained until Dration is completed.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion dge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan
OTHER: 13. Describe proposed or compof starting any proposed we or recompletion. 8/17/05 Spot 25 sx. cmt. @ 2575', 68/18/05 Spot 25 sx. cmt. @ 2166', 68/18/05 Cut 4-1/2" csg. @ 360', pul 8/19/05 Spot 10 sx. cmt., surface ple 8/16/05 RDMO. Cut off wellhead & Liability und surface resto	OTHER: oleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: lisplace to 2197', WOC & tag @ 2166'. lisplace to 1788'. l, spot 50 sx. cmt. @ 410', WOC & tag @ 247'. ag. anchors, install dry hole marker, and clean location sto plugging of the Well Bore. ler bond is retained until Dration is completed.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion dge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan
OTHER: 13. Describe proposed or compost starting any proposed we or recompletion. 8/17/05 Spot 25 sx. cmt. @ 2575', 68/18/05 Spot 25 sx. cmt. @ 2166', 68/18/05 Cut 4-1/2" csg. @ 360', put 8/19/05 Spot 10 sx. cmt., surface plt 8/16/05 RDMO. Cut off wellhead & Liability und surface restored in the surface restored in	OTHER: oleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: lisplace to 2197', WOC & tag @ 2166'. lisplace to 1788'. l, spot 50 sx. cmt. @ 410', WOC & tag @ 247'. ag. anchors, install dry hole marker, and clean location sto plugging of the Well Bore. ler bond is retained until Dration is completed.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion dge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan
OTHER: 13. Describe proposed or compost starting any proposed we or recompletion. 8/17/05 Spot 25 sx. cmt. @ 2575', 68/18/05 Spot 25 sx. cmt. @ 2166', 68/18/05 Cut 4-1/2" csg. @ 360', put 8/19/05 Spot 10 sx. cmt., surface ple 8/16/05 RDMO. Cut off wellhead & Liability und surface restored in the surface restored in	OTHER: oleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: lisplace to 2197', WOC & tag @ 2166'. lisplace to 1788'. l, spot 50 sx. cmt. @ 410', WOC & tag @ 247'. ag. anchors, install dry hole marker, and clean location sto plugging of the Well Bore. ler bond is retained until Dration is completed.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion dge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan
OTHER: 13. Describe proposed or compost starting any proposed we or recompletion. 8/17/05 Spot 25 sx. cmt. @ 2575', 68/18/05 Spot 25 sx. cmt. @ 2166', 68/18/05 Cut 4-1/2" csg. @ 360', put 8/19/05 Spot 10 sx. cmt., surface ple 8/16/05 RDMO. Cut off wellhead & Liability und surface restored in the surface restored in	OTHER: oleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: lisplace to 2197', WOC & tag @ 2166'. lisplace to 1788'. l, spot 50 sx. cmt. @ 410', WOC & tag @ 247'. ag. anchors, install dry hole marker, and clean location sto plugging of the Well Bore. ler bond is retained until Dration is completed.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion dge and belief. I further certify that any pit or belowdran or an (attached) alternative OCD-approved plan.
OTHER: 13. Describe proposed or compof starting any proposed we or recompletion. 8/17/05 Spot 25 sx. cmt. @ 2575', 68/18/05 Spot 25 sx. cmt. @ 2166', 68/18/05 Cut 4-1/2" csg. @ 360', pul 8/19/05 Spot 10 sx. cmt., surface ple 8/16/05 RDMO. Cut off wellhead & Liability und surface restored in the surface restored in	OTHER: Deleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: displace to 2197', WOC & tag @ 2166'. displace to 1788'. Il, spot 50 sx. cmt. @ 410', WOC & tag @ 247'. Deleted operations. It is to plugging of the Well Bore. The bond is retained until praction is completed. TITLE Agent Agent of Massey OF FIELD RESENTATIVE.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion dge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan EII/STAFF MANAGER DATE
OTHER: 13. Describe proposed or compof starting any proposed we or recompletion. 8/17/05 Spot 25 sx. cmt. @ 2575', 68/18/05 Spot 25 sx. cmt. @ 2166', 68/18/05 Spot 10 sx. cmt., surface pla 8/19/05 Spot 10 sx. cmt., surface pla 8/16/05 RDMO. Cut off wellhead & Liability und surface restored in the surface restored i	OTHER: oleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: lisplace to 2197', WOC & tag @ 2166'. lisplace to 1788'. l, spot 50 sx. cmt. @ 410', WOC & tag @ 247'. ag. anchors, install dry hole marker, and clean location sto plugging of the Well Bore. ler bond is retained until Dration is completed.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion dge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan . EII/STAFF MANAGER DATE 8/23/05 Telephone No. (432) 530-0907
OTHER: 13. Describe proposed or compof starting any proposed we or recompletion. 8/17/05 Spot 25 sx. cmt. @ 2575', 68/18/05 Spot 25 sx. cmt. @ 2166', 68/18/05 Cut 4-1/2" csg. @ 360', pul 8/19/05 Spot 10 sx. cmt., surface ple 8/16/05 RDMO. Cut off wellhead & Liability und surface restored in the surface restored in	OTHER: Deleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: displace to 2197', WOC & tag @ 2166'. displace to 1788'. Il, spot 50 sx. cmt. @ 410', WOC & tag @ 247'. Deleted operations. It is to plugging of the Well Bore. The bond is retained until praction is completed. TITLE Agent Agent of Massey OF FIELD RESENTATIVE.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion dge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan