Submit I Copy To Appropriate District HOBBS OCD State of New Mexico	Form C-103	
District I – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 APR 17 2013 District II. (575) 749 1992	Revised August 1, 201 WELL API NO.	
OIL CONSERVATION DIVISION	5. Indicate Type of Lease	
$\frac{\text{District III} - (505) 334-6178}{1000 \text{ Rio Brazos Rd., Aztec, NM 87410}} \text{ RECEIVED} 1220 \text{ South St. Francis Dr.} \\ \text{Santa Fe, NM 87505} $	6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM	0. State on & Gas Dease No.	
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	Rock Queen Unit	
1. Type of Well: Oil Well 🔲 Gas Well 🚺 Other Injection	8. Well Number 19	
2. Name of Operator Celero Energy II, LP	9. OGRID Number 247128	
3. Address of Operator 400 W. Illinois, Ste. 1601	10. Pool name or Wildcat	
Midland, 1X 79701	Caprock; Queen	
4. Well Location Unit Letter J : 1980 feet from the S line and	1980 fect from the E line	
Section 23 Township 13S Range 31E	NMPM County Chaves	
11. Elevation (Show whether DR, RKB, RT, GR	elc.)	
12. Check Appropriate Box to Indicate Nature of Not	ice, Report or Other Data	
	UBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL V TEMPORARILY ABANDON CHANGE PLANS COMMENCE	VORK ALTERING CASING	
	Renground Injection Control Program Manual	
	C Packer shall be set within or less than 100	
OTHER: Sidetrack I OTHER feet of the uppermost injection perfs or open bac 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
	 Set CICR @ 2870' & sqz w/ 100 sx Class C w/2% CaCl2. Set whipstock on CICR w/out orienting Mill window in csg. RIH w/ 4 7/8" bit, 1.8 degree mtr & DC's. Slide drill 100-125'. POOH, RBIH 4 7/8" bit, straight mtr & 10-12 DC's. Continue drlg 	
2. Set whipstock on CICR w/out orienting Mill window in csg.	7/8" bit, straight mtr & 10-12 DC's. Continue drlg	
 Set whipstock on CICR w/out orienting Mill window in csg. RIH w/ 4 7/8" bit, 1.8 degree mtr & DC's. Slide drill 100-125'. POOH, RBIH 4 new hole to TD @ 3080'. 		
 Set whipstock on CICR w/out orienting Mill window in csg. RIH w/ 4 7/8" bit, 1.8 degree mtr & DC's. Slide drill 100-125'. POOH, RBIH 4 new hole to TD @ 3080'. PU duplex shoe & 10 jts 4", 11#, L-80 UFJ csg & RIH w/ 2 3/8" x 2 7/8" tapered 5. RIH w/ bit to TOL. RIH w/pkr & pressure test TOL. Sqz cmt TOL if necessary. 	workstring. Cmt w/ min 150 sx Class C w/ 2%.	
 Set whipstock on CICR w/out orienting Mill window in csg. RIH w/ 4 7/8" bit, 1.8 degree mtr & DC's. Slide drill 100-125'. POOH, RBIH 4 new hole to TD @ 3080'. PU duplex shoe & 10 jts 4", 11#, L-80 UFJ csg & RIH w/ 2 3/8" x 2 7/8" tapered 5. RIH w/ bit to TOL. RIH w/pkr & pressure test TOL. Sqz cmt TOL if necessary. Make bit run to shoe. RU WL & run a GR/CCL/CNL. Perf Queen Sand w/ min 	workstring. Cmt w/ min 150 sx Class C w/ 2%. 15' gun loaded @ 4 SPF.	
 Set whipstock on CICR w/out orienting Mill window in csg. RIH w/ 4 7/8" bit, 1.8 degree mtr & DC's. Slide drill 100-125'. POOH, RBIH 4 new hole to TD @ 3080'. PU duplex shoe & 10 jts 4", 11#, L-80 UFJ csg & RIH w/ 2 3/8" x 2 7/8" tapered 5. RIH w/ bit to TOL. RIH w/pkr & pressure test TOL. Sqz cmt TOL if necessary. Make bit run to shoe. RU WL & run a GR/CCL/CNL. Perf Queen Sand w/ min 7. Run pkr & acdz perfs w/ 1500 gals inh 7 1/2% NEFE HCL using ball sealers for 8. RIH w/ inj pkr & IPC tbg to w/ in 50' of perfs. Circ w/ inhibited FW pkr fluid. S 	workstring. Cmt w/ min 150 sx Class C w/ 2%. 15' gun loaded @ 4 SPF. diversion.	
 Set whipstock on CICR w/out orienting Mill window in csg. RIH w/ 4 7/8" bit, 1.8 degree mtr & DC's. Slide drill 100-125'. POOH, RBIH 4 new hole to TD @ 3080'. PU duplex shoe & 10 jts 4", 11#, L-80 UFJ csg & RIH w/ 2 3/8" x 2 7/8" tapered 5. RIH w/ bit to TOL. RIH w/pkr & pressure test TOL. Sqz cmt TOL if necessary. Make bit run to shoe. RU WL & run a GR/CCL/CNL. Perf Queen Sand w/ min 7. Run pkr & acdz perfs w/ 1500 gals inh 7 1/2% NEFE HCL using ball sealers for 8. RIH w/ inj pkr & IPC tbg to w/ in 50' of perfs. Circ w/ inhibited FW pkr fluid. S 9. Schedule MIT & RWTI. 	workstring. Cmt w/ min 150 sx Class C w/ 2%. 15' gun loaded @ 4 SPF. diversion. et pkr & test.	
 Set whipstock on CICR w/out orienting Mill window in csg. RIH w/ 4 7/8" bit, 1.8 degree mtr & DC's. Slide drill 100-125'. POOH, RBIH 4 new hole to TD @ 3080'. PU duplex shoe & 10 jts 4", 11#, L-80 UFJ csg & RIH w/ 2 3/8" x 2 7/8" tapered 5. RIH w/ bit to TOL. RIH w/pkr & pressure test TOL. Sqz cmt TOL if necessary. Make bit run to shoe. RU WL & run a GR/CCL/CNL. Perf Queen Sand w/ min 7. Run pkr & acdz perfs w/ 1500 gals inh 7 1/2% NEFE HCL using ball sealers for 8. RIH w/ inj pkr & IPC tbg to w/ in 50' of perfs. Circ w/ inhibited FW pkr fluid. S 9. Schedule MIT & RWTI. 	workstring. Cmt w/ min 150 sx Class C w/ 2%. 15' gun loaded @ 4 SPF. diversion. et pkr & test. Condition of Approval: notify	
 Set whipstock on CICR w/out orienting Mill window in csg. RIH w/ 4 7/8" bit, 1.8 degree mtr & DC's. Slide drill 100-125'. POOH, RBIH 4 new hole to TD @ 3080'. PU duplex shoe & 10 jts 4", 11#, L-80 UFJ csg & RIH w/ 2 3/8" x 2 7/8" tapered 5. RIH w/ bit to TOL. RIH w/pkr & pressure test TOL. Sqz cmt TOL if necessary. Make bit run to shoe. RU WL & run a GR/CCL/CNL. Perf Queen Sand w/ min 7. Run pkr & acdz perfs w/ 1500 gals inh 7 1/2% NEFE HCL using ball sealers for 8. RIH w/ inj pkr & IPC tbg to w/ in 50' of perfs. Circ w/ inhibited FW pkr fluid. S 9. Schedule MIT & RWTI. 	workstring. Cmt w/ min 150 sx Class C w/ 2%. 15' gun loaded @ 4 SPF. diversion. et pkr & test. Condition of Approval: notify OCD Hobbs office 24 hours	
 2. Set whipstock on CICR w/out orienting Mill window in csg. 3. RIH w/ 4 7/8" bit, 1.8 degree mtr & DC's. Slide drill 100-125'. POOH, RBIH 4 new hole to TD @ 3080'. 4. PU duplex shoe & 10 jts 4", 11#, L-80 UFJ csg & RIH w/ 2 3/8" x 2 7/8" tapered 5. RIH w/ bit to TOL. RIH w/pkr & pressure test TOL. Sqz cmt TOL if necessary. 6. Make bit run to shoe. RU WL & run a GR/CCL/CNL. Perf Queen Sand w/ min 7. Run pkr & acdz perfs w/ 1500 gals inh 7 1/2% NEFE HCL using ball sealers for 8. RIH w/ inj pkr & IPC tbg to w/ in 50' of perfs. Circ w/ inhibited FW pkr fluid. S 9. Schedule MIT & RWTI. The Oil Conservation Division MUST BE NOTIFIED 24 Hours Spud Dat Prior to the beginning of operations Rig Release Date:	workstring. Cmt w/ min 150 sx Class C w/ 2%. 15' gun loaded @ 4 SPF. diversion. et pkr & test. Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart	
 2. Set whipstock on CICR w/out orienting Mill window in csg. 3. RIH w/ 4 7/8" bit, 1.8 degree mtr & DC's. Slide drill 100-125'. POOH, RBIH 4 new hole to TD @ 3080'. 4. PU duplex shoe & 10 jts 4", 11#, L-80 UFJ csg & RIH w/ 2 3/8" x 2 7/8" tapered 5. RIH w/ bit to TOL. RIH w/pkr & pressure test TOL. Sqz cmt TOL if necessary. 6. Make bit run to shoe. RU WL & run a GR/CCL/CNL. Perf Queen Sand w/ min 7. Run pkr & acdz perfs w/ 1500 gals inh 7 1/2% NEFE HCL using ball sealers for 8. RIH w/ inj pkr & IPC tbg to w/ in 50' of perfs. Circ w/ inhibited FW pkr fluid. S 9. Schedule MIT & RWTI. The Oil Conservation Division MUST BE NOTIFIED 24 Hours Spud Dat Prior to the beginning of operations Rig Release Date:	workstring. Cmt w/ min 150 sx Class C w/ 2%. 15' gun loaded @ 4 SPF. diversion. et pkr & test. Condition of Approval: notify OCD Hobbs office 24 hours	
 2. Set whipstock on CICR w/out orienting Mill window in csg. 3. RIH w/ 4 7/8" bit, 1.8 degree mtr & DC's. Slide drill 100-125'. POOH, RBIH 4 new hole to TD @ 3080'. 4. PU duplex shoe & 10 jts 4", 11#, L-80 UFJ csg & RIH w/ 2 3/8" x 2 7/8" tapered 5. RIH w/ bit to TOL. RIH w/pkr & pressure test TOL. Sqz cmt TOL if necessary. 6. Make bit run to shoe. RU WL & run a GR/CCL/CNL. Perf Queen Sand w/ min 7. Run pkr & acdz perfs w/ 1500 gals inh 7 1/2% NEFE HCL using ball sealers for 8. RIH w/ inj pkr & IPC tbg to w/ in 50' of perfs. Circ w/ inhibited FW pkr fluid. S 9. Schedule MIT & RWTI. The Oil Conservation Division MUST BE NOTIFIED 24 Hours Spud Dat Prior to the beginning of operations Rig Release Date:	workstring. Cmt w/ min 150 sx Class C w/ 2%. 15' gun loaded @ 4 SPF. diversion. et pkr & test. Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart	
 2. Set whipstock on CICR w/out orienting Mill window in csg. 3. RIH w/ 4 7/8" bit, 1.8 degree mtr & DC's. Slide drill 100-125'. POOH, RBIH 4 new hole to TD @ 3080'. 4. PU duplex shoe & 10 jts 4", 11#, L-80 UFJ csg & RIH w/ 2 3/8" x 2 7/8" tapered 5. RIH w/ bit to TOL. RIH w/pkr & pressure test TOL. Sqz cmt TOL if necessary. 6. Make bit run to shoe. RU WL & run a GR/CCL/CNL. Perf Queen Sand w/ min 7. Run pkr & acdz perfs w/ 1500 gals inh 7 1/2% NEFE HCL using ball sealers for 8. RIH w/ inj pkr & IPC tbg to w/ in 50' of perfs. Circ w/ inhibited FW pkr fluid. S 9. Schedule MIT & RWTI. The Oil Conservation Division MUST BE NOTIFIED 24 Hours Spud Dat Prior to the beginning of operations Rig Release Date: I hereby certify that the information above is true and complete to the best of my know	workstring. Cmt w/ min 150 sx Class C w/ 2%. 15' gun loaded @ 4 SPF. diversion. et pkr & test. Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart	
 2. Set whipstock on CICR w/out orienting Mill window in csg. 3. RIH w/ 4 7/8" bit, 1.8 degree mtr & DC's. Slide drill 100-125'. POOH, RBIH 4 new hole to TD @ 3080'. 4. PU duplex shoe & 10 jts 4", 11#, L-80 UFJ csg & RIH w/ 2 3/8" x 2 7/8" tapered 5. RIH w/ bit to TOL. RIH w/pkr & pressure test TOL. Sqz cmt TOL if necessary. 6. Make bit run to shoe. RU WL & run a GR/CCL/CNL. Perf Queen Sand w/ min 7. Run pkr & acdz perfs w/ 1500 gals inh 7 1/2% NEFE HCL using ball sealers for 8. RIH w/ inj pkr & IPC tbg to w/ in 50' of perfs. Circ w/ inhibited FW pkr fluid. S 9. Schedule MIT & RWTI. The Oil Conservation Division MUST BE NOTIFIED 24 Hours Spud Dat Prior to the beginning of operations Rig Release Date:	workstring. Cmt w/ min 150 sx Class C w/ 2%. 15' gun loaded @ 4 SPF. diversion. et pkr & test. Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart	
 2. Set whipstock on CICR w/out orienting Mill window in csg. 3. RIH w/ 4 7/8" bit, 1.8 degree mtr & DC's. Slide drill 100-125'. POOH, RBIH 4 new hole to TD @ 3080'. 4. PU duplex shoe & 10 jts 4", 11#, L-80 UFJ csg & RIH w/ 2 3/8" x 2 7/8" tapered 5. RIH w/ bit to TOL. RIH w/pkr & pressure test TOL. Sqz cmt TOL if necessary. 6. Make bit run to shoe. RU WL & run a GR/CCL/CNL. Perf Queen Sand w/ min 7. Run pkr & acdz perfs w/ 1500 gals inh 7 1/2% NEFE HCL using ball sealers for 8. RIH w/ inj pkr & IPC tbg to w/ in 50' of perfs. Circ w/ inhibited FW pkr fluid. S 9. Schedule MIT & RWTI. The Oil Conservation Division MUST BE NOTIFIED 24 Hours Spud Dat Prior to the beginning of operations Rig Release Date: I hereby certify that the information above is true and complete to the best of my know	workstring. Cmt w/ min 150 sx Class C w/ 2%. 15' gun loaded @ 4 SPF. diversion. et pkr & test. Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart rest & Chart Medge and belief. DATE 04/16/2013	
2. Set whipstock on CICR w/out orienting Mill window in csg. 3. RIH w/ 4 7/8" bit, 1.8 degree mtr & DC's. Slide drill 100-125'. POOH, RBIH 4 new hole to TD @ 3080'. 4. PU duplex shoe & 10 jts 4", 11#, L-80 UFJ csg & RIH w/ 2 3/8" x 2 7/8" tapered 5. RIH w/ bit to TOL. RIH w/pkr & pressure test TOL. Sqz cmt TOL if necessary. 6. Make bit run to shoe. RU WL & run a GR/CCL/CNL. Perf Queen Sand w/ min 7. Run pkr & acdz perfs w/ 1500 gals inh 7 1/2% NEFE HCL using ball sealers for 8. RIH w/ inj pkr & IPC tbg to w/ in 50' of perfs. Circ w/ inhibited FW pkr fluid. S 9. Schedule MIT & RWTI. The Oil Conservation Division MUST BE NOTIFIED 24 Hours Spud Dat Prior to the beginning of operations Rig Release Date: I hereby certify that the information above is true and complete to the best of my know SIGNATURE Juan Juan Lisa Hunt For State Use Only E-mail address: I hunt@celer Interformation Mutrice Distribution I hunt@celer Output Distribution Distribution Substantiation A state Use Only Distribution Distribution Distribution Distribution Distribution Substantiation Substantiation Distribution <td>workstring. Cmt w/ min 150 sx Class C w/ 2%. 15' gun loaded @ 4 SPF. diversion. et pkr & test. Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart rest & Chart Medge and belief. DATE 04/16/2013 oenergy.com PHONE: (432)686-1883</td>	workstring. Cmt w/ min 150 sx Class C w/ 2%. 15' gun loaded @ 4 SPF. diversion. et pkr & test. Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart rest & Chart Medge and belief. DATE 04/16/2013 oenergy.com PHONE: (432)686-1883	
 2. Set whipstock on CICR w/out orienting Mill window in csg. 3. RIH w/ 4 7/8" bit, 1.8 degree mtr & DC's. Slide drill 100-125'. POOH, RBIH 4 new hole to TD @ 3080'. 4. PU duplex shoe & 10 jts 4", 11#, L-80 UFJ csg & RIH w/ 2 3/8" x 2 7/8" tapered 5. RIH w/ bit to TOL. RIH w/pkr & pressure test TOL. Sqz cmt TOL if necessary. 6. Make bit run to shoe. RU WL & run a GR/CCL/CNL. Perf Queen Sand w/ min 7. Run pkr & acdz perfs w/ 1500 gals inh 7 1/2% NEFE HCL using ball sealers for 8. RIH w/ inj pkr & IPC tbg to w/ in 50' of perfs. Circ w/ inhibited FW pkr fluid. S 9. Schedule MIT & RWTI. The Oil Conservation Division MUST BE NOTIFIED 24 Hours Spud Dat Prior to the beginning of operations Rig Release Date: I hereby certify that the information above is true and complete to the best of my know SIGNATURE Anal Anal Struct Type or print name Lisa Hunt 	workstring. Cmt w/ min 150 sx Class C w/ 2%. 15' gun loaded @ 4 SPF. diversion. et pkr & test. Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart rest & Chart Medge and belief. DATE 04/16/2013	

MAY 20 2013