Submit 1 Copy To Appropriate District Office	Energy, Minerals and Natural Resources		Form C-103			
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240			Revised August 1, 2011 WELL API NO.			
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION		30-025-31874			
District III - (505) 334-6178	1220 South St. Francis Dr.		5. Indicate Type of Lease			
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505		6. State Oil & Gas Lease No.			
87505	ICES AND DEDODES ON WELLS		7. Lease Name or Unit Agreement Name			
(DO NOT USE THIS FORM FOR PROPC	ICES AND REPORTS ON WELLS DSALS TO DRILL OR TO DEEPEN OR PLU ICATION FOR PERMIT" (FORM C-101) FO	JG BACK TO A PR SUCH	VACUUM GLORIETA WEST UNIT			
1. Type of Well: Oil Well	Gas Well Other INJECTION		8. Well Number 106			
2. Name of Operator CHEVRON U.S.A. INC.			9. OGRID Number 4323			
 Address of Operator SMITH ROAD, MIDLAND, 7 	MAY 1 MAY 1	V 2010 I	10. Pool name or Wildcat VACUUM GLORIETA			
4. Well Location						
	from the SOUTH line and 2630 for					
Section 36	Township 17-S Range 11. Elevation (Show whether DR,		1PM County LEA			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL						
OTHER:			/CHART (MIT REPAIR)			
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.						
PLEASE FIND ATTACHED, THE SUMMARY REPORTS FOR WORK DONE FROM 03/28/2013 THROUGH 04/04/2013.						
ALSO FIND ATTACHED, THE CURRENT WELLBORE DIAGRAM.						
THE ORIGINAL CHART & COPY OF CHART IS IN THE NMOCD OFFICE.						
Spud Date:	Rig Release Da	te:				
I hereby certify that the information 0	above is true and complete to the be	est of my knowledge	and belief.			
SIGNATURE AUS IMARTA TITLE: REGULATORY SPECIALIST DATE: 05-07-2013						
Fype or print name: DENISE PINKERTON E-mail address: leakejd@chevron.com PHONE: 432-687-7375						
APPROVED BY Jongh TITLE DIST. MGR DATE 5-13-2013						
Conditions of Approval (if any):						

,

			\square
MAY	20	201 3	chm

Summary Report

Chevron

Major Rig Work Over (MRWO) Tubing Repair Job Start Date: 3/28/2013 Job End Date: 4/4/2013

			JOD Ella Date. 4/4/2013				
Well Name VACUUM GLORIETA WEST UNIT WI- 106	Lease Vacuum Glorieta West Unit	Field Name Vacuum	Business Unit Mid-Continent/Alaska				
Ground Elevation (ft) Original RKB (ft)	Current RKB Elevation		Mud Line Elevation (ft) Water Depth (ft)				
Report Start Date: 3/28/2013							
Review JSA's	·	Com					
Wait on Pro Wireline to get to location							
RU Pro Wireline							
		2.2/0" IDC the completely w/ DM. Cheer e	ff of plug and POOL w/ wireling tools				
BW stayed full in tbg indicating blanking	plug was set. RD Pro Wireline.	2-3/8" IPC tbg completely w/ BW. Shear o	in of plug and POOH w/ wireline tools.				
Begin ND of wellhead and sdon							
Travel time							
Report Start Date: 3/29/2013		······································					
Crow Lunch in Hobbs for 7 years of IEO	×	Com					
Crew Lunch in Hobbs for 7 years of IFO							
Report Start Date: 4/2/2013		Com					
CREW TRAVEL							
SAFETŸ MTG, REVIEW JSA'S							
Report Start Date: 4/2/2013	.						
	. • f	Com					
Crew travel to location							
JSA	·						
Wait for welder to arrive on location to cu	it bolts.						
Welder cut bolts off well head.							
NU 5K BOP with Hydraulic Accumulator							
RU floor and prep tools for POOH standii	ng back tbg in derrick.						
Unset pkr.							
JSA for slick line, to retrieve plug.							
	for plug, tag plug, engage plug (break s	eal), pull plug from profill nipple. pooh, RD	slick line unit.				
POOH while standing back tbg in derrick							
Crew travel home							
Report Start Date: 4/3/2013							
		Com					
Crew travel to location							
JSA							
Perform BOP Blind test with Peak PKR (500 psi) (good),		•				
RIH w 5.5" AS-1 8K Pkr w On/Off tool (w	Pump out plug) 182 jts 2.375" FG Tbg,	1-4' and 2-10' 2.375" FG Tbg.					
Pump Pkr fluid,		····					
Set Pkr @ 5,796'. Pkr set in Tension with	10 pts down.		···· ·				
Perform Pre-ND H-5 test (good test 500 psi)							
ND BOP, NU new B-5 flange. Make up n							
Pump out plug (550 psi). Establish Injection Rate 5.5 bpm @ 1600 psi. (unable to achieve H-5 test due to foam)							
Prepare location for move. SWI SDFN							
Report Start Date: 4/4/2013							
		Com					
crew travel to loc							
JSA Perform High and Low H-5 (good). 500 p	isi test (held 500 psi), Recorded on cha	rt. Turned original into Buckeye office, cop	es retained in both field office and				
Midland office files. RDPU							
turn well over to produxtion							
			4				
			1				



•