r f Form 3260-5 (August 2007)	UNITED STATE	.0 -	Hobbs		APPROVED NO. 1004-0135
DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT HOBBS OCD				Expires: July 31, 2010 5. Lease Serial No. NMNM60789	
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an					
abandoned we	II. Use form 3160-3 (AF	PD) for such propošalš(1	3 2013	6. If Indian, Allottee	or Tribe Name
	IPLICATE - Other instru	ctions on reverse side. DFCFI	VED	7. If Unit or CA/Agre	eement, Name and/or No
1. Type of Well Image: Solid Well Image:				8. Well Name and No. MALLON 33 FEDERAL 1	
2. Name of Operator Contact: TERRI STATHEM CIMAREX ENERGY COMPANY E-Mail: tstathem@cimarex.com				9. API Well No. 30-025-33738	
3a. Address 600 N. MARIENFELD ST., SU MIDLAND, TX 79701	3b. Phone No. (include area code Ph: 918-295-1763	,	10. Field and Pool, or Exploratory CHAILENDGE BONE SPRING S LEA. Delawage / NE		
4. Location of Well (Footage, Sec., 7	1)		11. County or Parish,		
Sec 33 T19S R34E 1880FSL		LEA COUNTY, NM		NM /	
12. CHECK APP	ROPRIATE BOX(ES) T	O INDICATE NATURE OF	NOTICE, R	L EPORT, OR OTHE	R DATA
TYPE OF SUBMISSION	TYPE OF ACTION				
X Notice of Intent	Acidize	Deepen	D Product	ion (Start/Resume)	🗖 Water Shut-Off
—	Alter Casing	Fracture Treat	🗖 Reclam	ation	Well Integrity
Subsequent Report	Casing Repair	New Construction	🗖 Recom		C Other
Final Abandonment Notice	Change Plans Convert to Injection	Plug and Abandon Plug Back	on Temporarily Abandon Water Disposal		
3. Describe Proposed or Completed Op	eration (clearly state all pertine	nt details including estimated startin	g date of any n	roposed work and appro	vimate duration thereof
 determined that the site is ready for f Cimarex respectfully requests following procedure: 1. Abandon current Bone Spr of cement on top of plug. 2. Pressure test casing 3. Perforate Brushy Canyon p 4. Establish Brushy Canyon p 	ings perfs (9668-74') ? S @ 7307-7326', and acidiz production.	et cast iron bridge plug at 961 e with 800 gallons of 7.5% H0	8' an CON t	DPTIONS OF	FOR APPROVAL
 Run composite bridge plug Perforate Cherry Canyon (NEFE acid. Frac Cherry Canyon with g 	5747-5752' & 5802-581	12', and acidize with 700 gallo	ns of 7.5% ł		O LIKE L BY STATE
 I hereby certify that the foregoing is Name(Printed/Typed) TERRI ST 	Electronic Submission # For CIMAREX Committed to AFMSS f	197591 verified by the BLM We ENERGY COMPANY, sent to or processing by KURT SIMMC Title COORI	the Hobbs NS on 02/11/	-	PLIA
Signature (Electronic S		Date 02/07/2		APPRO	
<u> </u>		DR FEDERAL OR STATE			
A manual Du				MAY -7	2013,
Approved By	itable title to those rights in the	not warrant or e subject lease Office	B	REAU OF LAND MA CARLSBAD FIELD	NAGEMENT
tle 18 U.S.C. Section 1001 and Title 3 States any false, fictitious or fraudules			willfully to ma		
		PERATOR-SUBMITTED *			
OFERAT	UN-SUBIVITIED O				. /
			ปบ	IN 0 5 2013	\

Additional data for EC transaction #197591 that would not fit on the form

32. Additional remarks, continued

- 8. Established Cherry Canyon production.
 9. Request DHC approval upon results of Brushy Canyon and Cherry Canyon production.
 10. DHC approval received Drill out CBP and commingle Cherry and Brushy Canyon.
 11. Return well to production.

 $\frac{1}{1} \frac{1}{1} \frac{1}$

Conditions of Approval

Cimarex Energy Company Mallon 33 Federal 1 API 30-025-33738 T19S-R34E, Sec 33 May 07, 2013 HOB3S OCD MAY 1 3 2013

RECEIVED

Prior to commencing any work, operator shall run a CBL and submit results to BLM for approval. <u>No work</u> will begin until approval to continue is granted.

Notify BLM at 575-361-2822 a minimum of 24 hours prior to commencing work.

Work to be completed by August 07, 2013.

- 1. Operator shall place a CIBP at 9618' and place 35' of cement on top of the plug. Tag required.
- 2. Operator shall place a balanced cement plug from 8,310'-8,130' to isolate the Bone Springs formation. Tag required. A minimum of 25 sx of cement is required for this procedure.
- 3. Subject to like approval by the New Mexico Oil Conservation Division.
- 4. Surface disturbance beyond the existing pad must have prior approval.
- 5. A closed loop system is required. The operator shall properly dispose of drilling/circulating contents at an authorized disposal site. Tanks are required for all operations, no excavated pits.
- 6. Functional H_2S monitoring equipment shall be on location.
- 7. A minimum of 3000 (3M) BOPE shall be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (3M) Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.

- 8. All waste (i.e. trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 9. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 10. Submit subsequent sundry required detailing work done and completion report for the new formation. Operator to include well plat and well bore schematic of current well condition when work is complete.

JAM 050713

. ...