Submit 1 Copy To Appropriate District Office District I - (575) 393-6161State of New Mexico Energy, Minerals and Natural Resources1625 N. French Dr., Hobbs, NM 88240HOBBS OCTL District II - (575) 748-1283 District III - (575) 748-1283 District III - (505) 334-6178HOBBS OCTL I 220 South St. Francis Dr. Santa Fe, NM 875051000 Rio Brazos Rd., Aztec, NM 874UN 12 2013 District IV - (505) 476-34601220 South St. Francis Dr. Santa Fe, NM 87505		Form C-103 October 13, 2009
		API NO.
		-10543
		cate Type of Lease
		e Oil & Gas Lease No.
SUNDRY NOCHOS AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		e Name or Unit Agreement Name
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other TA ini		l Number `005
2. Name of Operator		RID Number
PROVIDENCE ENERGY SERVICES, INC. dba KELTON OPERATING 3. Address of Operator		ol name or Wildcat
P.O. BOX 928, ANDREWS, TEXAS 79714-0928		LIE MATTIX (37240)
4. Well Location		
Unit Letter F : 1980 feet from the NORTH line and 2310 feet from the WEST line		
Section 32 Township 22S Range 37E NMPM LEA County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
11. Elevation (Snow whether DR, RKD, RT, GR, etc.)		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
	ERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING EMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB		
DOWNHOLE COMMINGLE		
OTHER:	OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
proposed completion or recompletion. 1. MIRU plugging equipment.		
2. Tag CIBP @3,550' ~		
3. Circulate hole with mud laden fluid 🖌		
4. Spot 25 sx cement @ 2630-2380 WOC & Tag. (Btm of Salt) Spot Crwt. from 2600 to 1400 WOC 5. Spot 25 sx cement @ 2630-2380 WOC & Tag. (Btm of Salt) Spot Crwt. from 2600 to 1400 WOC 6. Spot 25 sx cement @ 1450-1200 WOC & Tag. (top of Salt) Perf @ 1350'. 597 w/255X. WOC 7. Spot 65 sx cement @ 360-surface.		
6. Spot 25 sx-coment @ 1450-1200 WOC & Tag. (top of Salthe D D D D D D D D D D D D D D D D D D D		
7. Spot 65 sx-cement @ 360-surface Pert @ 1350. SUF W/23SN. WUC		
8. Cut off wellhead and install dry hole marker. Oper 370', Circ Chut to Surface		
* This well is in the R.5003 area. Comput required across entire salt		
Spud Date: Rig Release I		Section.
	Jacc.	
The set of	···· C 1 ··· 1 1 ··· 11 1	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
		11 13
SIGNATURETITLE		DATE 6-11-13
Type or print name E-mail addres	s:	PHONE:
For State Use Only	/ -	/
APPROVED BY: Conditions of Approval (if any):		
	Form provided by Forme On	-A-Disk · (214) 340-9429 · FormsOnADisk.com
Oil Conservation Division - Hobbs office: Must be Notified 24 hours prior to the beginning of Plugging Operations begin.	Tom provided by Forms Of	
		JUN 1 3 20 🕅

Kelton Operating Corporation - WELL DIAGRAM



