Office	o Appropriate District	State of New Mexico	Form C-103
<u>District I</u> – (575)	393-6161	Energy, Minerals and Natural Resources	Revised August 1, 2011
1625 N. French I	Or., Hobbs, NM 88240	cO	WELL API NO. 30-025-05437
811 S. First St., A	Artesia, NM 88210	SOOTL CONSERVATION DIVISION	5. Indicate Type of Lease
<u>District III</u> – (505	5) 334-6178 Rd. Aztec. NM 87410	Energy, Minerals and Natural Resources  Solution Division  Santa Fe, NM 87505	STATE  FEE
District IV - (505	5) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Franc 87505	is Dr., Santa Fe, NM	Sooil CONSERVATION DIVISION  1,21,20,1,220 South St. Francis Dr.  Santa Fe, NM 87505	
	SUNDRY NOTIC	ES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE T	HIS FORM FOR PROPOSA	LS TO DRILL OR TO DEEPEN OR RUNG BACK TO A	North Hobbs (G/SA) Unit
PROPOSALS.)	SERVOIR. USE "APPLICA	TION FOR PERMIT" (FORM C-101) FOR SUCH	Section 13
1. Type of W	ell: Oil Well 🔲 G	as Well Other Injector	8. Well Number 141
2. Name of O	-		9. OGRID Number: 157984
Occidental Pe		HORDEOCD	10. D. L. Will (0/04)
3. Address of	Operator  Obenver City, TX 7932	<b>Q</b> 50	10. Pool name or Wildcat Hobbs (G/SA)
4. Well Locat			
		See See Alexander Court Line and CO	Seat Seem the West line
		feet from the Sorth line and 660	<del></del>
Secti		Township 18S Range 37  11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
		3664' GL	
Configuration (Company)	m 1. 2. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.	3004 GE	
	12. Check Ap	propriate Box to Indicate Nature of Notice	, Report or Other Data
	NOTIOE OF INT	ENTION TO:	OCCOLIENT DEPORT OF
DEDEODM DI	NOTICE OF INT EMEDIAL WORK ⊠	ENTION TO: SUBPLUG AND ABANDON ☐ REMEDIAL WO	BSEQUENT REPORT OF:  RK
		_ ,	RILLING OPNS. P AND A
PULL OR ALT	<del></del>	MULTIPLE COMPL CARCHE	AT TOB: 1.
DOWNHOLE	<del></del>	_ to ondergr	ound Injection Control Program Manual
		11.0 C 1 a	CAUL SHAll he set within an last the
OTHER:		ed operations. (Clearly state all pertinent details, a	iibbermoet inication
13 Deceri	the proposed or complet	od oporatione. ((`loorly etato all portinent detäileta	
of star	ting any proposed work	SEE PLUE 10.15.7.14 NMAC. For Multiple Co	muletions: Attach wellhore diagram of
of star	ting any proposed work	). SEE RULE 19.15.7.14 NMAC. For Multiple Co	ompletions: Attach wellbore diagram of
of star	ting any proposed work sed completion or recon	). SEE RULE 19.15.7.14 NMAC. For Multiple Co	ompletions: Attach wellbore diagram of
of star propos	ting any proposed work sed completion or recon	). SEE RULE 19.15.7.14 NMAC. For Multiple Co	ompletions: Attach wellbore diagram of
of star propos	ting any proposed work sed completion or recon	). SEE RULE 19.15.7.14 NMAC. For Multiple Co	ompletions: Attach wellbore diagram of
of star propos 1) POOL 2) Clean	ting any proposed work sed completion or recond with inj equip.  Out to 4230'	). SEE RULE 19.15.7.14 NMAC. For Multiple Co	MECEINED Attach wellbore diagram of
of star propos 1) POOH 2) Clean 3) PB w/	ting any proposed work sed completion or reconstant with inj equip. out to 4230' CIBP at 4222'	). SEE RULE 19.15.7.14 NMAC. For Multiple Co	ompletions: Attach wellbore diagram of
of star propos 1) POOH 2) Clean 3) PB w/ 4) Sqz pe	ting any proposed work sed completion or recond with inj equip.  Out to 4230'	). SEE RULE 19.15.7.14 NMAC. For Multiple Conpletion.	MECEINED  NON \$ 1 5013
of star propose 1) POOH 2) Clean 3) PB w/ 4) Sqz pe 5) Drill co 6) Acid t	ting any proposed worksed completion or reconstant injequip. Out to 4230' CIBP at 4222' Perfs at 3962-4217' Out sqz. Deepen to 4365' reat with 2000 gal	). SEE RULE 19.15.7.14 NMAC. For Multiple Conpletion.	MECEINED Attach wellbore diagram of
of star propose 1) POOH 2) Clean 3) PB w/ 4) Sqz pe 5) Drill co 6) Acid to 7) RIH w	ting any proposed worksed completion or reconstant in the sed completion or reconstant in the sed completion of the sed completion of the sed complete in the sed comp	). SEE RULE 19.15.7.14 NMAC. For Multiple Conpletion.	MECEINED  NON \$ 1 5013
of star propose 1) POOH 2) Clean 3) PB w/ 4) Sqz pe 5) Drill co 6) Acid to 7) RIH w	ting any proposed worksed completion or reconstant injequip. Out to 4230' CIBP at 4222' Perfs at 3962-4217' Out sqz. Deepen to 4365' reat with 2000 gal	). SEE RULE 19.15.7.14 NMAC. For Multiple Conpletion.	MECEINED  NON \$ 1 5013
of star propose 1) POOH 2) Clean 3) PB w/ 4) Sqz pe 5) Drill co 6) Acid to 7) RIH w	ting any proposed work sed completion or reconstant with inj equip. Out to 4230' CIBP at 4222' erfs at 3962-4217' out sqz. Deepen to 4365 reat with 2000 gal with dual injection pkrs in well to injection	.). SEE RULE 19.15.7.14 NMAC. For Multiple Conpletion.	MECEINED  NON \$ 1 5013
of star propose 1) POOH 2) Clean 3) PB w/ 4) Sqz pe 5) Drill co 6) Acid to 7) RIH w	I with inj equip. Out to 4230' CIBP at 4222' erfs at 3962-4217' out sqz. Deepen to 4363' reat with 2000 gal with dual injection pkrs in well to injection	). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.	WECEINED  NOW & I Sol3  HOBBS OCD
of star propose 1) POOH 2) Clean 3) PB w/ 4) Sqz pe 5) Drill c 6) Acid t 7) RIH w 8) Return	I with inj equip. Out to 4230' CIBP at 4222' erfs at 3962-4217' out sqz. Deepen to 4365' reat with 2000 gal with dual injection pkrs in well to injection  The Oil Conservation	ation Division  Co	SECEINED  WHOERS OCD  Attach wellbore diagram of the completions: Attach wellbore diagram of the complete of t
of star propose 1) POOH 2) Clean 3) PB w/ 4) Sqz pe 5) Drill c 6) Acid t 7) RIH w 8) Return	I with inj equip. Out to 4230' CIBP at 4222' erfs at 3962-4217' out sqz. Deepen to 4365' reat with 2000 gal with dual injection pkrs in well to injection  The Oil Conservation	ation Division  Co	CD Hobbs office?
of star propose 1) POOH 2) Clean 3) PB w/ 4) Sqz pe 5) Drill c 6) Acid t 7) RIH w 8) Return	I with inj equip. Out to 4230' CIBP at 4222' erfs at 3962-4217' out sqz. Deepen to 4365' reat with 2000 gal with dual injection pkrs in well to injection  The Oil Conservation	ation Division  Co	CD Hobbs office?
of star propose 1) POOH 2) Clean 3) PB w/ 4) Sqz pe 5) Drill c 6) Acid t 7) RIH w 8) Return	I with inj equip. Out to 4230' CIBP at 4222' erfs at 3962-4217' out sqz. Deepen to 4363' reat with 2000 gal with dual injection pkrs in well to injection	ation Division  Co	SECEINED  WHOERS OCD  Attach wellbore diagram of the completions: Attach wellbore diagram of the complete of t
of star proposed for proposed f	I with inj equip. Out to 4230' CIBP at 4222' erfs at 3962-4217' out sqz. Deepen to 4365' reat with 2000 gal with dual injection pkrs in well to injection  The Oil Conserv  MUST BE NOTE  Prior to the beginni	Cation Division  FIED 24 Hours  Rig Release Date:  Prior	CD Hobbs office ?
of star proposed for proposed f	I with inj equip. Out to 4230' CIBP at 4222' erfs at 3962-4217' out sqz. Deepen to 4365' reat with 2000 gal with dual injection pkrs in well to injection  The Oil Conserv  MUST BE NOTE  Prior to the beginni	ation Division  Co	CD Hobbs office ?
of star proposed for proposed f	I with inj equip. Out to 4230' CIBP at 4222' erfs at 3962-4217' out sqz. Deepen to 4365' reat with 2000 gal with dual injection pkrs in well to injection  The Oil Conserv  MUST BE NOTE  Prior to the beginni	Cation Division  FIED 24 Hours  Rig Release Date:  Prior	CD Hobbs office ?
of star proposed for proposed f	I with inj equip. Out to 4230' CIBP at 4222' erfs at 3962-4217' out sqz. Deepen to 4365' reat with 2000 gal with dual injection pkrs in well to injection  The Oil Conserv  MUST BE NOTE  Prior to the beginni	Cation Division  FIED 24 Hours  Rig Release Date:  Prior	CD Hobbs office ?
of star propose  1) POOH 2) Clean 3) PB w/ 4) Sqz pe 5) Drill co 6) Acid to 7) RIH w 8) Return  Spud Date:	I with inj equip. out to 4230' CIBP at 4222' erfs at 3962-4217' out sqz. Deepen to 4365 reat with 2000 gal with dual injection pkrs in well to injection  The Oil Conserv MUST BE NOTE  Prior to the beginni  that the information ab	Completion.  Completion.  Completion.  Completion.  Complete D24 Hours  Rig Release Date:  prior  ove is true and complete to the best of my knowled  TITLE_Well Analyst DATE	and belief.  Attach wellbore diagram of CHAED I & NOT CHAED SEBOH  Indition of Approval: notify  CD Hobbs office ? Chart  ge and belief.
of star propose  1) POOH 2) Clean 3) PB w/ 4) Sqz pe 5) Drill c 6) Acid t 7) RIH w 8) Return  Spud Date:  I hereby certify  SIGNATURE_  Type or print na	I with inj equip. Out to 4230' CIBP at 4222' erfs at 3962-4217' out sqz. Deepen to 4365 reat with 2000 gal with dual injection The Oil Conserve MUST BE NOTE Prior to the beginni	Completion.  Completion  Complete D 24 Hours  Rig Release Date:  Prior  Ove is true and complete to the best of my knowled	and belief.  Attach wellbore diagram of CHAED I & NOT CHAED SEBOH  Indition of Approval: notify  CD Hobbs office ? Chart  ge and belief.
of star propose  1) POOH 2) Clean 3) PB w/ 4) Sqz pe 5) Drill co 6) Acid to 7) RIH w 8) Return  Spud Date:	I with inj equip. Out to 4230' CIBP at 4222' erfs at 3962-4217' out sqz. Deepen to 4365 reat with 2000 gal with dual injection The Oil Conserve MUST BE NOTE Prior to the beginni	Completion.  Completion.  Completion.  Completion.  Complete D24 Hours  Rig Release Date:  prior  ove is true and complete to the best of my knowled  TITLE_Well Analyst DATE	and belief.  Attach wellbore diagram of CHAED I & NOT CHAED SEBOH  Indition of Approval: notify  CD Hobbs office ? Chart  ge and belief.
of star propose  1) POOH 2) Clean 3) PB w/ 4) Sqz pe 5) Drill c 6) Acid t 7) RIH w 8) Return  Spud Date:  I hereby certify  SIGNATURE_  Type or print na	I with inj equip. Out to 4230' CIBP at 4222' erfs at 3962-4217' out sqz. Deepen to 4363' reat with 2000 gal with dual injection The Oil Conserv MUST BE NOTE Prior to the beginni that the information ab	Completion.  Completion.  Completion.  Completion.  Complete D24 Hours  Rig Release Date:  prior  ove is true and complete to the best of my knowled  TITLE_Well Analyst DATE	and belief.  Attach wellbore diagram of CHAED I & NOT CHAED SEBOH  Indition of Approval: notify  CD Hobbs office ? Chart  ge and belief.
of star propose  1) POOH- 2) Clean 3) PB w/ 4) Sqz pe 5) Drill co 6) Acid to 7) RIH w 8) Return  Spud Date:  I hereby certify  SIGNATURE_ Type or print not For State Use of APPROVED B	I with inj equip. Out to 4230' CIBP at 4222' erfs at 3962-4217' out sqz. Deepen to 4363' reat with 2000 gal with dual injection The Oil Conserv MUST BE NOTE Prior to the beginni that the information ab	Completion.  Completion.  Completion.  Completion.  Complete D24 Hours  Rig Release Date:  prior  ove is true and complete to the best of my knowled  TITLE_Well Analyst DATE	million of Approval: notify  CD Hobbs office ?4  Of runn: Chart  ge and belief.  PHONE: 806-592-6287
of star propose  1) POOH- 2) Clean 3) PB w/ 4) Sqz pe 5) Drill co 6) Acid to 7) RIH w 8) Return  Spud Date:  I hereby certify  SIGNATURE_ Type or print not For State Use of APPROVED B	I with inj equip. Out to 4230' CIBP at 4222' erfs at 3962-4217' out sqz. Deepen to 4363' reat with 2000 gal with dual injection  The Oil Conserv MUST BE NOTI  Prior to the beginni  that the information ab	Completion.  Completion.  Completion.  Completion.  Complete D24 Hours  Rig Release Date:  prior  ove is true and complete to the best of my knowled  TITLE_Well Analyst DATE	million of Approval: notify  CD Hobbs office ?4  Of runn: Chart  ge and belief.  PHONE: 806-592-6287