Submit 1 Copy To Appropriate District	State of New Mexico	Form C-103
District I – (575) 393-6161	State of New Mexico CEnergy, Minerals and Natural Res	Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240 (5)2	Alm	WELL API NO. 30-025-28164
District I – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 1220 S. St. Francis Dr., Santa Fe, NM		5. Indicate Type of Lease
District III - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis D	r. STATE X FEE
<u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	BECA	LG-1546-0004/0005
· ·	ES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		,
PROPOSALS.)		State MX No. 1 8. Well Number 1
	Well Other	
2. Name of Operator Lawson Opera	ting, LLC	9. OGRID Number 270358
3. Address of Operator		10. Pool name or Wildcat
P O Box 52667, Midland, TX 79710		55610-Schrab Bone Spring
4. Well Location		
Unit Letter A 10:660 feet from the North line and 710 feet from the West line		
Section 15 Township 19S Range 35E NMPM Lea County		
	11. Elevation (Show whether DR, RKB,	RT, GR, etc.)
	3783.3' GR	
12 Ch - 1- A		-CNI-C Donato Otto Dete
12. Check A	opropriate Box to Indicate Nature	of Notice, Report or Other Data
NOTICE OF INT	ENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK X		EDIAL WORK
TEMPORARILY ABANDON		MENCE DRILLING OPNS. P AND A
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL CASI	NG/CEMENT JOB
DOWNHOLE COMMINGLE	}	
OTHER:	□ ОТНЕ	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
proposed completion or recompletion.		
Pull out of hole with production equipment		
Run bridge plug on wireline and set at 9450' dump 20' of cement on bridge plug		
Perforate 9336'-9356' with 2 JSPF		
RIH with packer on tubing and acidize new perforations with 7 ½% acid and ball sealers Fracture stimulate new perforations via 2 7/8" tubing-single stage-estimated 36,000 gallons and 75,000 pounds proppant		
Flow well down and clean out past new perforations		
Return well to production.		
Spud Date:	Rig Release Date:	
<u> </u>		
I hereby certify that the information al	pove is true and complete to the best of m	y knowledge and belief.
[1][[1		
SIGNATURE/ KM	TITLE Manager	DATE 7-5-13
	TILDS Manager	DIVID 1-0-10
Type or print name Phillip Lawson	E-mail address: pllay	vson@aol.com PHONE: 432-556-0797
For State Use Only		
APPROVED BY	TITLE DIST	MGZ DATE 7-9-2013
Conditions of Approval (if any)	11111	DAIL / DA

JUL 0 9 2013