

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
October 13, 2009

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-09052
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator LINN OPERATING, INC.		6. State Oil & Gas Lease No.
3. Address of Operator 600 TRAVIS, SUITE 5100, HOUSTON, TEXAS 77002		7. Lease Name or Unit Agreement Name SEVEN RIVERS QUEEN UNIT
4. Well Location Unit Letter <u>B</u> ; <u>660</u> feet from the <u>N</u> line and <u>1980</u> feet from the <u>E</u> line Section <u>27</u> Township <u>22S</u> Range <u>36E</u> NMPM LEA County		8. Well Number: <u>2</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) GL 3512		9. OGRID Number <u>269324</u>
		10. Pool name or Wildcat Langlie Mattix; 7 Rvrs-Q-Grybg

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A
CASING/CEMENT JOB ☐

OTHER:

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. MIRU plugging equipment.
2. ND wellhead and NU BOP.
3. RIH and tag CIBP w/ cmt. @ 3600. Circulate hole with mud laden fluid.
4. Spot 25 sx @ 3000'. (Base of Salt)
5. Spot 25 sx @ 1450'. (Top of Salt)
6. Perf & Sqz. 100 sx @ 310' to surface.
7. Cut off wellhead and weld on Dry Hole Marker.

The use of a closed loop system will be used with steel pit.

HOBBS OCD

AUG 15 2013

RECEIVED

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE: Laura A Moreno TITLE: REG. COMPLIANCE ADVISOR DATE: AUG. 14, 2013

Type or print name: LAURA A MORENO
For State Use Only

E-mail address: lmoreno@linnenergy.com

PHONE: 713-904-6657

APPROVED BY: [Signature] TITLE: DIST MGR DATE: 8-21-2013
Conditions of Approval (if any):

AUG 21 2013

OIL CONSERVATION DIVISION - Hobbs office Must Be Notified
24 hours prior to the beginning of Plugging Operations.

