

Submit 1 Copy To Appropriate District Office

District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
August 1, 2011

FEB 04 2014

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.

RECEIVED

Santa Fe, NM 87505

WELL API NO.

30-025-01535

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Caprock Maljamar Unit

8. Well Number 092

9. OGRID Number

269324

10. Pool name or Wildcat

Maljamar; Grybg-San Andres

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Linn Operating, Inc.

3. Address of Operator

600 Travis, Ste. 5100, Houston, Texas 77002

4. Well Location

Unit Letter G : 1980 feet from the N line and 1980 feet from the E line

Section 28 Township 17S Range 33E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Proposed P&A Procedure

1. MIRU plugging equipment. NU BOP

2. RIH w/ tbg and tag CIBP @ 4090'. Circulate hole w/ mud laden fluid. Spot 25 sx cement on top of CIBP.

3. Perf 5 1/2 @ 2560' and Sqz. 25 sx cement and displace to 2460. (Btm of Salt)

4. Perf 5 1/2 @ 1550 and Sqz. 45 sx cement and displace to 1450. WOC & Tag. (Top of Salt)

5. Perf 5 1/2 @ 400' and Sqz. 145 sx cement and circulate to surface.

6. Cut off wellhead and weld on Dry Hole Marker.

*Use close loop system to circulate into

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ben Montgomery TITLE Agent DATE 2-3-14

Type or print name Ben Montgomery E-mail address: benmontgomery@bmaandassociates.com PHONE: 432-580-7161

APPROVED BY: Mahe Brown TITLE Compliance Officer DATE 2/7/2014

Conditions of Approval (if any)

OIL CONSERVATION DIVISION - Hobbs office **Must Be Notified**
24 hours prior to the beginning of Plugging Operations.

Form provided by Forms On-A-Disk - (214) 340-9429 - FormsOnADisk.com

FEB 10 2014

