Submit 1 Copy To Appropriate District Office State of New Mexico	Form C-103
<u>District I</u> Energy, Minerals and Natural Resources	October 13, 2009
1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Ave. Artesia. NM 88210 OIL CONSERVATION DIVISION	WĒLL API NO. 30-025-04360
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410 JAN 2 3 2014 220 South St. Francis Dr. Santa Fe, NM 87505	STATE X FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No.
87505	32213
SUNDRY NOTIFICAL SUNDRY	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	State E-28
PROPOSALS.) 1. Type of Well: Oil Well Gaş Well Other	8. Well Number 2
2. Name of Operator	9. OGRID Number
Finley Resources Inc	180387 /
3. Address of Operator	10. Pool name or Wildcat
1308 Lake Street Fort Worth, TX 76102	Eumont:Yates-7rivers
4. Well Location	1980 feet from the W line
Unit Letter K : 1980 feet from the S line and	
Section 28 Township 20S Range 36E 11. Elevation (Show whether DR, RKB, RT, GR,	
3.624.GL	
12. Check Appropriate Box to Indicate Nature of Not	ce, Report or Other Data
NOTICE OF INTENTION TO	UBSEQUENT REPORT OF:
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL V	
	DRILLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEM	MENT JOB
DOWNHOLE COMMINGLE	
OTHER: OTHER:	. –
13. Describe proposed or completed operations. (Clearly state all pertinent details	
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple	
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion.	
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 1. RU - Drill out cement plug 516' to 950'.	Completions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion.	Completions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 1. RU - Drill out cement plug 516' to 950'. 2. Circulate and clean out to CIBP @ 3800'. Dril PBTD @ 3935'.	Completions: Attach wellbore diagram of led out CIBP and cleaned out to
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 1. RU - Drill out cement plug 516' to 950'. 2. Circulate and clean out to CIBP @ 3800'. Dril	Completions: Attach wellbore diagram of led out CIBP and cleaned out to psi, tested good.
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 1. RU - Drill out cement plug 516' to 950'. 2. Circulate and clean out to CIBP @ 3800'. Drill PBTD @ 3935'. 3. RIH w/ pkr, set @ 3788'. Test casing to 500	Completions: Attach wellbore diagram of led out CIBP and cleaned out to psi, tested good. back 95 bbls fluid. TOOH w/pkr.
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 1. RU - Drill out cement plug 516' to 950'. 2. Circulate and clean out to CIBP @ 3800'. Drill PBTD @ 3935'. 3. RIH w/ pkr, set @ 3788'. Test casing to 500 4. Acidized perfs w/ 1500 gals 15% HCl. Swabbed	Completions: Attach wellbore diagram of led out CIBP and cleaned out to psi, tested good. back 95 bbls fluid. TOOH w/pkr.
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 1. RU - Drill out cement plug 516' to 950'. 2. Circulate and clean out to CIBP @ 3800'. Drill PBTD @ 3935'. 3. RIH w/ pkr, set @ 3788'. Test casing to 500 4. Acidized perfs w/ 1500 gals 15% HCl. Swabbed	Completions: Attach wellbore diagram of led out CIBP and cleaned out to psi, tested good. back 95 bbls fluid. TOOH w/pkr.
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 1. RU - Drill out cement plug 516' to 950'. 2. Circulate and clean out to CIBP @ 3800'. Drill PBTD @ 3935'. 3. RIH w/ pkr, set @ 3788'. Test casing to 500 4. Acidized perfs w/ 1500 gals 15% HCl. Swabbed	Completions: Attach wellbore diagram of led out CIBP and cleaned out to psi, tested good. back 95 bbls fluid. TOOH w/pkr.
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 1. RU - Drill out cement plug 516' to 950'. 2. Circulate and clean out to CIBP @ 3800'. Drill PBTD @ 3935'. 3. RIH w/ pkr, set @ 3788'. Test casing to 500 4. Acidized perfs w/ 1500 gals 15% HCl. Swabbed	Completions: Attach wellbore diagram of led out CIBP and cleaned out to psi, tested good. back 95 bbls fluid. TOOH w/pkr.
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 1. RU - Drill out cement plug 516' to 950'. 2. Circulate and clean out to CIBP @ 3800'. Drill PBTD @ 3935'. 3. RIH w/ pkr, set @ 3788'. Test casing to 500 4. Acidized perfs w/ 1500 gals 15% HCl. Swabbed	Completions: Attach wellbore diagram of led out CIBP and cleaned out to psi, tested good. back 95 bbls fluid. TOOH w/pkr.
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 1. RU - Drill out cement plug 516' to 950'. 2. Circulate and clean out to CIBP @ 3800'. Drill PBTD @ 3935'. 3. RIH w/ pkr, set @ 3788'. Test casing to 500 4. Acidized perfs w/ 1500 gals 15% HCl. Swabbed	Completions: Attach wellbore diagram of led out CIBP and cleaned out to psi, tested good. back 95 bbls fluid. TOOH w/pkr.
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 1. RU - Drill out cement plug 516' to 950'. 2. Circulate and clean out to CIBP @ 3800'. Drill PBTD @ 3935'. 3. RIH w/ pkr, set @ 3788'. Test casing to 500 4. Acidized perfs w/ 1500 gals 15% HCl. Swabbed 4. RIH w/ tbg and pump. Restored to production.	Completions: Attach wellbore diagram of led out CIBP and cleaned out to psi, tested good. back 95 bbls fluid. TOOH w/pkr.
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 1. RU - Drill out cement plug 516' to 950'. 2. Circulate and clean out to CIBP @ 3800'. Drill PBTD @ 3935'. 3. RIH w/ pkr, set @ 3788'. Test casing to 500 4. Acidized perfs w/ 1500 gals 15% HCl. Swabbed 4. RIH w/ tbg and pump. Restored to production. Spud Date: Rig Release Date:	Completions: Attach wellbore diagram of led out CIBP and cleaned out to psi, tested good. back 95 bbls fluid. TOOH w/pkr.
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 1. RU - Drill out cement plug 516' to 950'. 2. Circulate and clean out to CIBP @ 3800'. Drill PBTD @ 3935'. 3. RIH w/ pkr, set @ 3788'. Test casing to 500 4. Acidized perfs w/ 1500 gals 15% HCl. Swabbed 4. RIH w/ tbg and pump. Restored to production.	Completions: Attach wellbore diagram of led out CIBP and cleaned out to psi, tested good. back 95 bbls fluid. TOOH w/pkr.
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 1. RU - Drill out cement plug 516' to 950'. 2. Circulate and clean out to CIBP @ 3800'. Drill PBTD @ 3935'. 3. RIH w/ pkr, set @ 3788'. Test casing to 500 4. Acidized perfs w/ 1500 gals 15% HCl. Swabbed 4. RIH w/ tbg and pump. Restored to production.	Completions: Attach wellbore diagram of led out CIBP and cleaned out to psi, tested good. back 95 bbls fluid. TOOH w/pkr.
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 1. RU - Drill out cement plug 516' to 950'. 2. Circulate and clean out to CIBP @ 3800'. Drill PBTD @ 3935'. 3. RIH w/ pkr, set @ 3788'. Test casing to 500 4. Acidized perfs w/ 1500 gals 15% HCl. Swabbed 4. RIH w/ tbg and pump. Restored to production. Spud Date: Rig Release Date:	Completions: Attach wellbore diagram of led out CIBP and cleaned out to psi, tested good. back 95 bbls fluid. TOOH w/pkr.
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 1. RU - Drill out cement plug 516' to 950'. 2. Circulate and clean out to CIBP @ 3800'. Drill PBTD @ 3935'. 3. RIH w/ pkr, set @ 3788'. Test casing to 500 4. Acidized perfs w/ 1500 gals 15% HCl. Swabbed 4. RIH w/ tbg and pump. Restored to production. Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my know SIGNATURE A. D. W. Mer. TITLE Regulatory Ana	Completions: Attach wellbore diagram of led out CIBP and cleaned out to psi, tested good. back 95 bbls fluid. TOOH w/pkr. 01/07/14 ledge and belief.
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 1. RU - Drill out cement plug 516' to 950'. 2. Circulate and clean out to CIBP @ 3800'. Drill PBTD @ 3935'. 3. RIH w/ pkr, set @ 3788'. Test casing to 500 4. Acidized perfs w/ 1500 gals 15% HCl. Swabbed 4. RIH w/ tbg and pump. Restored to production. Spud Date: Rig Release Date: Thereby certify that the information above is true and complete to the best of my known and the state of the set of my known and the state of the set of my known and the set o	Completions: Attach wellbore diagram of led out CIBP and cleaned out to psi, tested good. back 95 bbls fluid. TOOH w/pkr. Oloo/IU ledge and belief. Lyst DATE inleyresources.com PHONE: 817-231-8735
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 1. RU - Drill out cement plug 516' to 950'. 2. Circulate and clean out to CIBP @ 3800'. Drill PBTD @ 3935'. 3. RIH w/ pkr, set @ 3788'. Test casing to 500 4. Acidized perfs w/ 1500 gals 15% HCl. Swabbed 4. RIH w/ tbg and pump. Restored to production. Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my know SIGNATURE A. D. W. Mer. TITLE Regulatory Ana	Completions: Attach wellbore diagram of led out CIBP and cleaned out to psi, tested good. back 95 bbls fluid. TOOH w/pkr. Oloo/IU ledge and belief. Lyst DATE inleyresources.com PHONE: 817-231-8735
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 1. RU - Drill out cement plug 516' to 950'. 2. Circulate and clean out to CIBP @ 3800'. Drill PBTD @ 3935'. 3. RIH w/ pkr, set @ 3788'. Test casing to 500 4. Acidized perfs w/ 1500 gals 15% HCl. Swabbed 4. RIH w/ tbg and pump. Restored to production. Spud Date: Rig Release Date: Thereby certify that the information above is true and complete to the best of my known and the state of the set of my known and the state of the set of my known and the set o	Completions: Attach wellbore diagram of led out CIBP and cleaned out to psi, tested good. back 95 bbls fluid. TOOH w/pkr. 01/07/14 ledge and belief. DATE inleyresources.com PHONE: 817-231-8735