Submit 1 Copy To Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources	Form C-103 Revised July 18, 2013
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, witherars and Natural Resources	WELL API NO.
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	30-025-23427
<u>District III</u> - (505) 334-6178	1220 South St. Francis Dr.	5. Indicate Type of Lease STATE FEE STATE
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM		
87505 SUNDRY NOTICE	ES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		East Pearl Queen Unit
1. Type of Well: Oil Well Gas Well Other		8. Well Number 59
2. Name of Operator State of NM formerly Xeric Oil & Gas Corp.		9. OGRID Number
3. Address of Operator		10. Pool name or Wildcat
1625 N French Drive Hobbs, NM 88240		Pearl Queen
4. Well Location Unit Letter H: 2735 feet from the South line and 1300 feet from the East line		
Unit Letter H : 2735 feet from the South line and 1300 feet from the East line Section 27 Township 19S Range 35E NMPM County Lea		
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
The Elevation (Snow whemer BK, KKB, KF, OK, etc.)		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A		
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB DOWNHOLE COMMINGLE		
CLOSED-LOOP SYSTEM		
OTHER:	OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
•	Plugging Services.	
5-23-13 GIH w/ tbg. Tag at 4206'. Spot 25 sx. WOC. Tag at 3920'. Circ		
, 3		
hole w/ mud laden fluid. POOH to 3397' Spot 25 sx. WOC.		
5-24-13 Tag at 3203'. Perf at 1750'. Sqz w/ 25 sx cmt. WOC. Tag 1718'.		
Spot 25 sx cmt at 1718'. WOC.		
5-25-13 Tag at 1463'. Perf at 455'. Sqz w/ 130 sx cmt. Circ cmt to		
surface inside/outside 5 1/2" csg.		
5-28-13 Top csg off w/ cmt. RDMO. Install dry hole marker.		
Spud Date:	Rig Release Date:	
Spud Date.	Rig Release Date.	·
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
\sim \sim \sim \sim \sim \sim \sim		
SIGNATURE Wall hitaly TITLE Compliance Officer DATE 02/13/2014		
Type or print name	E-mail address:	PHONE:
For State Use Only AA (OV)		
APPROVED BY: Mayer Stown TITLE Compliance Office DATE 2/14/2014 ON		
Conditions of Approval (if any):		
V		, P.

DATE 2/14/2014 PM FEB 18 2014