State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERVA	ATION DIVISION		Revised 3-27-2004
DISTRICT I 1625 N. French Dr. , Hobbs, NM 88240	1220 South St. Francis Dr. Santa Fe, NM 87505		WELL API NO. 30-025-05479	
<u>DISTRICT II</u>	Santa 1 c,	1441 07505	5. Indicate Type of Lease	
1301 W. Grand Ave, Artesia, NM 88210			STATE X	FEE
DISTRICT III			6. State Oil & Gas Lease No.	
1000 Rio Brazos Rd, Aztec, NM 87410			7. Lease Name or Unit Agreement Name	
SUNDRY NOTICES AND REPORTS ON WELLS			1	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)			NORTH HOBBS (G/SA) UNIT	
1. Type of Well:			8. Well No. 412	
Oil Well X	Gas Well Other			
2. Name of Operator			9. OGRID No. 157984	
Occidental Permian Ltd. 3. Address of Operator			10. Pool name or Wildcat	HOBBS (G/SA)
1017 W. Stanolind Rd., HOBBS, NM	4 88240 505/397-82	200		110225 (6/5/1)
4. Well Location				
Unit Letter A : 330	Feet From The NORTH		et From The EAST	Line
Section 24	Township 18-S	Range 37-I	E NMPM	LEA County
	11. Elevation (Show whether DF, RKB, 3670 GL	RT GR, etc.)		
	3070 GL			
Pit or Below-grade Tank Application	or Closure			
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water				
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material				
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING	CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPNS	S. DLUG & A	BANDONMENT
PULL OR ALTER CASING	Multiple Completion	CASING TEST AND CEMENT	JOB	
OTHER: Deepen and run liner	X	OTHER:	<u> </u>	
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)				
SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
1. Deepen well to 4280' 2. Run liner to TD.				
3. Perforate and acid stimulate.				
4. Run Production equipment.				
4. Run Production equipment. This well is being returned to active production from a TA'd status with this work.				
This well is being returned to active production from a TA'd status with this work.				
			9 7 6.	87
				12
			S. A. C.	22
			18 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	S W
I hereby certify that the information above is true at	nd complete to the best of my knowledge and	d belief. I further certify that any pit	or below-grade tank has been/will t	pe constructed or
closed according to NMOCD guide in es	, a general permit	or an (attached) alternative	OCD-approved plan] 343/
SIGNATURE 4		TITLE Engineering Adv	visor DAT	12/0/6/05
TYPE OR PRINT NAME David Nelson	E-mail address:	EPRESENTATIVE II/STAI	TELEPHONE NO.	505-397-8200
For State Use Only	1 1 TELD R	EPRESENTATIVE WAT		00T 1 0 200E
APPROVED BY	LUNK	TITLE TITLE	FF MANAGER DA	QC [18 2005
CONDITIONS OF APPROVAL IF ANY	Mary .			