Submit 1 Copy To Appropriate District	State of New	Mexico	Form C-103	
District 1 - (575) 393-6161	Energy, Minerals and I	Natural Resources	Revised July 18, 2013	
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283			WELL API NO. 30-025-10109	
811 S. First St., Artesia, NM 88210	OIL CONSERVAT		5. Indicate Type of Lease	
District III – (505) 334-6178 1000 Río Brazos Rd., Aztec, NM 87410	1220 South St.		STATE FEE	
District IV - (505) 476-3460	Santa Fe, NM	А 87505	6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505				
SUNDRY NOT	TICES AND REPORTS ON WE	CLLS	7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROP DIFFERENT RESERVOIR. USE "APPL	DSALS TO DRILL OR TO DEEPEN O ICATION FOR PERMIT" (FORM C-10	R PLEGBACK TOA	Grizzell	
PROPOSALS.)	_		8. Well Number 003	
1. Type of Well: Oil Well 🗸	Gas Well [] Other	JUL 2 3 2014		
2. Name of Operator Apache Corporation	/		9. OGRID Number 873	
3. Address of Operator			10. Pool name or Wildcat	
303 Veterans Airpark Lane, Suite 1	000 Midland, TX 79705	RECEIVED	Penrose Skelly; GB (50350)	
4. Well Location	000			
Unit Letter P	feet from the	line and 660	feet from the East line	
Section 8	Township 22S	Range 37E	NMPM County Lea	
	11. Elevation (Show whether)	
	3399' GI			
12 Charle	Annuanista Day ta Indias	Noturo of Notico	Bonort or Other Date	
12. Check	Appropriate Box to Indicat	le Nature of Notice,	Report of Other Data	
NOTICE OF I	NTENTION TO:	SUE	SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK 🗌		REMEDIAL WOR		
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DR		
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	ТЈОВ 🗌 .	
	1			
CLOSED-LOOP SYSTEM	SE 🛛	OTHER:	П	
			d give pertinent dates, including estimated date	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of				
proposed completion or re	completion.			
Apache would like to TA the Graybur	g and RC in the Penrose, with p	ossible request to comm	ningle at a later date, per the attached procedure.	
			· · · · · · · · · · · · · · · · · · ·	
		·		
Spud Date: 10/9/1938	Rig Releas	e Date: 11/8/1938		
10/9/1938				
I hereby certify that the information	above is true and complete to t	he best of my knowledg	e and belief.	
Λ	1.1			
SIGNATURE KELSA Y	haha TITLE SE	Staff Reg Analyst	DATE 7/22/2014	
SIGNATORE 1 YOUGO J			DATE	
Type or print name Reesa Fisher	E-mail ad	dress: Reesa.Fisher@ap	achecorp.com PHONE: (432) 818-1062	
For State Use Only	No N			
ADDROVED BY, W BIOLVILLAND TO THE DIAT SUDATE 7170/2014				
Conditions of Approval (if any):		nor. nop	MULENDATE I COIT	
Conditions of Approval (It any):		I	JUL 2 9 2014	

r	A
\mathcal{I}	1.



Grizzell No. 3

API #: 30-025-10109 660 FSL, 660 FEL P Sec. 8 T-22S R-37E Lea County, New Mexico

TA – Grayburg Recomplete – Penrose Commingle – Penrose/Grayburg

____, 2014

Recommended Procedure:

Note: 5-1/2 14# casing set @ 3559. OH from 3559 to 3709.

TA GRAYBURG:

- 1. 48 hrs prior to rigging up, dump 2 drums paraffin solvent down csg. Circulate well for 24 hrs.
- 2. 24 hrs prior to rigging up, return well to production to battery.
- 3. MIRU PU. POOH w/ rods. Install BOP. TOH w/ 2 3/8" tbg.
- 4. PU & RIH w/ 4 ³/₄" Bit on 2-7/8" work string to +/-3559. POOH.
- 5. RIH w/ RBP. Set RBP above OH @ +/-3530. POOH.
- 6. RU WL. RIH w/ GRL/CBL/CCL to determine TOC and get on depth. Verify that TOC is above top of Penrose @ +/- 3425 by at least 100 feet (+/-3325) before perforating. *See attached "THE WESTERN COMPANY GAMMATRON GR/NL (4/2/1954).*

Recomplete in PENROSE:

- 7. RIH w/ perf gun and GRL. Perforate Penrose @ 3440, 3445, 3455, 3468, 3500 w/ 1spf (5 shots). **Perforations selected from "THE WESTERN COMPANY GAMMATRON GR/NL (4/2/1954)*.
- 8. RD WL. RIH 2-7/8" tbg and pkr. Set pkr @ +/- 3325.
- 9. Acidize Penrose (3440-3500) w/ 2000 gal 15% HCI-NE-FE BX DX acid in two stages. Use RCN balls as diverter. RIH and knock off balls.
- 10. Swab back load.
- 11. POOH.
- 12. RIH w/ production equipment. Set SN @ +/-3517 w/ retrieving head on tbg for RBP.
- 13. RD and MO rig. Put well on test.

Commingle (pending NMOCD_approval) PENROSE/GRAYBURG:

- 14. MIRU PU. POOH w/ rods. Install BOP. RIH and retrieve RBP w/ retrieving head on bottom of tbg. TOH w/ 2 3/8" tbg and RBP.
- RIH w/ production equipment to original configuration for Grayburg production. SN @ 3679.
 45 7/8" (1125') KD rods with four, 5' sub(s), and 100 3/4" (2500') KD rods. 1.5 x 26 polish rod.
- 16. RD and MO rig. Put well on test.



WELL DATA SHEET:



PROPOSED WELL DATA SHEET: