Office	State of New Me		Form C-1			
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		October 13, 2009 WELL API NO.			
District II	OH CONCEDIATION DIVISION		30-025-25558			
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis Dr.		5. Indicate Type of Lease STATE	•		
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505		6. State Oil & Gas Lease No.			
1220 S. St. Francis Dr., Santa Fe, NM 87505	87505		LG-2824			
SUNDRY NOT	ICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Nam	ė		
DIFFERENT RESERVOIR. USE "APPLIC	SALS TO DRILL OR TO DEEPEN OR PLI CATION FOR PERMIT" (FORM C-101) FO		State 28			
PROPOSALS.) 1. Type of Well: Oil Well	PROPOSALS.) 1. Type of Well: Oil Well Gas Well X Other SWD		8. Well Number 1			
2. Name of Operator New Mexico Salt Water Disposal Company, Inc.		mony Inc	9. OGRID Number			
3. Address of Operator P. O. Box 1518, Roswell, NM 88202-1518		15878 10. Pool name or Wildcat				
1: O. Box 1516, Roswell, 1017 66202-1516]			
4. Well Location		<u> </u>				
Unit Letter 1 :	1980 feet from the South	line and <u>66</u> ange 34É		ne		
Section 28	Township 10S Ra 11. Elevation (Show whether DR		NMPM Lea County			
	4,209' GR			3.55		
12 Charles	Ammonwioto Dov to Indianto N	(-tfNI-4:00 I	Domont on Othon Data			
	Appropriate Box to Indicate N					
			SEQUENT REPORT OF:			
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORTEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DR						
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT		.		
DOWNHOLE COMMINGLE						
OTHER: Recompletion		OTHER:				
13. Describe proposed or comp of starting any proposed we	ork). SEE RULE 19.15.7.14 NMA(give pertinent dates, including estimated apletions: Attach wellbore diagram of	date		
proposed completion or rec	-					
			2.3/8" tbg. Tag top of fish @ 5266'. Estal			
		Drill fiberglass tbg & fill to 6100'. Circ hole clean. Pump 100' cmt plug @ 6100'-6000'. Pull uphole. WOC. TIH @ tag plug no lower				
than 6000'. Close BOP. Pressure csg to 500# and hold for 30 min. If pressure is ok, TOH w/tbg, DC's, bit. If pressure drops pull BHA. Run pkr above cmt plug. Pressure test to 500# via tbg. If no pressure drop, find location of csg leak. Set pkr @ 5500' &						
				ps pull		
BHA. Run pkr above cm	t plug. Pressure test to 500# via the	. If no pressure drop,		ops pull 00' &		
BHA. Run pkr above cm pressure test csg/tbg to 50 5500'. TOH w/tbg, tools.	t plug. Pressure test to 500# via tbg 10#. If pressure doesn't hold isolate RUWL. TIH, correlate depth, peri	If no pressure drop, csg leak, repair and of f 2 spf @5588'-5602'	, find location of csg leak. Set pkr @ 550 drill out same. TIH w/scrapper, 3 1/2" bi '; 5614'-36'; 5640'-48'; 5652'-60'. Total o	ops pull 00' & t, tbg to f 108 holes.		
BHA. Run pkr above cm pressure test csg/tbg to 50 5500'. TOH w/tbg, tools. TOH & RDWL. TIH w/4	t plug. Pressure test to 500# via tbg 10#. If pressure doesn't hold isolate RUWL. TIH, correlate depth, peri 1 1/2" pkr, 2 3/8" tbg, set pkr @ 555	If no pressure drop, csg leak, repair and of 2 spf @5588'-5602' 0'. Acidize perfs w/s	, find location of csg leak. Set pkr @ 550 drill out same. TIH w/scrapper, 3 1/2" bi '; 5614'-36'; 5640'-48'; 5652'-60'. Total of 5000 gals 28% HCI acid spacing 80 BS's	ops pull 00' & t, tbg to f 108 holes. throughout		
BHA. Run pkr above cm pressure test esg/tbg to 50 5500'. TOH w/tbg, tools. TOH & RDWL. TIH w/4 job. Establish injection ra	t plug. Pressure test to 500# via the 10#. If pressure doesn't hold isolate RUWL. TIH, correlate depth, peri 11/2" pkr, 23/8" the, set pkr @ 555 ate & pressure. Pull BHA. TIH w/p	If no pressure drop, csg leak, repair and of 2 spf @5588'-5602' 0'. Acidize perfs w/s okr, on-off tool, 2 3/8	, find location of csg leak. Set pkr @ 550 drill out same. TIH w/scrapper, 3 1/2" bi '; 5614'-36'; 5640'-48'; 5652'-60'. Total of 5000 gals 28% HCI acid spacing 80 BS's 3" lined tbg. Set pkr @ 5550'. Sting off c	ops pull 00' & t, tbg to f 108 holes. throughout on-off tool.		
BHA. Run pkr above cm pressure test csg/tbg to 50 5500. TOH w/tbg, tools. TOH & RDWL. TIH w/4 job. Establish injection radius Displace csg/tbg annulus	t plug. Pressure test to 500# via the 10#. If pressure doesn't hold isolate RUWL. TIH, correlate depth, period 1/2" pkr., 2 3/8" the set pkr. @ 555 ate & pressure. Pull BHA. TIH w/rw/2% KCI wtr containing corrosion.	If no pressure drop, csg leak, repair and of 2 spf @5588'-5602' 0'. Acidize perfs w/s okr, on-off tool, 2 3/8 a inhibitor. Latch ont	, find location of csg leak. Set pkr @ 550 drill out same. TIH w/scrapper, 3 1/2" bi '; 5614'-36'; 5640'-48'; 5652'-60'. Total or 5000 gals 28% HCI acid spacing 80 BS's '" lined tbg. Set pkr @ 5550'. Sting off of to pkr. NDBOP. NUWH. Pressure test	ops pull 00' & t, tbg to f 108 holes. throughout on-off tool.		
BHA. Run pkr above cm pressure test csg/tbg to 50 5500. TOH w/tbg, tools. TOH & RDWL. TIH w/4 job. Establish injection radius Displace csg/tbg annulus	t plug. Pressure test to 500# via the 10#. If pressure doesn't hold isolate RUWL. TIH, correlate depth, peri 11/2" pkr, 23/8" the, set pkr @ 555 ate & pressure. Pull BHA. TIH w/p	If no pressure drop, csg leak, repair and of 2 spf @5588'-5602' 0'. Acidize perfs w/s okr, on-off tool, 2 3/8 a inhibitor. Latch ont	, find location of csg leak. Set pkr @ 550 drill out same. TIH w/scrapper, 3 1/2" bi '; 5614'-36'; 5640'-48'; 5652'-60'. Total or 5000 gals 28% HCI acid spacing 80 BS's '" lined tbg. Set pkr @ 5550'. Sting off of to pkr. NDBOP. NUWH. Pressure test	ops pull 00' & t, tbg to f 108 holes. throughout on-off tool.		
BHA. Run pkr above cm pressure test csg/tbg to 50 5500. TOH w/tbg, tools. TOH & RDWL. TIH w/4 job. Establish injection radius Displace csg/tbg annulus	t plug. Pressure test to 500# via the 10#. If pressure doesn't hold isolate RUWL. TIH, correlate depth, period 1/2" pkr., 2 3/8" the set pkr. @ 555 ate & pressure. Pull BHA. TIH w/rw/2% KCI wtr containing corrosion.	this pressure drop, csg leak, repair and cf 2 spf @5588'-5602', 0'. Acidize perfs w/sokr, on-off tool, 2 3/8 inhibitor. Latch ont 24 hrs prior. Begin c	, find location of csg leak. Set pkr @ 550 drill out same. TIH w/scrapper, 3 1/2" bi '; 5614'-36'; 5640'-48'; 5652'-60'. Total or 5000 gals 28% HCI acid spacing 80 BS's '" lined tbg. Set pkr @ 5550'. Sting off of to pkr. NDBOP. NUWH. Pressure test	ops pull 00' & t, tbg to f 108 holes. throughout on-off tool.		
BHA. Run pkr above cm pressure test csg/tbg to 50 5500. TOH w/tbg, tools. TOH & RDWL. TIH w/4 job. Establish injection radius to 500#. Hold for	t plug. Pressure test to 500# via the 10#. If pressure doesn't hold isolate RUWL. TIH, correlate depth, period 1/2" pkr, 2 3/8" the set pkr @ 555 ate & pressure. Pull BHA. TIH w/r w/2% KCI wtr containing corrosion r 30 min using charg. Notify OCD	this pressure drop, csg leak, repair and cf 2 spf @5588'-5602', 0'. Acidize perfs w/sokr, on-off tool, 2 3/8 inhibitor. Latch ont 24 hrs prior. Begin c	, find location of csg leak. Set pkr @ 550 drill out same. TIH w/scrapper, 3 1/2" bi '; 5614'-36'; 5640'-48'; 5652'-60'. Total or 5000 gals 28% HCI acid spacing 80 BS's '" lined tbg. Set pkr @ 5550'. Sting off of to pkr. NDBOP. NUWH. Pressure test	ops pull 00' & t, tbg to f 108 holes. throughout on-off tool.		
BHA. Run pkr above cm pressure test esg/tbg to 50 5500°. TOH w/tbg, tools. TOH & RDWL. TIH w/4 job. Establish injection radius Displace csg/tbg annulus annulus to 500#. Hold fo	t plug. Pressure test to 500# via the 10#. If pressure doesn't hold isolate RUWL. TIH, correlate depth, period 1/2" pkr, 2 3/8" the set pkr @ 555 ate & pressure. Pull BHA. TIH w/pw/2% KCI wtr containing corrosion or 30 min using charg. Notify OCD Rig Release Definition of the pressure of the pressure of the pressure.	If no pressure drop, csg leak, repair and of 2 spf @5588'-5602' 0'. Acidize perfs w/5 okr, on-off tool, 2 3/8 a inhibitor. Latch ont 24 hrs prior. Begin of	, find location of csg leak. Set pkr @ 550 drill out same. TIH w/scrapper, 3 1/2" bi '; 5614'-36'; 5640'-48'; 5652'-60'. Total or 5000 gals 28% HCI acid spacing 80 BS's B' lined tbg. Set pkr @ 5550'. Sting off cto pkr. NDBOP. NUWH. Pressure test disposal.	ops pull 00' & t, tbg to f 108 holes. throughout on-off tool.		
BHA. Run pkr above cm pressure test csg/tbg to 50 5500. TOH w/tbg, tools. TOH & RDWL. TIH w/4 job. Establish injection radius to 500#. Hold for	t plug. Pressure test to 500# via the 10#. If pressure doesn't hold isolate RUWL. TIH, correlate depth, period 1/2" pkr, 2 3/8" the set pkr @ 555 ate & pressure. Pull BHA. TIH w/pw/2% KCI wtr containing corrosion or 30 min using charg. Notify OCD Rig Release Definition of the pressure of the pressure of the pressure.	If no pressure drop, csg leak, repair and of 2 spf @5588'-5602' 0'. Acidize perfs w/5 okr, on-off tool, 2 3/8 a inhibitor. Latch ont 24 hrs prior. Begin of	, find location of csg leak. Set pkr @ 550 drill out same. TIH w/scrapper, 3 1/2" bi '; 5614'-36'; 5640'-48'; 5652'-60'. Total or 5000 gals 28% HCI acid spacing 80 BS's B' lined tbg. Set pkr @ 5550'. Sting off cto pkr. NDBOP. NUWH. Pressure test disposal.	ops pull 00' & t, tbg to f 108 holes. throughout on-off tool.		
BHA. Run pkr above cm pressure test esg/tbg to 50 5500°. TOH w/tbg, tools. TOH & RDWL. TIH w/4 job. Establish injection radius Displace csg/tbg annulus annulus to 500#. Hold fo	t plug. Pressure test to 500# via the 10#. If pressure doesn't hold isolate RUWL. TIH, correlate depth, period 1/2" pkr, 2 3/8" the set pkr @ 555 ate & pressure. Pull BHA. TIH w/r w/2% KCI wtr containing corresions at 30 min using charg. Notify OCD Rig Release Deadove is true and complete to the b	csg leak, repair and of 2 spf @5588'-5602' 0'. Acidize perfs w/5 okr, on-off tool, 2 3/8 a inhibitor. Latch ont 24 hrs prior. Begin of ate:	, find location of csg leak. Set pkr @ 550 drill out same. TIH w/scrapper, 3 1/2" bi '; 5614'-36'; 5640'-48'; 5652'-60'. Total or 5000 gals 28% HCI acid spacing 80 BS's B' lined tbg. Set pkr @ 5550'. Sting off cto pkr. NDBOP. NUWH. Pressure test disposal.	ops pull 00' & t, tbg to f 108 holes. throughout on-off tool.		
BHA. Run pkr above cm pressure test esg/tbg to 50 5500°. TOH w/tbg, tools. TOH & RDWL. TIH w/4 job. Establish injection ra Displace csg/tbg annulus annulus to 500#. Hold for Spud Date: I hereby certify that the information SIGNATURE Time Collier.	t plug. Pressure test to 500# via the 10#. If pressure doesn't hold isolate RUWL. TIH, correlate depth, peril 1/2" pkr, 2 3/8" the set pkr @ 555 ate & pressure. Pull BHA. TIH w/p w/2% KCI wtr containing corrosion or 30 min using charg. Notify OCD Rig Release Distributed in the base of the base of the base of the base of the set of the set of the base of the set	If no pressure drop, csg leak, repair and of 2 spf @5588'-5602' 0'. Acidize perfs w/5 okr, on-off tool, 2 3/8 a inhibitor. Latch ont 24 hrs prior. Begin of ate: est of my knowledge Exploration & 1 s: tcollier@read-	, find location of csg leak. Set pkr @ 550 drill out same. TIH w/scrapper, 3 1/2" bit 1/2; 5614'-36'; 5640'-48'; 5652'-60'. Total or 5000 gals 28% HCI acid spacing 80 BS's "lined tbg. Set pkr @ 5550'. Sting office to pkr. NDBOP. NUWH. Pressure test of disposal. The and belief. Development DATE	ops pull 00' & t, tbg to f 108 holes. throughout on-off tool. csg/tbg		
BHA. Run pkr above cm pressure test esg/tbg to 50 5500'. TOH w/tbg, tools. TOH & RDWL. TIH w/4 job. Establish injection radius annulus to 500#. Hold for Spud Date:	t plug. Pressure test to 500# via the 10#. If pressure doesn't hold isolate RUWL. TIH, correlate depth, peril 1/2" pkr, 2 3/8" the set pkr @ 555 ate & pressure. Pull BHA. TIH w/p w/2% KCI wtr containing corrosion or 30 min using charg. Notify OCD Rig Release Distributed in the base of the base of the base of the base of the set of the set of the base of the set	If no pressure drop, csg leak, repair and of 2 spf @5588'-5602' 0'. Acidize perfs w/5 okr, on-off tool, 2 3/8 a inhibitor. Latch ont 24 hrs prior. Begin of ate: est of my knowledge Exploration & 1 s: tcollier@read-	, find location of csg leak. Set pkr @ 550 drill out same. TIH w/scrapper, 3 1/2" bit 1/2; 5614'-36'; 5640'-48'; 5652'-60'. Total of 5000 gals 28% HCI acid spacing 80 BS's "lined tbg. Set pkr @ 5550'. Sting office to pkr. NDBOP. NUWH. Pressure test of disposal. The and belief. Development DATE	ops pull 00' & t, tbg to f 108 holes. throughout on-off tool. csg/tbg		