

Submit 1 Copy To Appropriate District Office
 District I - (575) 393-6161
 1625 N. French Dr., Hobbs, NM 88240
 District II - (575) 748-1283
 811 S. First St., Artesia, NM 88210
 District III - (505) 334-6178
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV - (505) 476-3460
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 Revised August 1, 2011

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) PROPOSALS.)		WELL API NO. 30-025-22870
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator State of New Mexico formerly Xeric Oil & Gas Corp.		6. State Oil & Gas Lease No.
3. Address of Operator 1625 N. French Drive Hobbs, New Mexico 88240		7. Lease Name or Unit Agreement Name West Pearl Queen Unit
4. Well Location Unit Letter <u>D</u> : <u>5</u> feet from the <u>N</u> line and <u>1315</u> feet from the <u>W</u> line Section <u>33</u> Township <u>19S</u> Range <u>35E</u> NMPM County <u>Lea</u>		8. Well Number <u>163</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number 25482
10. Pool name or Wildcat Pearl Queen		

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input checked="" type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPL <input type="checkbox"/> DOWNHOLE COMMINGLE <input type="checkbox"/>		SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> P AND A <input type="checkbox"/> CASING/CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

SEE ATTACHMENTS: PROCEDURE & SCHEMATIC

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mary Brown TITLE Compliance Officer DATE 7/17/2013
 Type or print name _____ E-mail address: _____ PHONE: 575-393-6161

For State Use Only

APPROVED BY: _____ TITLE _____ DATE _____

Conditions of Approval (if any):

NOV 04 2014

State of New Mexico formerly XERIC OIL & GAS

LEASE NAME WEST_PEARL QUEEN UNIT #163 API 30-0 25 - 22870

U.L. D Section 33 -T 19 S-R 35 E FROM 5 N / & L, 1315 / W L.

SPECIAL NOTE—Mud Laden Fluid will consist of 9.5# brine with 12.5# Salt Gel per BBL (25 sacks of gel/ per 100 BBLS Brine). All cement plugs will be 25 sacks of cement or 100', whichever is greater. **Unless otherwise specified in the approved procedure**, cement plugs shall consist of class "C" for depths to 7500'. Class "H" will be used for plugs deeper than 7500'.

1. MIRU plugging unit. Lay down production equipment.
2. Set CIBP @ 4700 '. Circulate MLF. Spot 25 sxs cmt on CIBP. **PRESSURE TEST CSG.**
3. ~~Perf/Sqz~~ or Spot 25 sxs cmt @ 3500 '. If perf, WOC & TAG.
4. Perf/Sqz ~~or Spot~~ 25 sxs cmt @ 1800 '. If perf, WOC and TAG.
5. Perf/Sqz ~~or Spot~~ @ 432 ', w/ sufficient volume to circ cmt to surface inside/outside of csg strings.
6. Cutoff wellhead and anchors, install marker.

-----SPECIAL NOTES-----


UNKNOWN EQUIPMENT IN WELL AT PRESENT. SHOWS RE-ENTRY 12/13/1991.

T/A TEST 7/31/2002. CAN NOT FIND IF CIBP WAS USED, OR IF T/A'D WITH PACKER & TBG.

PLUGGING & ABANDONMENT WORKSHEET

OPERATOR STATE OF NM FORMERLY XERTIC OIL & GAS
 LEASENAME WEST PEARL QUEEN UNIT

WELL # 163
 SECT 33 TWN 19S RNG 35E
 FROM 5 N1/4 L 1315 E/W L
 TD: _____ FORMATION @ TD _____
 PBD: _____ FORMATION @ PBD _____



	SIZE	SET @	TOC	TOC DETERMINED BY
SURFACE	8 5/8	382	SURF	CIRC
INTMED 1				
INTMED 2				
PROD	5 1/2	5019	3125	TEMP SURVEY
	SIZE	TOP	BOT	TOC DETERMINED BY
LINER 1				
LINER 2				
CUT & PULL @			TOP - BOTTOM	
INTMED 1			PERFS	-
INTMED 2			OPENHOLE	-
PROD				

* REQUIRED PLUGS DISTRICT I

PLUG	TYPE	SACKS	DEPTH
PLUG #1	OH	25 SCS	9350'
PLUG #2	SHOE	50 SCS	8700-8800'
PLUG #3	CIBP/35'		5300'
PLUG #4	CEP	25 SCS	5300'
PLUG #5	STUB	50 SCS	4600-4700'
PLUG #6	PERF SQZ	200 SCS	400'
PLUG #7	SURF	10 SCS	0-10'
PLUG #8			
PLUG #9			
PLUG #10			
PLUG #11			
PLUG #12			
PLUG #13			
PLUG #14			
PLUG #15			
PLUG #16			
PLUG #17			
PLUG #18			
PLUG #19			
PLUG #20			
PLUG #21			
PLUG #22			
PLUG #23			
PLUG #24			
PLUG #25			
PLUG #26			
PLUG #27			
PLUG #28			
PLUG #29			
PLUG #30			
PLUG #31			
PLUG #32			
PLUG #33			
PLUG #34			
PLUG #35			
PLUG #36			
PLUG #37			
PLUG #38			
PLUG #39			
PLUG #40			
PLUG #41			
PLUG #42			
PLUG #43			
PLUG #44			
PLUG #45			
PLUG #46			
PLUG #47			
PLUG #48			
PLUG #49			
PLUG #50			

PLUG	TYPE	SACKS	DEPTH
PLUG #1	OH	25 SCS	9350'
PLUG #2	SHOE	50 SCS	8700-8800'
PLUG #3	CIBP/35'		5300'
PLUG #4	CEP	25 SCS	5300'
PLUG #5	STUB	50 SCS	4600-4700'
PLUG #6	PERF SQZ	200 SCS	400'
PLUG #7	SURF	10 SCS	0-10'
PLUG #8			
PLUG #9			
PLUG #10			
PLUG #11			
PLUG #12			
PLUG #13			
PLUG #14			
PLUG #15			
PLUG #16			
PLUG #17			
PLUG #18			
PLUG #19			
PLUG #20			
PLUG #21			
PLUG #22			
PLUG #23			
PLUG #24			
PLUG #25			
PLUG #26			
PLUG #27			
PLUG #28			
PLUG #29			
PLUG #30			
PLUG #31			
PLUG #32			
PLUG #33			
PLUG #34			
PLUG #35			
PLUG #36			
PLUG #37			
PLUG #38			
PLUG #39			
PLUG #40			
PLUG #41			
PLUG #42			
PLUG #43			
PLUG #44			
PLUG #45			
PLUG #46			
PLUG #47			
PLUG #48			
PLUG #49			
PLUG #50			