Office	State of New N	Aexico	Form C-103				
	Energy Minorels and Natural Resources		Revised July 18, 2013				
<u>District I</u> (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, witherars and Wa	itural Resources	WELL API NO.				
District II - (575) 748-1283			30-025-23941				
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of Lease				
District III - (505) 334-6178	1220 South St. Fi	rancis Dr.	STATE FEE				
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fe, NM	87505	6. State Oil & Gas Lease No.				
$\frac{DSHE(1V)}{1220 \text{ S. St. Francis Dr., Santa Fe, NM}$			0. State Off & Gas Lease No.				
87505							
	TICES AND REPORTS ON WEL		7. Lease Name or Unit Agreement Name				
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCCES OCD		Hill A					
PROPOSALS.)	ICATION FOR PERMIT* (FORM C-101)	HOBBS OCD					
1. Type of Well: Oil Well	Gas Well Dother 8. Well Number 008						
2. Name of Operator		NOV 1 9 2014	9. OGRID Number				
Mar Oil and Gas Corporation			151228				
3. Address of Operator			10. Pool name or Wildcat				
PO BOX	5155 Santa Fe, NM 87502	RECEIVED	Eumont; Yates,7Rvrs,Queen				
4. Well Location							
Unit LetterE:		line and87	77feet from theWestline				
Section 6	Township 21S	Range 37E	NMPM Lea County				
	11. Elevation (Show whether L	OR, RKB, RT, GR, etc.					
12 Check	Appropriate Box to Indicate	Nature of Notice	Report or Other Data				
	rippiopriate box to indicate	· · · · · · · · · · · · · · · · · · ·					
NOTICE OF I	NTENTION TO:		MITTING				
PERFORM REMEDIAL WORK		REN P&A N	R P&A R				
TEMPORARILY ABANDON	CHANGE PLANS		P&A R. COMP				
PULL OR ALTER CASING		CAE CSNG	CHG Loc				
CLOSED-LOOP SYSTEM		· · · · · · · · · · · · · · · · · · ·	RBDMS CHART				
OTHER:	, La cala cala cala cala cala cala cala c	OTHER:	Г				
	nleted operations. (Clearly state a		nd give pertinent dates, including estimated date				
			ompletions: Attach wellbore diagram of				
proposed completion or re		i ci i ci i i i i i i i i i i i i i i i	and the second				
Mar proposes to plug and abandon the Hill A # 8 as follows No earthen pits will be constructed all well fluids will circulated to steel pit or tank							
No earthen pits will be construct		o steel pit or tank					
	ed all well fluids will circulated t						
8 5/8" CSA 495 feet. Cemented w	ed all well fluids will circulated t rith 350sks of cement. Cement ci	rculated to surface)% Fill				
	ed all well fluids will circulated t rith 350sks of cement. Cement ci	rculated to surface)% Fill				
8 5/8" CSA 495 feet. Cemented w 4 ½" CSA 3778 feet. Cemented w Perforations 3624-3735'	ed all well fluids will circulated t ith 350sks of cement. Cement ci ith 500 sks of cement. TOC calc	rculated to surface)% Fill				
8 5/8" CSA 495 feet. Cemented w 4 ½" CSA 3778 feet. Cemented w Perforations 3624-3735' Top of Salt at 1414 feet x Base of	ed all well fluids will circulated t ith 350sks of cement. Cement ci ith 500 sks of cement. TOC calc Salt 2580 feet	rculated to surface ulated at 1750' w/ 7(
8 5/8" CSA 495 feet. Cemented w 4 ½" CSA 3778 feet. Cemented w Perforations 3624-3735'	ed all well fluids will circulated t rith 350sks of cement. Cement ci rith 500 sks of cement. TOC calc Salt 2580 feet ks of cement x Displace well with	rculated to surface ulated at 1750' w/ 7(
8 5/8" CSA 495 feet. Cemented w 4 ½" CSA 3778 feet. Cemented w Perforations 3624-3735' Top of Salt at 1414 feet x Base of Set CIBP at 3575' Cap with 25 sl	ed all well fluids will circulated t with 350sks of cement. Cement ci ith 500 sks of cement. TOC calc Salt 2580 feet ks of cement x Displace well with eet	rculated to surface ulated at 1750' w/ 7(
8 5/8" CSA 495 feet. Cemented w 4 ½" CSA 3778 feet. Cemented w Perforations 3624-3735" Top of Salt at 1414 feet x Base of Set CIBP at 3575' Cap with 25 sl Spot 25sx Cement plug at 2630 fe Perforate at 1464 feet x Squeeze Perforate at 545 feet x Circulate	ed all well fluids will circulated t rith 350sks of cement. Cement ci rith 500 sks of cement. TOC calc Salt 2580 feet ss of cement x Displace well with ret w/ 30 sks cement (Top of Salt Pl cement to surface (Suface and St	rculated to surface ulated at 1750' w/ 7(gelled brine water $WOC \in TAG$	POT 25 Suscen T 1130-1030 COVER CSG LEAK)				
8 5/8" CSA 495 feet. Cemented w 4 ½" CSA 3778 feet. Cemented w Perforations 3624-3735' Top of Salt at 1414 feet x Base of Set CIBP at 3575' Cap with 25 sl Spot 25sx Cement plug at 2630 fe Perforate at 1464 feet x Squeeze Perforate at 545 feet x Circulate Leave all casing strings full of cert	ed all well fluids will circulated t ith 350sks of cement. Cement ci ith 500 sks of cement. TOC calc Salt 2580 feet ss of cement x Displace well with set w/ 30 sks cement (Top of Salt Pl cement to surface (Suface and Something) ment	rculated to surface ulated at 1750' w/ 7(gelled brine water WOC * TAG ug) urface shoe Plug)					
8 5/8" CSA 495 feet. Cemented w 4 ½" CSA 3778 feet. Cemented w Perforations 3624-3735" Top of Salt at 1414 feet x Base of Set CIBP at 3575' Cap with 25 sl Spot 25sx Cement plug at 2630 fe Perforate at 1464 feet x Squeeze Perforate at 545 feet x Circulate	ed all well fluids will circulated t ith 350sks of cement. Cement ci ith 500 sks of cement. TOC calc Salt 2580 feet ss of cement x Displace well with set w/ 30 sks cement (Top of Salt Pl cement to surface (Suface and Something) ment	rculated to surface ulated at 1750' w/ 7(gelled brine water WOC * TAG ug) urface shoe Plug)					
8 5/8" CSA 495 feet. Cemented w 4 ½" CSA 3778 feet. Cemented w Perforations 3624-3735' Top of Salt at 1414 feet x Base of Set CIBP at 3575' Cap with 25 sl Spot 25sx Cement plug at 2630 fe Perforate at 1464 feet x Squeeze Perforate at 545 feet x Circulate Leave all casing strings full of cert	ed all well fluids will circulated t ith 350sks of cement. Cement ci ith 500 sks of cement. TOC calc Salt 2580 feet ss of cement x Displace well with set w/ 30 sks cement (Top of Salt Pl cement to surface (Suface and Something) ment	rculated to surface ulated at 1750' w/ 7(gelled brine water WOC + TAG ug) urface shoe Plug) ease	POT 25 SUSCM T-1130-1030 (COVER CSG LEAK)				
8 5/8" CSA 495 feet. Cemented w 4 ½" CSA 3778 feet. Cemented w Perforations 3624-3735' Top of Salt at 1414 feet x Base of Set CIBP at 3575' Cap with 25 sl Spot 25sx Cement plug at 2630 fe Perforate at 1464 feet x Squeeze Perforate at 545 feet x Circulate Leave all casing strings full of cert	ed all well fluids will circulated t ith 350sks of cement. Cement ci ith 500 sks of cement. TOC calc Salt 2580 feet ss of cement x Displace well with set w/ 30 sks cement (Top of Salt Pl cement to surface (Suface and Something) ment	rculated to surface ulated at 1750' w/ 7(gelled brine water www.rTAG urface shoe Plug) ease	POT 25 SUSCENT 1130-1030 COVER CSG LEARD				
8 5/8" CSA 495 feet. Cemented w 4 ½" CSA 3778 feet. Cemented w Perforations 3624-3735' Top of Salt at 1414 feet x Base of Set CIBP at 3575' Cap with 25 sl Spot 25sx Cement plug at 2630 fe Perforate at 1464 feet x Squeeze Perforate at 545 feet x Circulate Leave all casing strings full of cer Cut off wellhead x service unit at	ed all well fluids will circulated t rith 350sks of cement. Cement ci rith 500 sks of cement. TOC calc Salt 2580 feet ss of cement x Displace well with ret w/ 30 sks cement (Top of Salt Pl cement to surface (Suface and Soment nchors x Prepare location for rel	rculated to surface ulated at 1750' w/ 7(gelled brine water ug) urface shoe Plug) ease Th	POT 25 SUSCM T-1130-1030 (COVER CSG LEAK)				
8 5/8" CSA 495 feet. Cemented w 4 ½" CSA 3778 feet. Cemented w Perforations 3624-3735' Top of Salt at 1414 feet x Base of Set CIBP at 3575' Cap with 25 sl Spot 25sx Cement plug at 2630 fe Perforate at 1464 feet x Squeeze Perforate at 545 feet x Circulate Leave all casing strings full of cert	ed all well fluids will circulated t ith 350sks of cement. Cement ci ith 500 sks of cement. TOC calc Salt 2580 feet ss of cement x Displace well with set w/ 30 sks cement (Top of Salt Pl cement to surface (Suface and Something) ment	rculated to surface ulated at 1750' w/ 7(gelled brine water ug) urface shoe Plug) ease Th Date	POT 25 Syscm T 1130'- 1030' (COVER CSG LEAK) ne Oil Conservation Division IST BE NOTIFIED 24 Hours				
8 5/8" CSA 495 feet. Cemented w 4 ½" CSA 3778 feet. Cemented w Perforations 3624-3735' Top of Salt at 1414 feet x Base of Set CIBP at 3575' Cap with 25 sl Spot 25sx Cement plug at 2630 fe Perforate at 1464 feet x Squeeze Perforate at 545 feet x Circulate Leave all casing strings full of cer Cut off wellhead x service unit at	ed all well fluids will circulated t rith 350sks of cement. Cement ci rith 500 sks of cement. TOC calc Salt 2580 feet ss of cement x Displace well with ret w/ 30 sks cement (Top of Salt Pl cement to surface (Suface and Soment nchors x Prepare location for rel	rculated to surface ulated at 1750' w/ 7(gelled brine water ug) urface shoe Plug) ease Th Date	POT 25 SUSCENT 1130-1030 COVER CSG LEARD				
8 5/8" CSA 495 feet. Cemented w 4 ½" CSA 3778 feet. Cemented w Perforations 3624-3735' Top of Salt at 1414 feet x Base of Set CIBP at 3575' Cap with 25 sl Spot 25sx Cement plug at 2630 fe Perforate at 1464 feet x Squeeze Perforate at 545 feet x Circulate Leave all casing strings full of cer Cut off wellhead x service unit at	ed all well fluids will circulated t rith 350sks of cement. Cement ci rith 500 sks of cement. TOC calc Salt 2580 feet ss of cement x Displace well with ret w/ 30 sks cement (Top of Salt Pl cement to surface (Suface and Soment nchors x Prepare location for rel	rculated to surface ulated at 1750' w/ 7(gelled brine water ug) urface shoe Plug) ease Th Date	POT 25 Syscm T 1130'- 1030' (COVER CSG LEAK) ne Oil Conservation Division IST BE NOTIFIED 24 Hours				
8 5/8" CSA 495 feet. Cemented w 4 ½" CSA 3778 feet. Cemented w Perforations 3624-3735' Top of Salt at 1414 feet x Base of Set CIBP at 3575' Cap with 25 sl Spot 25sx Cement plug at 2630 fe Perforate at 1464 feet x Squeeze Perforate at 545 feet x Circulate Leave all casing strings full of cer Cut off wellhead x service unit at	ed all well fluids will circulated t rith 350sks of cement. Cement ci rith 500 sks of cement. TOC calc Salt 2580 feet ss of cement x Displace well with ret w/ 30 sks cement (Top of Salt Pl cement to surface (Suface and Soment nchors x Prepare location for rel Rig Release	rculated to surface ulated at 1750' w/ 7(gelled brine water ug) urface shoe Plug) ease Th Date: Prior	POT 25 SUSCENT 1130 - 1030 COVER CSG LEARS Ne Oil Conservation Division IST BE NOTIFIED 24 Hours to the beginning of operations				
8 5/8" CSA 495 feet. Cemented w 4 ½" CSA 3778 feet. Cemented w Perforations 3624-3735' Top of Salt at 1414 feet x Base of Set CIBP at 3575' Cap with 25 sl Spot 25sx Cement plug at 2630 fe Perforate at 1464 feet x Squeeze Perforate at 545 feet x Circulate Leave all casing strings full of cer Cut off wellhead x service unit at Spud Date:	ed all well fluids will circulated t rith 350sks of cement. Cement ci rith 500 sks of cement. TOC calc Salt 2580 feet ss of cement x Displace well with ret w/ 30 sks cement (Top of Salt Pl cement to surface (Suface and Soment nchors x Prepare location for rel Rig Release	rculated to surface ulated at 1750' w/ 7(gelled brine water ug) urface shoe Plug) ease Th Date: Prior	POT 25 SUSCENT 1130 - 1030 COVER CSG LEARS Ne Oil Conservation Division IST BE NOTIFIED 24 Hours to the beginning of operations				
8 5/8" CSA 495 feet. Cemented w 4 ½" CSA 3778 feet. Cemented w Perforations 3624-3735' Top of Salt at 1414 feet x Base of Set CIBP at 3575' Cap with 25 sl Spot 25sx Cement plug at 2630 fe Perforate at 1464 feet x Squeeze Perforate at 545 feet x Circulate Leave all casing strings full of cer Cut off wellhead x service unit at Spud Date:	ed all well fluids will circulated to the state of the s	rculated to surface ulated at 1750' w/ 7(gelled brine water (ug) urface shoe Plug) ease Th Date: Prior	POT 25 Syscm T-1130 - 1030 COVER CSG LEAKS Not Cover CSG LEAKS IST BE NOTIFIED 24 Hours to the beginning of operations				
8 5/8" CSA 495 feet. Cemented w 4 ½" CSA 3778 feet. Cemented w Perforations 3624-3735' Top of Salt at 1414 feet x Base of Set CIBP at 3575' Cap with 25 sl Spot 25sx Cement plug at 2630 fe Perforate at 1464 feet x Squeeze Perforate at 545 feet x Circulate Leave all casing strings full of cer Cut off wellhead x service unit at Spud Date:	ed all well fluids will circulated t rith 350sks of cement. Cement ci ith 500 sks of cement. TOC calc Salt 2580 feet ss of cement x Displace well with ret w/ 30 sks cement (Top of Salt Pl cement to surface (Suface and Soment nchors x Prepare location for rel Rig Release	rculated to surface ulated at 1750' w/ 7(gelled brine water (ug) urface shoe Plug) ease Th Date: Prior	POT 25 SUSCENT 1130 - 1030 COVER CSG LEARS Ne Oil Conservation Division IST BE NOTIFIED 24 Hours to the beginning of operations				
8 5/8" CSA 495 feet. Cemented w 4 ½" CSA 3778 feet. Cemented w Perforations 3624-3735' Top of Salt at 1414 feet x Base of Set CIBP at 3575' Cap with 25 sk Spot 25sx Cement plug at 2630 fe Perforate at 1464 feet x Squeeze Perforate at 545 feet x Circulate Leave all casing strings full of cer Cut off wellhead x service unit at Spud Date:	ed all well fluids will circulated to the state of the s	rculated to surface ulated at 1750' w/ 7(gelled brine water (ug) urface shoe Plug) ease Th Date: Prior	POT 25 Syscm T-1130 - 1030 COVER CSG LEAKS Not Cover CSG LEAKS IST BE NOTIFIED 24 Hours to the beginning of operations				
8 5/8" CSA 495 feet. Cemented w 4 ½" CSA 3778 feet. Cemented w Perforations 3624-3735' Top of Salt at 1414 feet x Base of Set CIBP at 3575' Cap with 25 sk Spot 25sx Cement plug at 2630 fe Perforate at 1464 feet x Squeeze Perforate at 545 feet x Circulate Leave all casing strings full of cer Cut off wellhead x service unit at Spud Date:	ed all well fluids will circulated to the 350sks of cement. Cement ci- tith 500 sks of cement. TOC calc Salt 2580 feet as of cement x Displace well with set w/ 30 sks cement (Top of Salt Pl cement to surface (Suface and Soment net to surface (Suface and	rculated to surface ulated at 1750' w/ 7(gelled brine water (ug) urface shoe Plug) ease Th Date: Prior	POT 25 Syscen T 1130 - 1030' COVER CSG LEAKS The Oil Conservation Division IST BE NOTIFIED 24 Hours to the beginning of operations ge and belief. DATE $11/16/14$				
8 5/8" CSA 495 feet. Cemented w 4 ½" CSA 3778 feet. Cemented w Perforations 3624-3735' Top of Salt at 1414 feet x Base of Set CIBP at 3575' Cap with 25 sl Spot 25sx Cement plug at 2630 fe Perforate at 1464 feet x Squeeze Perforate at 545 feet x Circulate Leave all casing strings full of cer Cut off wellhead x service unit at Spud Date: I hereby certify that the information SIGNATURE_BALL	ed all well fluids will circulated to the 350sks of cement. Cement ci- tith 500 sks of cement. TOC calc Salt 2580 feet as of cement x Displace well with set w/ 30 sks cement (Top of Salt Pl cement to surface (Suface and Soment net to surface (Suface and	rculated to surface ulated at 1750' w/ 7(gelled brine water ug) urface shoe Plug) ease Th Date: Prior e best of my knowledge eman	POT 25 Syscen T 1130 - 1030' COVER CSG LEAKS The Oil Conservation Division IST BE NOTIFIED 24 Hours to the beginning of operations ge and belief. DATE $11/16/14$				
8 5/8" CSA 495 feet. Cemented w 4 ½" CSA 3778 feet. Cemented w Perforations 3624-3735' Top of Salt at 1414 feet x Base of Set CIBP at 3575' Cap with 25 sk Spot 25sx Cement plug at 2630 fe Perforate at 1464 feet x Squeeze Perforate at 545 feet x Circulate Leave all casing strings full of cert Cut off wellhead x service unit at Spud Date: I hereby certify that the information SIGNATURE Buy E Type or print name Billy E. Pricha For State Use Only	ed all well fluids will circulated to the state of the s	rculated to surface ulated at 1750' w/ 7(gelled brine water (ug) urface shoe Plug) ease Th Date: Prior e best of my knowledg eman ress: billy@pwllc.ne	POT 25 Syscen T 1130 - 1030' COVER CSG LEAKS The Oil Conservation Division IST BE NOTIFIED 24 Hours to the beginning of operations ge and belief. DATE $11/16/14$				
8 5/8" CSA 495 feet. Cemented w 4 ½" CSA 3778 feet. Cemented w Perforations 3624-3735' Top of Salt at 1414 feet x Base of Set CIBP at 3575' Cap with 25 sl Spot 25sx Cement plug at 2630 fe Perforate at 1464 feet x Squeeze Perforate at 545 feet x Circulate Leave all casing strings full of cer Cut off wellhead x service unit an Spud Date: I hereby certify that the information SIGNATURE Buy E Type or print name Billy E. Pricha	ed all well fluids will circulated to the state of the s	rculated to surface ulated at 1750' w/ 7(gelled brine water ug) urface shoe Plug) ease Th Date: Prior e best of my knowledge eman	POT 25 Syscen T 1130 - 1030' COVER CSG LEAKS The Oil Conservation Division IST BE NOTIFIED 24 Hours to the beginning of operations ge and belief. DATE $11/16/14$				

APPROVED DT	$1 \cdot \mathbf{u}$	μ	<u> </u>
Conditions of Appro	oval (if a	ny):()

NOV 2 4 2014



