

**Nearburg Federal L #1 SWD 30-025-20811**

Brown, Maxey G, EMNRD

Sent: Wednesday, June 03, 2015 12:09 PM

To: tgreen@nearburg.com

Cc: scaffey@blm.gov; Sonnamaker, William, EMNRD; Goetze, Phillip, EMNRD; Dickey, Sylvia, EMNRD

Mr. Tim Green,

After reviewing BLM form 3160-5 Subsequent with attachment, OCD has found that a CIBP that was omitted on the wellbore diagram and possibly from the wellbore. If the CIBP was actually placed in the wellbore as spelled out in Order SWD-1471 (see paragraph below ), please provide corrected forms to indicate setting depth. If you find that the CIBP was not installed **cease injection immediately**. Submit 3160-5 intent to BLM to correct well bore conditions. Give 24 hours' notice prior to running chart test to both BLM and OCD.

**IT IS FURTHER ORDERED THAT:**

The operator shall take all steps necessary to ensure that the disposed water enters only the approved disposal interval and is not permitted to escape to other formations or onto the surface. This includes the well construction proposed and described in the application with the exception of the cast-iron bridge plug (CIBP). The proposed CIBP will be placed no greater than two hundred feet below the deepest perforation of the injection interval at approximately 3832 feet.

I think you would agree without the CIBP, there is not a feasible way to know if disposed water are escaping into lower formations. One such formation is the Capitan Reef which is located just below your approved injection interval. Thank you in advance for correcting this situation.

Maxey G. Brown  
OCD District 1 Supervisor  
575-393-6161 ext. 102

JUN 03 2015