Office	State of Nev	**		Form C-103	
<u>District 1</u> – (575) 393-6161	Energy, Minerals and	Natural Resources		ed July 18, 2013	
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.		
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-025-26588		
<u>District III</u> ~ (505) 334-6178	1220 South St. Francis Dr.		5. Indicate Type of Lease	- 5	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505		STATE FEI		
<u>District IV</u> ~ (505) 476-3460	Santa Fe, N	M 8/303	6. State Oil & Gas Lease No		
1220 S. St. Francis Dr., Santa Fe, NM					
SUNDRY NOT	TICES AND REPORTS ON W	ELIC	7. Lease Name or Unit Agree	ement Name	
(DO NOT USE THIS FORM FOR PROP			7. Lease Name of Offit Agree	ement Name	
DIFFERENT RESERVOIR. USE "APPL			A.B. Reeves		
PROPOSALS.)		,	8. Well Number		
1. Type of Well: Oil Well 🔲	Gas Well 🛛 Other 🗌	HOBBS O		/	
		IIODD3 O			
2. Name of Operator			9. OGRID Number		
	erVest Operating, LLC	JUN 0 8 2	143199	· .	
3. Address of Operator		10. Pool name or whicat			
1001 Fanni	in, Ste. 800, Houston, TX 770	02	Eumont; Yates-7R-Q	(Gas)	
4. Well Location		RECEIVE	D		
Unit Letter A :	660 feet from the Nort		610 feet from the East	line	
Section 29					
	11. Elevation (Show whether		e1c.)	salig to see	
A CONTRACTOR OF THE STATE OF TH	.3	509.3' GR			
12. Check	Appropriate Box to Indica	ate Nature of Notic	ce. Report or Other Data		
president and the second of th	2.7 7 . 4-1 4		o, report or carer bata		
E-PERMITTING <swd_< td=""><td>INJECTION&gt;</td><td>SU</td><td>JBSEQUENT REPORT O</td><td>F:</td></swd_<>	INJECTION>	SU	JBSEQUENT REPORT O	F:	
CONVERSION	RBDMS			GCASING 🗌	
RETURN TO	TA :		ORILLING OPNS. □ P AND A		
	CHG LOC	CASING/CEMI		123	
		J CASING/CLIVII	EINT JOB		
INT TO PA P&A NR	(† 1937) P&A R				
<del></del>	2	1 OTHER:			
OTHER:	plated approximate (Clearly sta	OTHER:	and give portinent dates, including	a actimated data	
OTHER:  13. Describe proposed or com		te all pertinent details,	and give pertinent dates, including		
OTHER:  13. Describe proposed or com of starting any proposed w	ork). SEE RULE 19.15.7.14 N	te all pertinent details,	and give pertinent dates, including Completions: Attach wellbore dia		
OTHER:  13. Describe proposed or com	ork). SEE RULE 19.15.7.14 N	te all pertinent details,			
OTHER:  13. Describe proposed or com of starting any proposed w	ork). SEE RULE 19.15.7.14 N	te all pertinent details,			
OTHER:  13. Describe proposed or com of starting any proposed w	ork). SEE RULE 19.15.7.14 N	te all pertinent details,			
OTHER:  13. Describe proposed or com of starting any proposed w	ork). SEE RULE 19.15.7.14 N	te all pertinent details,			
OTHER:  13. Describe proposed or com of starting any proposed w proposed completion or re	ork). SEE RULE 19.15.7.14 N	te all pertinent details,			
OTHER:  13. Describe proposed or com of starting any proposed w	ork). SEE RULE 19.15.7.14 N	te all pertinent details,			
OTHER:  13. Describe proposed or com   of starting any proposed w   proposed completion or re  5/27/15MIRU.	vork). SEE RULE 19.15.7.14 No completion.	te all pertinent details,			
OTHER:  13. Describe proposed or com of starting any proposed w proposed completion or re	vork). SEE RULE 19.15.7.14 No completion.	te all pertinent details,			
OTHER:  13. Describe proposed or com   of starting any proposed w   proposed completion or re  5/27/15MIRU.  5/28/15RIH 5½ gauge ring Tag (	ork). SEE RULE 19.15.7.14 No completion.  @ 2780'	te all pertinent details, NMAC. For Multiple (	Completions: Attach wellbore dia	gram of	
OTHER:  13. Describe proposed or com   of starting any proposed w   proposed completion or re  5/27/15MIRU.  5/28/15RIH 5½ gauge ring Tag (  5/29/15Load hole w/ 70 bbls brid	ork). SEE RULE 19.15.7.14 No completion.  © 2780'  ne mix w/ 20 sxs mud, spot 25	te all pertinent details, NMAC. For Multiple (	Completions: Attach wellbore dia	gram of	
OTHER:  13. Describe proposed or com   of starting any proposed w   proposed completion or re  5/27/15MIRU.  5/28/15RIH 5½ gauge ring Tag (	ork). SEE RULE 19.15.7.14 No completion.  © 2780'  ne mix w/ 20 sxs mud, spot 25	te all pertinent details, NMAC. For Multiple (	Completions: Attach wellbore dia	gram of	
OTHER:  13. Describe proposed or com   of starting any proposed w   proposed completion or re  5/27/15MIRU.  5/28/15RIH 5½ gauge ring Tag (  5/29/15Load hole w/ 70 bbls brid	ork). SEE RULE 19.15.7.14 No completion.  © 2780'  ne mix w/ 20 sxs mud, spot 25	te all pertinent details, NMAC. For Multiple (	Completions: Attach wellbore dia	gram of	
OTHER:  13. Describe proposed or com   of starting any proposed w   proposed completion or re  5/27/15MIRU.  5/28/15RIH 5½ gauge ring Tag (  5/29/15Load hole w/ 70 bbls brid	ork). SEE RULE 19.15.7.14 No completion.  © 2780'  ne mix w/ 20 sxs mud, spot 25	te all pertinent details, NMAC. For Multiple (	Completions: Attach wellbore dia	gram of	
OTHER:  13. Describe proposed or com   of starting any proposed w   proposed completion or re  5/27/15MIRU.  5/28/15RIH 5½ gauge ring Tag (  5/29/15Load hole w/ 70 bbls brid	ork). SEE RULE 19.15.7.14 No completion.  © 2780'  ne mix w/ 20 sxs mud, spot 25	te all pertinent details, NMAC. For Multiple (	Completions: Attach wellbore dia	gram of	
OTHER:  13. Describe proposed or com   of starting any proposed w   proposed completion or re  5/27/15MIRU.  5/28/15RIH 5½ gauge ring Tag (  5/29/15Load hole w/ 70 bbls brid	ork). SEE RULE 19.15.7.14 No completion.  © 2780'  ne mix w/ 20 sxs mud, spot 25	te all pertinent details, NMAC. For Multiple (	Completions: Attach wellbore dia	gram of	
OTHER:  13. Describe proposed or com   of starting any proposed w   proposed completion or re  5/27/15MIRU.  5/28/15RIH 5½ gauge ring Tag (  5/29/15Load hole w/ 70 bbls brid	ork). SEE RULE 19.15.7.14 No completion.  © 2780'  ne mix w/ 20 sxs mud, spot 25	te all pertinent details, NMAC. For Multiple of several severa	Completions: Attach wellbore dia	gram of	
OTHER:  13. Describe proposed or com of starting any proposed w proposed completion or re  5/27/15MIRU.  5/28/15RIH 5½ gauge ring Tag (  5/29/15Load hole w/ 70 bbls bring RIH to 508' - spot 70 sx	@ 2780' ne mix w/ 20 sxs mud, spot 25 s to surface. RDMO.	te all pertinent details, NMAC. For Multiple of several severa	Completions: Attach wellbore dia	gram of	
OTHER:  13. Describe proposed or com of starting any proposed w proposed completion or re  5/27/15MIRU.  5/28/15RIH 5½ gauge ring Tag (  5/29/15Load hole w/ 70 bbls bring RIH to 508' - spot 70 sx	@ 2780' ne mix w/ 20 sxs mud, spot 25 s to surface. RDMO.	te all pertinent details, NMAC. For Multiple of several severa	Completions: Attach wellbore dia	gram of	
OTHER:  13. Describe proposed or com   of starting any proposed w   proposed completion or re  5/27/15MIRU.  5/28/15RIH 5½ gauge ring Tag (  5/29/15Load hole w/ 70 bbls bring RIH to 508' - spot 70 sx  Spud Date:	work). SEE RULE 19.15.7.14 No completion.  @ 2780'  ne mix w/ 20 sxs mud, spot 25 s to surface. RDMO.  Rig Relea	te all pertinent details, NMAC. For Multiple of Section 1985.	Completions: Attach wellbore dia  D). PUH to 1927'- load hole, spot 2	gram of	
OTHER:  13. Describe proposed or com   of starting any proposed w   proposed completion or re  5/27/15MIRU.  5/28/15RIH 5½ gauge ring Tag (  5/29/15Load hole w/ 70 bbls bring RIH to 508' - spot 70 sx  Spud Date:	work). SEE RULE 19.15.7.14 No completion.  @ 2780'  ne mix w/ 20 sxs mud, spot 25 s to surface. RDMO.  Rig Relea	te all pertinent details, NMAC. For Multiple of Section 1985.	Completions: Attach wellbore dia  D). PUH to 1927'- load hole, spot 2	gram of	
OTHER:  13. Describe proposed or com of starting any proposed w proposed completion or re  5/27/15MIRU.  5/28/15RIH 5½ gauge ring Tag (  5/29/15Load hole w/ 70 bbls bring RIH to 508' - spot 70 sx	work). SEE RULE 19.15.7.14 No completion.  @ 2780'  ne mix w/ 20 sxs mud, spot 25 s to surface. RDMO.  Rig Relea	te all pertinent details, NMAC. For Multiple of Section 1985.	Completions: Attach wellbore dia  D). PUH to 1927'- load hole, spot 2	gram of	
OTHER:  13. Describe proposed or come of starting any proposed with proposed completion or responsed completion or responsed completion or responsed completion or responsed completion or response completion completion or response completion completi	2780' ne mix w/ 20 sxs mud, spot 25 s to surface. RDMO.  Rig Relea	te all pertinent details, NMAC. For Multiple of sexts @ 2780' (per OCE ase Date:	Completions: Attach wellbore dia  D). PUH to 1927'- load hole, spot 2	gram of 25 sxs. NDBOP,	
OTHER:  13. Describe proposed or com   of starting any proposed w   proposed completion or re  5/27/15MIRU.  5/28/15RIH 5½ gauge ring Tag (  5/29/15Load hole w/ 70 bbls bring RIH to 508' - spot 70 sx  Spud Date:	work). SEE RULE 19.15.7.14 No completion.  @ 2780'  ne mix w/ 20 sxs mud, spot 25 s to surface. RDMO.  Rig Relea	te all pertinent details, NMAC. For Multiple of Section 1985.	Completions: Attach wellbore dia  D). PUH to 1927'- load hole, spot 2	gram of 25 sxs. NDBOP,	
OTHER:  13. Describe proposed or com     of starting any proposed w     proposed completion or re  5/27/15MIRU.  5/28/15RIH 5½ gauge ring Tag (  5/29/15Load hole w/ 70 bbls bring     RIH to 508' - spot 70 sx  Spud Date:  I hereby certify that the information  SIGNATURE	@ 2780' ne mix w/ 20 sxs mud, spot 25 s to surface. RDMO.  Rig Relea	te all pertinent details, NMAC. For Multiple of sexts @ 2780' (per OCE ase Date:	Completions: Attach wellbore dia  D). PUH to 1927'- load hole, spot 2  edge and belief.  DATE6/1/2	gram of 25 sxs. NDBOP,	
OTHER:  13. Describe proposed or com of starting any proposed was proposed completion or responsed com	@ 2780' ne mix w/ 20 sxs mud, spot 25 s to surface. RDMO.  Rig Relea	te all pertinent details, NMAC. For Multiple of sexts @ 2780' (per OCE ase Date:	Completions: Attach wellbore dia  D). PUH to 1927'- load hole, spot 2	gram of 25 sxs. NDBOP,	
OTHER:  13. Describe proposed or com     of starting any proposed w     proposed completion or re  5/27/15MIRU.  5/28/15RIH 5½ gauge ring Tag (  5/29/15Load hole w/ 70 bbls bring     RIH to 508' - spot 70 sx  Spud Date:  I hereby certify that the information  SIGNATURE	@ 2780' ne mix w/ 20 sxs mud, spot 25 s to surface. RDMO.  Rig Releated TITLE.  The mail address:	te all pertinent details, NMAC. For Multiple of Section 1. Section 2780' (per OCE ase Date: P&A Tech	Completions: Attach wellbore dia  D). PUH to 1927'- load hole, spot 2  edge and belief.  DATE6/1/2  PHONE: _432-563-33	gram of 25 sxs. NDBOP,	
OTHER:  13. Describe proposed or com of starting any proposed was proposed completion or responsed com	@ 2780' ne mix w/ 20 sxs mud, spot 25 s to surface. RDMO.  Rig Releated TITLE.  The mail address:	te all pertinent details, NMAC. For Multiple of Section 1. Section 2780' (per OCE ase Date: P&A Tech	Completions: Attach wellbore dia  D). PUH to 1927'- load hole, spot 2  edge and belief.  DATE6/1/2  PHONE: _432-563-33	gram of 25 sxs. NDBOP,	
OTHER:  13. Describe proposed or com of starting any proposed was proposed completion or responsed com	@ 2780' ne mix w/ 20 sxs mud, spot 25 s to surface. RDMO.  Rig Relea	te all pertinent details, NMAC. For Multiple of Section 1. Section 2780' (per OCE ase Date: P&A Tech	Completions: Attach wellbore dia  D). PUH to 1927'- load hole, spot 2  edge and belief.  DATE6/1/2  PHONE: _432-563-33	gram of 25 sxs. NDBOP,	

JUN 09 2015

M