District I 1625 N. French Dr., Hobbs, NM 88240 Phone: (575) 393-6161 Fax: (575) 393-0720 District II			State of New Mexico Energy Minerals and Natural Resources								Form Revised July 18 ENDED REPOF	
811 S. First St., Arte Phone: (575) 748-12 District III					Oil Cons	servatio	on Divis	sion ¥	IOBBS OCD	/ ∐ AM	ENDED REPOR	
1000 Rio Brazos Roa Phone: (505) 334-61					1220 Sou	ith St. I	Francis	Dr.	iobbs occ SEP @ 2 20	15		
District IV 1220 S. St. Francis D Phone: (505) 476-34					Santa	• F <u>e,</u> NN	4 87505	5	SEP V 3 Ce			
		-	OR PERMIT	TO DRI	L. RE-	ENTE	CR. DE				ADD A ZON	
			' Operator Name a	nd Address	X		2		Hills	² OGRID Nun 1364	nber	
Lynx Petroleum Consultants, Inc.							-					
P.O. Box 1708 Hobbs, NM 88241										³ API Number		
										30-025-2	9865	
* Propert	y Code			[•] Property I h AEM S	State No. 1				° Well No 001			
·	<u> </u>		L		⁷ Surface	e Locati	on			L	<u>-</u>	
		Township	nip Range Lot Idn Fe			from N/S Line			Feet From	E/W Line	County	
P	8	18S	36E		66	0	S		660	Е	Lea	
<u>i</u>		l	_ <u></u>	8 D rono	sed Botto		Logati	[
UL - Lot	Section	Township	Range	Lot Idn	Feet fi		N/S L		Feet From	E/W Line	County	
010 500	<u> </u>	Township										
		L								<u></u>		
······································				······································	⁹ Pool In	formati	on					
			5U	Devoniar	ı						2610	
Additiona						Well Information						
11 Work Type E			¹² Well Type SWD-1572	ł	¹³ Cable/R R	· · ·		sease Type		³ Ground Level Elevation 3838' GL		
19 Multiple			17 Proposed Depth	⁷ Proposed Depth ¹⁸ For					Contractor ²⁰ Spud Date		20 Spud Date	
<u>N</u>				<u></u>			onian Undes			ance to nearest surface water 50 Miles		
Depth to Ground W			l	arest fresh water wel	72 IVIII	·				arest surface wate		
X We will be using			a lieu of lined pits			Ť		Program	· · · · · · · · · · · · · · · · · · ·		·	
Туре	Type Hole Size		Casing Size	Casing Weight/ft		Setting Depth		Sacks of Cement		Estimated TOC		
Surface			13_3/8	54.5#		425'		425 sxs		Surface		
Intermediate Production	Intermediate 11 Production 11		<u>8 5/8</u> 5 ½	32		3805		1500		Surface 3500'		
FIOQUEUOU			<u>J_/2</u>	1/			120,0	·		·		
			Ca	sing/Cement	t Prograi	m: Addi	tional (Commen	ts			
									· · · · · · · · · · · · · · · · · · ·			
				²¹ 2Proposed		t Prever						
Туре			V	Working Pressure			Test Pressure			Manufacturer		
See Attached				5000 psi			1500 pis			. Cameron or Equivalent		
		ation given a	bove is true and comple	te to the best of m	у							
	at I have c		h 19.15.14.9 (A) NMA	C 🛛, and/or				OIL CO	ONSERVATIO	ON DIVISION	I	
1915.149(B) NMA		ppiicable.							: Approved	Bv		
Signature:	. •	, ,		•		·				~,		
л. _Б ишинс. Ф	O'll	re 1	nºK. O.					4	en h	-		
Printed name:	••	McKelv	\ <i>\</i> /	7		Title:	Datrol	eum Er	gineer			
Fitle:	Agent	- <u></u>				Approved		09/2		viration Date:	99/alv/1	
E-mail Address:	debmo	ckelvey@	earthlink.net	E-PEI	RM-	KE	·····			C	107 11	
											·····	
Date: 9/2/201	5		Phone: 575-39	2-3575	1 (Conditions	s of Appro	oval Attache	d.			

.

.

Ke

.



. .

Airpath AEM State No. 1 Re-Entry & Completion Procedure

API No.: 30-025-29865

Location: 660' FSL & 660' FEL Section 8, T-18S, R-36E Lea County, New Mexico

Elevation: 3838' GL **KB:** +15'

PBTD: (P&A)

Casing & Cement:

TD: 13,004'

13-3/8", 54.5#/ft., J-55, ST&C @ 425' cmt. w/425 sx. circulated 8-5/8", 32#/ft., K-55, ST&C @ 3805' cmt. w/1500 sx. circulated

Tubing:

None

Cement Plugs:

Surface, 2000'-2100', 3750'-3850', 5150'-5250', 6860'-6960', 10100'-10200', 11425'-11525', and 12744'-12844'

Procedure:

- 1. Clean off location, remove P&A marker, and dig out cellar.
- 2. Rebuild wellhead to leave a 9" x 5M casing flange looking up.
- 3. MIRU drilling rig or workover rig. NU double ram 5,000 psi working pressure BOP stack with 3000 psi rated annular preventer.
- 4. PU 7-7/8" mill tooth bit, DCs, and 3-1/2" drill pipe. Drill out plugs inside casing to 3800'. Test casing to 1500 psig and BOP stack with test plug to 5000 psig.
- 5. Drill cement plugs circulating and conditioning mud system between plugs. Mud properties to be adjusted to conform to the attached Nova Mud recommendations prior to reaching the Wolfcamp formation.
- 6. Circulate and condition hole at TD. Short trip to confirm hole condition.
- 7. POOH laying down drill pipe, DCs, and bit. PU and run 12,875' of 5-1/2", 17#/ft., N-80 casing. Land casing in full tension.
- 8. Cement w/1000 sx. per attached Baker Hughes procedure.
- 9. WOC. ND BOP stack. NU wellhead. RDMO drilling equipment.
- 10. MIRU completion unit. NU hydraulic BOP.
- 11. PU 4-3/4" bit, 6-3-1/2" DCs and 2-7/8" tubing
- 12. RU reverse unit. TIH to float collar.
- 13. Drill out float collar, cement float shoe and open hole to original TD of 13,004'.
- 14. Circulate hole with clean 2% KCL based packer fluid. POOH laying down workstring, DCs, and bit.
- 15. PU AS1X-10K nickel plated packer or equivalent with accessories as follows:

Profile nipple

6' tailpipe

Packer

Profile nipple

On/Off Tool

Plastic coated production tubing.

16. Set packer at +/- 12,800'.

17. ND BOP. NU wellhead.

:

18. Establish injection rate and acidize if necessary with 5000 gallons 15% HCL-NE-FE acid.

19. RDMO completion equipment and place well on injection



