	Form C-103
Office Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 87240	WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	30-025- 11013
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 District IV	STATE FEE Z
1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No. 8910138170 -
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	Myers Langlie Mattix Unit
1. Type of Well:	8. Well Number
Oil Well Gas Well Other Triection	130
2. Name of Operator	9. OGRID Number
OXY USA WTP Limited Partnership	192463
3. Address of Operator	10. Pool name or Wildcat
P.O. Box 50250 Midland, TX 79710-0250	Langlie Mattix 7Rvr On-GB
4. Well Location	
Unit Letter A: 647 feet from the North line and 660 feet from the east line	
Section 5 Township 245 Range 37E	NMRM COUNTY Lea
11. Elevation (Show whether DR, RKB, RT, GR, et	c.)/s
Pit or Below-grade Tank Application or Closure	15 mm (12 B)
Pit type Depth to Groundwater Distance from nearest fresh water well Dis	tance from nearest surface water
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construction	15.3
	CV (17)
12. Check Appropriate Box to Indicate Nature of Notice,	Report, or Other Data
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	_
	LI ALTERING CASING I
TEMPORARILY ABANDON	ALTERING CASING NG OPNS. PLUG AND
TEMPORARILY ABANDON	
TEMPORARILY ABANDON	NG OPNS. PLUG AND
TEMPORARILY ABANDON	NG OPNS. PLUG AND ABANDONMENT
TEMPORARILY ABANDON	NG OPNS. PLUG AND ABANDONMENT Status
TEMPORARILY ABANDON	NG OPNS. PLUG AND ABANDONMENT Status Pertinent dates, including estimated date.
TEMPORARILY ABANDON	Status PLUG AND ABANDONMENT Status E pertinent dates, including estimated date wellbore diagram of proposed completion
TEMPORARILY ABANDON	Status Status PLUG AND ABANDONMENT Status Pertinent dates, including estimated date wellbore diagram of proposed completion for possible future use.
TEMPORARILY ABANDON	Status Status PLUG AND ABANDONMENT Status E pertinent dates, including estimated date wellbore diagram of proposed completion for possible future use.
TEMPORARILY ABANDON	Status PLUG AND ABANDONMENT Status Pertinent dates, including estimated date wellbore diagram of proposed completion for possible future use. Pkr/CIBP 3400
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: CIT - TA 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion. OXY USA WTP LP requests to temporarily abandon this well TD-3788 PBTD-369 Perfs-3479-3658 1. Notify BLM/NMOCD of casing integrity test 24hrs in adv 2. RU pump truck total actions are completed well with treated to the complete starting and the complete starting	Status PLUG AND ABANDONMENT Status Pertinent dates, including estimated date wellbore diagram of proposed completion for possible future use. Pkr/CIBP 3400
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: CIT - TA 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion. OXY USA WTP LP requests to temporarily abandon this well TD-3788 PBTD-369 Perfs-3479-3658 1. Notify BLM/NMOCD of casing integrity test 24hrs in adv 2. RU pump truck Lotton, circulate well with treated	Status PLUG AND ABANDONMENT Status Pertinent dates, including estimated date wellbore diagram of proposed completion for possible future use. Pkr/CIBP 3400 ance. water, pressure test casing
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB OTHER: OTHER: CIT - TA 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion. OXY USA WTP LP requests to temporarily abandon this well TD-3788' PBTD-3695' Perfs-3479-3658 1. Notify BLM/NMOCD of casing integrity test 24hrs in adv 2. RU pump truck 101468, circulate well with treated to 320 # for 30 min.	Status Status PLUG AND ABANDONMENT Status Pertinent dates, including estimated date wellbore diagram of proposed completion for possible future use. Pkr/CIBP 3'(00) ance. water, pressure test casing his Approval of Temporom.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB OTHER: OTHER: CIT - TA 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion. OXY USA WTP LP requests to temporarily abandon this well TD-3788 PBTD-3696 Perfs-3479-3658 1. Notify BLM/NMOCD of casing integrity test 24hrs in adv 2. RU pump truck 104(65, circulate well with treated to 520 # for 30 min.	Status PLUG AND ABANDONMENT Status Pertinent dates, including estimated date wellbore diagram of proposed completion for possible future use. Pkr/GIBP 3400 ance. water, pressure test casing his Approval of Temporary bandonment Expires
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB OTHER: OTHER: CIT - TA 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion. OXY USA WTP LP requests to temporarily abandon this well TD-3188 PBTD-3696 Perfs-3476-3658 1. Notify BLM/NMOCD of casing integrity test 24hrs in adv 2. RU pump truck 1014(65, circulate well with treated to 520 # for 30 min.	Status PLUG AND ABANDONMENT Status Pertinent dates, including estimated date wellbore diagram of proposed completion for possible future use. Pkr/CIBP 3400 ance. water, pressure test casing his Approval of Temporary bandonment Expires and belief I further certify that any pit or below.
TEMPORARILY ABANDON	Status Status PLUG AND ABANDONMENT Status Pertinent dates, including estimated date wellbore diagram of proposed completion for possible future use. Pkr/GIBP 3'(00) ance. water, pressure test casing his Approval of Temporary bandonment Expires and belief. I further certify that any pit or beloward or an (attached) alternative OCD-approved plan
TEMPORARILY ABANDON	Status PLUG AND ABANDONMENT Status Pertinent dates, including estimated date wellbore diagram of proposed completion for possible future use. Pkr/CIBP 3400 ance. water, pressure test casing his Approval of Temporary bandonment Expires and belief I further certify that any pit or below.
TEMPORARILY ABANDON	Status PLUG AND ABANDONMENT Status Pertinent dates, including estimated date wellbore diagram of proposed completion for possible future use. Pkr/CIBP 3'(00) ance. water, pressure test casing his Approval of Temporary bandonment Expires and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan cory Analyst DATE 11 (1) Telephone No. 432-685-5717
TEMPORARILY ABANDON	Status PLUG AND ABANDONMENT Status Pertinent dates, including estimated date wellbore diagram of proposed completion for possible future use. Pkr/CIBP 3'(00) ance. water, pressure test casing his Approval of Temporary bandonment Expires and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan cory Analyst DATE 11 (1) Telephone No. 432-685-5717
TEMPORARILY ABANDON	Status PLUG AND ABANDONMENT Status Pertinent dates, including estimated date wellbore diagram of proposed completion for possible future use. Pkr/CIBP 3'(00) ance. water, pressure test casing his Approval of Temporary bandonment Expires and belief. I further certify that any pit or beloward and belief. I further certify that any pit or below and belief. I further certify that any pit or below and belief. I further certify that any pit or b
TEMPORARILY ABANDON	Status PLUG AND ABANDONMENT Status Pertinent dates, including estimated date wellbore diagram of proposed completion for possible future use. Pkr/CIBP 3'(00) ance. water, pressure test casing his Approval of Temporary bandonment Expires and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan cory Analyst DATE 11 (1) Telephone No. 432-685-5717

