Submit 3 Copies To Appropriate District Office State of New Me. Fineracy Minerals and Nature			Form C-103
Office Energy, Minerals and Natural Resources District I 1625 N. French Dr., Hobbs, NM 87240		May 27, 2004 WELL API NO.	
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION	EDIVISION	30-025-25	
District III 1220 South St. Fra	IRGS DI.	5. Indicate Type of L STATE X	FEE
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87		6. State Oil & Gas L	
1220 S. St. Francis Dr., Santa Fe, NM 87505		o. State Off & Gas E	ease IVO.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Ur STATE A A/C 1	nit Agreement Name:
1. Type of Well:		8. Well Number	
Oil Well Gas Well X Other 2. Name of Operator		9. OGRID Number	
MISSION RESOURCES CORPORATION		148381	
3. Address of Operator		10. Pool name or Wildcat	
1100 LOUISIANA, STE. 1455 HOUSTON, TX 77002 JALMAT; TAN, YATES, 7-RVRS 79240 4. Well Location			7-RVRS /9240
Unit Letter P : 990 feet from the SOU	TH line and	990 feet from	the <u>EAST</u> line
Section 21 Township 23S	Range 36 E	NMPM	County LEA
11. Elevation (Show whether DR. RKB, RT, GR, etc.) 3420 GR			
Pit or Below-grade Tank Application or Closure			
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water			
Pit Liner Thickness: mil Below-Grade Tank: Volume _	bbls; Construction	Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK ALTERING CASING			
<u>_</u> _			
TEMPORARILY ABANDON	COMMENCE DRILLIN	IG OPNS. L	PLUG AND ABANDONMENT
PULL OR ALTER CASING MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB		
OTHER:	OTH ER:		
 Describe proposed or completed operations. (Clearly state all per of starting any proposed work). SEE RULE 1103. For Multiple or recompletion. 		wellbore diagram of p	roposed completion
See attached for Procedure and Wellbore Schematic to	Plug and Abandon	Well. 🚀 🗀	
THE OIL CONSERVATION BY BE NOTIFIED 24 HOURS PARE BEGINNING OF PLUGGING OF	ON MUST TO THE ERATIONS.	Well.	NOV 33 1415 76 NOV 33 Nobbs No
I hereby certify that the information above is true and complete to the			rtify that any pit or below-
grade tank has been/will be constructed or closed according to NMOCD guidelines			
SIGNATURE TITI	Regulatory (boord mator D	ATE
Type or print name Valorie J. Garza		Telepho	one No. 832-369-2125
For State Use Only			TE NOV 1 7 200
Conditions of Approval, if any: DATE NUV 1 / 200 Conditions of Approval, if any:			
or approved, it units.	- 10 STA	· MAINAGEM	

NOV 1 7 2005

Mission Resources Corp. State A A/C-1 #113

Jalmat Field Lea County, NM November 8, 2005

Plugging and Abandonment Procedure

- 1. MIRU work over rig. Bull head water into perfs to kill well. ND tree; NU BOP's.
- 2. RU EL. Run GR/junk basket to 3000'±. Set CIBP @ 2995'±. Test casing to 500 psi..
- 3. TIH with workstring. Load hole with gelled 10# brine.
- 4. Mix and spot 200' cement plug from 2795-2995' (base of salt @ 2895').
- 5. Mix and spot 200' cement plug from 1350-1550' (top of salt @ 1450').
- 6. Mix and spot 200' surface cement plug
- 7. Cut off wellhead weld on P&A marker.
- 8. Clean off location for OCD inspection.

1390 - 1290 1390 - 1290 1390 - 300? 136.540E 1A6



