୍ଦି କ୍ଷେତିmet 3 Copies To Appropriate District Office District I	State of New Mexico Energy, Minerals and Natural Resources		Form C-103 May 27, 2004
1625 N. French Dr., Hobbs, NM 88240	877		WELL API NO. 30-025-24182
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210 District III	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410		e, NM 87505	STATE FEE X
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Sama P	C, INIVI 67303	6. State Oil & Gas Lease No. OG-426 & E-26
87505	TORG AND DEDORTE O	AT TARRET & C	
(DO NOT USE THIS FORM FOR PROPODIFFERENT RESERVOIR. USE "APPLIPROPOSALS.)		PEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name Bagley State Com
1. Type of Well: Oil Well X Gas Well Other			8. Well Number 1
Name of Operator Latigo Petroleum, Inc.			9. OGRID Number 227001
3. Address of Operator 550 W. 7 Midland,	Texas, Suite 700 , TX 79701		10. Pool name or Wildcat Bagley; Permo Penn, North
4. Well Location			
Unit Letter F:	1980 feet from the	N line and	1980 feet from the W line
Section 34	Township 11		NMPM CountyLea
	11. Elevation (Show will 4286' GR.	hether DR, RKB, RT, GR,	etc.)
Pit or Below-grade Tank Application			<u> </u>
Pit typeDepth to Groundy	vaterDistance from ne	arest fresh water well	Distance from nearest surface water
Pit Liner Thickness: mil	Below-Grade Tank: Vo	olume bbls;	Construction Material
12 Check	Appropriate Roy to Ir	ndicate Nature of Notic	ce, Report or Other Data
			•
	NTENTION TO:		JBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS		'ORK ☐ ALTERING CASING ☐ ☐ DRILLING OPNS.☐ P AND A ☐
TEMPORARILY ABANDON PULL OR ALTER CASING		☐ COMMENCE	
TOLE ON NETER ON ONTO	MOETH LE COM L		
OTHER:	1, 1, 1, (01, 1	OTHER:	
			, and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
Unable to fish rods and tubing beld 1) RIH w/ cement retainer, set (a)			
2) Circulate hole w/ 10# mud 3) Cut and pull 4-1/2" pipe @ 3	800°.		
4) Spot 30 sx cement plug @ 38	850- 37	60 W.O.C.+	TAG
5) Spot 30 sx cement plug @ 1650'			
3) Cut and pull 4-1/2" pipe @ 3800'. 4) Spot 30 sx cement plug @ 3835' 3 850 - 3760' W.O.C. + TAG 5) Spot 30 sx cement plug @ 1650' 6) Spot 30 sx cement plug @ 450' - W.D.C. + TAG 7) Spot 10 sx surface plug @ 350' 1234" SHOE PLUG 8) Cut off wellhead, install DH marker, clean and level location.			
8) Cut off wellhead, install DH	marker, clean and level lo	cation.	Mark Control
			and the second s
			ns (AW
,	THE OIL CONSER	VATION DIVISION	MUSI
	~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~		
	EL ADIMILE ALDI	LUGGING OPERAT	IONS.
	BECKNILLING OF		
	-		
			edge and belief. I further certify that any pit or below- t or an (attached) alternative OCD-approved plan
SIGNATURE Lisa	Huxt	TITLE Regulatory Analys	DATE 12/22/2005
Type or print name Lisa Hunt For State Use Only			
- or search out Only		E-mail address: lhunt@lar	tigopetro.com Telephone No. (432)684-4293
APPROVED BY: Hary U	1. Wink	E-mail address: lhunt@la	•

